


AD-A091 268

RUMMEL KELEPPER AND KAHL BALTIMORE MD  
NATIONAL DAM INSPECTION PROGRAM. JOHNSON'S POND (NDI-ID NUMBER --ETC(U)  
JUL 80 E J ZEIGLER DACW31-80-C-0050

F/G 13/13

NL

UNCLASSIFIED



END  
DATE  
FILMED  
42-80  
DTIC

WICOMICO RIVER BASIN  
WICOMICO RIVER, WICOMICO COUNTY

MARYLAND


JOHNSON'S POND

NDI ID NO. MD-11

CITY OF SALISBURY

LEVEL

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



DTIC  
NOV 6 1980  
C

Prepared For  
DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

DACW31-80-C-0050  
By

RUMMEL, KLEPPER & KAHL  
Consulting Engineers  
Baltimore, Maryland 21202

JULY 1980

DISTRIBUTION STATEMENT A  
Approved for public release;  
Distribution Unlimited

AD A091268


DDG FILE COPY

\*Original contains color  
plates. All DTIC reproductions  
will be in black and  
white.

8011 03 078

⑩ Edward G. Hoiglet

P



⑪ Jul 80

⑮ DACW31-80-C-0050

⑫ 93

Prepared for:  
DEPARTMENT OF THE ARMY  
Baltimore District Corps of Engineers  
Baltimore, Maryland 21203

By:  
RUMMEL, KLEPPER & KAHL  
Consulting Engineers  
1035 N. Calvert Street  
Baltimore, Maryland 21202

July 1980

DISTRIBUTION STATEMENT A  
Approved for public release;  
Distribution Unlimited

411913

SP

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Department of the Army, Office of Chief of Engineers, Washington, D.C. 20314.

The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon visual observations and review of available data. Detailed investigations and analyses involving topographic mapping, subsurface investigations, material testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the inspection is intended to identify any need for such studies which should be performed by the owner.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of the dam depends on numerous and constantly changing internal and external factors which are evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The assessment of the conditions and recommendations was made by the consulting engineer in accordance with generally and currently accepted engineering principles and practices.

WICOMICO RIVER BASIN  
WICOMICO RIVER, WICOMICO COUNTY  
MARYLAND

JOHNSON'S POND  
NDI ID NO. MD-11  
CITY OF SALISBURY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

July 1980

CONTENTS

<u>Description</u>	<u>Page</u>
SECTION 1 - Project Information	1
SECTION 2 - Design Data	4
SECTION 3 - Visual Inspection	6
SECTION 4 - Operational Procedures	9
SECTION 5 - Hydrology and Hydraulics	10
SECTION 6 - Structural Stability	14
SECTION 7 - Assessment, Recommendations, and Proposed Remedial Measures	15

APPENDICES

<u>Appendix</u>	<u>Title</u>
A	Visual Inspection Checklist
B	Engineering Data Checklist
C	Photographs
D	Hydrology and Hydraulics
E	Plates
F	Geology

Accession For	
NTIS GRA&I	
DTIC TAB	
Unannounced	
Justification <i>per form</i>	
<i>So a file</i>	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or
	Special
<b>A</b>	

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITION  
AND RECOMMENDED ACTION

Name of Dam: Johnson's Pond  
NDI ID NO. MD-11  
Size: Intermediate (1930 acre-feet, 16.5 feet high)  
Hazard Classification: High  
Owner: City of Salisbury  
P.O. Box 791  
Salisbury, Maryland 21801  
State Located: Maryland  
County Located: Wicomico  
Stream: Wicomico River  
Date of Inspections: July 10, 1980 and August 5, 1980

Based on the visual inspection, available records, past operational performance, and in accordance with the guideline criteria established for these studies, Johnson's Pond dam is judged to be in good condition.

The dam is constructed across the full width of the North Prong of the Wicomico River in Salisbury, Maryland. The dam consists of a concrete and steel ogee spillway, wingwalls, and a clay fill embankment constructed on either side of the spillway. Including the lengths of clay fill embankments shown on the contract drawings of the dam, the total length of the dam is 580+ feet. The concrete and steel structure is comprised of a 300 foot long ogee spillway with wingwalls at the left and right abutments. According to the dam crest survey, the lowest point along the clay fill is elevation 14.5 and is located adjacent to the right wingwall. The crest elevation of the ogee spillway is +11.1, and a 30 foot long notch with a crest elevation of 10.6 is located in the middle of the spillway. Three sluice gates are located in the spillway directly below the notch.

The water level in Johnson's Pond is normally maintained at elevation +11, the crest elevation of the ogee spillway. The water level can be controlled by opening any of the three manually operated sluice gates. The gates are normally opened once a year during the winter to lower the water level by approximately 6 feet. This is done to expose and kill plants growing on the bottom of the pond. The water level was lowered one foot below the crest elevation for this inspection so that the condition of the ogee spillway could be checked.

Several cracks were noted in the concrete of the ogee spillway and the wingwalls, but the cracks are not considered large enough to adversely affect the structural stability of the dam at this time. The two largest cracks were noted on the wingwalls, extending through the

walls from the spillway crest to the top of the wingwall. The crack in the left wingwall is approximately 0.25 inch wide and the crack in the right wingwall is approximately 0.5 inch wide. Cracking is responsible for a piece of concrete being displaced on the upstream side of the spillway along a joint located 20+' left of the spillway notch. No displacement was noted along any other cracks in the spillway, and no water was noted seeping through the cracks on the downstream side of the spillway. Minor spalling of the concrete was noted on the crest of spillway near the left wingwall.

According to the hydrologic and hydraulic analyses, the Johnson's Pond embankment will overtop by 0.4 foot for a duration of 10 hours during a flood equaling 50 percent of the Probable Maximum Flood (PMF). The analyses indicate that the Johnson's Pond spillway can pass approximately 43% of the PMF before overtopping commences. Dam breach analyses suggest that failure of the Johnson's Pond dam would raise water levels in the industrialized area between Isabella Street and U.S. Route 50 by less than one foot over the water surface that would have existed just prior to failure. It is judged that this nominal rise in flood levels would not significantly increase the hazard to loss of life than that already existing prior to dam failure. Therefore, the spillway of the Johnson's Pond dam is rated as inadequate, but not seriously inadequate.

The following remedial measures are recommended to be accomplished by the Owner:

1. Conduct a hydrologic and hydraulic study to determine what remedial measures are necessary to provide adequate capacity of the spillway.
2. Repair the cracks which extend through the right and left wingwalls from the crest of the ogee spillway to the top of each wingwall.
3. Repair the cracks noted in the ogee spillway before the cracks enlarge.
4. Raise the embankment to the design elevation.
5. Carefully inspect the ogee spillway for additional cracks, seepage through cracks or displacement of concrete along the cracks at least once a year while the water level is down.
6. Develop a formal warning system to alert downstream residents in the event of emergencies.

Submitted by:

RUMMEL, KLEPPER & KAHL



Edward J. Zeigler  
Edward J. Zeigler, P.E.  
Associate

Date: August 28, 1980

Approved by:

James W. Peck  
JAMES W. PECK  
Colonel, Corps of Engineers  
District Engineer

Date: 18 Sep 80

JOHNSON'S POND



A. OVERVIEW

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JOHNSON'S POND  
NDI ID NO. MD-11

SECTION 1  
PROJECT INFORMATION

1.1 General.

- a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.
- b. Purpose. The purpose of the dam inspection program is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

- a. Dam and Appurtenances. Johnson's Pond dam consists of a concrete and steel ogee spillway, wingwalls, and a clay fill embankment constructed on either side of the spillway. According to the profile of the dam shown on the contract drawings, the total length of the dam, including the clay fill embankments, is 580+ feet. The concrete and steel ogee spillway is 300 feet long. The low point elevation along the clay fill, noted adjacent to the right wingwall, is 14.5; the elevation of the wingwalls is 16; the crest elevation of the ogee spillway is 11.1; and the elevation of a 30 foot long notch located in the center of the ogee spillway is 10.6. The water level in Johnson's Pond is normally maintained at the crest elevation of the ogee spillway. The water level can be lowered by opening three manually operated sluice gates located below the notch in the ogee spillway.
- b. Location. The dam is constructed across the North Prong of the Wicomico River in Salisbury, Maryland approximately 0.6 mile upstream of the Route 50 bridge. Johnson's Pond is shown on U.S.G.S. Quadrangle, Salisbury, Maryland, at latitude N 38° 22' 24" and longitude W 75° 36' 6". A location map is included as Plate E-1.
- c. Size Classification. Intermediate (1930 acre-feet, 16.5 feet high).

- d. Hazard Classification. High Hazard. There are businesses and residences along the Wicomico River downstream of the dam which could be damaged in a flood resulting from a dam failure. The embankment and bridge carrying Isabella Street over the Wicomico River 700 feet downstream of the dam could also sustain damage from a flood.
- e. Ownership. City of Salisbury, P.O. Box 791, Salisbury, Maryland 21801
- f. Purpose of Dam. Recreation.
- g. Design and Construction History. The dam was constructed in 1936 by the Federally funded Works Progress Administration. According to profiles and typical sections of the dam shown on the contract drawings, the dam is 580+ feet long, including the 300 foot long ogee spillway, wingwalls, and clay fill embankments on either side of the spillway. The ogee spillway is 20 feet wide at the base and is constructed in between two lines of steel sheet piles. The steel sheet piles extend 100 feet outside the wingwalls on either side of the spillway.
- h. Normal Operating Procedure. Johnson's Pond is normally maintained at the spillway crest elevation of +11. The sluice gates are usually opened during the winter to lower the water level enough to expose and kill plants growing on the bottom of the pond.

1.3 Pertinent Data.

- a. Drainage Area. 42 square miles
- b. Discharge at Dam Site. 6800 cfs (outflow at elevation 14.5)
- c. Elevation (Feet above m.s.l.).
  - Top of Dam 16.0 (design)  
14.5 (low point on clay fill embankment)
  - Normal Pool 11.1 (spillway crest)
  - Upstream Invert Outlet Works 2.5
  - Downstream Invert Outlet Works 2.5
  - Streambed at Centerline of Dam -5.0
  - Maximum Tailwater +8.0
  - Downstream Toe (Bottom of concrete on ogee spillway) -8.0
- d. Reservoir Length.
  - Normal Pool 7700 feet
  - Top of Dam 12400 feet

e. Storage (Acre-Feet).

Normal Pool	900
Top of Dam	1930

f. Reservoir Surface (Acres).

Normal Pool	104
Top of Dam	274

g. Dam.

Type	Clay fill
Length	580+'
Height	16.5' (low point on clay fill embankment)
Top Width	70+' at the wingwalls to 200+' at the natural bank
Volume of Fill	11000 cu.yds.
Side Slopes	Unknown
Zoning	None
Impervious Core	None
Cutoff	Steel Sheet Piling
Grout Curtain	None

h. Outlet Works.

Type	Pressure type
Pipe Size and Material	Three, 48 inch square openings formed in concrete of ogee spillway
Entrance Invert	2.5
Exit Invert	2.5
Type and Number of Gates	Three, 48 inch square sluice gates
Type of Energy Dissipator	Concrete toe of ogee spillway

i. Principal Spillway.

Type	Ogee Spillway
Crest Elevation of Spillway	11.1
Length of Spillway	300' (including notch)
Crest Elevation of Notch in Spillway	10.6
Length of Spillway Notch	30'
Cutoff	Steel Sheet Piling

SECTION 2  
DESIGN DATA

2.1 Design.

a. Data Available. The available information was provided by the State of Maryland, Water Resources Administration. The information consists of a revised set of contract drawings dated August 1, 1936 and a limited amount of design computations and correspondence relative to design of the dam.

(1) Hydrology and Hydraulics. A limited amount of hydrologic and hydraulic computations are available.

(2) Embankment. The only information available is shown on the contract drawings.

(3) Appurtenant Structure. The only information available is shown on the contract drawings.

b. Design Features.

(1) Embankment. According to the contract drawings, the embankment on either side of the ogee spillway is comprised of clay fill. Steel sheet piling which was driven for the upstream side of the ogee spillway extends approximately 100'+ from the wingwalls into the embankments on either side of the spillway. The top elevation of the sheet piling is +5 and the bottom elevation ranges from -2 to -15. The fill cannot be differentiated from natural ground, but based on the contract drawings, the clay fill extends approximately 140 feet from the wingwalls on either side of the spillway.

(2) Appurtenant Structures. The appurtenant structures of the dam consist of the ogee spillway and the outlet works. The concrete and steel ogee spillway is 300 feet long and has a 30 foot long notch at its center. The ogee spillway is constructed in between two lines of steel sheet piling having a top elevation of +5 on the upstream side and a top elevation of 0 on the downstream side. The outlet works consist of three, 48 inch square openings equi-spaced below the spillway notch and three 48 inch square sluice gates. The gate stems are located on a deck constructed above the spillway notch. The water level in Johnson's Pond can be lowered by opening the gates.

c. Design Data.

(1) Hydrology and Hydraulics. Limited design data are included in the available design computations.

(2) Embankment and Appurtenant Structures. The only design data available are shown on the contract drawings.

2.2 Construction. Construction of the dam was completed in 1936. No dam construction records are available.

2.3 Operation. No records are kept of the operation of the dam or appurtenant structures.

2.4 Other Investigations. No records of other investigations are available.

2.5 Evaluation.

a. Availability. The contract drawings, the limited design computations, and the correspondence provided by the State of Maryland, Water Resource Administration are the only data available.

b. Adequacy. The available data, not including any construction records or detailed design calculations, is considered insufficient to evaluate the design and construction of the dam.

SECTION 3  
VISUAL INSPECTION

3.1 Findings.

a. General. The on site inspection of Johnson's Pond consisted of:

- (1) Visual inspection of the embankment, abutments, and embankment toe.
- (2) Visual examination of the appurtenant structures.
- (3) Evaluation of the downstream area hazard potential.

The specific observations are shown on Plate A-1.

b. Embankment. The general inspection of the embankment consisted of searching for indications of structural distress, such as cracks, subsidence, bulging, wet areas, seeps and boils, and observing general maintenance conditions, vegetative cover, erosion, and other surficial features. The contract drawings indicate that the clay fill extends approximately 140 feet from the wingwalls on either side of the ogee spillway. Other than the noticeable projection of the fill into the river on the left side of the dam the clay fill cannot be differentiated from natural ground. The fill on the left side of the dam is covered primarily with grass, and trees grow along the bank. The fill on the right side is covered with grass and trees.

The crest of the clay fill embankment was surveyed and the variance in elevation was 10 inches between the high and low point on the left side, and was 36 inches between the high and low point on the right side. It should be noted that the contract drawings show that the clay fill on both sides of the ogee spillway was to be constructed even with the top of the wingwalls, or to elevation 16. The low point of the fill was elevation 14.5 noted adjacent to the right wingwall. The crest elevations measured on the left side of the dam ranged from 15.1 to 15.8. Since there is no evidence that any fill was removed from the crest by natural processes, it is presumed that either the fill was not constructed in accordance with the contract drawings, or regrading of the fill has been accomplished since construction of the dam.

Datum for the crest survey was based on a reference elevation on the crest of the ogee spillway provided by the chief surveyor for the City of Salisbury. The dam crest profile is included on Plate A-2.

- c. Appurtenant Structures. Generally, the appurtenant structures were found to be in good condition. Several cracks were noted in the concrete of the ogee spillway and the wingwalls, but the cracks are not considered large enough to adversely affect the structural stability of the dam at this time. The two largest cracks were noted on the wingwalls, extending through the walls from the spillway crest to the top of the wingwall. The crack in the left wingwall is approximately 0.25 inches wide and the crack in the right wingwall is approximately 0.5 inches wide. Cracking is responsible for a piece of concrete being displaced on the upstream side of the ogee spillway along a joint located 20+ feet left of the spillway notch. No displacement was noted along any other cracks in the spillway, and no water was noted seeping through the cracks on the downstream side of the spillway. Minor spalling of the concrete was noted on the spillway crest near the left wingwall.

To expose the spillway for our inspection, the pond level was lowered approximately 1 foot by opening the sluice gates the day before our visit.

During our inspection, personnel of the City of Salisbury manually closed all three sluice gates, and the gates appeared to function satisfactorily. The gates are normally opened at least once a year, and usually during the winter, to lower the water level in order to expose and kill plants growing on the bottom of the pond.

The crest of the ogee spillway was surveyed and the variance in elevation was 1 inch between the high and low point, not including the spillway notch at the center of the spillway. The low point elevation was 11.1, which is equal to the design crest elevation of the spillway. The Dam Crest Profile is included on Plate A-2.

- d. Reservoir Area. An urban residential area surrounds the impoundment. A community beach and recreational area is located along the left shoreline of Johnson's Pond approximately 800 feet upstream from the dam. No significant amount of shore erosion was noted.
- e. Downstream Channel. The downstream channel is the North Prong of the Wicomico River. Its confluence with the South Prong is 0.75 miles downstream of the dam. A railroad trestle bridge is located 400+ downstream of the dam, and the bridge opening at Isabella Street is 700+ feet downstream. Approximately 25 feet upstream of Isabella Street is a wooden weir which extends across the river and controls the tailwater level of Johnson's Pond. The floodplain downstream from the

dam is highly industrialized, particularly between the Isabella Street bridge and the Maryland Route 50 bridge, located approximately 0.6 miles downstream of the dam. A few residences were noted in the floodplain downstream of the Route 50 bridge.

- 3.2 Evaluation. The visual examination and observations of the Johnson's Pond dam indicated that the structure is in good condition. We recommend that the cracks in the wingwalls be repaired the next time the sluice gates are open for an extended period of time.

SECTION 4  
OPERATIONAL FEATURES

- 4.1 Procedure. There are no formal operating procedures for the dam. The pond level is normally maintained at the crest elevation of the ogee spillway. During the winter, personnel of the City of Salisbury open the sluice gates to lower the water level approximately 6 feet to expose and kill plants growing on the bottom of Johnson's Pond.
- 4.2 Maintenance of the Dam. Maintenance of the dam is considered to be satisfactory.
- 4.3 Maintenance of Operating Facilities. Maintenance of the Operating Facilities is considered to be satisfactory.
- 4.4 Warning System. No formal warning system exists for the dam. Telephone communication facilities are available from the residences along the shoreline upstream from the dam.
- 4.5 Evaluation. The overall maintenance condition of the dam and its appurtenant structures is considered to be good.

SECTION 5  
HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features.

- a. Design Data. Correspondence dated January 30, 1936 and addressed to the Water Resources Commission of Maryland by the City of Salisbury indicates that the spillway for Johnson's Pond was designed to carry a peak discharge of 8400 cubic feet per second (cfs) or 200 cfs per square mile from a 42-square mile Wicomico River drainage area. Subsequent review computations by the State of Maryland suggests that the design depth of flow over the spillway crest was approximately 4 feet. Based upon the final spillway crest elevation shown on August 1, 1936 contract drawings, the apparent design high water level for Johnson's Pond was about 15 feet above mean sea level when passing 8400 cfs.

- b. Experience Data. No records of maximum pool levels are available.

In August, 1933, prior to construction of the dam for Johnson's Pond at its present site, a major flood overtopped the existing bridge and embankment which formed the original dam for Johnson's Pond at Isabella Street some 700 feet downstream from the present dam site. It is reported that this flood event washed out the eastern bridge approach rendering the dam useless.

Tide data for the Wicomico River indicates a mean high tide of 2.07 feet above m.s.l. and a mean low tide of 0.93 feet below mean sea level. Driven timber sheeting forming a sharp crested weir across the Wicomico River just upstream from Isabella Street eliminates the affect of normal tidal fluctuations upon tailwater levels at the present dam for Johnson's Pond since its crest elevation exceeds mean high tide events. However, during record high tide events, the weir becomes submerged and tidewaters extend to the spillway apron at Johnson's Pond. Available data indicates that the August 1933 flood produced a record high tide of 8.07 feet above m.s.l.

- c. Visual Observations. Several observations made during the visual inspection of the Johnson's Pond impoundment are particularly relevant to the hydraulic and hydrological evaluations.

- (1) Embankment. The field survey of the embankments or non-overflow sections of the dam adjacent to the left and right wingwalls of the ogee spillway indicates that the crests of the existing non-overflow sections are lower than their design elevation of 16 feet above m.s.l. The low points for the left and right non-overflow sections are 15.1 and 14.5 feet above m.s.l., respectively. The data for the existing crests of the non-overflow sections was employed in subsequent hydraulic analyses.
  - (2) Ogee Spillway and Appurtenant Structures. The spillway crest has been constructed in accordance with the record contract drawings. The three 48-inch by 48-inch sluice gates which control discharges through openings in the ogee spillway below its crest were demonstrated during the visual inspection and operated as designed. These gates are normally closed except for a short period in the winter when the pool level is lowered to implement vegetation control measures. Subsequent hydraulic analyses assumes that these gates are in a closed position during the occurrence of a major flood event.
  - (3) Downstream Conditions. Failure of the dam impounding Johnson's Pond could cause significant damage to the intensely developed industrialized area downstream between Isabella Street and U.S. Route 50. Large fuel oil storage depots serving the Maryland Eastern Shore characterize the major type of industrial development in this area. Other facilities situated in this reach include a brickyard, feed supply center, automotive parts warehouse, concrete plant, and state highway maintenance yard. Because of the constricted opening at the Isabella Street bridge, a dam failure could also result in overtopping of the Isabella Street bridge approaches and severing Isabella Street, a Salisbury thoroughfare. Several shore residences situated just upstream from the dam but adjacent to and just slightly above the crest elevation of the left dam abutment could also be damaged if the dam abutments were overtopped. In keeping with the potential hazard classification criteria established by the Office of the Chief of Engineers (OCE), the downstream conditions suggest that a high hazard classification be assigned to the dam impounding Johnson's Pond.
- d. Overtopping Potential. According to the criteria promulgated by the Office of the Chief of Engineers, the recommended Spillway Design Flood (SDF) for a dam classified as "intermediate" with a "high" hazard potential is 100 percent of the Probable Maximum Flood (PMF).

The Probable Maximum Precipitation (PMP) index as adjusted for the Johnson's Pond drainage area is 21.1 inches in 24 hours. Employing criteria established by the Corps of Engineers, Baltimore District, 100 percent and 50 percent PMF inflow hydrographs developed using the HEC-1 computer program have peaks of 15,800 and 7,900 cfs, respectively. The 8400 cfs discharge rate employed in the original spillway design would occur during a flood event equivalent to 54 percent of the Probable Maximum Flood.

PMF inflow hydrographs were routed through Johnson's Pond for percentages ranging from 10 to 100 percent of the PMF with each routing starting at the normal pool level of 11.1 feet above m.s.l. These initial analyses employ ogee spillway discharge ratings which neglect the affect of spillway submergence caused by downstream conditions. . Spillway submergence resulting from backwater may occur as a result of the severe downstream channel constriction caused by the approaches to the Isabella Street bridge. The initial analyses suggest that the Johnson's Pond spillway can pass approximately 43 percent of the PMF without overtopping the adjacent non-overflow sections of the dam. However, for the 50 percent PMF routing, the reservoir water level reached an elevation of 14.9 feet above m.s.l. overtopping the low point in the right dam embankment by 0.4 feet. For the 100 percent PMF routing, the reservoir water level reached an elevation of 16.9 feet above m.s.l. overtopping the embankment low point by 2.5 feet. Additional results for the initial routing analyses are found in Appendix D.

Downstream channel routings of outflow hydrographs generated by the above reservoir routings indicate that the barrier caused by the approaches to the Isabella Street bridge will produce backwater conditions extending upstream to the Johnson's Pond spillway. In addition these analyses indicate that these approaches will be overtopped if the flood event exceeds 10 percent of the PMF. If these bridge approaches fail upon overtopping, the results from the initial reservoir routing analyses for Johnson's Pond can be considered valid since backwater conditions caused by the bridge embankment would not materialize for the 50 and 100 percent PMF events. If it is assumed that the bridge approaches do not fail, this affect or resultant backwater conditions upon the spillway discharge must be considered.

Additional analyses, which consider these potential backwater conditions, were performed for Johnson's Pond using inflow hydrographs ranging from 10 to 100 percent of the PMF. Under these conditions the additional analyses suggest that the Johnson's Pond spillway can pass only approximately 11 percent of the PMF without overtopping the non-overflow sections of the dam. For the 50 percent PMF routing the reservoir water level reached an elevation of 16.9 feet

above m.s.l. overtopping the embankment low point by 2.4 feet. For the 100 percent PMF routing, the corresponding water level and overtopping depth are 18.2 feet above m.s.l. and 3.7 feet, respectively. Results for intermediate routings of the alternate analyses are found in Appendix D.

- e. Spillway Adequacy. It is probable that the approaches to the Isabella Street bridge would fail prior to any failure of embankments adjacent to the Johnson's Pond spillway. For this reason, the initial reservoir routing analyses, which neglect tailwater conditions caused by the constriction at Isabella Street, have been employed in evaluating the spillway adequacy. These analyses indicate that overtopping of the Johnson's Pond embankment during the occurrence of a 50 percent PMF event would have a duration of 10.0 hours. It is judged that a 0.4 foot maximum overtopping depth and 10.0-hour duration could be sufficient to result in failure of the dam embankment. Dam failure analyses have been performed for two different failure configurations for a 50-percent PMF event assuming each failure begins when the dam first starts to be overtopped. (Failure configurations are identified in Appendix D). On the basis of these analyses, routing of the resultant flood wave downstream suggests that failure of the Johnson's Pond dam would raise water levels in the industrialized area between Isabella Street and U.S. 50 by only 0.5 feet to 0.7 feet over the water surface that existed just prior to failure, depending upon the breach configuration employed. It is important to note, however, that flood levels produced by passage of a 50 percent PMF flood event through this industrialized reach, assuming no dam failure, would exceed the top of the adjacent seawalls by approximately 5 feet. Such levels could cause serious damage to the industrialized development in this area and would undoubtedly pose a hazard to loss of life. It is judged that an increase of less than one foot over this flood level by a concurrent failure of Johnson's Pond would not significantly increase the hazard to loss of life already existing prior to the dam failure. Therefore the spillway is rated as inadequate but not seriously inadequate in accordance with Office of the Chief of Engineers guidelines.
- f. Additional Considerations. In evaluating the overtopping potential and spillway adequacy of Johnson's Pond, it was assumed that the peak spillway discharge resulting from a 50 percent probable maximum flood event occurred when the water level in the downstream reaches was at a mean high tide level of 2.1 feet above m.s.l. Should the occurrence of such an event coincide with a high tide equal in magnitude to the 8.1 high tide of record for the Salisbury area, it follows from the previous analyses that failure of the Johnson's Pond dam would not significantly increase the hazards associated with the flood and record high tide event over those hazards already existing prior to the failure.

SECTION 6  
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations.

- (1) Embankment. No deficiencies were noted for the clay fill embankment on either side of the ogee crest which could adversely affect the structural stability of the dam.
- (2) Appurtenant Structures. At this time, the cracks noted in the wingwalls and in the ogee spillway are not considered large enough to adversely affect the structural stability of the dam. However, the existing cracks should be repaired so that they do not enlarge and pose a potential threat to the stability of the dam.

b. Design and Construction Data.

- (1) Embankment. The stability of the clay fill embankment cannot be adequately evaluated because of insufficient construction records and design calculations.
- (2) Appurtenant Structures. The contract drawings include the structural details of the appurtenant structures and are sufficient to assess the adequacy of the ogee spillway, wingwalls, and sluice gates.

c. Operating Records. The structural stability of the dam is not considered to be affected adversely by its operational features of the dam.

d. Seismic Stability. Johnson's Pond dam is located in Seismic Zone 1. Based on our visual observations, the static stability of the dam appears to be adequate. Consequently, the structure should present no hazard from earthquakes.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment.

- a. Assessment. Johnson's Pond is an intermediate, high hazard impoundment. Failure of the dam embankment could cause significant damage to the intensely developed industrialized area downstream between Isabella Street and U.S. Route 50. The visual observations indicate that the embankment of Johnson's Pond is in good condition. At this time, the cracks noted in the wingwalls and the ogee spillway are not large enough to adversely affect the structural stability of the dam. However, the cracks should be repaired before they enlarge and pose a threat to the structural stability.

Hydrologic and hydraulic analyses indicate that the Johnson's Pond dam would be overtopped during a flood equaling 50 percent of the Probable Maximum Flood (PMF), but would not be overtopped by a flood event equal to or less than 48 percent of the PMF. Dam breach analyses suggest that failure of the Johnson's Pond dam would raise water levels in the industrialized area between Isabella Street and U.S. Route 50 by less than one foot over the water surface that would have existed just prior to failure. It is judged that this nominal rise in flood levels would not significantly increase the hazard to loss of life than that already existing prior to dam failure. Therefore, the spillway of the Johnson's Pond dam is rated as inadequate, but not seriously inadequate.

- b. Adequacy of Information. Coupled with the visual observations, the available information, even though it does not include construction records or design calculations for the clay fill embankments, is considered to be sufficient to make the recommendations that are given below.
- c. Urgency. Although there is no urgency in instituting the remedial measures recommended below, the measures should be accomplished in a timely manner.
- d. Necessity for Additional Information. No additional information is needed.

7.2 Recommendations/Remedial Measures.

It is recommended that the following remedial measures be implemented by the Owner:

- a. Conduct a hydrologic and hydraulic study to determine what remedial measures are necessary to provide adequate capacity of the spillway.

- b. Repair the cracks which extend through the right and left wingwalls from the crest of the ogee spillway to the top of each wingwall.
- c. Repair the cracks noted in the ogee spillway before the cracks enlarge.
- d. Raise the embankment to the design elevation.
- e. Carefully inspect the ogee spillway for additional cracks, seepage through cracks, or displacement of concrete along the cracks at least once a year while the water level is down.
- f. Develop a formal warning system to alert downstream residents in the event of emergencies.

APPENDIX A

VISUAL INSPECTION CHECKLIST

PHASE I

APPENDIX A  
VISUAL INSPECTION CHECKLIST  
PHASE I

Name of Dam: Johnson's Pond County (or City): Wicomico State: Maryland  
NDI ID. No.: MD- 11 Type of Dam: Concrete spillway Hazard Category: High  
Date(s) Inspection: 7/10/80 & 8/5/80 Weather: Partly Cloudy Temperature: 90°F  
Pool Elevation at Time of Inspection: 10'± above M.S.L. Tailwater at Time of Insp. 4'± M.S.L.

Inspection Personnel:

Douglas Nauman  
Jim Wise  
\_\_\_\_\_

Review Inspection Personnel:

Edward J. Zeigler  
Frank H. Donaldson  
Douglas Nauman  
Douglas Nauman Recorder

VISUAL INSPECTION  
 PHASE I  
 EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Several cracks were noted in the concrete of the wing-walls and ogee spillway of the dam.	No leakage through or displacement along the cracks in the ogee spillway were noted.
USUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal alignment satisfactory Vertical alignment of embankment left of spillway varies 0.7', and right of spillway varies 3.0'	Vertical alignment of spillway crest varied 1 inch, and the low point elevation was equal to the design crest elev.
RIPRAP FAILURES		

VISUAL INSPECTION  
 PHASE I  
 EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	A crack was noted through both left and right wingwalls extending from spillway crest to top of wingwall	Patch the cracks
ANY NOTICEABLE SEEPAGE	None	
STAFF GAGE AND RECORDER	None	
DRAINS	None	

VISUAL INSPECTION  
 PHASE I  
 OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	The 3 outlet openings through spillway are in satisfactory condition	
INTAKE STRUCTURE	N/A	
OUTLET STRUCTURE	N/A	
OUTLET CHANNEL	N/A	
EMERGENCY GATE	Three, 48" x 48" sluice gates on upstream side of spillway at spillway notch	

VISUAL INSPECTION  
 PHASE I  
 UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	30 foot section of 300 foot ogee spillway is notched. Notch centrally located on spillway.	
APPROACH CHANNEL	None	
DISCHARGE CHANNEL	None	
BRIDGE AND PIERS	None	

VISUAL INSPECTION  
 PHASE I  
 GATED SPILLWAY

VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

VISUAL INSPECTION  
 PHASE I  
 INSTRUMENTATION


VISUAL EXAMINATION OF MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None	
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER		

VISUAL INSPECTION  
 PHASE I  
 RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Area surrounding reservoir is urbanized; vegetated up to bank	
SEDIMENTATION	No significant amount of sedimentation was evident	
UPSTREAM RESERVOIRS	Leonard Pond located approximately 3 miles upstream at U.S. Rte. 13	

VISUAL INSPECTION  
 PHASE I  
 DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	400± downstream of dam is railroad trestle bridge; 700± downstream is Isabella St. embankment and bridge.	An old wooden weir extends across channel immediately upstream of Isabella St. bridge.
SLOPES	Slopes upstream of Isabella St. are generally wooded. Slopes downstream are protected by timber floodwall.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	Heavily industrialized area along banks downstream of Isabella St. Some residences along banks downstream of Rte 50.	



PHASE I INSPECTION REPORT  
 NATIONAL DAM INSPECTION PROGRAM


JOHNSON'S POND

CITY OF SALISBURY

RESULTS OF  
 VISUAL INSPECTION

JULY 1980

PLATE A-1



**DAM CREST PROFILE**  
(LOOKING DOWNSTREAM)

**NOTE:**  
DAM CREST SURVEY STATIONS  
ARE SHOWN ON PLATE A-1.  
DATUM ELEVATION WAS PROVIDED  
BY THE CHIEF SURVEYOR FOR  
THE CITY OF SALISBURY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

**JOHNSON'S POND**  
CITY OF SALISBURY  
**DAM CREST SURVEY**

JULY 1980

PLATE A-2

APPENDIX B

ENGINEERING DATA CHECKLIST

PHASE I

APPENDIX B

CHECKLIST

ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

NAME OF DAM Johnson's Pond

ID# NDI ID No. MD-11

ITEM	REMARKS
AS-BUILT DRAWINGS	Contract Drawings entitled, "Proposed Steel and Concrete Dam at Johnson's Pond" by Mayor and Council, Salisbury, Md., dated January 10, 1936, and revised August 1, 1936.
REGIONAL VICINITY MAP	Refer to Location Map; Plate E-1 in Appendix
CONSTRUCTION HISTORY	No construction records available
TYPICAL SECTIONS OF DAM	Included on Contract Drawings and as Plate E-2 in Appendix
OUTLETS - PLAN - DETAILS - CONSTRAINTS - DISCHARGE RATINGS	For outlet plan and details, refer to Plate E-2 in Appendix

CHECKLIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

ITEM	REMARKS
RAINFALL/RESERVOIR RECORDS	None
DESIGN REPORTS	None
GEOLOGY REPORTS	None
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Limited design computations and correspondence relative to design of dam are available
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None

CHECKLIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

ITEM	REMARKS
POST CONSTRUCTION SURVEYS OF DAM	None
BORROW SOURCES	No data available
MONITORING SYSTEMS	None
MODIFICATIONS	None
HIGH POOL RECORDS	None



CHECKLIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

ITEM	REMARKS
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None
MAINTENANCE OPERATION RECORDS	None
SPILLWAY PLAN  SECTIONS DETAILS	Sections and Details included on Contract Drawings. Refer to Plates E-2 and E-3 in Appendix
OPERATING EQUIPMENT PLANS AND DETAILS	Plans and Details included on Contract Drawings. Refer to Plate E-2 in Appendix

APPENDIX C

PHOTOGRAPHS

← Camera Location And Direction  
A Photograph Identification Letter




PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
JOHNSON'S POND

GUIDE TO LOCATION  
OF PHOTOGRAPHS


JULY 1980

PLATE C-1

JOHNSON'S POND



A. Dam with sluice gates open




B. City of Salisbury personnel closing sluice gates

JOHNSON'S POND




C. Upstream side of dam



D. Vertical crack in dam near left end of dam

JOHNSON'S POND



E. Structural crack in retaining wall  
above dam crest at left end of dam



F. Structural crack in retaining wall  
above dam crest at right end of dam

JOHNSON'S POND



G. Isabella Street Bridge crossing  
river downstream of dam



H. Downstream of Isabella Street Bridge

APPENDIX D  
HYDROLOGY AND HYDRAULICS

BASE DATA FOR DETERMINATION OF PROBABLE  
MAXIMUM FLOOD, UNIT HYDROGRAPH AND  
INFLOW HYDROGRAPHS

Name of Dam: Johnson's Pond Dam NDI-ID MD-11

Unit Hydrograph Parameters

Watershed Drainage Area	42 sq. miles
Main Channel Length, L	11.18 miles
Main Channel to Centroid Length, Lca	4.94 miles
Lag Time $t_p = Ct (L \times Lca)^{0.3}$	13.6 hours
Basin Zone Location from Unit Hydrograph Coefficient Map	37
Basin Coefficients	
$Cp^1$	0.35
$Ct^1$	4.07

Inflow Hydrograph Parameters<sup>1</sup>

Base Flow at Start of Storm	1.5 c.f.s./sq. mile
Initial Rainfall Loss	1 inch
Uniform Rainfall Loss	0.05 inches/hour
Ratio of Peak Discharge Used to Compute Base Flow which Deviates from Hydrograph Falling Limb	0.05
Ratio of Recession Flow occurring 10 Tabulation Intervals Later	2.0

Rainfall Data<sup>2</sup>

Probable Maximum Precipitation Index for 24 hours and 200 square miles	25 inches (Zone 6)
Percentage Adjustments of PMP for Drainage Area	
6 hour storm	99%
12 hour storm	108%
24 hour storm	118%

<sup>1</sup>Basin Coefficients and Hydrograph Data established by Corps of  
Engineers Baltimore District.

<sup>2</sup>Hydrometeorological Report 33, Corps of Engineers, 1956

Tabulation of  
Reservoir Area and Storage Vs. Elevation

Name of Dam: Johnson's Pond Dam, NDI-ID MD-11

<u>Pool Elevation</u> feet above m.s.l.	<u>Surface Area</u> acres	<u>Reservoir Storage</u> acre-feet
-5 (Bottom of Pool)		0
11.1 (Normal Pool)	104 <sup>3</sup>	904 <sup>1</sup>
14.5 (Top of Dam)	274 <sup>2</sup>	1930 <sup>2</sup>
15.0 (Maximum Design Flood Level)	300 <sup>2</sup>	2070 <sup>2</sup>
20.0	550 <sup>4</sup>	3562 <sup>1</sup>

Comments:

Actual bottom pool elevation equals - 5 feet m.s.l. However a bottom pool elevation of -15 feet m.s.l. was used in employing the HEC-1 "Conical Storage" computer analysis to reflect the bowl shape of Johnson's Pond for a more accurate storage capacity determination.

- 
- <sup>1</sup> Computed by HEC-1 Computer Analysis
  - <sup>2</sup> Interpolated by Rummel, Klepper and Kahl
  - <sup>3</sup> Source "Watershed Construction Permit Activity Record,"  
Johnson's Pond Dam
  - <sup>4</sup> Area planimetered from 2000 scale USGS maps, dated 1942

SPILLWAY RATING CURVE TABLE<sup>1</sup>

Name of Dam: Johnson's Pond Dam, NDI-ID MD-11

<u>Reservoir Water Elevation</u> ft.	<u>Spillway Capacity Without Tailwater</u> c.f.s.	<u>Spillway Capacity With Tailwater</u> c.f.s.
10.6	0	0
10.81	7.74	7.74
11.0	21.8	21.8
11.07	27.0	27.0
12.0	949	200
13.0	2837	700
14.0	5306	1450
15.0	8243	2500
16.0	11581	4250
17.0	-	7400

Calculation Basics

Ogee Spillway Capacity Without Tailwater:

$$\begin{aligned}
 Q &= CLH^{1.5} \\
 &= 3.6 \times (300 \text{ ft} - 6 \text{ ft}) H^{1.5} \\
 &= 1058 H^{1.5}, \text{ where } H = \text{Reservoir Water Elevation minus } 11.07
 \end{aligned}$$

Ogee Spillway Capacity With Tailwater:

$$\begin{aligned}
 Q &= C_s LH^{1.5} \\
 &= C_s \times 294 H^{1.5}, \text{ where } H \text{ is as defined above and } C_s \text{ varies with} \\
 &\quad \text{tailwater levels}^2.
 \end{aligned}$$

<sup>1</sup> Calculated by Rummel, Klepper and Kahl

<sup>2</sup> Refer to "Modified Discharge Coefficient,  $C_s$ , Computations" on Page D-4

TRIAL NO.	PERCENT OF P.M.F.	DISCHARGE AT ISABELLA STREET	TAILWATER ELEVATION AT Johnson's Pond	ASSUMED ELEVATION FROM DAM	HD MINUS TAILWATER	He ASSUMED ELEVATION MINUS 11.1 ft.	Hd/He DEGREE OF SUBMERGENCE	Cs/Co RATIO OF MODIFIED COEFFICIENT TO FREE DISCHARGE COEFFICIENT	Cs MODIFIED DISCHARGE COEFFICIENT	Q2 = Cs L He 1.5 DISCHARGE AT DAM ADJUSTED FOR SUBMERGENCE	REMARKS
1	10	1570	13.8	13.9	0.1	2.8	0.036	0.375	1.35	1859	TOO HIGH USE 13.85
1	20	3130	15.6	15.9	0.3	4.8	0.0625	0.5	1.8	5565	TOO HIGH
2	20	3130	15.6	15.7	0.1	4.6	0.022	0.22	0.792	2297	TOO LOW
3	20	3130	15.6	15.8	0.2	4.7	0.042	0.4	1.44	4313	TOO HIGH USE 15.75
1	40	6275	16.5	16.7	0.2	5.6	0.036	0.36	1.30	5064	TOO LOW
2	40	6275	16.5	16.8	0.3	5.7	0.052	0.47	1.70	6800	TOO HIGH USE 16.75
1	50	7843	16.8	17.2	0.4	6.1	0.066	0.5	1.80	7972	TOO HIGH
2	50	7843	16.8	17.1	0.3	6.0	0.05	0.46	1.65	7129	TOO LOW
3	50	7843	16.8	17.15	0.35	6.05	0.058	0.49	1.764	7718	OK USE 17.15
1	70	10910	17.3	17.9	0.6	6.8	0.089	0.62	2.23	11,625	TOO HIGH
2	70	10910	17.3	17.8	0.5	6.7	0.075	0.55	1.98	10,100	TOO LOW USE 17.85
1	100	15,673	17.8	18.3	0.5	7.2	0.069	0.53	1.91	10,848	TOO LOW
2	100	15,673	17.8	18.5	0.7	7.4	0.095	0.64	2.3	13,612	TOO LOW
3	100	15,673	17.8	18.7	0.9	7.6	0.118	0.685	2.47	15,214	TOO LOW USE 18.75

1. For G/c. refer to figure 194 from Design of Small Dams
2. Co = 3.6
3. Assumed elevation upstream from dam is correct when Q1 = Q2

DESIGN OF SMALL DAMS

280





Figure 194. Ratio of discharge coefficients due to tailwater effect.

BY GFS DATE 7/28/30  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT Johnson's Pond  
Spillway Rating Curve  
Without Tailwater Effect

SHEET NO. 10 OF \_\_\_\_\_  
JOB NO. 580-21-10

OGEE SPILLWAY



ELEV.  
FT.

Q C.F.S.


D-6

BY GFS DATE 8/8/80  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT Johnson's Pond

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
JOB NO. 580-21-12

Spillway Rating Curves With And  
Without Tailwater Effect




RUMMEL, KLEPPER & KAHL ENGINEERS

D-7

OUTLET CURVE DATA<sup>2</sup>

<u>Elevation ft.</u>	<u>Storage Data ac.ft.</u>	<u>Outflow</u>	<u>Rate cfs.</u>
3.5		0	
4.0	11.53	54	
4.5		150	
5.0	16.89	191	
7.0	28.28	420	
9.0	40.84	701	
11.0	55.7	1027	
12.2	68.0	1242	
14.0		1600	
15.0		1821	
16.0		3995	
17.0		8528	
19.0	158.0	27541	




<sup>2</sup> Refer to Page D-10 For Isabella Street Rating Curve Computations.

BY GES DATE 8/5/30  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT Jehson's Pond  
Reach 1 Outlet Rating Curve

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
 JOB NO. 582-21-1P



RUMMEL, KLEPPER & KAHL ENGINEERS

BY GFS DATE 8/27/80  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT Transon's Pond  
Isabella Street  
Rating Curve Computations

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
 JOB NO. 580-21-1D

<u>Water Surface Elevation</u> feet	<u>Flow Under Bridge</u> c.f.s.	<u>Orifice Flow at Bridge</u> c.f.s.	<u>Flow Over Bridge</u> c.f.s.	<u>Discharge at Isabella Street</u> c.f.s.
3.5	0			0
4.0	54			54
4.5	150			150
5.0	191			191
7.0	420			420
9.0	701			701
11.0	1027			1027
12.2	1242			1242
14.0	(transition flow derived from graph)			1600
15.0		1295	526	1821
16.0		1696	2477	3995
17.0		2018	6832	8528
19.0		2162	25,523	27,541

Calculation Basics

Flow Under Bridge

$$Q = CLH^{1.5}$$

$$= 2.63 \times 14.7 H^{1.5}$$

$$= 38.7 H^{1.5}$$

H = Water Surface Elevation -  
2.1 feet above m.s.l.

Orifice Flow at Bridge

$$Q = CA \sqrt{2gH}$$

$$= 0.6 \times 161 \sqrt{2gH}$$

$$= 774 H^{1.5}$$

H = Water Surface Elevation -  
12.2 feet above m.s.l.  
(orifice flow with "supported outlet" conservatively assumed in rating curve derivation)

Flow Over Bridge

$$Q = CLH^{1.5}$$


$$= 2.63 \times L \times H^{1.5}$$

H = Water Surface Elevation -  
14.0 feet above m.s.l.

L becomes larger as the elevation increases.

D-10

BY GFS DATE 8/7/30 SUBJECT Johnson's Pond SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_ Reach Data Rt. 50 JOB NO. 580-21-1D  
 \_\_\_\_\_



REACH DATA

QN(1)	0.1
QN(2)	0.02
QN(3)	0.1
ELNVRT	2.1
ELMAX	19.0
RLNTH	2800
SEL	0.001

n. of 0.1 to account for buildings on side slope area

BY GFS DATE 8/6/80  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_


SUBJECT Johnson's Pond Dam  
Phase I Dam Inspection Program  
Breach I

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
JOB NO. 580-21-10

### BREACH DATA

Shape of Breach	Trapezoid
Bottom Width of Breach	20 feet
Maximum Depth of Breach	5 feet
Side Slope of Breach	1 to 1
Water Level at Beginning of Breach	11.07 feet above m.s.l.
Time to Maximum Size	1 hour

### BREACH DIAGRAM



NOT TO SCALE

D-12

RUMMEL, KLEPPER & KAHL ENGINEERS

BY GFS DATE 8/6/80  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_


SUBJECT Johnson's Pond Dam  
Phase I Dam Inspection Program  
Breach 2

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
JOB NO. 580-21-10

### BREACH DATA

Shape of Breach	Trapezoid
Bottom Width of Breach	40 feet
Maximum Depth of Breach	5 feet
Side Slope of Breach	1 to 1
Water Level at Beginning of Breach	11.07 feet above m.s.l.
Time to Maximum Size	1 hour

### BREACH DIAGRAM



NOT TO SCALE

D-13

RUMMEL, KLEPPER & KAHL

ENGINEERS



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 06 FEB 80  
 \*\*\*\*\*

SNYDER UNIT HYDROGRAPH, FLOOD ROUTING AND DAM OVERTOPPING ANALYSES FOR  
 JOHNSONS POND DAM  
 NDI-I. D. MD11 COMM. NO. 580-21-1D

JOB SPECIFICATION											
NG	NHR	NFIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN		
150	1	0	0	0	0	0	0	-4	0		
			JOPER	NWT	LROPT	TRACE					
			5	0	0	0					

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 NRTID= 9 LRTID= 1  
 RTIDS= 0.10 0.20 0.30 0.40 0.50 0.60 0.70 0.80 0.90 1.00

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

CALCULATION OF SNYDER INFLOW HYDROGRAPH TO JOHNSONS POND DAM  
 ISTAT ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO  
 1 0 0 0 0 0 0 0 0 0 0 0

HYDROGRAPH DATA											
IHYDQ	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL		
1	1	42.00	0.00	42.00	0.00	0.000	0	1	0		

TRSPC COMPUTED BY THE PROGRAM IS 0.845

PRECIP DATA											
		SPFE	PMS	R6	R12	R24	R48	R72	R96		
		0.00	25.00	99.00	108.00	118.00	0.00	0.00	0.00		

LOSS DATA  
 STRKS RTICK STRTL CNSTL ALSMX RTIMP  
 0 0.00 1.00 0.00 1.00 1.00 0.05 0.00 0.00 0.00

UNIT HYDROGRAPH DATA  
 TP= 13.60 CP=0.35 NTA= 0  
 STRTQ= -1.50 GRCEM= -0.05 RTIDR= 2.00

RECESSION DATA											
		LAG	HOURS	CP							
		13.56	13.56	0.35	0.35	0.35	0.35	0.35	0.35	0.35	0.35

UNIT HYDROGRAPH100 END-OF-PERIOD ORDINATES, LAG= 13.56 HOURS, CP= 0.35 VOL= 0.95

12.	46	96	156	224	299	379	459	532	595	595	42
646	711	717	702	679	657	635	615	532	595	595	42
575	538	521	504	487	472	456	441	441	427	427	307
413	400	387	374	362	350	339	328	317	307	307	220
297	287	277	268	260	251	243	235	227	220	220	158
213	206	199	193	186	180	174	169	163	158	158	113
153	148	143	138	134	129	125	121	117	113	113	81
110	106	103	99	96	93	90	87	84	81	81	58
79	76	74	71	69	67	65	62	60	58	58	42
57	55	53	51	50	48	46	45	43	42	42	

0 MO. DA MR. MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW MO. DA MR. MN PERIOD RAIN EXCS LOSS COMP 0  
 ( 633. )( 585. )( 48. )( 17140. 97 )

\*\*\*\*\*  
 \*\*\*\*\*  
 \*\*\*\*\*  
 \*\*\*\*\*

HYDROGRAPH ROUTING

ROUTED FLOWS THROUGH JOHNSONS POND DAM.

ISTAG ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO  
 2 1 0 0 0 0 0 0 0  
 ROUTING DATA  
 GLOSS CLOSS AVG IRES ISAME IOPT IPMP LSTR  
 0.0 0.000 0.00 1 1 0 0  
 NSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT  
 1 0 0 0.000 0.000 0.000 -11. -1

STAGE 10.60 10.81 11.00 11.07 12.00 13.00 14.00 15.00 16.00  
 FLOW 0.00 7.74 21.80 27.00 949.00 2837.00 5306.00 8243.00 11581.00

SURFACE AREA= 0. 104. 550.  
 CAPACITY= 0. 904. 3562.  
 ELEVATION= -15. 11. 20.

CREL SPWID COGN EXPW ELEV COOL CAREA EXPL  
 11.1 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
 TOPEL COGD EXPD DAMWID  
 14.5 2.6 1.5 10.

CREST LENGTH 80. 185. 309.  
 AT OR BELOW ELEVATION 15.9 16.0 17.0  
 PEAK OUTFLOW IS 1564. AT TIME 30.00 HOURS  
 PEAK OUTFLOW IS 3132. AT TIME 30.00 HOURS  
 PEAK OUTFLOW IS 4692. AT TIME 30.00 HOURS  
 PEAK OUTFLOW IS 6260. AT TIME 30.00 HOURS  
 PEAK OUTFLOW IS 7814. AT TIME 30.00 HOURS  
 PEAK OUTFLOW IS 9382. AT TIME 30.00 HOURS  
 PEAK OUTFLOW IS 10944. AT TIME 30.00 HOURS  
 PEAK OUTFLOW IS 12512. AT TIME 30.00 HOURS

PEAK OUTFLOW IS 15646. AT TIME 30.00 HOURS

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTED FLOW MOD PULS REACH1	ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
3	1	0	0	0	0	0	0	0	0
ROUTING DATA									
GLOSS	CLOSS	AVG	IRCS	ISAME	IOPT	IPMP	LSTR		
0.0	0.000	0.00	1	1	0	0	0		
ROUTING DATA									
NSTPS	NSTDPL	LAG	AMSKK	X	TSK	STORA	ISPRAT		
1	0	0	0.000	0.000	0.000	0.	0		
STORAGE	11.53	16.89	28.28	40.84	55.70	64.00	158.00		
OUTFLOW	54.00	191.00	420.00	701.00	1027.00	1200.00	27541.00	14.00	15.00
STAGE	3.50	4.00	4.50	5.00	7.00	9.00	11.00	12.20	14.00
	16.00	17.00	19.00						
FLOW	0.00	54.00	150.00	191.00	420.00	701.00	1027.00	1242.00	1600.00
	3995.00	8528.00	27541.00						1821.00

- MAXIMUM STAGE IS 13.8
- MAXIMUM STAGE IS 15.6
- MAXIMUM STAGE IS 16.2
- MAXIMUM STAGE IS 16.5
- MAXIMUM STAGE IS 16.8
- MAXIMUM STAGE IS 17.1
- MAXIMUM STAGE IS 17.3
- MAXIMUM STAGE IS 17.4
- MAXIMUM STAGE IS 17.8

\*\*\*\*\*

HYDROGRAPH ROUTING

FLOOD ROUTING MOD PULS REACH 2	ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
4	1	0	0	0	0	0	0	0	0
ROUTING DATA									
GLOSS	CLOSS	AVG	IRCS	ISAME	IOPT	IPMP	LSTR		
0.0	0.000	0.00	1	1	0	0	0		
ROUTING DATA									
NSTPS	NSTDPL	LAG	AMSKK	X	TSK	STORA	ISPRAT		



PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS								
				RATIO 1 0.10	RATIO 2 0.20	RATIO 3 0.30	RATIO 4 0.40	RATIO 5 0.50	RATIO 6 0.60	RATIO 7 0.70	RATIO 8 0.80	RATIO 9 1.00
HYDROGRAPH AT	1	42.00 ( 108.78)	1	1577. ( 44.67)	3155. ( 89.34)	4732. ( 134.00)	6310. ( 178.67)	7887. ( 223.34)	9445. ( 268.01)	11042. ( 312.68)	12620. ( 357.35)	15774. ( 446.69)
ROUTED TO	2	42.00 ( 108.78)	1	1564. ( 44.30)	3132. ( 88.68)	4692. ( 132.85)	6260. ( 177.25)	7814. ( 221.28)	9382. ( 265.66)	10944. ( 309.89)	12512. ( 354.29)	15646. ( 443.04)
ROUTED TO	3	42.00 ( 108.78)	1	1566. ( 44.34)	3130. ( 88.64)	4701. ( 133.10)	6275. ( 177.68)	7843. ( 222.08)	9371. ( 265.37)	10910. ( 308.93)	12491. ( 353.71)	15673. ( 443.81)
ROUTED TO	4	42.00 ( 108.78)	1	1562. ( 44.23)	3135. ( 88.78)	4704. ( 133.21)	6257. ( 177.17)	7804. ( 220.98)	9383. ( 265.70)	10953. ( 310.16)	12518. ( 354.46)	15638. ( 442.83)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	TIME OF FAILURE HOURS
		11.07	11.07	14.50	
		904.	904.	1468.	
		27.	27.	6775.	
RATIO OF PMF	MAXIMUM RESERVOIR W. S. ELEV	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS
0.10	12.33	1060.	1564.	0.00	30.00
0.20	13.12	1187.	3132.	0.00	30.00
0.30	13.75	1306.	4692.	0.00	30.00
0.40	14.32	1428.	6260.	0.00	30.00
0.50	14.85	1554.	7814.	10.00	30.00
0.60	15.34	1681.	9382.	17.00	30.00
0.70	15.79	1810.	10944.	23.00	30.00
0.80	16.20	1936.	12512.	28.00	30.00
1.00	16.93	2181.	15646.	35.00	30.00

PLAN 1 STATION 3

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.10	1566.	13.8	30.00
0.20	3130.	15.6	29.00
0.30	4701.	16.2	29.00
0.40	6275.	16.5	30.00
0.50	7843.	16.8	30.00
0.60	9371.	17.1	30.00
0.70	10910.	17.3	29.00
0.80	12491.	17.4	30.00
1.00	15672.	17.8	30.00

PLAN 1 STATION 4

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.10	1562.	5.2	30.00
0.20	3133.	6.8	30.00
0.30	4704.	7.9	30.00
0.40	6257.	8.9	30.00
0.50	7804.	9.7	30.00
0.60	9383.	10.5	30.00
0.70	10953.	11.2	30.00
0.80	12518.	11.8	30.00
1.00	15638.	12.8	30.00



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 3-M SAFETY VERSION JULY 1978  
 LAST MODIFICATION 06 FEB 80  
 \*\*\*\*\*

SNYDER UNIT HYDROGRAPH, FLOOD ROUTING AND DAM OVERTOPPING ANALYSES FOR  
 JOHNSONS POND DAM  
 HDI-I D MD11 COMM. NO. 580-21-ID

LAG	NHR	MFIN	IDAY	IMR	IMIN	METRC	IPLT	IPRT	NSTAN
130	1	0	0	0	0	0	0	-4	0
			JOPER	NMT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

RTIOS= 0 10 0.20 0.30 0.40 0.50 0.60 0.70 0.80 0.95 1.00  
 :PLAN= 1 NRTIO= 9 LRTIO= 1

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

CALCULATION OF SNYDER INFLOW HYDROGRAPH TO JOHNSONS POND DAM

IHYDO	IUGC	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNDW	ISAME	LOCAL
1	1	42.00	0.00	42.00	0.00	0.000	0	1	0

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	25.00	99.00	108.00	118.00	0.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.845

LROPT	STRKR	DLTKR	RTIOL	ERAIN	STRKS	RTIOK	STIRL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.05	0.00	0.00

PRECIP DATA  
 TP= 13.60 CP=0.35 NTA= 0

LOSS DATA  
 STRTG= -1.50 GRCSN= -0.05 RTIOR= 2.00

UNIT HYDROGRAPH DATA	RECESSION DATA
12. 46.	96.
646. 686.	156.
575. 577.	717.
413. 400.	521.
297. 287.	387.
213. 206.	277.
153. 148.	199.
110. 106.	143.
79. 75.	103.
55. 51.	71.
	59.
	48.
	50.
	299.
	379.
	439.
	532.
	595.
	615.
	635.
	456.
	441.
	328.
	317.
	235.
	227.
	169.
	180.
	163.
	117.
	125.
	121.
	87.
	90.
	62.
	67.
	45.
	50.
	46.
	43.
	42.

MO. DA MR. MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW MO. DA MR. MN PERIOD RAIN EXCS LOSS COMP 0  
 0 24.92 23.05 1.88 605328.  
 ( 633 )( 585 )( 48 )( 17140.97 )

\*\*\*\*\*  
 \*\*\*\*\*  
 \*\*\*\*\*  
 \*\*\*\*\*

HYDROGRAPH ROUTING

ROUTED FLOWS THROUGH JOHNSONS POND DAM.

STAGE	10.60	11.00	11.07	12.00	13.00	14.00	15.00	16.00	17.00
FLOW	0.00	21.80	27.00	200.00	700.00	1200.00	2000.00	4000.00	7400.00
SURFACE AREA	0.	104.	550.						
CAPACITY	0.	904.	3562.						
ELEVATION	-15.	11.	20.						

ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
2	1	0	0	0	0	0	0	0
ROUTING DATA								
OLOSS	CLOSS	AVG	IRES	ISAME	IDPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS NSTDL								
1	0	0	0	0.000	0.000	0.000	0.000	-11.
LAG AMSKK X TSK STORA ISPRAT								
0	0	0.000	0.000	0.000	0.000	0.000	-11.	-1

DAM DATA

TOPEL	COGD	EXPD	DAMWID
14.5	2.6	1.5	10.
80.	185.	309.	800.
15.5	16.0	17.0	18.0
19.0	19.0	20.0	20.0

CREST LENGTH AT OR BELOW ELEVATION	80.	185.	309.	452.	605.	800.
PEAK OUTFLOW IS	1422.	AT TIME	33.00 HOURS			
PEAK OUTFLOW IS	3049.	AT TIME	31.00 HOURS			
PEAK OUTFLOW IS	4680.	AT TIME	30.00 HOURS			
PEAK OUTFLOW IS	6257.	AT TIME	30.00 HOURS			
PEAK OUTFLOW IS	7824.	AT TIME	30.00 HOURS			
PEAK OUTFLOW IS	9404.	AT TIME	30.00 HOURS			
PEAK OUTFLOW IS	10772.	AT TIME	30.00 HOURS			



NSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT  
 1 0 0 0.000 0.000 0.000 0.000 0

NORMAL DEPTH CHANNEL ROUTING

GN(1) GN(2) GN(3) ELNVT ELMAX RLNTH SEL  
 0.1000 0.0200 0.1000 2.1 19.0 2100. 0.00100

CROSS SECTION COORDINATES--STA. ELEV. STA. ELEV.--ETC  
 2.00 19.00 100.00 10.00 275.00 4.50 275.00 2.10  
 375.00 4.50 675.00 10.00 2200.00 19.00

STORAGE	0.00	4.29	8.58	13.01	19.94	30.17	43.68	60.50	80.60	104.03
	132.94	168.74	211.43	261.00	317.47	380.81	451.05	528.17	612.18	703.07
OUTFLOW	0.00	191.55	601.14	1172.60	1912.32	2832.95	3948.21	5270.71	6812.52	8569.54
	10912.58	12801.46	15449.20	18479.71	21919.26	25794.32	30130.96	34954.61	40290.08	46161.58
STAGE	2.10	2.99	3.88	4.77	5.66	6.55	7.44	8.33	9.22	10.11
	10.99	11.88	12.77	13.66	14.55	15.44	16.33	17.22	18.11	19.00
FLOW	0.00	191.55	601.14	1172.60	1912.32	2832.95	3948.21	5270.71	6812.52	8569.54
	10912.58	12801.46	15449.20	18479.71	21919.26	25794.32	30130.96	34954.61	40290.08	46161.58

- MAXIMUM STAGE IS 5.1
- MAXIMUM STAGE IS 6.7
- MAXIMUM STAGE IS 7.9
- MAXIMUM STAGE IS 8.9
- MAXIMUM STAGE IS 9.7
- MAXIMUM STAGE IS 10.5
- MAXIMUM STAGE IS 11.2
- MAXIMUM STAGE IS 11.8
- MAXIMUM STAGE IS 12.8

\*\*\*\*\*

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS								
				RATIO 1 0.10	RATIO 2 0.20	RATIO 3 0.30	RATIO 4 0.40	RATIO 5 0.50	RATIO 6 0.60	RATIO 7 0.70	RATIO 8 0.80	RATIO 9 1.00
HYDROGRAPH AT	1	42.00 ( 108.78)	1	1577. ( 44.67)	3155. ( 89.34)	4732. ( 134.00)	6310. ( 178.67)	7887. ( 233.34)	9465. ( 268.01)	11042. ( 312.68)	12620. ( 357.35)	15774. ( 446.68)
ROUTED TO	2	42.00 ( 108.78)	1	1422. ( 40.25)	3049. ( 86.33)	4680. ( 132.53)	6257. ( 177.19)	7824. ( 221.54)	9404. ( 266.28)	10972. ( 310.69)	12540. ( 355.09)	15676. ( 443.89)
ROUTED TO	3	42.00 ( 108.78)	1	1427. ( 40.40)	3077. ( 87.12)	4675. ( 132.37)	6295. ( 178.27)	7821. ( 221.47)	9414. ( 266.57)	10972. ( 310.68)	12573. ( 356.03)	15693. ( 444.39)
ROUTED TO	4	42.00 ( 108.78)	1	1423. ( 40.31)	3046. ( 86.25)	4687. ( 132.73)	6244. ( 176.80)	7826. ( 221.61)	9419. ( 266.72)	10981. ( 310.95)	12542. ( 355.14)	15685. ( 444.15)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	RATIO OF PMF	MAXIMUM RESERVOIR STORAGE W. S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	SPILLWAY CREST	TOP OF DAM	TIME OF FAILURE HOURS	TIME OF MAX OUTFLOW HOURS	DURATION OVER TOP HOURS
	0.10	14.28	0.00	1417.	1422.	11.07	14.50	0.00	33.00	0.00
	0.20	15.52	1.02	1732.	3049.	904.	1468	0.00	31.00	30.00
	0.30	16.14	1.64	1916.	4680.	27.	1600	0.00	30.00	44.00
	0.40	16.52	2.02	2038.	6257.			0.00	30.00	54.00
	0.50	16.87	2.37	2158.	7824.			0.00	30.00	62.00
	0.60	17.17	2.67	2267.	9404.			0.00	30.00	67.00
	0.70	17.43	2.93	2364.	10972.			0.00	30.00	73.00
	0.80	17.68	3.18	2464.	12540.			0.00	30.00	77.00
	1.00	18.15	3.65	2650.	15676.			0.00	30.00	85.00

PLAN 1 STATION 3

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.10	1427.	13.1	34.00
0.20	3077.	15.6	31.00
0.30	4575.	16.1	31.00
0.40	6295.	16.5	30.00
0.50	7821.	16.8	30.00
0.60	9414.	17.1	29.00
0.70	10972.	17.3	30.00
0.80	12573.	17.4	30.00
1.00	15693.	17.8	30.00

PLAN 1 STATION 4

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.10	1423	5.1	33.00
0.20	3046.	6.7	32.00
0.30	4687.	7.9	30.00
0.40	6244.	8.9	30.00
0.50	7826.	9.7	30.00
0.60	9419.	10.5	30.00
0.70	10981.	11.2	30.00
0.80	12542.	11.8	30.00
1.00	15685.	12.8	30.00



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 06 FEB 80  
 \*\*\*\*\*

SNYDER UNIT HYDROGRAPH, FLOOD ROUTING AND DAM FAILURE ANALYSES FOR  
 JOHNSONS POND DAM  
 NDI-I.D. MD11 CONH. NO. 580-21-1D

NG NHR NMIN IDAY IHR IMIN METRC IPLT IPRT NSTAN  
 150 1 0 0 0 0 0 0 0 0 0  
 JOPEL S 0 0 0 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 2 NRTIO= 1 LRTIO= 1

RTIOS= 0.50

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

0  
 MU DA HR MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW  
 COMP 0 MO. DA HR. MN PERIOD RAIN EXCS LOSS COMP 0  
 SUM 24.92 23.05 1.88 605328.  
 ( 633.)( 385.)( 48.)(17140.97)

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUNDED FLOWS THROUGH JOHNSONS POND DAM.  
 ISTAG ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTD  
 2 1 0 0 0 0 0 0 0 0 0 0

ALL PLANS HAVE SAME ROUTING DATA

GLOSS CLOSS AVG IRES ISAME IOPT IPMP LSTR  
 0.0 0.000 0.00 1 1 0 0  
 NSTPS NSTDL LAG AMSKK X TSK STORA JSPRAT  
 1 0 0 0.000 0.000 0.000 -11.

STAGE 10.60 11.00 11.07 12.00 13.00 14.00 15.00 16.00  
 FLOW 0.00 7.74 21.80 27.00 949.00 2837.00 5306.00 8243.00 11581.00  
 SURFACE AREA= 0. 104. 550.  
 CAPACITY= 0. 904. 3562.  
 ELEVATION= -15. 11. 20.

CREL SPHID COGW EXPH EVEL COGL CAREA EXPL  
 11.1 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA

TOPEL COGD EXPD DAMHID  
 14.5 2.6 1.5 10.  
 CREST LENGTH 80. 185 309. 452. 605. 800.  
 AT OR BELOW 13.5 16.0 17.0 18.0 19.0 20.0  
 ELEVATION  
 BRMID 20. 1.00 5.00 1.00 11.07 14.50  
 DAM BREACH DATA WSEL FAILEL  
 2 ELBM TFAIL WSEL FAILEL

BEGIN DAM FAILURE AT 26.00 HOURS

PEAK OUTFLOW IS 9101. AT TIME 27.00 HOURS

BRMID 40 1.00 5.00 1.00 11.07 14.50  
 DAM BREACH DATA WSEL FAILEL  
 2 ELBM TFAIL WSEL FAILEL

BEGIN DAM FAILURE AT 26.00 HOURS

PEAK OUTFLOW IS 10358. AT TIME 27.00 HOURS

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTED FLOW MOD PULS REACH1  
 ISTAT ICOMP IECON ITAPE JPLY JPRT INAME ISTAGE IAUTO  
 3 1 0 0 0 0 0 0 0 0 0 0

ALL PLANS HAVE SAME

ROUTING DATA  
 GLOSS CLOSS AVG IRES ISAME IOPT IPMP LSTR  
 0.0 0.000 0.00 1 1 0 0 0  
 NSTPS NSTDL LAG ANSKK X TSK STORA ISPRAT  
 1 0 0 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000

NORMAL DEPTH CHANNEL ROUTING

ON(1) ON(2) ON(3) ELMVT ELMAX RLNTH SEL  
 0.1000 0.0200 0.1000 2.1 19.0 2800. 0.00100

CROSS SECTION COORDINATES--STA. ELEV. STA. ELEV.--ETC

0.00 19.00 100.00 10.00 275.00 4.50 275.00 2.10 375.00 2.10  
 375.00 4.50 675.00 10.00 2200.00 19.00

STORAGE	0.00	5.72	11.43	17.35	26.99	40.22	58.25	80.66	107.47	138.70
	177.25	224.99	281.91	348.01	423.29	507.75	601.40	704.23	816.24	937.43
OUTFLOW	0.00	191.55	601.14	1172.60	1912.32	2832.95	3948.21	5270.71	6812.52	8569.54
	10312.58	12801.46	15449.20	18479.71	21919.26	25794.32	30130.76	34954.61	40290.08	46161.58
STAGE	2.10	2.99	3.88	4.77	5.66	6.55	7.44	8.33	9.22	10.11
	10.99	11.88	12.77	13.66	14.55	15.44	16.33	17.22	18.11	19.00
FLOW	0.00	191.55	601.14	1172.60	1912.32	2832.95	3948.21	5270.71	6812.52	8569.54
	10512.58	12801.46	15449.20	18479.71	21919.26	25794.32	30130.76	34954.61	40290.08	46161.58

MAXIMUM STAGE IS 10.2

MAXIMUM STAGE IS 10.5


\*\*\*\*\*

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS


OPERATION	STATION	AREA	PLAN	RATIO	1
					0.50
HYDROGRAPH AT	1	42.00 ( 108.78)	1	7887	( 223.34)(
	2		2	7887	( 223.34)(
ROUTED TO	2	42.00 ( 108.78)	1	9101	( 237.71)(
			2	10358	( 293.30)(
ROUTED TO	4	42.00 ( 108.78)	1	8687	( 245.99)(
			2	9440	( 267.32)(






APPENDIX E

PLATES




JOHNSON'S POND  
LOCATION MAP  
PLATE E-1







PLAN OF DAM & WING WALLS  
SCALE 1"=30'



PLAN OF WING WALL  
SCALE 1/2"=12'



END ELEVATION OF WING WALLS  
SCALE 1/2"=12'




SECTION THROUGH SLUICE GATE  
SCALE 1/2"=12'


THIS DRAWING IS BEST QUALITY REPRODUCIBLE  
FROM COPY FURNISHED TO BDC

PLATE E-2

PROPOSED STEEL & CONCRETE DAM AT JOHNSON'S POND	SHEET	SCALE	
	NO. 1 OF 2	AS SHOWN	



PROFILE OF DAM STANDING ABOVE DAM & LOOKING DOWNSTREAM  
 VERTICAL SCALE 1" = 20.0'  
 HORIZONTAL SCALE 1/4" = 10.0'



CROSS SECTION OF FILL AT WING WALL  
 SCALE 1/8" = 12'

W.P.A. PROJECT SPONSOR'S PROPOSAL NO 2

MAYOR & COUNCIL  
 SALISBURY, MD.

APPROVED: January 10, 1936


Revised August 1, 1936

CITY ENGINEER

PROP

1

4400  
 4170  
 4160  
 4150  
 4140  
 4130  
 4120  
 4110  
 4100  
 4090  
 4080  
 4070  
 4060  
 4050  
 4040  
 4030  
 4020  
 4010  
 4000  
 3990  
 3980  
 3970  
 3960  
 3950  
 3940  
 3930  
 3920  
 3910  
 3900  
 3890  
 3880  
 3870  
 3860  
 3850  
 3840  
 3830  
 3820  
 3810  
 3800  
 3790  
 3780  
 3770  
 3760  
 3750  
 3740  
 3730  
 3720  
 3710  
 3700  
 3690  
 3680  
 3670  
 3660  
 3650  
 3640  
 3630  
 3620  
 3610  
 3600  
 3590  
 3580  
 3570  
 3560  
 3550  
 3540  
 3530  
 3520  
 3510  
 3500  
 3490  
 3480  
 3470  
 3460  
 3450  
 3440  
 3430  
 3420  
 3410  
 3400  
 3390  
 3380  
 3370  
 3360  
 3350  
 3340  
 3330  
 3320  
 3310  
 3300  
 3290  
 3280  
 3270  
 3260  
 3250  
 3240  
 3230  
 3220  
 3210  
 3200  
 3190  
 3180  
 3170  
 3160  
 3150  
 3140  
 3130  
 3120  
 3110  
 3100  
 3090  
 3080  
 3070  
 3060  
 3050  
 3040  
 3030  
 3020  
 3010  
 3000  
 2990  
 2980  
 2970  
 2960  
 2950  
 2940  
 2930  
 2920  
 2910  
 2900  
 2890  
 2880  
 2870  
 2860  
 2850  
 2840  
 2830  
 2820  
 2810  
 2800  
 2790  
 2780  
 2770  
 2760  
 2750  
 2740  
 2730  
 2720  
 2710  
 2700  
 2690  
 2680  
 2670  
 2660  
 2650  
 2640  
 2630  
 2620  
 2610  
 2600  
 2590  
 2580  
 2570  
 2560  
 2550  
 2540  
 2530  
 2520  
 2510  
 2500  
 2490  
 2480  
 2470  
 2460  
 2450  
 2440  
 2430  
 2420  
 2410  
 2400  
 2390  
 2380  
 2370  
 2360  
 2350  
 2340  
 2330  
 2320  
 2310  
 2300  
 2290  
 2280  
 2270  
 2260  
 2250  
 2240  
 2230  
 2220  
 2210  
 2200  
 2190  
 2180  
 2170  
 2160  
 2150  
 2140  
 2130  
 2120  
 2110  
 2100  
 2090  
 2080  
 2070  
 2060  
 2050  
 2040  
 2030  
 2020  
 2010  
 2000  
 1990  
 1980  
 1970  
 1960  
 1950  
 1940  
 1930  
 1920  
 1910  
 1900  
 1890  
 1880  
 1870  
 1860  
 1850  
 1840  
 1830  
 1820  
 1810  
 1800  
 1790  
 1780  
 1770  
 1760  
 1750  
 1740  
 1730  
 1720  
 1710  
 1700  
 1690  
 1680  
 1670  
 1660  
 1650  
 1640  
 1630  
 1620  
 1610  
 1600  
 1590  
 1580  
 1570  
 1560  
 1550  
 1540  
 1530  
 1520  
 1510  
 1500  
 1490  
 1480  
 1470  
 1460  
 1450  
 1440  
 1430  
 1420  
 1410  
 1400  
 1390  
 1380  
 1370  
 1360  
 1350  
 1340  
 1330  
 1320  
 1310  
 1300  
 1290  
 1280  
 1270  
 1260  
 1250  
 1240  
 1230  
 1220  
 1210  
 1200  
 1190  
 1180  
 1170  
 1160  
 1150  
 1140  
 1130  
 1120  
 1110  
 1100  
 1090  
 1080  
 1070  
 1060  
 1050  
 1040  
 1030  
 1020  
 1010  
 1000  
 990  
 980  
 970  
 960  
 950  
 940  
 930  
 920  
 910  
 900  
 890  
 880  
 870  
 860  
 850  
 840  
 830  
 820  
 810  
 800  
 790  
 780  
 770  
 760  
 750  
 740  
 730  
 720  
 710  
 700  
 690  
 680  
 670  
 660  
 650  
 640  
 630  
 620  
 610  
 600  
 590  
 580  
 570  
 560  
 550  
 540  
 530  
 520  
 510  
 500  
 490  
 480  
 470  
 460  
 450  
 440  
 430  
 420  
 410  
 400  
 390  
 380  
 370  
 360  
 350  
 340  
 330  
 320  
 310  
 300  
 290  
 280  
 270  
 260  
 250  
 240  
 230  
 220  
 210  
 200  
 190  
 180  
 170  
 160  
 150  
 140  
 130  
 120  
 110  
 100  
 90  
 80  
 70  
 60  
 50  
 40  
 30  
 20  
 10  
 0  
 -10  
 -20  
 -30  
 -40  
 -50  
 -60  
 -70  
 -80  
 -90  
 -100  
 -110  
 -120  
 -130  
 -140  
 -150  
 -160  
 -170  
 -180  
 -190  
 -200  
 -210  
 -220  
 -230  
 -240  
 -250  
 -260  
 -270  
 -280  
 -290  
 -300  
 -310  
 -320  
 -330  
 -340  
 -350  
 -360  
 -370  
 -380  
 -390  
 -400  
 -410  
 -420  
 -430  
 -440  
 -450  
 -460  
 -470  
 -480  
 -490  
 -500  
 -510  
 -520  
 -530  
 -540  
 -550  
 -560  
 -570  
 -580  
 -590  
 -600  
 -610  
 -620  
 -630  
 -640  
 -650  
 -660  
 -670  
 -680  
 -690  
 -700  
 -710  
 -720  
 -730  
 -740  
 -750  
 -760  
 -770  
 -780  
 -790  
 -800  
 -810  
 -820  
 -830  
 -840  
 -850  
 -860  
 -870  
 -880  
 -890  
 -900  
 -910  
 -920  
 -930  
 -940  
 -950  
 -960  
 -970  
 -980  
 -990  
 -1000



LAKE STREET

NOTE: Damming stream to create pond for Lake Street at this point.

CLAY FILL  
ELEV VALUES

THIS PAGE IS BEST QUALITY PRACTICABLE  
 EXACT COPY FURNISHED TO BSA

PLATE E-3

PROPOSED STEEL & CONCRETE DAM AT JOHNSON'S POND

SHEET NO. 2 OF 2	SCALE AS SHOWN	1-4 B-3621 Q
------------------------	----------------------	--------------------

APPENDIX F


GEOLOGY

JOHNSON'S POND

APPENDIX F

REGIONAL GEOLOGY

The Johnson's Pond dam is situated on the sediments of the Pliocene Beaverdam Sand and the Pleistocene Parsonsburg Sand, which include sand and silty sand which is locally interbedded with gravelly sand and clayey silt. These sediments of the Coastal Plain Province lie unconformably on the Upper Miocene deposits of the Yorktown Cohansey and the Pensaulken Formations. The Parsonsburg Sand is a relatively thin deposit in the area, rarely exceeding a depth of 10 feet. The thickness of the Beaverdam Sand is approximately 30 feet, and the deposits generally thicken to the northwest and to the southeast.



SCALE



**REFERENCE:**

**GEOLOGIC MAP OF WICOMICO COUNTY,  
PREPARED BY STATE OF MARYLAND,  
MARYLAND GEOLOGICAL SURVEY,  
DATED 1979.**

**JOHNSON'S POND**

**GEOLOGY MAP**

**RUMMEL, KLEPPER & KAHL**

**Tw**

**WALSTON SILT (UPPER(?) AND MIDDLE(?) PLIOCENE) -** Clay and silt, interstratified with poorly sorted clayey sand. Orange, brown, or mottled red and white in upper weathered part of Formation, grading to greenish gray and dark gray in unweathered lower part of Formation. Most of the formation is deeply weathered, hence brightly colored. Locally, thin, light-colored, horizontally stratified, burrowed sand overlies the clay-silt beds and may be part of the Formation. The Walston Silt underlies the highlands (elevations as much as 24 m or 80 ft) in the central and eastern parts of the County. Despite the rolling topography of this highland region, the Formation is for the most part poorly exposed. Extensive outcrops of this unit are found, however, in the road cuts just east of Powellville on Md. Route 350. Here, as much as 6.0 m (20 ft) or nearly half the total thickness of the Formation is exposed. At these locations the Formation consists of pale-gray massive clayey silt (typically 1.3 m or 4 ft thick) and white to pale-gray sequences of thinly bedded poorly sorted sand and clay (typically 3.0 m or 10 ft thick). The basal contact with the Beaverdam Sand is sharp but undulatory. Gravel, mostly weathered chert as much as 6 cm (2.5 in) in diameter, is found locally along this contact.

**Tb**

**BEAVERDAM SAND (UPPER(?) AND MIDDLE(?) PLIOCENE) -** Sand and silty sand locally interbedded with gravelly sand, clay-silt, and rare peaty sand or clay. Aquamarine, pale green or white where unweathered; orange or red brown where weathered.

**REFERENCE:**

**GEOLOGIC MAP OF WICOMICO COUNTY,  
PREPARED BY STATE OF MARYLAND,  
MARYLAND GEOLOGICAL SURVEY,  
DATED 1979.**

**JOHNSON'S POND**

**GEOLOGY MAP LEGEND**

**RUMMEL, KLEPPER & KAHL**

Qal

**ALLUVIUM (HOLOCENE)** - Largely sand, gravelly sand or clay. Narrow deposits fill most stream valleys, particularly in the eastern half of the County; generally thin and poorly exposed. The headward part of a typical valley is swampy and underlain by peaty sand or clay. Downstream, the alluvium is mainly sand or gravelly sand, depending upon the texture of the formation traversed by any given stream.

Qtm

**TIDAL MARSH DEPOSITS (HOLOCENE)** - Silty clay to fine sand, dark gray to gray-brown, largely muck. Woody debris and finely comminuted organic matter abundant.

Op

**PARSONSBURG SAND (UPPER WISCONSIN)** - Mostly sand, loose and light colored; pale yellow, yellowish orange, pale red-brown, or white. Locally at base where peaty, the sands are dark gray-brown. Most of the sand is medium-grained, although coarse sand and sand containing granules is locally common. Sorting varies in vertical cuts from good to poor. In outcrop the upper few meters of the Formation are red-brown, slightly clayey, and appear to be extensively burrowed. The material is laced with numerous cylindrical burrows about 3 cm (1 in) in diameter and 5-15 cm (2-6 in) long. Below the massive reddened zone, thin bands of red-brown clayey sand are common in the thicker sections to a depth of as much as 3 m (10 ft). In some of the thickest sections, the lower part of the Parsonsburg Sand is well stratified with small scale cross beds. Concentrations of black minerals are common in the cross-bedded portion.

Qk

**KENT ISLAND FORMATION (MIDDLE WISCONSIN OR UPPER SANGAMON)** - Predominantly sand, white, yellow, brown, or pale to medium gray, interstratified with thin beds of dark-gray silt or silty fine-grained sand. Light-gray to white gravelly sands common at the base of the Formation. Underlies a broad lowland in the western part of the County between hilly topography of the Parsonsburg Sand along the east side of the Nanticoke River and a sandy terrain about 5 miles east of the river along a highly dissected northwest-trending scarp extending from Crows Nest on the southeast to Mardela Springs on the northwest. Most of the land surface here is at elevations ranging from 3.0-7.6 m (10 to 25 ft). Small dune-shaped sand bodies which rise above this general level are scattered across the lowland. North of Mardela Springs, a small area of lowland deposits flanks the east side of the lower Nanticoke River as far as the northern part of the County.

**REFERENCE:**

**GEOLOGIC MAP OF WICOMICO COUNTY,  
PREPARED BY STATE OF MARYLAND,  
MARYLAND GEOLOGICAL SURVEY,  
DATED 1979.**

**JOHNSON'S POND**

**GEOLOGY MAP LEGEND**

**RUMMEL, KLEPPER & KAHL**

