

AD-A099 094

6AI CONSULTANTS INC MONROEVILLE PA

F/6 13/13

NATIONAL DAM INSPECTION PROGRAM. POCONO MOUNTAIN LAKE DAM (NDI --ETC(U)

MAR 81 B M MIHALCIN

DACW31-81-C-0015

NL

UNCLASSIFIED

For 1
AD-A099094

END
DATE
FILMED
6-81
DTIC

AD A099094

DELAWARE RIVER BASIN,
TOMS CREEK, PIKE COUNTY, Pennsylvania.

⑥

PENNSYLVANIA.

National Dam Inspection Program.

POCONO MOUNTAIN LAKE DAM

(NDI LD. NO. PA-00767

PENNDER LD. 52-171)

Number


POCONO MOUNTAIN LAKE ESTATES
COMMUNITY ASSOCIATION

PHASE I INSPECTION REPORT •

NATIONAL DAM INSPECTION PROGRAM

⑮ PACW-31-VLC-2015

② Bernard M. Mihalek



DTIC
ELECTE
MAY 18 1984

⑪ Mar 84

⑫ 84

PREPARED FOR

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

PREPARED BY

CAI CONSULTANTS, INC.
510 BRATTY ROAD
MIDDLETOWN, PENNSYLVANIA 17057
MARCH 1984

PROHIBITED FROM PUBLIC RELEASE
EXCEPT BY AUTHORITY OF
THE SECRETARY OF THE ARMY

DTIC
ELECTRONIC
S
MAY 18 1981
C

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the Spillway Design Flood is based on the estimated Probable Maximum Flood (greatest reasonably possible storm runoff) for the region, or fractions thereof. The Spillway Design Flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

Breach analyses are performed, when necessary, to provide data to assess the potential for downstream damage and possible loss of life. The results are based on specific theoretical scenarios peculiar to the analysis of a particular dam and are not applicable to other related studies such as those conducted under the Federal Flood Insurance Program.

DISTR. STATEMENT A
Approved for public release;
Distribution Unlimited

Accession For	NTIS GRA&I
	DTIC TAB
	Unannounced
	Justification by
By	<i>[Signature]</i>
Distribution	<i>[Signature]</i>
Availability Codes	
Date	
	<i>A</i>

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

ABSTRACT

Pocono Mountain Lake Dam: NDI I.D. No. PA-00767

Owner: Pocono Mountain Lake Estates Community Association

State Located: Pennsylvania (PennDER I.D. No. 52-171)

County Located: Pike

Stream: Toms Creek

Inspection Date: 20 October 1980

Inspection Team: GAI Consultants, Inc.
570 Beatty Road
Monroeville, Pennsylvania 15146

Based on a visual inspection, operational history, and available engineering data, the dam is considered to be in good condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Since the facility is classified near the lower bounds of the small category, the SDF is considered to be the 1/2 PMF. Results of the hydrologic and hydraulic analysis indicate the facility is capable of accommodating a 1/2 PMF event. Specifically, the facility will pass and/or store about 84 percent of the PMF prior to embankment overtopping. Consequently, the spillway is considered adequate.

It is recommended that the owner immediately:


- a. Exterminate burrowing animals that are possibly inhabiting the embankment and refill their burrows with earth.
- b. Repair all deteriorated concrete associated with the spillway.
- c. Continue to observe, in all future inspection, the seepage encountered downstream of the outlet conduit noting any turbidity and/or changes in rate of flow.


Pocono Mountain Lake Dam: NDI I.D. No. PA-00767


d. Develop formal manuals of operation and maintenance to ensure future proper care and operation of the facility. Included in the manuals should be a formal warning system for the notification of downstream inhabitants should hazardous embankment conditions develop with provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

GAI Consultants, Inc.

Approved by:


Bernard M. Mihalcin P.E.


JAMES W. PECK
Colonel, Corps of Engineers
District Engineer



Date 27 March 1981

Date 15 APR 81



OVERVIEW PHOTOGRAPH

TABLE OF CONTENTS

	<u>Page</u>
PREFACE.	i
ABSTRACT	ii
OVERVIEW PHOTOGRAPH.	iv
TABLE OF CONTENTS.	v
SECTION 1 - GENERAL INFORMATION.	1
1.0 Authority.	1
1.1 Purpose.	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	5
2.1 Design	5
2.2 Construction Records	6
2.3 Operational Records.	6
2.4 Other Investigations	6
2.5 Evaluation	6
SECTION 3 - VISUAL INSPECTION.	7
3.1 Observations	7
3.2 Evaluation	8
SECTION 4 - OPERATIONAL PROCEDURES	9
4.1 Normal Operating Procedure	9
4.2 Maintenance of Dam	9
4.3 Maintenance of Operating Facilities.	9
4.4 Warning System	9
4.5 Evaluation	9
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION.	10
5.1 Design Data.	10
5.2 Experience Data.	10
5.3 Visual Observations.	10
5.4 Method of Analysis	10
5.5 Summary of Analysis.	10
5.6 Spillway Adequacy.	11
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY	12
6.1 Visual Observations.	12
6.2 Design and Construction Techniques	12
6.3 Past Performance	12
6.4 Seismic Stability.	12
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES.	13
7.1 Dam Assessment	13
7.2 Recommendations/Remedial Measures.	13

TABLE OF CONTENTS

- APPENDIX A - VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES
- APPENDIX B - ENGINEERING DATA CHECKLIST
- APPENDIX C - PHOTOGRAPHS
- APPENDIX D - HYDROLOGIC AND HYDRAULIC ANALYSES
- APPENDIX E - FIGURES
- APPENDIX F - GEOLOGY

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
POCONO MOUNTAIN LAKE DAM
NDI #PA-00767, PennDER #52-171

SECTION 1
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Pocono Mountain Lake Dam is a 22-foot high, homogeneous earth embankment approximately 970 feet long, including spillway. The facility is constructed with an uncontrolled, rectangular shaped, concrete chute channel spillway located near the center of the embankment. Spillway discharges are regulated by a concrete, ogee-type weir. Drawdown capacity is provided by an 18-inch diameter reinforced concrete pipe located to the right of the spillway. Flows through the conduit are controlled at the inlet by an 18-inch diameter slide gate that is manually operated from atop the embankment crest.

b. Location. Pocono Mountain Lake Dam is located across Toms Creeks in Lehman Township, Pike County, Pennsylvania. The dam is part of a residential development known as Pocono Mountain Lake Estates which is located about 4.2 miles north of U.S. Route 209 at Egypt Mills, Pennsylvania. The dam, reservoir and watershed are contained within the Lake Maskenozha, Pennsylvania-New Jersey, 7.5 minute U.S.G.S. topographic quadrangle (see Figure 1, Appendix E). The coordinates of the dam are N41°9.9' and W74°58.8'.

c. Size Classification. Small (22 feet high, 146 acre-feet storage capacity at the top of the dam).

d. Hazard Classification. High (see Section 3.1.e).

e. Ownership. Pocono Mountain Lake Estates
Community Association
Sections 1, 2, 3 and 4
P.O. Box 104
Bushkill, Pennsylvania 18324
ATTN: Mr. Frank Cwik
Maintenance Superintendent

f. Purpose. Recreation.

g. Historical Data. Pocono Mountain Lake Dam was constructed in 1972-73 as part of a real estate development venture funded by Pocono Mountain Lake Estates, Inc. of Englewood Cliff, New Jersey (John J. Fiume, President). The facility was designed by the E.C. Hess Associates, Inc. of Stroudsburg, Pennsylvania. Subsequent to completion of the facility, contractual disagreements, however, between the developer and individuals within the development community prompted legal action whereby a class action suit was filed against the developer and its owner on behalf of the Pocono Mountain Lake Estates Community Association. According to interviews with members of the Association, the courts reportedly awarded the dam and lake to the Association as part of a damage settlement. No modifications have been made to the facility since its completion.

1.3 Pertinent Data.

a. Drainage Area (square miles). 0.3

b. Discharge at Dam Site.

Discharge Capacity of Outlet Conduit - Discharge curves are not available.

Discharge Capacity of Spillway at Maximum Pool \approx 570 cfs (see Appendix D, Sheet 12).

c. Elevations (feet above mean sea level). The following elevations were obtained from design drawings and through field measurements based on the elevation of normal pool at 1140.0 feet (see Appendix D, Sheets 1 and 2).

Top of Dam	1145.0 (design). 1144.6 (field).
Maximum Design Pool	1145.0
Maximum Pool of Record	Not known.
Normal Pool	1140.0 (assumed datum).
Spillway Crest	1140.0
Upstream Inlet Invert	1123.0 (design).
Downstream Outlet Invert	1123.0 (field).
Streambed at Dam Centerline	1123.0
Maximum Tailwater	Not known.

d.	<u>Reservoir Length (feet).</u>	
	Top of Dam	1500
	Normal Pool	1400
e.	<u>Storage (acre-feet).</u>	
	Top of Dam	146
	Normal Pool	74
f.	<u>Reservoir Surface (acres).</u>	
	Top of Dam	19
	Normal Pool	13
g.	<u>Dam.</u>	
	Type	Homogeneous earth.
	Length	954 feet (excluding spillway).
	Height	22 feet (field measured; embankment crest to downstream outlet invert).
	Top Width	15 feet (design). 14 feet (field).
	Upstream Slope	2.5H:1V
	Downstream Slope	2.5H:1V
	Zoning	Homogeneous fill with small granular downstream toe drain (see Figure 2).
	Impervious Core	None indicated.
	Cutoff	Trapezoidal shaped trench with 10-foot bottom width and 1H:1V side slopes located just upstream of embankment centerline (see Figure 2).
	Grout Curtain	None indicated.
h.	<u>Diversion Canal and Regulating Tunnels.</u>	None.

i. Spillway.

Type	Uncontrolled, rectangular shaped, concrete chute channel with an ogee-type weir located near the center of the embankment.
Crest Elevation	1140.0 feet.
Crest Length	16 feet.

j. Outlet Conduit.

Type	18-inch diameter reinforced concrete pipe.
Length	Approximately 110 feet (see Figure 5).
Closure and Regulating Facilities	18-inch diameter slide gate located at the inlet.
Access	Control mechanism is manually operated from atop the embankment crest.

SECTION 2

ENGINEERING DATA

2.1 Design.

a. Design Data Availability and Sources. No formal design reports or calculations are available concerning any aspect of this facility. PennDER files contain a complete set of four design drawings by the E.C. Hess Associates, Inc., dated 1971. These drawings have been included in Appendix E of this report (see Figures 2 through 5). A construction permit application report, issued by the state and dated 1972, is also available in PennDER files. This report contains a brief description of some of the various design aspects of the facility.

b. Design Features.

1. Embankment. Design features of the embankment are presented in Figure 2. As indicated, the structure is composed of homogeneous earthfill. Its upstream and downstream faces are sloped at 2.5H:1V and its crest measures 14 feet wide. A layer of riprap is provided on a portion of the upstream face while the remainder of the embankment is grass covered. The design provides for a gravel filter along the downstream embankment toe and trapezoidal shaped cutoff trench located ten feet upstream of the embankment centerline along the entire length of the embankment. The cutoff trench reportedly extends to bedrock or five to ten feet into impervious material, and has a 10-foot bottom width with 1H:1V side slopes.

2. Appurtenant Structures.

a) Spillway. Design features of the spillway are presented in Figures 3 and 5. It is noted that the configuration of the discharge channel downstream of the baffle blocks is not accurately depicted in these figures (see Photographs 5, 7 and 8). The spillway is an uncontrolled, rectangular shaped, concrete chute channel with an ogee-type weir located near the center of the embankment. The weir crest is 16 feet long and about five feet below the tops of the channel wingwalls. Beyond the concrete channel, a 400-foot long, trapezoidal shaped, rock lined channel directs discharges back into the original stream channel below the embankment.

b) Outlet Conduit. Design features of the outlet conduit are presented in Figures 4 and 5. As shown, the outlet conduit is 18-inch diameter reinforced concrete pressure pipe placed on a concrete cradle for its full length through the base of the embankment fill. Flow through the conduit is controlled by an 18-inch diameter slide gate located on the inlet and manually operated from atop the embankment crest. The channel at the discharge end of the conduit is rock lined for a distance of 20 feet.

c. Specific Design Data and Criteria. No specific design data or information relative to design procedures are available other than the general notes contained in the available drawings.

2.2 Construction Records.

No formal construction records are available for this facility. Brief correspondence in PennDER files indicates that construction was inspected by the designer, Edward C. Hess Associates, Inc.

2.3 Operational Records.

No records of the day-to-day operation of the facility are available.

2.4 Other Investigations.

There are no available records concerning formal studies or investigations of Pocono Mountain Lake Dam since its completion.

2.5 Evaluation.

The available data are considered sufficient to make a reasonable Phase I evaluation of the facility.

SECTION 3

VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of the facility suggests the dam and its appurtenances are in good condition.

b. Embankment. Observations made during the visual inspection indicate the embankment is in good condition. No evidence of sloughing, erosion, seepage through the downstream embankment face, excessive settlement, or signs of maintenance neglect were observed (see Photographs 1, 2, 3 and 4). An area of seepage, estimated at about one to two gallons per minute (gpm), was observed in the outlet conduit discharge channel approximately 160 feet beyond the downstream embankment toe. The ponded water shown in Photograph 12 appears to collect primarily from this seepage source. Another possible deficiency encountered was an apparent animal burrow observed along the lower downstream embankment face between the right abutment and outlet conduit.

c. Appurtenant Structures.

1. Spillway. The visual inspection revealed the spillway is in good condition (see Photographs 5, 6, 7 and 8). The extreme upstream portion of the left wingwall exhibits an area of spalling that should be repaired while the overall structure, in general, displays minor cracking and scaling of little significance, at present.

2. Outlet Conduit. The outlet conduit has reportedly not been operated in several years. The visible exposed portions of this appurtenance, however, appear to be in excellent condition. No evidence of significant deterioration was observed.

d. Reservoir Area. The Pocono Mountain Lake watershed consists of moderate to steep, heavily forested slopes. Numerous access roads and dwellings have already been constructed within the boundaries of the watershed and future expansion appears likely. Thus, the current complexion of the watershed is considered temporary.

e. Downstream Channel. Discharge from Pocono Mountain Lake Dam flows through a steep, narrow and heavily forested valley with steep confining slopes. Two inhabited dwellings are located near the streambed along the banks of Toms Creek approximately 2.1 miles downstream of the embankment. No other inhabitable structures are located sufficiently near the streambed within the reach between the embankment and the confluence of Toms Creek and the Delaware River. It is estimated that four to ten lives could be affected as the result of an embankment breach. Consequently, the hazard classification is considered to be high.

3.2 Evaluation.

The overall condition of the facility based on visual observations is considered to be good. Remedial measures should be implemented to repair the minor deterioration associated with the spillway concrete and to exterminate rodents that inhabit the embankment and backfill their burrows. In addition, the seepage condition encountered downstream of the outlet conduit should continue to be observed in all future inspections.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Normal Operating Procedure.

Pocono Mountain Lake Dam is essentially a self-regulating facility. That is, excess inflows are automatically discharged through the uncontrolled spillway and directed downstream. Typically, the outlet conduit is closed and reportedly has not been opened for several years. The conduit was not operated in the presence of the inspection team. No formal operations manual is available.

4.2 Maintenance of Dam.

The facility is reportedly maintained on an unscheduled basis by the owner's maintenance staff. No formal maintenance program has been established at this facility and no formal manuals are available.

4.3 Maintenance of Operating Facilities.

See Section 4.2 above.

4.4 Warning System.

No formal warning system is presently in effect.

4.5 Evaluation.

The general appearance of the facility suggests that it has been adequately maintained to date. No formal maintenance or operations manuals are available, but, are recommended to ensure the continued proper care and operation of the facility. In addition, formal warning system procedures should be incorporated into these manuals to provide for the protection of downstream residents should hazardous embankment conditions develop.

SECTION 5
HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

No formal design reports are available for this facility. According to information contained in PennDER files, the spillway at Pocono Mountain Lake Dam was sized with sufficient capacity to exceed 1972 state requirements of 450 cfs as established by the Pennsylvania "C" Curve.

5.2 Experience Data.

Daily records of reservoir levels and/or spillway discharges are not available. The general appearance of the facility suggests adequate past performance.

5.3 Visual Observations.

On the date of inspection, no conditions were observed that would indicate the facility could not perform satisfactorily within the limits of its design capacity.

5.4 Method of Analysis.

The facility has been analyzed in accordance with the procedures and guidelines established by the U.S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U.S. Army, Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly outlined in the preface contained in Appendix D.

5.5 Summary of Analysis.

a. Spillway Design Flood (SDF). In accordance with procedures and guidelines contained in the National Guidelines for Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Pocono Mountain Lake Dam ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. This classification is based on the relative size of the dam (small) and the potential hazard of dam failure to downstream developments (high). Since the facility is classified near the lower bounds of the small category, the SDF for the facility is considered to be the 1/2 PMF.

b. Results of Analysis. Pocono Mountain Lake Dam was evaluated under near normal operating conditions. That is, the reservoir was initially at its normal pool or spillway elevation of approximately 1140.0 feet, with the spillway weir discharging freely. The outlet conduit was assumed to be non-functional for the purpose of analysis, since the discharge capacity of the conduit is not such that it would significantly increase the total discharge capabilities of the dam and reservoir. The spillway consists of an uncontrolled, rectangular shaped, concrete chute channel with a concrete ogee-type weir. All pertinent engineering calculations relative to the evaluation of this facility are provided in Appendix D.

Overtopping analysis (using the Modified HEC-1 computer program) indicated that the discharge/storage capacity of Pocono Mountain Lake Dam can accommodate storms in excess of the 1/2 PMF (SDF) or, specifically, about 84 percent of the PMF prior to embankment overtopping. The peak 1/2 PMF inflow of approximately 440 cfs was attenuated by the discharge/storage capabilities of the dam and reservoir such that the resulting peak outflow was about 320 cfs. The maximum water surface level of the reservoir under 1/2 PMF conditions was about 1143.2 feet, or 1.4 feet below the top of the dam (Appendix D, Summary Input/Output Sheets, Sheets B and C).

5.6 Spillway Adequacy.

Pocono Mountain Lake Dam was found to be capable of passing and/or storing the inflow resulting from a 1/2 PMF event (SDF), and therefore, its spillway is considered to be adequate.

SECTION 6

EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations, the embankment is considered to be in good structural condition. The seepage condition encountered downstream of the embankment is not considered to be significant at this time. The condition should, however, continue to be observed in all future inspections specifically noting any turbidity and/or changes in rate of flow. The possibility of burrowing animals inhabiting the embankment is cause for some concern. Animal burrows may become paths for potential seepage and piping which could lead to failure of the structure. Care should taken to periodically search out and locate any burrows, exterminate the burrowing animals, and refill the burrows with earth.

b. Appurtenant Structures.

1. Spillway. The spillway is considered to be in good structural condition. Observed areas of minor concrete deterioration are not considered to be significant at this time. Nevertheless, repairs should be implemented immediately while the extent of the deterioration is still local.

2. Outlet Conduit. The outlet conduit is considered to be in excellent condition. No significant deficiencies were noted.

6.2 Design and Construction Techniques.

No information is available that details the methods of design and/or construction of the facility.

6.3 Past Performance.

There are no records documenting any events during which the facility has not adequately functioned.

6.4 Seismic Stability.

The dam is located in Seismic Zone No. 1 and may be subject to minor earthquake induced dynamic forces. As the facility appears to be well constructed and sufficiently stable, it is believed that it can withstand the expected dynamic forces; however, no calculations and/or investigations were performed to confirm this belief.

SECTION 7

ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The results of this investigation indicate the facility is in good condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Since the facility is classified near the lower bounds of the small category, the SDF is considered to be the 1/2 PMF. Results of the hydrologic and hydraulic analysis indicate the facility is capable of accommodating a 1/2 PMF event. Specifically, the facility will pass and/or store about 84 percent of the PMF prior to embankment overtopping. Consequently, the spillway is considered to be adequate.

b. Adequacy of Information. The available data are considered sufficient to make a reasonable Phase I assessment of the facility.

c. Urgency. The recommendations listed below should be implemented immediately.

d. Necessary for Additional Investigations. No additional investigations are deemed necessary at this time.

7.2 Recommendations/Remedial Measures.

It is recommended that the owner immediately:

a. Exterminate burrowing animals that are possibly inhabiting the embankment and refill the burrows with earth.

b. Repair all deteriorated concrete associated with the spillway.

c. Continue to observe, in all future inspections, the seepage encountered downstream of the outlet conduit noting any turbidity and/or changes in rate of flow.

d. Develop formal manuals of operation and maintenance to ensure future proper care and operation of the facility. Included in the manuals should be a formal warning system for the notification of downstream inhabitants should hazardous embankment conditions develop with provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

APPENDIX A
VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES

**CHECK LIST
VISUAL INSPECTION
PHASE 1**

NAME OF DAM Pocono Mountain Lake Dam STATE Pennsylvania COUNTY Pike
TYPE OF DAM Earth NDI # PA -- 00767 PENNDR # 52-171 SIZE Small HAZARD CATEGORY High
DATE(S) INSPECTION 20 October 1980 WEATHER Overcast & Windy TEMPERATURE 45° @ 2:00 PM
POOL ELEVATION AT TIME OF INSPECTION 1137.2 Feet M.S.L.
TAILWATER AT TIME OF INSPECTION N/A M.S.L.

INSPECTION PERSONNEL

B. M. Mihalcin

D. J. Spaeder

D. L. Bonk

OWNER REPRESENTATIVES

Pocono Mountain Lake Estates Community Association

Frank Cwik - Maintenance Superintendent

Dave Stitt - Maintenance Crew Member

Jim Sattur - Maintenance Crew Member

OTHERS

RECORDED BY D. L. Bonk

EMBANKMENT

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA · 00767
SURFACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed. Rock lined v-ditch located along downstream toe between right abutment and natural ground knoll adjacent spillway. Small rock toe is located at the base of the downstream face across the entire length of the embankment.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None observed. Slopes covered primarily with crownvetch. Crest is mowed regularly.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Vertical - Good (see "Profile of Dam Crest from Field Survey," Appendix A). Horizontal - Good.	
RIPRAP FAILURES	None observed. Hard, durable, well graded sandstone riprap in excellent condition.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Good.	

EMBANKMENT

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDM PA - 00767
DAMP AREAS IRREGULAR VEGETATION (LUSH OR DEAD PLANTS)	None observed.	
ANY NOTICEABLE SEEPAGE	Seepage (\approx 1 to 2 gpm) observed in outlet discharge channel about 160 feet downstream of outlet.	
STAFF GAGE AND RECORDER	None.	
DRAINS	Two six-inch diameter toe drains located in concrete outlet headwall to the left and right of the outlet. Not discharging.	
MISCELLANEOUS	Possible animal burrow located along downstream embankment face 200 to 250 feet left of the right abutment.	

OUTLET WORKS

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA. 00767
INTAKE STRUCTURE	Submerged, not observed.	
OUTLET CONDUIT (CRACKING AND SPALLING OF CON- CRETE SURFACES)	18-inch diameter concrete pressure pipe. Not exposed, except at discharge end.	
OUTLET STRUCTURE	Small concrete headwall at discharge end of outlet conduit in good condition.	
OUTLET CHANNEL	Small, trapezoidal shaped, rock lined channel.	
GATE(S) AND OPERA- TIONAL EQUIPMENT	18-inch diameter slide gate manually operated from embankment crest. Operating mechanism appears to be in good condition, but reportedly has not been operated for several years.	

EMERGENCY SPILLWAY

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA . 00767
TYPE AND CONDITION	Uncontrolled, rectangular shaped, concrete chute channel with an ogee-type weir in good condition.	
APPROACH CHANNEL	Rock lined.	
SPILLWAY CHANNEL AND SIDEWALLS	Minor vertical cracking observed in the sidewalls particularly around the weepholes. Channel floor exhibits minor scaling. A small spalled area is located at the upstream end of the left sidewall.	
STILLING BASIN PLUNGE POOL	None. Concrete energy dissipators located immediately beyond ogee weir.	
DISCHARGE CHANNEL	Rectangular shaped, concrete chute discharges into a trapezoidal shaped, rock lined channel.	
BRIDGE AND PIERS EMERGENCY GATES	None.	

SERVICE SPILLWAY


ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA · 00767
TYPE AND CONDITION	N/A.	
APPROACH CHANNEL	N/A.	
OUTLET STRUCTURE	N/A.	
DISCHARGE CHANNEL	N/A.	

INSTRUMENTATION


ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA · 00767
MONUMENTATION SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHERS		

RESERVOIR AREA AND DOWNSTREAM CHANNEL

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA · 00767
SLOPES: RESERVOIR	Moderate to steep and heavily wooded.	
SEDIMENTATION	None observed.	
DOWNSTREAM CHANNEL (OBSTRUCTIONS, DEBRIS, ETC.)	Natural channel unobstructed except for several road culverts which it passes through between the embankment and the Delaware River.	
SLOPES: CHANNEL VALLEY	Steep, narrow and heavily forested valley with steep confining slopes.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	Two inhabited dwellings are located near the streambed along the banks of Toms Creek approximately 2.1 miles downstream of the embankment. It is estimated that four to ten lives could be affected as the result of an embankment breach.	



POCONO MOUNTAIN LAKE DAM
GENERAL PLAN-FIELD INSPECTION NOTES



SUBJECT: POCONO MOUNTAIN LAKE DAM
BY: JAS. J. TATE (JAT/EA/JA) SHEET NO. 1 OF
CONSULTANTS: S. G. B. PROJECT NO. 60-238-201

APPENDIX B
ENGINEERING DATA CHECKLIST

**CHECK LIST
ENGINEERING DATA
PHASE I**

NAME OF DAM Pocono Mountain Lake Dam

ITEM	REMARKS	NDIN PA - 00767
PERSONS INTERVIEWED AND TITLE	Pocono Mountain Lake Estates Community Association Frank Cwik - Maintenance Superintendent Dave Stitt - Maintenance Crew Member Jim Sattur - Maintenance Crew Member	
REGIONAL VICINITY MAP	See Figure 1, Appendix E.	
CONSTRUCTION HISTORY	Designed by E. C. Hess Associates, Inc., of Stroudsburg, Pennsylvania. Completed in November 1973.	
AVAILABLE DRAWINGS	Complete set of four design drawings by E. C. Hess Associates, Inc., dated September 1971, are contained in PENNDER files. See Figures 2 through 5, Appendix E.	
TYPICAL DAM SECTIONS	See Figure 2, Appendix E.	
OUTLETS: PLAN DETAILS DISCHARGE RATINGS	See Figures 4 and 5, Appendix E. Discharge rating curves are not available.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	NDI# PA - 00767
SPILLWAY: PLAN SECTION DETAILS	See Figures 3 and 5, Appendix E.	
OPERATING EQUIP- MENT PLANS AND DETAILS	See Figures 4 and 5, Appendix E.	
DESIGN REPORTS	None available.	
GEOLOGY REPORTS	None available.	
DESIGN COMPUTATIONS: HYDROLOGY AND HYDRAULICS STABILITY ANALYSES SEEPAGE ANALYSES	None available.	
MATERIAL INVESTIGATIONS: BORING RECORDS LABORATORY TESTING FIELD TESTING	Six test pits dug along embankment centerline. See Figure 2, Appendix E.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	NDI# PA. 00767
BORROW SOURCES	Not known.	
POST CONSTRUCTION DAM SURVEYS	None.	
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Periodic water testing performed by state officials.	
HIGH POOL RECORDS	On the order of 1-foot over weir.	
MONITORING SYSTEMS	None.	
MODIFICATIONS	None.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	NDI# PA . 00767
PRIOR ACCIDENTS OR FAILURES	None.	
MAINTENANCE: RECORDS MANUAL	No formal manual or records are available.	
OPERATION: RECORDS MANUAL	No formal manual or records are available.	
OPERATIONAL PROCEDURES	Self-regulating.	
WARNING SYSTEM AND/OR COMMUNICATION FACILITIES	None.	
MISCELLANEOUS		

GAI CONSULTANTS, INC.

**CHECK LIST
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA**

NDI ID # PA-00767
PENNER ID # 52-171

SIZE OF DRAINAGE AREA: 0.3 square miles.
ELEVATION TOP NORMAL POOL: 1140.0 STORAGE CAPACITY: 74 acre-feet.
ELEVATION TOP FLOOD CONTROL POOL: - STORAGE CAPACITY: -
ELEVATION MAXIMUM DESIGN POOL: - STORAGE CAPACITY: -
ELEVATION TOP DAM: 1144.6 STORAGE CAPACITY: 146 acre-feet.

SPILLWAY DATA

CREST ELEVATION: 1140.0 feet.
TYPE: Uncontrolled, rectangular shaped, concrete chute with ogee-type weir.
CREST LENGTH: 16 feet.
CHANNEL LENGTH: Approximately 60 feet.
SPILLOVER LOCATION: Near embankment center.
NUMBER AND TYPE OF GATES: None.

OUTLET WORKS



TYPE: 18-inch diameter reinforced concrete pipe.
LOCATION: About midway between spillway and right abutment.
ENTRANCE INVERTS: 1123.0 feet.
EXIT INVERTS: 1123.0 feet.
EMERGENCY DRAWDOWN FACILITIES: 13-inch diameter slide gate at inlet.

HYDROMETEOROLOGICAL GAGES

TYPE: None.
LOCATION: -
RECORDS: -

MAXIMUM NON-DAMAGING DISCHARGE: Not known.

APPENDIX C
PHOTOGRAPHS



POCONO MOUNTAIN LAKE DAM
PHOTOGRAPH KEY MAP

Photograph 1 Overview of Pocono Mountain Lake Dam as seen from the left abutment.

Photograph 2 View of the embankment crest looking toward the spillway and left abutment.

Photograph 3 View of the riprap protection covering the upstream embankment face.

Photograph 4 View of the downstream embankment face as seen from the right abutment.



2



4



1



3

Photograph 5

View of the spillway channel looking upstream.

Photograph 6

Close-up view of the spillway weir and left wingwall.

Photograph 7

View, looking downstream, of the spillway forebay and concrete discharge channel.

Photograph 8

View, looking downstream, of the trapezoidal shaped discharge channel that directs flow back into the original stream.



6

8

5

7

Photograph 9

View of the outlet conduit valve control mechanism located along the upstream embankment face to the right of the spillway.

Photograph 10

View of the concrete headwall at the discharge end of the outlet conduit.

Photograph 11

View of the wooded knoll situated immediately downstream of the embankment between the spillway and outlet conduit discharge channels.

Photograph 12

View of ponded water fed by seepage observed about 160 feet downstream of the outlet.



10



12



9



11

APPENDIX D

HYDROLOGIC AND HYDRAULIC ANALYSES

PREFACE

The modified HEC-1 program is capable of performing two basic types of hydrologic analyses: 1) the evaluation of the overtopping potential of the dam; and 2) the estimation of the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. Briefly, the computational procedures typically used in the dam overtopping analysis are as follows:

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.
- c. Routing of the outflow hydrograph(s) from the reservoir to desired downstream locations. The results provide the peak discharge(s), time(s) of occurrence the peak discharge(s), and the maximum stage(s) of each routed hydrograph at the downstream end of each reach.

The evaluation of the hydrologic-hydraulic consequences resulting from an assumed structural failure (breach) of the dam is typically performed as shown below.

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir.
- c. Development of a failure hydrograph(s) based on specified breach criteria and normal reservoir outflow.
- d. Routing of the failure hydrograph(s) to desired downstream locations. The results provide estimates of the peak discharge(s), time(s) to peak and maximum water surface elevation(s) of failure hydrograph(s) for each location.

HYDROLOGY AND HYDRAULIC ANALYSIS
DATA BASE

NAME OF DAM: POCONO MOUNTAIN LAKE DAM

PROBABLE MAXIMUM PRECIPITATION (PMP) = 22.0 INCHES/24 HOURS (1)

STATION	1	2	3
STATION DESCRIPTION	Pocono Mountain Lake Dam		
DRAINAGE AREA (SQUARE MILES)	0.29		
CUMULATIVE DRAINAGE AREA (SQUARE MILES)	-		
ADJUSTMENT OF PMF FOR DRAINAGE AREA LOCATION (%) (1)	Zone 1		
6 HOURS	111		
12 HOURS	123		
24 HOURS	133		
48 HOURS	142		
72 HOURS	-		
SNYDER HYDROGRAPH PARAMETERS			
ZONE (2)	1		
C_p (3)	0.45		
C_t (3)	1.23		
L (MILES) (4)	1.0		
L_{ca} (MILES) (4)	0.4		
$t_p = C_t (L \cdot L_{ca})^{0.3}$ (HOURS)	0.93		
SPILLWAY DATA			
CREST LENGTH (FEET)	16		
FREEBOARD (FEET)	4.6		

- (1) HYDROMETEOROLOGICAL REPORT 33, U.S. ARMY CORPS OF ENGINEERS, 1956.
 (2) HYDROLOGIC ZONE DEFINED BY CORPS OF ENGINEERS, BALTIMORE DISTRICT, FOR DETERMINATION OF SNYDER COEFFICIENTS (C_p AND C_t).
 (3) SNYDER COEFFICIENTS
 (4) L = LENGTH OF LONGEST WATERCOURSE FROM DAM TO BASIN DIVIDE
 L_{ca} = LENGTH OF LONGEST WATERCOURSE FROM DAM TO POINT OPPOSITE BASIN CENTROID.

SUBJECT

DAM SAFETY INSPECTIONPOCONO MOUNTAIN LAKE DAM

BY

JJS

DATE

1-8-81

PROJ. NO.

80-238-767

CHKD. BY

JRL

DATE

2-12-81

SHEET NO.

1

OF

12

CONSULTANTS, INC.

Engineers • Geologists • Planners
Environmental SpecialistsDAM STATISTICS

HEIGHT OF DAM = 22 FEET (FIELD MEASURED: TOP OF DAM
TO OUTLET INVERT; "TOP OF DAM" HERE AND ON ALL SUBSEQUENT
CALCULATION SHEETS REFERS TO THE LOW SPOT IN THE UPDRAINWARD CREST.)

NORMAL POOL STORAGE CAPACITY = 74 AC-FT (HEC-1)

MAXIMUM POOL STORAGE CAPACITY = 146 AC-FT (HEC-1)
(@ TOP OF DAM)

DRAINAGE AREA = 0.29 SQUARE MILES (PLANIMETERED ON USGS 7.5'
TOPO QUAD - LAKE MASKEGONZA, PA)

ELEVATIONS:

TOP OF DAM (DESIGN)	=	1145.0	(FIG 3, SEE NOTE 1)
TOP OF DAM (FIELD)	=	1144.6	
NORMAL POOL	=	1140.0	(SEE NOTE 1)
SPILLWAY CREST	=	1140.0	
UPSTREAM INLET INVERT (DESIGN)	=	1123.0	(EST; FIG 5; SEE NOTE 1)
DOWNSTREAM OUTLET INVERT (DESIGN)	=	1123.0	(EST; FIG 5; SEE NOTE 1)
DOWNSTREAM OUTLET INVERT (FIELD)	=	1123.0	
STREAMBED @ DAM CENTERLINE	=	1123.0	(EST., FIG 5; SEE NOTE 1)

NOTE 1: THE DESIGN DRAWINGS ARE BASED ON A NORMAL POOL
OR SPILLWAY CREST ELEVATION OF 966.0. HOWEVER, THE USGS TOPO QUAD
FOR LAKE MASKEGONZA, PA, INDICATES THAT THE NORMAL POOL ELEVATION
IS ON THE ORDER OF 1140.0. ALSO, IN COMPARING THE "GENERAL LOCATION
PLAN" WITH THE "SITE PLAN" FOR THE PROPOSED DAM (BOTH ON FIG 2),
ELEVATION 950.0 ON THE SITE PLAN (STREAMBED AT DAM CENTERLINE)

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
BY JJS DATE 1-8-81 PROJ. NO. 80-238-767
CHKD. BY JRL DATE 2-12-81 SHEET NO. 2 OF 12



CORRESPONDS APPROXIMATELY WITH ELEVATION 1120.0 ON THE GENERAL LOCATION PLAN. THUS, IT WILL BE ASSUMED THAT 170.0 FEET MUST BE ADDED TO ALL ELEVATIONS INDICATED ON THE SITE PLAN. IN ADDITION, IN COMPARING THE GENERAL LOCATION PLAN WITH THE USGS TOPO QUAD (FIG. 1), IT APPEARS THAT THE DAM WAS ACTUALLY CONSTRUCTED ABOUT 300 TO 400 FEET UPSTREAM FROM THE ORIGINAL DESIGN LOCATION. THEREFORE, FROM FIGURES 1 & 2, IT WILL BE ASSUMED THAT THE OUTLET INVERT (OR TOE OF THE DAM) IS APPROXIMATELY AT ELEVATION 1123.0, AS OPPOSED TO ELEVATION 1119.0. THUS, 174.0 FEET MUST BE ADDED TO ALL ELEVATIONS INDICATED ON THE DESIGN SKETCHES. IT MUST BE NOTED THAT THE ELEVATIONS USED HERE ARE CONSIDERED ESTIMATES, AND ARE NOT NECESSARILY ACCURATE.

DAM CLASSIFICATION

- DAM SIZE: SMALL (REF 1, TABLE 1)
- HAZARD CLASSIFICATION: HIGH (FIELD OBSERVATION)
- REQUIRED SDF: $\frac{1}{2}$ PMF TO PMF (REF 1, TABLE 3)

HYDROGRAPH PARAMETERS

- LENGTH OF LONGEST WATERCOURSE: $L = 1.0$ MILE
- LENGTH OF LONGEST WATERCOURSE FROM DAM TO A POINT OPPOSITE BASIN CENTROID: $L_{ca} = 0.4$ MILES
(USGS TOPO QUAD - LAKE MASKENOZHA, PA)

SUBJECT DAM SAFETY INSPECTION

POCONO MOUNTAIN LAKE DAM

BY BJS DATE 1-8-71 PROJ. NO. 80-238-767

CHKD BY JML DATE 2-2-81 SHEET NO. 3 OF 12



$C_e = .85$
 $C_p = .945$

APPLIED TO CUE ZONE 1, DELAWARE
(OVER BAYAN)

SNYDER'S STANDARD LAG: $t_s = (L/LCA)^{.3}$
 $= (.85 / .945)^{.3}$
 $= .93$ HOURS

(NOTE: - PROGRAM VARIABLES USED WERE NOT DEFINED IN SET 2,
SECTION ENTITLED 'SNYDER SYNTHETIC UNIT HYDROGRAPH')

RESERVOIR CAPACITY

RESERVOIR SURFACE AREAS:

SURFACE AREA (SA) @ NORMAL POOL (EL. 1140.0) = 13 ACRES

SA @ ELEV. 1160.0 = 37 ACRES

(USGS TOPO QUAD - LAKE MAURITIENS, S)

S.A. @ TOP OF DAM (EL. 1144.6) = 18.5 ACRES

(BY LINEAR INTERPOLATION)

- THE "ZERO-STORAGE" ELEVATION IS ASSUMED TO BE AT
ELEVATION 1123.0, OR THE DESIGN UPSTREAM INLET INVERT
ELEVATION.

SUBJECT DAM SAFETY INSPECTION
PUSCONG MOUNTAIN LAKE DAM
 BY RJS DATE 1-9-81 PROJ NO 80-238-767
 CHKD BY JRL DATE 2-12-81 SHEET NO 4 OF 12



ELEVATION-STORAGE RELATIONSHIP:

THE ELEVATION-STORAGE RELATIONSHIP IS COMPUTED INTERNALLY IN THE HEC-1 PROGRAM, BY USE OF THE CONIC METHOD, BASED ON THE ELEVATION-SURFACE AREA DATA GIVEN ABOVE. (SEE SUMMARY INPUT/OUTPUT SHEETS.)

PMP CALCULATIONS

- APPROXIMATE RAINFALL INDEX = 220 INCHES
 (CORRESPONDING TO A DURATION OF 24 HOURS AND A DRAINAGE AREA OF 200 SQUARE MILES.)

(REF. 3, FIG. 1)

- DEPTH-AREA-DURATION ZONE 1

(REF. 3, FIG. 1)

- ASSUME DATA CORRESPONDING TO A 10-SQUARE MILE AREA MAY BE APPLIED TO THIS 0.29-SQUARE MILE BASIN:

<u>DURATION (HRS)</u>	<u>PERCENT OF INDEX RAINFALL</u>
6	111
2	123
24	133
48	142

(REF. 3, FIG. 3)

HOP BROOK FACTOR (ADJUSTMENT FOR BASIN SHAPE AND FOR THE LESSER LIKELIHOOD OF A SEVERE STORM CENTERING OVER A SMALL BASIN) FOR A DRAINAGE AREA OF 0.29 SQUARE MILES IS 0.80.


(REF. 4, p. 48)

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY ZJS DATE 1-9-81 PROJ. NO. 80-238-767
 CHKD. BY JRL DATE 2-12-81 SHEET NO. 5 OF 12




SPILLWAY CAPACITY

PROFILE:



- NOT TO SCALE -

CROSS-SECTION: (LOOKING UPSTREAM)



- NOT TO SCALE -

(SKETCHES BASED ON FIELD MEASUREMENTS AND DESIGN DRAWINGS - FIGS 3 AND 5).

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
BY DDS DATE 1-9-81 PROJ. NO. 80-238-767
CHKD. BY JRL DATE 2-12-81 SHEET NO. 6 OF 12



THE SPILLWAY CONSISTS OF A RECTANGULAR CONCRETE CHUTE CHANNEL WITH DISCHARGES REGULATED BY A CONCRETE OGEE-TYPE WEIR. DISCHARGE OVER THE WEIR CAN BE ESTIMATED BY THE RELATION

$$Q = CLH^{3/2} \quad (\text{REF. 4, p. 373})$$

WHERE
 Q = DISCHARGE OVER THE WEIR, IN CFS,
 C = DISCHARGE COEFFICIENT,
 L = LENGTH OF WEIR CREST = 16 FT,
 H = TOTAL HEAD ON CREST, IN FT.

THE DESIGN HEAD, H_0 , IS ASSUMED TO BE 5.0 FEET, OR TO THE DESIGN TOP OF DAM (SPILLWAY WINGWALLS). IT IS ASSUMED THAT THE RELATIONSHIPS IN REF. 4, PP. 370-382, ARE APPLICABLE TO THIS OGEE-TYPE WEIR. FOR A FOREBAY DEPTH OF 2.2 FEET,

$$\frac{d}{H_0} = \frac{2.2}{5.0} = 0.44$$

$$\therefore C_0 = 3.77 \quad (\text{REF. 4, FIG 249, p. 378})$$

APPROACH CHANNEL LOSSES @ DESIGN HEAD DISCHARGE:

- APPROACH CHANNEL LENGTH = 20 FT (FIELD MEASURED)
- APPROACH CHANNEL WIDTH = 16 FT
- AT EL. 1145.0 (DESIGN POOL),

$$\text{AVERAGE APPROACH CHANNEL DEPTH} = 5.0 + 2.2 = \underline{7.2} \text{ FEET}$$

$$\text{FLOW AREA} = 7.2 \times 16.0 = \underline{115.2} \text{ FT}$$

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY DJS DATE 1-9-81 PROJ. NO. 20-238-767
 CHKD. BY NRL DATE 2-12-81 SHEET NO. 7 OF 12



- INITIAL ESTIMATE OF DISCHARGE:

$$Q = CLH^{3/2} = (3.77)(16)(5^{3/2}) = \underline{674 \text{ CFS}}$$

- AVERAGE VELOCITY IN APPROACH CHANNEL:

$$V_A = \frac{Q}{A} = \frac{674}{115.2} = \underline{5.9 \text{ FPS}}$$

- AVERAGE APPROACH VELOCITY HEAD

$$h_a = \frac{V_a^2}{2g} = \frac{5.9^2}{64.4} = \underline{0.54 \text{ FT}}$$

- ASSUMING THAT THE APPROACH CHANNEL ENTRANCE LOSS = 0.1 h_a (REF 4, p. 379),

$$\text{ENTRANCE LOSS} = 0.1 \times 0.54 = \underline{0.05 \text{ FT}}$$

- APPROACH CHANNEL FRICTION LOSS, h_F:

$$h_F = \left[\frac{V_a n}{1.486 R^{2/3}} \right]^2 \times L_c \quad (\text{REF 4, p. 379})$$

WHERE
 L_c = LENGTH OF APPROACH CHANNEL = 20 FT,
 n = MANNINGS ROUGHNESS COEFFICIENT = 0.040,
 (COMPOSITE; FIELD OBSERVATION)
 R = HYDRAULIC RADIUS = FLOW AREA / WETTED PERIMETER.

WETTED PERIMETER:

$$\begin{aligned} \text{AVG. HT. OF WINGWALL} &= \frac{(7.1)(7.5) + \frac{(7.1+2.2)}{2}(12.5)}{30} \\ &= \underline{5.6 \text{ FT}} \end{aligned}$$

$$\therefore \text{AVG. WETTED PERIMETER} = 2(5.6) + 16 = \underline{27.2 \text{ FT}}$$

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY DJS DATE 1-12-81 PROJ. NO. 80-238-767
 CHKD. BY JRL DATE 2-12-81 SHEET NO. 8 OF 12



$$\text{AUG. HYDRAULIC RADIUS} = R_H = \frac{A}{P} = \frac{115.2}{27.2} = \underline{4.2 \text{ FT}}$$

$$\therefore h_F = \left[\frac{(5.9)(0.040)}{(1.486)(4.2)^{4/3}} \right]^2 \times 20 = \underline{0.07 \text{ FT}}$$

$$\therefore \text{TOTAL APPROACH CHANNEL LOSS} = 0.07 + 0.05 = \underline{0.12 \text{ FT}}$$

$$\text{- ACTUAL EFFECTIVE HEAD } H_E = 5.0 - 0.12 = \underline{4.88 \text{ FT}}$$

$$\begin{aligned} \text{SPILLWAY CAPACITY AT DESIGN HEAD} &= (3.77)(16)(4.88^{3/2}) \\ &= \underline{650 \text{ CFS}} \end{aligned}$$

- FOR HEADS OTHER THAN DESIGN HEAD, THE APPROACH CHANNEL LOSSES WILL BE ASSUMED TO BE PROPORTIONAL TO THE LOSSES AT DESIGN HEAD:

$$h_L = \left(\frac{0.12}{5.0} \right) H$$

WHERE h_L = APPROACH CHANNEL LOSS, IN FT, AND
 H = RESERVOIR ELEVATION - 1140.0 FT.

EFFECTS OF HEAD OTHER THAN DESIGN HEAD:

AS THE HEAD ON THE WEIR BECOMES SMALL, DISCHARGE IS REDUCED DISPROPORTIONATELY, DUE TO THE ROUGHNESS AND THE CONTACT PRESSURE BETWEEN THE WATER AND THE WEIR SURFACE. THUS, THE DISCHARGE COEFFICIENT (C) TAKES ON A VALUE LOWER THAN THAT OF DESIGN HEAD. THE OPPOSITE TENDS TO OCCUR FOR HEADS GREATER THAN THAT OF DESIGN. THEREFORE, THE DESIGN DISCHARGE COEFFICIENT WILL BE MODIFIED APPROPRIATELY, ACCORDING TO FIG. 250, REF. 4.

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY RSS DATE 1-12-81 PROJ. NO. 80-238-767
 CHKD. BY JLL DATE 2-12-81 SHEET NO. 9 OF 12



SPILLWAY RATING TABLE

RESERVOIR ELEVATION (FT)	H (FT)	H/H ₀ ^①	C/C ₀ ^②	C ^③	ESTIMATED APPROACH LOSS, h _L (FT) ^④	EFFECTIVE HEAD, H _E (FT) ^⑤	Q (CFS) ^⑥
1140.0	0	-	-	-	-	-	0
1141.0	1.0	0.20	0.85	3.20	0.02	0.98	50
1142.0	2.0	0.40	0.90	3.39	0.05	1.95	150
1143.0	3.0	0.60	0.94	3.54	0.07	2.93	280
1144.0	4.0	0.80	0.97	3.66	0.10	3.90	450
(TOP OF DAM) (TOP OF SPILLWAY WINGWALLS) 1144.6	4.6	0.92	0.99	3.73	0.11	4.49	570
1144.9	4.9	0.98	1.00	3.77	0.12	4.78	630
1145.0	5.0	1.00	1.00	3.77	0.12	4.88	650
1145.3	5.3	1.06	1.01	3.81	0.13	5.17	720
1145.5	5.5	1.10	1.02	3.85	0.13	5.37	770
1146.0	6.0	1.20	1.02	3.85	0.14	5.86	870
1146.5	6.5	1.30	1.04	3.92	0.16	6.34	1000
1147.0	7.0	1.40	1.05	3.96	0.17	6.83	1130
1148.0	8.0	1.60	1.07	4.03	0.19	7.81	1410

- ① H₀ = DESIGN HEAD = 5.0 FT
- ② C/C₀ : FROM REF 4, FIG. 250, p. 378.
- ③ C₀ = 3.77 ; C = 3.77 x C/C₀
- ④ h_L = $\left(\frac{0.12}{5.0}\right)H$ (SEE SHEET 8)
- ⑤ H_E = H - h_L
- ⑥ Q = CLH_E^{3/2} ; L = 16 FT ; (COMPUTED TO NEAREST 10 CFS).

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY DJS DATE 1-12-81 PROJ. NO. 80-238-767
 CHKD. BY JML DATE 2-12-81 SHEET NO. 10 OF 12



EMBANKMENT RATING CURVE

ASSUME THAT THE EMBANKMENT BEHAVES ESSENTIALLY AS A BROAD-CRESTED WEIR WHEN OVERTOPPING OCCURS. THUS, THE DISCHARGE CAN BE ESTIMATED BY THE RELATIONSHIP

$$Q = CLH^{3/2} \quad (\text{REF 5, p. 5-23})$$

WHERE Q = DISCHARGE OVER EMBANKMENT, IN CFS,
 L = LENGTH OF EMBANKMENT OVERTOPPED, IN FT,
 H = HEAD, IN FT; IN THIS CASE IT IS THE AVERAGE "FLOW AREA WEIR HEAD" HEAD ABOVE THE LOW TOP OF DAM,
 C = COEFFICIENT OF DISCHARGE; DEPENDENT UPON THE HEAD AND THE WEIR BREADTH.

LENGTH OF EMBANKMENT INUNDATED
VS RESERVOIR ELEVATION:

<u>ELEVATION (FT)</u>	<u>LENGTH (FT)</u>
1144.6	0
1144.9	40
1145.1	100
1145.2	170
1145.3	350
1145.4	640
1145.6	860
1146.0	940
1146.5	950
1147.0	950
1148.0	960

(FROM FIELD SURVEY AND FIG. 2;
 SIDE-SLOPES: RIGHT ABUTMENT - 7H:1V
 LEFT ABUTMENT - 5H:1V)

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY RJS DATE 1-12-81 PROJ. NO. 80-238-767
 CHKD. BY JRL DATE 2-12-81 SHEET NO. 11 OF 12



ASSUME THAT INCREMENTAL DISCHARGES OVER THE EMBANKMENT FOR SUCCESSIVE RESERVOIR ELEVATIONS ARE APPROXIMATELY TRAPEZOIDAL IN CROSS-SECTIONAL FLOW AREA. THEN ANY INCREMENTAL AREA OF FLOW CAN BE ESTIMATED AS $H_i [(L_1 + L_2) / 2]$, WHERE L_1 = LENGTH OF EMBANKMENT OVERTOPPED AT HIGHER ELEVATION, L_2 = LENGTH AT LOWER ELEVATION, AND H_i = DIFFERENCE IN ELEVATIONS. THUS, THE TOTAL AVERAGE "FLOW-AREA WEIGHTED" HEAD CAN BE ESTIMATED AS $H_w = (\text{TOTAL FLOW AREA} / L_1)$.

EMBANKMENT RATING TABLE:

RESERVOIR ELEVATION (FT)	L_1 (FT)	L_2 (FT)	INCREMENTAL HEAD, H_i (FT)	INCREMENTAL FLOW AREA, A_i (FT ²)	TOTAL FLOW AREA, A_T (FT ²)	WEIGHTED HEAD, H_w (FT)	$\frac{H_w}{I}$	C	Q (CFS)
1144.6	0	-	-	-	-	-	-	-	0
1144.9	40	0	0.3	6	6	0.15	0.01	2.95	10
1145.1	100	40	0.2	14	20	0.20	0.01	2.97	30
1145.2	170	100	0.1	14	34	0.20	0.01	2.97	40
1145.3	350	170	0.1	26	60	0.17	0.01	2.96	70
1145.4	640	350	0.1	50	110	0.17	0.01	2.96	130
1145.6	860	640	0.2	150	260	0.30	0.02	2.99	420
1146.0	940	860	0.4	360	620	0.66	0.05	3.03	1520
1146.5	950	940	0.5	473	1093	1.15	0.08	3.04	3560
1147.0	950	950	0.5	475	1568	1.65	0.12	3.04	6120
1148.0	960	950	1.0	955	2523	2.63	0.19	3.07	12,550

- ① $A_i = H_i [(L_1 + L_2) / 2]$
- ② $H_w = A_T / L_1$
- ③ I = BREADTH OF CREST = 14 FT
- ④ $C = f(H, I)$; FROM REF 12, FIG 24
- ⑤ $Q = CL_1 H_w^{3/2}$ (TO NEAREST 10 CFS)

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY DJS DATE 1-12-81 PROJ. NO. 86-238-767
 CHKD. BY JRL DATE 2-12-81 SHEET NO. 12 OF 12



Engineers • Geologists • Planners
 Environmental Specialists

TOTAL FACILITY RATING TABLE

$$Q_{TOTAL} = Q_{SPILLWAY} + Q_{EMBANKMENT}$$

RESERVOIR ELEVATION (FT)	① Q _{SPILLWAY} (CFS)	③ Q _{EMBANKMENT} (CFS)	Q _{TOTAL} (CFS)
1140.0	0	-	0
1141.0	50	-	50
1142.0	150	-	150
1143.0	280	-	280
1144.0	450	-	450
(TOP OF DAM) 1144.6	570	0	570
(TOP OF SPILLWAY WINGWALLS) 1144.9	630	10	640
1145.1	670*	30	700
1145.3	720	70	790
1145.4	750*	130	880
1145.6	790*	420	1210
1146.0	870	1520	2390
1146.5	1000	3560	4560
1147.0	1130	6120	7250
1148.0	1410	12,550	13,960

* - BY LINEAR INTERPOLATION

- ① FROM SHEET 9.
- ③ FROM SHEET 11.

(NOTE: THE WATERSHED DIVIDE IN THE AREA JUST SOUTH OF THE
 UPSTREAM END OF THE RESERVOIR IS SOMEWHERE BETWEEN ELEVATIONS
 1140.0 AND 1160.0. ALTHOUGH THE EXACT ELEVATION IS NOT KNOWN, IT IS
 ASSUMED IN THIS ANALYSIS THAT NO WATER IS LOST TO THE ADJACENT
 WATERSHED.)

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY DJS DATE 2-25-81 PROJ. NO. 80-238-767
 CHKD. BY DLB DATE 2-25-81 SHEET NO. A OF C



SUMMARY INPUT/OUTPUT SHEETS

OVERTOPPING ANALYSIS

DAM SAFETY INSPECTION
 POCONO MOUNTAIN LAKE DAM ***** OVERTOPPING ANALYSIS *****
 10-MINUTE TIME STEP AND 48-HOUR STORM DURATION

NO	MHR	MPIN	LDAY	IHR	IMIN	METMC	LPDI	JPMT	INSTAN
288	0	10	0	0	0	0	0	0	0
JOB SPECIFICATION									
JUPER	MMI	LKOPT	TRACE						
5	0	0	0						

MULTI-PLAN ANALYSES TO BE PERFORMED
 MPLANE 1 MHTIO= 4 LRTIO= 1
 KTIOS= .40 .50 .60 1.00

***** SUB-AREA RUNOFF COMPUTATION *****

RESERVOIR INFLOW

ISTAO	ICOMP	IECUN	ITAPE	JPUT	INAME	ISTAGE	IAUTO
1	0	0	0	0	1	0	0

INYDQ	IUNG	TAREA	SNAP	TNSDA	THSPC	RATIO	ISUM	ISAME	LOCAL
1	1	.29	0.00	.29	0.00	0.000	0	1	0

PRECIP DATA
 R6 R12 R24 R48 R72 R96
 0.00 22.00 111.00 723.00 133.00 142.00 0.00 0.00
 INITIAL AND CONSTANT RAINFALL
 LOSSES, AS PER C.O.E.

LRUPT	STRKH	DLTKR	RTIOL	GRAIN	STNKS	RTIUK	STRIL	CNSTL	ALSHX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA
 TP= .93 CPE= .45 NIA= 0
 BASE FLOW PARAMETERS,
 AS PER C.O.E.

RESERVOIR DATA
 STRIO= -1.50 ORCSN= -.05 RELIN= 2.00
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SWIFER CP AND TP ARE TC= 5.82 AND R= 8.95 INTERVALS

END-UP-PERIOD	FLUM	MLDA	HRMN	PERIOD	MAIN	EXCS	LOSS	CURR
0.	27.	45.	64.	85.	90.	95.	99.	100.
55.	49.	44.	34.	15.	31.	24.	22.	20.
10.	14.	11.	10.	4.	4.	4.	4.	4.
6.	5.	7.	4.	3.	3.	3.	2.	2.
1.	7.	1.	1.	1.	1.	1.	1.	1.

SUBJECT DAM SAFETY INSPECTION
POCONO MOUNTAIN LAKE DAM
 BY DJS DATE 2-25-81 PROJ. NO. 80-238-767
 CHKD. BY DLB DATE 2-25-81 SHEET NO. C OF C



RESERVOIR
 OUTFLOW
 HYDROGRAPHS

0.5 PMF

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	310.	79.	40.	11493.
INCHES	9.	7.	1.	325.
MM	7.51	10.08	10.24	10.24
AC-FT	190.85	250.03	260.11	260.11
THOUS CU M	116.	156.	158.	158.
	143.	192.	195.	195.

PMF

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	687.	161.	82.	23550.
INCHES	19.	14.	2.	667.
MM	15.54	20.66	20.98	20.98
AC-FT	394.69	524.84	532.98	532.98
THOUS CU M	240.	319.	324.	324.
	296.	394.	400.	400.

SUMMARY OF DAM SAFETY ANALYSIS

ELEVATION	INITIAL VALUE	SPILLWAY CHEST	TOP OF DAM
STORAGE	1140.00	1140.00	1144.60
OUTFLOW	74.	74.	146.
	0.	0.	510.

(OVERTOPPING
 OCCURS @ = 0.84 PMF)

RATIO OF PMF	MAXIMUM RESERVOIR W.S. FEET	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.40	1142.75	0.00	114.	248.	0.00	42.00	0.00
.50	1143.23	0.00	122.	318.	0.00	41.83	0.00
.60	1143.64	0.00	129.	369.	0.00	41.83	0.00
1.00	1145.06	.46	154.	687.	2.17	41.50	0.00

LIST OF REFERENCES

1. "Recommended Guidelines for Safety Inspection of Dams," prepared by Department of the Army, Office of the Chief of Engineers, Washington, D. C. (Appendix D).
2. "Unit Hydrograph Concepts and Calculations," by the U. S. Army, Corps of Engineers, Baltimore District (L-519).
3. "Seasonal Variation of Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24, and 48 Hours," Hydrometeorological Report No. 33, prepared by J. T. Reidel, J. F. Appleby and R. W. Schloemer, Hydrologic Service Division, Hydrometeorological Section, U. S. Army, Corps of Engineers, Washington, D. C., April 1956.
4. Design of Small Dams, U. S. Department of the Interior, Bureau of Reclamation, Washington, D. C., 1973.
5. Handbook of Hydraulics, H. W. King, and E. F. Brater, McGraw-Hill, Inc., New York, 1963.
6. Standard Handbook for Civil Engineers, F. S. Merritt, McGraw-Hill, Inc., New York, 1963.
7. Open-Channel Hydraulics, V. T. Chow, McGraw-Hill, Inc., New York, 1959.
8. Weir Experiments, Coefficients, and Formulas, R. E. Horton, Water Supply and Irrigation Paper No. 200, Department of the Interior, United States Geological Survey, Washington, D. C., 1907.
9. "Probable Maximum Precipitation, Susquehanna River Drainage Above Harrisburg, Pennsylvania," Hydrometeorological Report No. 40, prepared by H. V. Goodyear and J. T. Riedel, Hydrometeorological Branch Office of Hydrology, U. S. Weather Bureau, U. S. Department of Commerce, Washington, D. C., May, 1965.
10. Flood Hydrograph Package (HEC- 1) Dam Safety Version, Hydrologic Engineering Center, U. S. Army, Corps of Engineers, Davis, California, July 1978.
11. "Simulation of Flow Through Broad Crest Navigation Dams with Radial Gates," R. W. Schmitt, U. S. Army, Corps of Engineers, Pittsburgh District.
12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.


13. Applied Hydraulics in Engineering, H. M. Morris and J. N. Wiggert, Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
14. Standard Mathematical Tables, 21st Edition, The Chemical Rubber Company, 1973, page 15.
15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C., 1969.
16. Water Resources Engineering, R. K. Linsley and J. B. Franzini, McGraw-Hill, Inc., New York, 1972.
17. Engineering for Dams, Volume 2, W. P. Creager, J. D. Justin, J. Hinds, John Wiley & Sons, Inc., New York, 1964.
18. Roughness Characteristics of Natural Channels, H. H. Barnes, Jr., Geological Survey Water-Supply Paper 1849, Department of the Interior, United States Geological Survey, Arlington, Virginia, 1967.
19. "Hydraulic Charts for the Selection of Highway Culverts," Hydraulic Engineering Circular No. 5, Bureau of Public Roads, Washington, D. C., 1965.

APPENDIX E


FIGURES

LIST OF FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	Regional Vicinity and Watershed Boundary Map
2	Site Plan and Cross Section
3	Spillway and Channel Details
4	Outlet Conduit Details
5	Spillway Wall Details and Outlet Conduit Details









THIS PAGE IS BEST QUALITY REACTION
FROM COPY FURNISHED TO DMC

22-171-1
 U.S. DEPARTMENT OF THE ARMY
 ENGINEERING CENTER
 WASHINGTON, D.C.



1. THE DRAWING IS TO BE USED FOR THE DESIGN OF THE PROJECT AND IS NOT TO BE USED FOR ANY OTHER PURPOSE.
 2. THE DRAWING IS TO BE USED FOR THE DESIGN OF THE PROJECT AND IS NOT TO BE USED FOR ANY OTHER PURPOSE.
 3. THE DRAWING IS TO BE USED FOR THE DESIGN OF THE PROJECT AND IS NOT TO BE USED FOR ANY OTHER PURPOSE.

NOTE: BOTTLES SHOWN TO BE INSTALLED AT SPACING
 200 FEET
 BOTTLES SHOULD BE 2 FT IN
 DIAMETER BETWEEN BOTTLES



SECTION 100' BY 100' AT
 100' BY 100'



BEST PAPER IS BEST QUALITY PAPER
 FROM COPY FURNISHED TO BAC



NOTE: LOCATION OF BOTTLES IS SHOWN IN PLAN VIEW OF
 FINAL CEILING AND IS NOT TO BE
 CONSIDERED.
 FOR MAP TO BE USED TO LOCATE AT
 DIRECTOR'S OFFICE

DATE	3/2/77
RECEIVED BY	[Signature]
NO. OF PAGES	10
COPY TO	10
BY	[Signature]


SECTION 100' BY 100' AT
 100' BY 100'



THIS PAGE IS BEST QUALITY FRAGMENTATION
FROM COPY FURNISHED TO BING

CS-101-3
DATE
TIME
BY


NO. 101-3
PUBLIC MOUNTAIN LAKE ESCORTS
APPROVED FOR
LEADERS: [unclear]
DATE: [unclear]
SCALE: BY [unclear]
ELABORATED BY: [unclear]
DATE: [unclear]



1. 1st Floor
2. 2nd Floor
3. 3rd Floor
4. 4th Floor
5. 5th Floor
6. 6th Floor
7. 7th Floor
8. 8th Floor
9. 9th Floor
10. 10th Floor
11. 11th Floor
12. 12th Floor
13. 13th Floor
14. 14th Floor
15. 15th Floor
16. 16th Floor
17. 17th Floor
18. 18th Floor
19. 19th Floor
20. 20th Floor
21. 21st Floor
22. 22nd Floor
23. 23rd Floor
24. 24th Floor
25. 25th Floor
26. 26th Floor
27. 27th Floor
28. 28th Floor
29. 29th Floor
30. 30th Floor
31. 31st Floor
32. 32nd Floor
33. 33rd Floor
34. 34th Floor
35. 35th Floor
36. 36th Floor
37. 37th Floor
38. 38th Floor
39. 39th Floor
40. 40th Floor
41. 41st Floor
42. 42nd Floor
43. 43rd Floor
44. 44th Floor
45. 45th Floor
46. 46th Floor
47. 47th Floor
48. 48th Floor
49. 49th Floor
50. 50th Floor
51. 51st Floor
52. 52nd Floor
53. 53rd Floor
54. 54th Floor
55. 55th Floor
56. 56th Floor
57. 57th Floor
58. 58th Floor
59. 59th Floor
60. 60th Floor
61. 61st Floor
62. 62nd Floor
63. 63rd Floor
64. 64th Floor
65. 65th Floor
66. 66th Floor
67. 67th Floor
68. 68th Floor
69. 69th Floor
70. 70th Floor
71. 71st Floor
72. 72nd Floor
73. 73rd Floor
74. 74th Floor
75. 75th Floor
76. 76th Floor
77. 77th Floor
78. 78th Floor
79. 79th Floor
80. 80th Floor
81. 81st Floor
82. 82nd Floor
83. 83rd Floor
84. 84th Floor
85. 85th Floor
86. 86th Floor
87. 87th Floor
88. 88th Floor
89. 89th Floor
90. 90th Floor
91. 91st Floor
92. 92nd Floor
93. 93rd Floor
94. 94th Floor
95. 95th Floor
96. 96th Floor
97. 97th Floor
98. 98th Floor
99. 99th Floor
100. 100th Floor



1. 1st Floor
2. 2nd Floor
3. 3rd Floor
4. 4th Floor
5. 5th Floor
6. 6th Floor
7. 7th Floor
8. 8th Floor
9. 9th Floor
10. 10th Floor
11. 11th Floor
12. 12th Floor
13. 13th Floor
14. 14th Floor
15. 15th Floor
16. 16th Floor
17. 17th Floor
18. 18th Floor
19. 19th Floor
20. 20th Floor
21. 21st Floor
22. 22nd Floor
23. 23rd Floor
24. 24th Floor
25. 25th Floor
26. 26th Floor
27. 27th Floor
28. 28th Floor
29. 29th Floor
30. 30th Floor
31. 31st Floor
32. 32nd Floor
33. 33rd Floor
34. 34th Floor
35. 35th Floor
36. 36th Floor
37. 37th Floor
38. 38th Floor
39. 39th Floor
40. 40th Floor
41. 41st Floor
42. 42nd Floor
43. 43rd Floor
44. 44th Floor
45. 45th Floor
46. 46th Floor
47. 47th Floor
48. 48th Floor
49. 49th Floor
50. 50th Floor
51. 51st Floor
52. 52nd Floor
53. 53rd Floor
54. 54th Floor
55. 55th Floor
56. 56th Floor
57. 57th Floor
58. 58th Floor
59. 59th Floor
60. 60th Floor
61. 61st Floor
62. 62nd Floor
63. 63rd Floor
64. 64th Floor
65. 65th Floor
66. 66th Floor
67. 67th Floor
68. 68th Floor
69. 69th Floor
70. 70th Floor
71. 71st Floor
72. 72nd Floor
73. 73rd Floor
74. 74th Floor
75. 75th Floor
76. 76th Floor
77. 77th Floor
78. 78th Floor
79. 79th Floor
80. 80th Floor
81. 81st Floor
82. 82nd Floor
83. 83rd Floor
84. 84th Floor
85. 85th Floor
86. 86th Floor
87. 87th Floor
88. 88th Floor
89. 89th Floor
90. 90th Floor
91. 91st Floor
92. 92nd Floor
93. 93rd Floor
94. 94th Floor
95. 95th Floor
96. 96th Floor
97. 97th Floor
98. 98th Floor
99. 99th Floor
100. 100th Floor



APPENDIX F

GEOLOGY

Geology

Pocono Mountain Lake Dam is located in the glaciated Low Plateaus section of the Appalachian Plateaus physiographic province of eastern Pennsylvania. In this area, the Appalachian Plateaus province is characterized topographically by flat-topped, hummocky hills formed as a result of glaciation and subsequent stream dissection of nearly flat-lying strata. The Devonian age sedimentary rock strata in Pike County regionally strike N35°E and dip gently to the northwest. The Delaware River is the major drainage basin in the area. Major tributary streams intersect the Delaware River at right angles; whereas, smaller streams display a slightly more random tributary pattern. Both major and minor tributary stream systems are joint controlled and exhibit modified rectangular and trellis-type drainage patterns.

Structurally, the area containing Pike County lies on the south flank of a broad, asymmetrical synclorium that plunges to the southwest. Superimposed on this broad structural basin are numerous anticlinal and synclinal folds characterized by planar limbs and narrow hinges. Due to prior glaciation, low relief and surficial soil cover, fold axes are difficult to trace.


The sedimentary rock sequences in the vicinity of the dam and reservoir are probably members of the Susquehanna Group of Upper Devonian age (see Geology Map). The sedimentological changes observed in the Catskill Formation indicate that the rate of sedimentation exceeded the rate of basin subsidence resulting in a facies change from marine to non-marine strata. On the accompanying geology map the delineation between the Middle and Upper Devonian age sedimentary rock sequences represents the Allegheny Front which separates the Valley and Ridge physiographic province from the Appalachian Plateaus physiographic province.

Approximately half of Pike County, including the dam site, is covered by a blanket of Wisconsin age (most recent) glacial drift which, based on the degree of weathering, was probably deposited during the Woodfordian stage. Valley bottoms are typically covered by recent alluvium and Woodfordian outwash of variable thickness, but typically less than 10 feet. These deposits are characteristically unconsolidated stratified sand and gravel usually with more gravel than sand and some small boulders. The direction of the Wisconsin ice advance, was from the northeast over the Catskill Mountains and from the north over the Appalachian Plateau. The terminal moraine resulting from the southern most advance of the Wisconsin ice sheet in this area is located in the southern portion of Monroe County which borders Pike County to the South.

References:

1. Fletcher, F. W., Woodrow, D. L., "Geology and Economic Resources of the Pennsylvania Portion of the Milford and Port Jervis 15 minute U.S.G.S. Topographic Quadrangles," Pennsylvania Geological Survey, Fourth Series, Harrisburg, Atlas 223, 1970.

2. Sevon, W. D., Berg, T. M., "Geology and Mineral Resources of the Skytop Quadrangle, Monroe and Pike Counties, Pennsylvania", Pennsylvania Geological Survey, Fourth Series, Harrisburg, Atlas 214A., 1978.
3. Sevon, W., Personal Communication, Commonwealth of Pennsylvania Department of Environmental Resources, Harrisburg, December 3, 1980.



NOTE: THE BEDROCK SURFACE IS COVERED WITH PLEISTOCENE AGE WISCONSIN TILL COMPOSED OF SANDS, GRAVELS AND SILTY CLAYS OF VARIABLE THICKNESS

REVISION 12-17-80

LEGEND

UPPER DEVONIAN



SUSQUEHANNA GROUP

Catskill Formation - Shohola Member and includes 1- to 25-foot thick units of greenish-gray and grayish-red very fine to medium-grained sandstone and sandy shale and lesser medium-gray to medium-dark-gray sandstone and shale. Sandstones are predominantly low-sink granular. Beds are thin to very thick and most have simple or planar sets of small- to medium-scale, generally low-angle cross stratification. Contacts with shale units are abruptly disconformable to gradational. Sandstones are poorly cleaved. Shale is thinly laminated and well-sloped. Mud cracks, convolute bedding, and sole marks are present near contacts with sandstone units. Member is more than 2,000 feet thick. Lower contact is gradational and is placed at top of highest red bed of the underlying Anaconink. Anaconink bed shale Member, medium-grayish red silty, micaceous, finely laminated well-sloped shale containing thin beds of brownish-gray sandy siltstone and silty very fine grained sandstone. Unit is the "first red" going up section in Upper Devonian sequence. Member is about 100 feet thick. Lower contact is gradational and is placed at the base of lowest red bed. Delaware River Flag Member, grayish-green, micaceous, laminated sandstone and lesser interbedded sandy shale. Beds range from a few inches to as much as 4 feet thick. Sandstones are low-sink granular and contain no marine fossils. Member is about 300 feet thick. Lower contact is gradational.

MIDDLE DEVONIAN




HAMILTON GROUP

Mahantango Formation - Upper member medium-dark-gray, fairly coarse grained, thin-bedded siltstone and silty shale, member is about 200 feet thick and is separated from lower member by the "Centerfield Reef," a calcareous siliceous limestone containing abundant horn corals. The Centerfield is about 25 feet thick, lower member, virtually same lithology as upper member. Unit is about 1,100 feet thick. Lower contact is gradational.

Marcellus Shale - Dark-gray, evenly laminated, silty clay shale and clayey silt shale. Unit contains very hard thin concretions and is well-sloped; bedding is generally obscured. Member is about 25-foot thick. Lower contact is gradational.

SCALE



REFERENCE

GEOLOGIC MAP OF NORTHEASTERN PENNSYLVANIA, COMPILED BY GEO. W. STOSE AND O.A. LJUNGSTEDT COMMONWEALTH OF PENNSYLVANIA DEPT. OF INTERNAL AFFAIRS DATED 1932, SCALE 1" = 6 MILES

GEOLOGY MAP



DATE
ILME