

AD-A102 724

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON --ETC F/8 13/13
NATIONAL DAM SAFETY PROGRAM. N.J. NO NAME NUMBER 56 DAM (NJ0080--ETC(U)
MAY 81 R J MCDERMOTT, J E GRIBBIN DACW61-79-C-0011

UNCLASSIFIED

DAEN/NAP-53842/NJ00804-81/ NL

1 OF 1
AD A
02724

END
DATE
FILMED
9-81
DTIC

~~APPROVED FOR PUBLIC RELEASE;~~
DISTRIBUTION UNLIMITED.

P

WHIPPANY RIVER BASIN
MALAPARDIS BROOK, MORRIS COUNTY
LEVEL NEW JERSEY

N.J. NO NAME NO. 56

DAM

NJ00804

DTIC
ELECTE
S AUG 1 2 1981

PHASE 1 INSPECTION REPORT^C
NATIONAL DAM SAFETY PROGRAM



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

81 8 10 000

MAY 1981

REPT. NO: DAEN/NAP-53842/NJ00804-81/05

AD A102724

FILE COPY

National Dam Safety Program.
 No Name Number 56 Dam (NJ00804), Whip-
 pany River Basin, Malapardis Brook, Mor-
 ris County, New Jersey. Phase I
 Inspection Report.


SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE

1. REPORT NUMBER DAEN/NAP-53842/NJ00804-81/05		2. GOVT ACCESSION NO. DAEN-103724		3. RECIPIENT'S CATALOG NUMBER	
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program N.J. No Name Dam No. 56 NJ00804 Morris County, NJ				5. TYPE OF REPORT & PERIOD COVERED FINAL	
7. AUTHOR(s) McDermott, Richard J., P.E. Grib-in, John E., PE				8. CONTRACT OR GRANT NUMBER(s) DACW61-79-C-0011	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Storch Engineers 220 Ridgedale Ave. Florham Park, NJ 07932				10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS C-174	
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CNO29 Trenton, NJ 08625				12. REPORT DATE May, 1981	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106				13. NUMBER OF PAGES 50	
				15. SECURITY CLASS. (of this report) Unclassified	
				15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.					
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)					
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.					
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)					
Dams		Malapardis Brook, NJ		National Dam Safety Program	
Embankments		Spillways		Whippany River Basin, NJ	
Visual Inspection		Erosion		Morris County, N.J.	
Structural Analysis		Embankment		N.J. No Name Dam No. 56, N.J.	
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.					

DTIC
 ELECTE
 AUG 12 1981
 C

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.



WHEN REPLY REFER TO
NAPEN-N

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT CORPS OF ENGINEERS
CUSTOM HOUSE-2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

①

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for N.J. No Name Dam No. 56 in Morris County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, N.J. No Name No. 56 Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 7 percent of the Spillway Design Flood (SDF) would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Within three months of the consultant's findings remedial measures to ensure spillway adequacy should be initiated.

b. Within six months from the date of approval of this report the following remedial actions should be initiated:

(1) Erosion of the channel immediately downstream of the dam should be repaired, and the channel properly stabilized.

(2) All trees and adverse vegetation on the embankment should be removed, and the embankment suitably graded and protected against erosion.

(3) The concrete wall along the upstream side of the embankment should be repaired, etc.

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

NAPEN-N

Honorable Brendan T. Byrne

c. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam, within one year from the date of approval of this report.

d. An emergency action plan and warning system should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congresswoman Fenwick of the Fifth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



ROGER L. BALDWIN
Lieutenant Colonel, Corps of Engineers
Commander and District Engineer

1 Incl
As stated

Copies furnished:

Mr. Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief
Bureau of Flood Plain Regulation
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

N.J. NO NAME NO. 56 DAM (NJ00804)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 17 December 1980 by Stora Engineers, under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

N.J. No Name No. 56 Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 7 percent of the Spillway Design Flood (SDF) would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Within three months of the consultant's findings remedial measures to ensure spillway adequacy should be initiated.

b. Within six months from the date of approval of this report the following remedial actions should be initiated:

(1) Erosion of the channel immediately downstream of the dam should be repaired, and the channel properly stabilized.


(2) All trees and adverse vegetation on the embankment should be removed, and the embankment suitably graded and protected against erosion.

(3) The concrete wall along the upstream side of the embankment should be repaired.

c. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam, within one year from the date of approval of this report.

d. An emergency action plan and warning system should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

APPROVED:


ROGER L. BALDWIN
Lieutenant Colonel, Corps of Engineers
Commander and District Engineer

DATE:



PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: N.J. No Name No. 56, Dam, NJ00804
State Located: New Jersey
County Located: Morris
Drainage Basin: Whippany River
Stream: Malapardis Brook
Date of Inspection: December 17, 1980

Assessment of General Conditions of Dam

Based on visual inspection, past operational performance and Phase I engineering analyses, the dam is assessed as being in fair overall condition.

Based on investigations of the downstream flood plain made in connection with this report, it is recommended that the hazard potential classification be downgraded from high to significant hazard.

Hydraulic and hydrologic analyses indicate that the spillway is inadequate. Discharge from the spillway is not sufficient to pass the designated spillway design flood (SDF) without an overtopping of the dam. (The SDF for N.J. No Name No. 56 Dam is equivalent to the 100-year storm.) The spillway is capable of passing approximately 6 percent of the SDF. Therefore, the owner should engage a professional engineer experienced in the design and construction of dams in the near future to perform more accurate hydraulic and hydrologic analyses. Based on the findings of the analyses, the need for and type of remedial measures should be determined and then implemented.

i

Accession For	000
By	
Distribution/	
Availability Codes	
Avail and/or	
Special	
Dist	A

The owner should, in the near future, develop an emergency action plan together with an effective warning system outlining actions to be taken by the operator to minimize the downstream effects of an emergency at the dam.

In addition, it is recommended that the following remedial measures be undertaken by the owner in the near future.

- 1) Erosion of the channel immediately downstream of the dam should be repaired, and the channel properly stabilized.
- 2) All trees and adverse vegetation on the embankment should be removed, and the embankment suitably graded and protected against erosion.
- 3) The concrete wall along the upstream side of embankment should be repaired.

In the future, the owner of the dam should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.


Richard J. McDermott, P.E.

John E. Gribbin, P.E.



OVERVIEW - NJ NO NAME NO. 56 DAM

20 JANUARY 1961

TABLE OF CONTENTS

	<u>Page</u>
ASSESSMENT OF GENERAL CONDITION OF DAM	i
OVERVIEW PHOTO	iii
TABLE OF CONTENTS	iv
PREFACE	vi
SECTION 1 - PROJECT INFORMATION	1
1.1 General	
1.2 Description of Project	
1.3 Pertinent Data	
SECTION 2 - ENGINEERING DATA	7
2.1 Design	
2.2 Construction	
2.3 Operation	
2.4 Evaluation	
SECTION 3 - VISUAL INSPECTION	9
3.1 Findings	
SECTION 4 - OPERATIONAL PROCEDURES	12
4.1 Procedures	
4.2 Maintenance of Dam	
4.3 Maintenance of Operating Facilities	
4.4 Description of Warning System	
4.5 Evaluation	

TABLE OF CONTENTS (cont.)

	<u>Page</u>
SECTION 5 - HYDRAULIC/HYDROLOGIC	14
5.1 Evaluation of Features	
SECTION 6 - STRUCTURAL STABILITY	16
6.1 Evaluation of Structural Stability	
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS	18
7.1 Dam Assessment	
7.2 Recommendations	
PLATES	
1 KEY MAP	
2 VICINITY MAP	
3 SOIL MAP	
4 GENERAL PLAN	
5 SECTIONS	
6 PHOTO LOCATION PLAN	
APPENDICES	
1 Check List - Visual Inspection	
Check List - Engineering Data	
2 Photographs	
3 Engineering Data	
4 Hydraulic/Hydrologic Computations	
5 Bibliography	

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that the unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydraulic and hydrologic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydraulic and hydrologic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

N.J. NO NAME NO. 56 DAM, I.D. NJ00804

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The Division of Water Resources of the New Jersey Department of Environmental Protection (NJDEP) in cooperation with the Philadelphia District of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the State of New Jersey. Storch Engineers has been retained by the NJDEP to inspect and report on a selected group of these dams. The NJDEP is under agreement with the Philadelphia District of the Corps of Engineers.

b. Purpose of Inspection

The visual inspection of N.J. No Name No. 56 Dam was made on December 17, 1980. The purpose of the inspection was to make a general assessment of the structural integrity and operational adequacy of the dam structure and its appurtenances.

1.2 Description of Project

a. Description

N.J. No Name No. 56 Dam is an earthfill dam with a boulder lined chute spillway and an adjacent outlet conduit connected to a downstream mill building. The upstream face of the dam is formed by a concrete wall to the right of the spillway and a stone rubble wall to the left of the spillway.

The intake structure for the outlet conduit consists of a concrete inlet located at the left end of the dam. The structure is fitted with steel fish screens and contains no observable gate operating mechanism. The conduit is a 24-inch cast iron pipe.

The elevation of the spillway crest is 275.0 National Geodetic Vertical Datum (N.G.V.D.) while that of the crest of dam is 277.0. The downstream channel bed elevation is 269.8. The overall length of the dam is 123 feet and its height is 7.2 feet. the top width of the embankment is 20 feet and the slope of the downstream face is 4 horizontal to 1 vertical.

b. Location

N.J. No Name No. 56 Dam is located in the Township of Hanover, Morris County, New Jersey. It impounds an unnamed lake located west of North Jefferson Road. Principal access to the dam is by an unpaved road which is entered from North Jefferson Road. Discharge from the spillway of the dam flows into the Malapardis Brook, tributary to the Whippany River.

c. Size and Hazard Classification

The dam is classified in accordance with criteria presented in "Recommended Guidelines for Safety Inspection of Dams" published by the U.S. Army Corps of Engineers. Size categories consist of Small, Intermediate and Large while hazard categories are designated as Low, Significant and High.

Size Classification: N.J. No Name No. 56 Dam is classified as "Small" size since its maximum storage volume is 128 acre-feet (which is less than 1000 acre-feet) and its height is 7.2 feet (which is less than 40 feet).

Hazard Classification: Visual inspection of the downstream flood plain of the dam together with breach analysis indicate that failure of the dam due to overtopping during a storm equivalent to the spillway design flood (SDF) could cause property damage to the mill building and grounds located 350 feet downstream from the dam. Extensive structural damage to the road bridge (North Jefferson Road) located 350 feet from the dam is not anticipated as a result of dam failure. Loss of more than a few lives is not anticipated. Accordingly, N.J. No Name No. 56 Dam is classified as "Significant" hazard.

d. Ownership

N.J. No Name No. 56 Dam is owned and operated by the Whippany Paper Board Company, 10 North Jefferson Road, Whippany, New Jersey 07981.

e. Purpose of Dam

The purpose of the dam was the impoundment of a lake used for flood control and for water supply for the downstream mill owned by the Whippany Paper Board Company. Reportedly, the impoundment is not presently being used for any purpose.

f. Design and Construction History

N.J. No Name No. 56 Dam reportedly was constructed by Whippany Paper Board Company around 1960.

g. Normal Operational Procedures

The dam and appurtenances are operated and maintained by the Whippany Paper Board Company. Repairs are made on an "as needed" basis. However, the dam is not presently in use and, reportedly, the Whippany Paper Board Company does not intend to make use of the dam in the future.

1.3 Pertinent Data

a. Drainage Area	4.55 square miles
b. Discharge at Damsite	
Maximum flood at damsite	Unknown
Outlet works at pool elevation	N.A.
Spillway capacity at top of dam	189 c.f.s.
c. Elevation (N.G.V.D.)	
Top of Dam	277.0
Maximum pool-design surcharge	279.1
Spillway crest	275.0
Stream bed at toe of dam	269.8
Maximum tailwater	275 (Estimated)
d. Reservoir	
Length of maximum pool	1100 feet (Estimated)
Length of recreation pool	900 feet (Scaled)

e. Storage (Acre-feet)

Recreation pool	15
Design surcharge	654
Top of dam	128

f. Reservoir Surface (acres)

Top of dam	234	(Estimated)
Maximum pool - design surcharge	459	(Estimated)
Recreation pool	8.7	

g. Dam

Type	Earthfill
Length	123 feet
Height	7.2 feet
Sideslopes - Upstream	Left Section: 1 horiz. to 1 vert
	Right Section: Vertical
- Downstream	4 horiz. to 1 vert.
Zoning	Unknown
Impervious core	Unknown
Cutoff	Unknown
Grout curtain	Unknown

h. Diversion and Regulating Tunnel

N.A.

i. Spillway

Type	Boulder lined chute, Trapezoidal Section
Length of weir	16 feet
Crest elevation	275.0
Approach channel	N.A.
Discharge channel	Natural Streambed

j. Regulating Outlet

24-inch C.I.P. running to downstream mill
(Operating mechanism unknown)

SECTION 2: ENGINEERING DATA

2.1 Design

No plans or calculations pertaining to the original design of the dam could be obtained.

2.2 Construction

No data or reports pertaining to the construction of the dam are available.

2.3 Operation

No data or reports pertaining to the operations of the dam are available. Reportedly, drawings relating to a pending lake lowering permit are presently available in the files of the Hanover Township Engineering Department.

2.4 Evaluation

a. Availability

Available engineering data is limited to that which is on file at the Hanover Township Engineering Department. The file contains drawings relating to the lake lowering permit presently pending.

b. Adequacy

Available engineering data pertaining to N.J. No Name No. 56 Dam is not adequate to be of significant assistance to the performance of a Phase I evaluation. A list of absent information is included in paragraph 7.1.b.

c. Validity

The validity of engineering data cannot be assessed due to the absence of data.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

The inspection of N.J. No Name No. 56 Dam was performed on December 17, 1980 by staff members of Storch Engineers. A copy of the visual inspection check list is contained in Appendix 1. The following procedures were employed for the inspection:

- 1) The embankment of the dam, appurtenant structures and adjacent areas were examined.
- 2) The embankment and accessible appurtenant structures were measured and key elevations determined by surveyor's level.
- 3) The embankment, appurtenant structures and adjacent areas were photographed.

b. Dam

The concrete wall forming the upstream side of the dam appeared to be in fair condition. The crest and downstream side of the dam appeared to be deteriorated condition. The crest was covered with weeds and the downstream side was irregularly shaped and overgrown with weeds and small trees. No evidence of seepage or animal holes on the downstream side of the dam was observed, although the dam was obscured by approximately 1-inch of snow.

The spillway discharge channel leads directly away from the dam for approximately 20 feet and then bends sharply to the right, or south, for another 30 feet and then sharply to the left,

or east, to lead away from the dam as the downstream channel. At the first bend considerable erosion was observed along the left bank of the channel or chute, with many roots of trees exposed.

c. Appurtenant Structures

The outlet structure located at the left end of the dam appears to be an outlet for a 24-inch cast iron pipe used to supply water to a mill downstream from the dam.

The concrete forming the outlet structure chamber and the headwall appeared to be in satisfactory condition. It appeared that there were two fish screens or trashracks on both the upstream and downstream sides of the headwall. Their conditions appeared to be satisfactory. Approximately 1 foot downstream from the headwall there was a slot with another fish screen protruding and its condition appeared to be satisfactory as well.

d. Reservoir Area

The impoundment of the dam is 900 feet long with a width varying from 300 to 400 feet. The land surrounding the reservoir appeared to be undeveloped grassland. The reservoir bank is approximately 2 feet high and the land beyond the bank has a terrain with flat slopes. To the left of the reservoir at its upstream end there is an adjacent garage with approximately 10 bays and a yard for trucks and equipment. The upstream end of the impoundment is connected by culverts under Route 287 to an additional impoundment including a large area known as Lee Meadows.

e. Downstream Channel

The spillway discharges into the Malapardis Brook, a tributary of the Whippany River. Between the dam and the North Jefferson Road Bridge (approximately 350 feet downstream) the downstream channel is a rock-lined stream with high banks having slopes of approximately 50 percent and tree and brush growth on the banks. Downstream from the bridge the channel bed remains the same, rocky and slightly meandering; however, the right bank is formed by the Brick Mill Building and the left bank is rocky and tree and brush covered. The 24-inch cast iron pipe bringing water from the dam impoundment to the mill crosses the channel at a skewed angle approximately 100 feet downstream from the bridge.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

The level of water in the impoundment of the subject dam is regulated by discharge over the boulder lined chute spillway. The outlet works of the dam is used to draw off water for the purpose of supplying the mill downstream via the 24 inch C.I.P. but reportedly is no longer in use.

The Whippany Paper Board Company has applied to Hanover Township for permission to lower the normal lake level by approximately two feet for the purpose of lowering the water table at the request of the Prudential, which is located in the vicinity of the subject dam.

4.2 Maintenance of the Dam

Reportedly, maintenance is performed on an "as needed" basis.

4.3 Maintenance of Operating Facilities

Reportedly, the outlet works is maintained on an "as needed" basis.

4.4 Description of Warning System

Reportedly, no warning system is currently in use for the dam.

4.5 Evaluation of Operational Adequacy

The operation of the dam has not been successful to the extent that the dam reportedly has been overtopped in the past.

Maintenance is inadequate and maintenance documentation is poor.

Areas of maintenance that have not been adequately performed are:

- 1) Erosion of the spillway discharge channel immediately downstream of the dam not repaired.
- 2) Trees and bushes on the embankment not removed.
- 3) Embankment not suitably protected against erosion.
- 4) Concrete wall along upstream side of embankment not repaired.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design Data

The quantity of storm water runoff that the spillway should be able to handle is based on the size and hazard classification of the dam. This runoff quantity, called the spillway design flood (SDF) is described in terms of return frequency or probable maximum flood (PMF) depending on the extent of the dam's size and potential hazard. According to the "Recommended Guidelines for Safety Inspection of Dams" published by the U.S. Army Corps of Engineers, the SDF for N.J. No Name No. 56 Dam falls in a range of 100-year storm to 1/2 PMF. In this case, the low end of the range, 100-year storm is chosen since the factors used to select size and hazard classification are on the low side of their respective ranges.

The SDF peak computed for N.J. No Name No. 56 Dam is 3183 c.f.s. This value is derived from the 100-year flood hydrograph computed by the use of the HEC-1-DAM Flood Hydrograph Computer Program using the Soil Conservation Service triangular unit hydrograph method with curvilinear transformation. Hydrologic computations and computer output are contained in Appendix 4.

The spillway discharge rates were computed by analysis of critical depth flow at the entrance to a channel. The spillway discharge with lake level equal to the top of the dam was computed to be 189 c.f.s. The SDF was routed through the dam by use of the HEC-1-DAM computer program using the modified Puls method. In routing the SDF, it was found that the dam crest would be overtopped by a depth of 2.1 feet. Accordingly, the subject spillway is assessed as being inadequate in accordance with criteria developed by the U.S. Army Corps of Engineers.

b. Experience Data

Reportedly, the dam has been overtopped in the past. No damage to downstream structures was reported at the time of the overtoppings.

c. Visual Observation

Severe erosion of the spillway discharge channel was observed at the time of inspection. Also, the observed irregular shape of the downstream face of dam could be due to overtopping erosion.

d. Overtopping Potential

As indicated in paragraph 5.1.a. a storm of magnitude equal to the SDF would cause overtopping of the dam by a depth of 2.1 feet over the crest of the dam. The spillway is capable of passing approximately 6 percent of the SDF with lake level equal to the top of dam.

e. Drawdown Data

No drawdown computations can be performed due to the apparent absence of a functioning low level outlet.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

The dam appeared, at the time of inspection to be outwardly structurally sound with no evidence of cracks or distress. The crest and the downstream face of the dam however, appeared to be irregularly shaped, possibly due to erosion.

b. Generalized Soils Description

The generalized soils description of the dam site consists of clay and silt deposited during the Wisconsin glaciation intermingled with recent alluvium composed largely of gravel and sand deposited by streams. The glacial moraine overlies shale and sandstone bedrock known as the Brunswick Formation.

c. Design and Construction Data

Analyses of structural stability and construction data for the embankment are not available.

d. Operating Records

No operating records are available for the dam. The water level of the lake impounded by N.J. No Name No. 56 Dam is not monitored.

e. Post-Construction Changes

Reportedly, there have been no post-construction changes since the dam was constructed in 1960.

f. Seismic Stability

N.J. No Name No. 56 Dam is located in Seismic Zone 1 as defined in "Recommended Guidelines for Safety Inspection of Dams" which is a zone of very low seismic activity. Experience indicates that dams in Seismic Zone 1 will have adequate stability under seismic loading conditions if they have adequate stability under static loading conditions. N.J. No Name No. 56 Dam appeared to be stable under static loading conditions at the time of inspection.

SECTION 7: ASSESSMENT AND RECOMMENDATIONS

7.1 Dam Assessment

a. Safety

Based on hydraulic and hydrologic analyses outlined in Section 5 and Appendix 4, the spillway of the subject dam is assessed as being inadequate. The spillway is not able to pass the SDF without an overtopping of the dam.

The embankment appeared, at the time of inspection to be outwardly stable. The crest and the downstream face of the dam, however, appeared to be in deteriorated condition, possibly due to erosion.

b. Adequacy of Information

Information sources for this report include 1) field inspections, 2) USGS quadrangle, 3) plans on file with the Hanover Township Engineering Department, 4) consultation with personnel of the Hanover Township Engineering Department, 5) consultation with personnel of the Whippany Paper Board Company. The information obtained is sufficient to allow a Phase I assessment as outlined in "Recommended Guidelines for Safety Inspection of Dams."

Some of the absent data are as follows:

1. Construction and as-built drawings
2. Description of fill material for embankment.
3. Design computations and reports.
4. Maintenance documentation.
5. Soils report for the site.

c. Necessity for Additional Data/Evaluation

Although some data pertaining to N.J. No. Name No. 56 Dam are not available, additional data are not considered imperative for this Phase I evaluation.

7.2 Recommendations

a. Remedial Measures

Based on hydraulic and hydrologic analyses outlined in paragraph 5.1.a, the spillway is considered to be inadequate. It is therefore recommended that a professional engineer experienced in the design and construction of dams be engaged in the near future to perform more accurate hydraulic and hydrologic analyses. Based on the findings of these analyses, the need for and type of remedial measures should be determined and then implemented.

The owner should, in the near future develop an emergency plan together with an effective warning system outlining actions to be taken by the operator to minimize the downstream effects of an emergency at the dam.

In addition, it is further recommended that the following remedial measures be undertaken by the owner in the near future.

- 1) Erosion of the channel immediately downstream of the dam should be repaired and the channel properly stabilized.
- 2) All trees and adverse vegetation on the embankment should be removed, and the embankment suitably graded and protected against erosion.
- 3) The concrete wall along the upstream side of embankment should be repaired.

b. Maintenance

In the future, the owner of the dam should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

PLATES

N.J. No Name No. 56 DAM




PLATE 1

STORCH ENGINEERS
FLORHAM PARK, NEW JERSEY


INSPECTION AND EVALUATION OF DAMS
KEY MAP

DIVISION OF WATER RESOURCES
N.J. DEPT. OF ENVIR. PROTECTION
TRENTON, NEW JERSEY

N.J. No Name No. 56 DAM

SCALE: NONE

DATE: FEB. 1981



STORCH ENGINEERS
 FLORHAM PARK, NEW JERSEY

DIVISION OF WATER RESOURCES
 N.J. DEPT. OF ENVIR. PROTECTION
 TRENTON, NEW JERSEY

INSPECTION AND EVALUATION OF DAMS

VICINITY MAP

N.J. No Name No. 56 DAM

SCALE: AS SHOWN

DATE: FEB. 1981



Legend

- AR/GL-67 Remains of glacial lake bed deposits, composed of stratified materials, and intermingled with recent alluvium placed by streams.
- GM-4 Glacial ground moraine; composed of unstratified material deposited during the Wisconsin glaciation.

Note: Information taken from: Rutgers University, Engineering Soil Survey of New Jersey, Report No. 9, Morris County, November 1953 and Geologic Map of New Jersey prepared by J. V. Lewis and H. Kummel 1910-1912, revised by H. B. Kummel 1931 and M. Johnson 1950.

PLATE 3

STORCH ENGINEERS
FLORHAM PARK, NEW JERSEY.

INSPECTION AND EVALUATION OF DAMS

SOIL MAP

N.J. No Name No. 56 DAM

DIVISION OF WATER RESOURCES
N.J. DEPT. OF ENVIR. PROTECTION
TRENTON, NEW JERSEY.

SCALE: NONE

DATE: FEB. 1981






PLATE 4

<p>STORCH ENGINEERS FLORHAM PARK, NEW JERSEY</p>	<p>INSPECTION AND EVALUATION OF DAMS GENERAL PLAN</p>	
<p>DIVISION OF WATER RESOURCES N.J. DEPT. OF ENVIR. PROTECTION TRENTON, NEW JERSEY</p>	<p>N.J. NO NAME NO 56 DAM I.D. N.J. 00804</p>	<p>SCALE: NONE DATE: FEB. 1981</p>



SPILLWAY SECTION




TYPICAL DAM SECTION

Note:
 Information taken from field
 inspection December 17, 1980

PLATE 5

<p>STORCH ENGINEERS FLORHAM PARK, NEW JERSEY</p>	<p>INSPECTION AND EVALUATION OF DAMS SECTIONS</p>					
<p>DIVISION OF WATER RESOURCES N.J. DEPT. OF ENVIR. PROTECTION TRENTON, NEW JERSEY</p>	<p>N.J. NO NAME NO 56 DAM</p> <table border="1" data-bbox="666 1976 1511 2052"> <tr> <td data-bbox="666 1976 1084 2020">I.D. N.J. 00804</td> <td data-bbox="1084 1976 1511 2020">SCALE: NONE</td> </tr> <tr> <td data-bbox="666 2020 1084 2052"></td> <td data-bbox="1084 2020 1511 2052">DATE: FEB. 1981</td> </tr> </table>		I.D. N.J. 00804	SCALE: NONE		DATE: FEB. 1981
I.D. N.J. 00804	SCALE: NONE					
	DATE: FEB. 1981					



Note:
Information taken from field inspection Dec. 17, 1980

PLATE 6

<p>STORCH ENGINEERS FLORHAM PARK, NEW JERSEY</p>	<p>INSPECTION AND EVALUATION OF DAMS PHOTO LOCATION PLAN N.J. NO NAME NO 56 DAM</p>	
<p>DIVISION OF WATER RESOURCES N.J. DEPT. OF ENVIR. PROTECTION TRENTON, NEW JERSEY</p>	<p>I.D. N.J. 00804</p>	<p>SCALE: NONE DATE: FEB. 1981</p>

APPENDIX 1

Check List - Visual Inspection

Check List - Engineering Data

Check List

Visual Inspection

Phase I

Name of Dam N.J. No Name 56 Dam County Morris State N.J. Coordinators NJDEP

Date(s) Inspection 12/17/80 Weather Sunny Temperature 20° F

Pool Elevation at time of Inspection 275.0 M.S.L. Tailwater at Time of Inspection 270.0 M.S.L.

Inspection Personnel:

John Gribbin Richard McDermott

Charles Osterkorn

Daniel Buckelew

John Gribbin Recorder

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
GENERAL	Crest covered with weeds. Downstream face covered with weeds and small trees and not well defined. Conc. wall forming upstream face (right side) in fair condition. Stone rubble wall forming upstream face (left side) in fair condition.	Trees and weeds should be removed. Conc. wall should be repaired.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Junctions appeared stable.	
ANY NOTICEABLE SEEPAGE	None observed.	
STAFF GAGE AND RECORDER	None observed.	
DRAINS	None observed.	

EMBANKMENT

VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None observed.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Vertical: generally level Horizontal: irregular	
RIPRAP	None observed.	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SURFACES IN OUTLET CONDUIT	Outlet conduit composed of cast iron, could not be observed in vicinity of dam. Conduit above ground in vicinity of downstream mill building appeared to be in satisfactory condition.	Function of outlet conduit unknown. Operating condition of outlet conduit unknown. Operating mechanism not observed.
INTAKE STRUCTURE	Concrete surfaces in satisfactory condition. Fish screens appeared to be in satisfactory condition, but not observed below the water line.	
OUTLET STRUCTURE	Not observed.	Conduit enters mill building.
OUTLET CHANNEL	N/A	
GATE AND GATE HOUSING	Not observed.	Presence of gate unknown.

SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CREST	Crest formed by entrance section to chute, lined with small boulders. Boulders irregularly placed and appeared to provide insufficient erosion protection.	Crest should be properly stabilized.
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	Formed by chute located on downstream side of dam. Bottom of chute lined with small boulders. Sides consist of earth banks. Banks significantly eroded at bend in chute (with exposed roots observed).	Channel sides and bottom should be properly stabilized.

INSTRUMENTATION

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None observed.	
OBSERVATION WELLS	None observed.	
WEIRS	None observed.	
PIEZOMETERS	None observed.	
OTHER		

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Shores were grass covered with 5' high banks and flat to moderately sloping terrain beyond.	
SEDIMENTATION	Unknown.	
STRUCTURES ALONG BANKS	Industrial garage and yard located adjacent to left side at upstream end. Road bridge crosses reservoir near upstream end.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
<p>COMPUTATION SECTION, DEBRIS, ETC.)</p>	<p>Between dam and bridge 350' downstream, channel is natural stream with rocky bottom and wooded banks. Downstream from bridge, stream meanders through mill complex.</p>	
<p>SLOPES</p>	<p>Banks high with slopes of approx. 1 horizontal to 1 vertical.</p>	
<p>STRUCTURES ALONG BANKS</p>	<p>Road bridge (Jefferson Road) located 350' downstream. Mill building adjacent to stream located immediately below bridge. Brick weigh station located adjacent to channel immediately upstream from Jefferson Road bridge.</p>	

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
DAM - PLAN	Not Available
SECTIONS	
SPILLWAY - PLAN	Not Available
SECTIONS	
DETAILS	
OPERATING EQUIPMENT PLANS & DETAILS	Not Available
OUTLETS - PLAN	Not Available
DETAILS	
CONSTRAINTS	
DISCHARGE RATINGS	
HYDRAULIC/HYDROLOGIC DATA	Not Available
RAINFALL/RESERVOIR RECORDS	Not Available
CONSTRUCTION HISTORY	Not Available
LOCATION MAP	Not Available

REMARKS

ITEM

DESIGN REPORTS Not Available

GEOLOGY REPORTS Not Available

DESIGN COMPUTATIONS Not Available
HYDROLOGY & HYDRAULICS
DAM INSTABILITY
SEEPAGE STUDIES

MATERIALS INVESTIGATIONS Not Available
BORING RECORDS
LABORATORY
FIELD

POST-CONSTRUCTION SURVEYS OF DAM Not Available

BORROW SOURCES Not Available

REMARKS

ITEM

MONITORING SYSTEMS Not Available

MODIFICATIONS Not Available

HIGH POOL RECORDS Not Available

POST CONSTRUCTION ENGINEERING AND REPORTS Drawings relating to pending lake lowering permit available in the files of the Hanover Twp. Engineering Department, P.O. Box 250, Whippany, New Jersey, 07981.

PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS Not Available

MAINTENANCE OPERATION RECORDS Pending lake lowering permit (see above)

APPENDIX 2

Photographs



PHOTO 1
SPILLWAY




PHOTO 2
INTAKE STRUCTURE FOR PIPE TO MILL

NJ NO NAME No. 56 DAM
17 DECEMBER 1980



PHOTO 3
CREST OF EMBANKMENT



PHOTO 4
DOWNSTREAM FACE OF EMBANKMENT

NJ NO NAME No. 56 DAM
17 DECEMBER 1980




PHOTO 5
UPSTREAM FACE OF EMBANKMENT



PHOTO 6
UPSTREAM FACE OF EMBANKMENT - RIGHT SIDE

NJ NO NAME No. 56 DAM
17 DECEMBER 1980



20 JANUARY 1981

PHOTO 7

AERIAL VIEW OF LAKE AND DOWNSTREAM CHANNEL



17 DECEMBER 1980

PHOTO 8

DOWNSTREAM CHANNEL ADJACENT TO MILL BUILDING

NJ NO NAME No. 56 DAM

APPENDIX 3

Engineering Data

CHECK LIST

HYDROLOGIC AND HYDRAULIC DATA

ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: Wooded, residential and swampy areas

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 275.0 (15 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): N/A

ELEVATION MAXIMUM DESIGN POOL: 279.1

ELEVATION TOP DAM: 277.0

SPILLWAY CREST: Boulder lined channel

a. Elevation 275.0

b. Type Chute (trapezoidal section)

c. Width 16 feet

d. Length 20 feet

e. Location Spillover Downstream side of dam

f. Number and Type of Gates N/A

OUTLET WORKS: 24-inch C.I.P. connected to downstream mill building

a. Type Pipe conduit

b. Location Left end of dam

c. Entrance Invert Unknown

d. Exit Invert Unknown (pipe enters mill bldg.)

e. Emergency Draindown Facilities: None

HYDROMETEOROLOGICAL GAGES: None

a. Type N/A

b. Location N/A

c. Records N/A

MAXIMUM NON-DAMAGING DISCHARGE:

(Lake Stage Equal to Top of Dam) 189 c.f.s.

APPENDIX 4

Hydraulic/Hydrologic Computations

STORCH ENGINEERS

Sheet 1 of 12

Project N.J. NO NAME NO. 56

Made By T.D. Date 2-23-81

113Z-05

Chkd By JG Date 2/23/81

HYDROLOGY

HYDROLOGIC ANALYSIS

RUNOFF HYDROGRAPH WILL BE DEVELOPED BY HEC-1 DAM

USING SCS TRIANGULAR HYDROGRAPH WITH CURVILINEAR

TRANSFORMATION.

DRAINAGE AREA = 4.55 SQ. MI.

INFILTRATION DATA

INITIAL INFILTRATION 1.0 IN.

CONSTANT INFILTRATION 0.10 IN/HR.

TIME OF CONCENTRATION - SUMMARY (SEE ATTACHED SHEETS)

<u>METHOD</u>	<u>t_c (HR)</u>
METHOD #1, S.C.S. TR-55	5.76
METHOD #2, CHOW	2.89
METHOD #3, N.J.H.A. & D.E.P. MONOGRAPH	2.60
METHOD #4 TEXAS HIGHWAY DEPT. & TP DW-5	3.56

FOR COMPUTER INPUT:

$t_c = 4.7$ HR

LAG TIME = 60% $t_c = \underline{\underline{2.5}} \text{ Hr}$

Project 113Z-05 5 N.S. NO NAME NO. 56

Made By T.D. Date 2-23-81

Chkd By JG Date 2/23/81

TIME OF CONCENTRATION

SCS TR-55 (Cc METHOD #1)

OVERLAND FLOW: L = 3500'
 Δ ELEV = 60'
 S = 1.7190
 V = 0.31 F.P.S.
 TIME = 3.14 HR.

CHANNEL FLOW: L = 4000'
 Δ ELEV = 80'
 S = 2.0090
 V = 2.8 F.P.S.
 TIME = 0.40 HR.

L = 2000'
 Δ ELEV = 20'
 S = 0.2590
 V = 1.0 F.P.S.
 TIME = 2.72 HR

Cc = 5.76 HR

"HANDBOOK OF APPLIED HYDROLOGY" BY CHOW, P. 14-36, (Cc METHOD #2)

$$T_c = 1.49 \sqrt{N^2 L^3 / S}$$

L = LENGTH OF FLOW (FT.)

S = SLOPE

N = COEFF. OF ROUGHNESS

Tc = TIME OF CONCENTRATION (MIN.)

OVERLAND FLOW: L = 3500'
 S = 0.0171
 N = 0.40
 TIME = 1.05 HR.

CHANNEL FLOW: L=4000'

S=0.0200

N=0.10

TIME

0.57 HR

L=8000'

S=0.0075

N=0.10

TIME -

1.27 HR

$E_c = 2.69$ HR

||

N.J. HIGHWAY AUTHORITY NOMOGRAPH (E_c METHOD #3)

OVERLAND FLOW: L=3500'

S=1.71%

AVERAGE GRASS

TIME -

0.92 HR

D.E.P. NOMOGRAPH (E_c METHOD #3 CONT.)

CHANNEL FLOW: L=4000'

Δ ELEV = 80'

TIME

0.39 HR

L=8000'

Δ ELEV = 70'

TIME -

1.3 HR

$E_c = 2.60$ HR

||

Project 1132-05 S N.S. NO NAME NO. 56

Made By T.D. Date 2-23-81

Chkd By JG Date 2/23/81

TEXAS HIGHWAY DEPT. "DESIGN OF SMALL DAMS" U.S. DEPT. OF INTERIOR, A70
(EC METHOD # 4)

OVERLAND FLOW: L = 3500', S = 1.17%, N = 1.0 F.P.S.

TIME 0.97 HR.

NAVDOCKS TP-PW-S "DESIGN OF SMALL DAMS" U.S. DEPT. OF INTERIOR, P70
(EC METHOD # 4 CONT.)

CHANNEL FLOW: L = 4000', S = 2.007%, N = 3.0 F.P.S.

TIME 0.37 HR.

L = 8000', S = 0.75%, N = 1.0 F.P.S.

TIME = 2.22 HR.

EC = 3.56 HR.

//

Project N. J. LAKE NO NAME NO. 56 DAM Made By Ji Ho Date 2-23-81

1132 - 05

Chkd By JG Date 2/23/81

24 HOURS 100 YEAR RAINSTROM

DISTRIBUTION FOR LAKE NoName No. 56 DAM

TIME [Hr]	RAIN [IN]
1	0.08
2	0.08
3	0.08
4	0.08
5	0.08
6	0.08
7	0.09
8	0.09
9	0.18
10	0.18
11	0.18
12	0.19
13	0.3
14	0.3
15	0.8
16	3.0
17	0.4
18	0.3
19	0.19
20	0.18
21	0.09
22	0.09
23	0.08
24	0.08
<u>24 Hr</u>	<u>Z 7.20</u>

FROM TP 40. U.S. WEATHER BUREAU

STORCH ENGINEERS

Sheet 6 of 12

Project

N.J. NO NAME NO.56 DAM
1132-05

Made By

JHG

Date

2-23-81

Chkd By

JG

Date

2/23/81

ELEVATION - SURFACE AREA TABLE

ELEVATION (FT.)

AREA (ACRES)

270.0

0

275.0

8.7

280.0

572.0

300.0

1,013.0

HEC-1-DAM COMPUTER WILL DEVELOP STORAGE

CAPACITY FROM SURFACE AREAS AND ELE-

VATIONS

INFORMATION TAKEN FROM U.S.G.S QUADRANGLE,

MORRISTOWN, N.J.

SQUARE 4 X 4 TO THE INCH

10-10-11-58

Project N.J. NO NAME NO. 56 DAM Made By J.D. Date 2-22-81

1137-05



Chkd By JG Date 2/23/81

HYDRAULICS

STAGE DISCHARGE CALCULATION

SPILLWAY CAPACITY:

THE PRIMARY SPILLWAY AT NO NAME NO. 56 IS A BROAD
 CRESTED RUBBLE CHUTE WITH AN EFFECTIVE LENGTH OF 28',
 AND CREST ELEVATION 275.0. THE TOP OF DAM ELEVATION
 IS 277.0.



DISCHARGE Q, CAN BE CALCULATED BY:

$$Q = AR^{2/3} S^{1/2} \frac{1.486}{N}$$

Q = FLOW, (C.F.S.)

V.T. CHOW "OPEN CHANNEL HYDRAULICS"

R = HYDRAULIC RADIUS (FT.)

A = AREA, (S.F.)

S = SLOPE OF ENERGY GRADE LINE

N = MANNING'S COEFFICIENT (USE 0.050)

Project N.J. NO NAME NO. 56 DAM
113Z-05

Made By T.D. Date 2-23-81
 Chkd By JG Date 2/23/81

CHECK FOR CRITICAL FLOW:

$$S_c = \frac{14.56 N^2}{D_m^3} \quad \text{EQ 8-83 "HANDBOOK OF HYDRAULICS"}$$

BY BRATER AND KING

N = MANNINGS COEFFICIENT - (0.050)

D_m = MEAN DEPTH ≈ HYDRAULIC RADIUS - FT.

S_c = CRITICAL SLOPE -

$$S_c = \frac{14.56 (0.050)^2}{25^3} = 2.29970 \leq 10970 \text{ (CHANNEL SLOPE)}$$

CHANNEL SLOPE EXCEEDS CRITICAL SLOPE

$$Q = 25 D_0 (D_0)^{2/3} (0.1)^{1/2} \frac{1.486}{0.05} \quad A = 25 D_0$$

ASSUME D₀ = R

$$Q = 235 D_0^{5/3}$$

$$D_R = D_0 + \frac{Q^2}{25 A^2} \quad \text{EQ 8-86 "HANDBOOK OF HYDRAULICS"}$$

BY BRATER AND KING

$$D_R = D_0 + \frac{(235 D_0^{5/3})^2}{2(32.2)(25 D_0)^2}$$

g = 32.16 FT/SEC²
 A = AREA S.F.
 Q = FLOW, C.F.S.

STAGE DISCHARGE TABULATION

D ₀ (FT)	D _R (FT)	STAGE (FT)	Q (C.F.S.)
0	0	275	0
0.5	1.04	276.0	74
1.0	2.37	277.4	235
1.5	3.86	278.9	467
2.0	5.46	280.5	746
2.5	7.16	282.2	1082

Project N.S. NO NAME NO. 56 DAM

Made By T.D. Date 2-23-81


1132.05

Chkd By JG Date 2/23/81

SHEET 4 1 4 TO THE DRAW

STAGE DISCHARGE CURVE

WATER SURFACE ELEVATION




Project N.J. LAKE NoName No 56 DAM Made By JiHa Date 2-23-81
1132-05 Chkd By JG Date 2/23/81

BREACH ANALYSIS:

A BREACH HYDROGRAPH WILL BE COMPUTED BY THE HEC-1-DAM PROGRAM AND ROUTED THROUGH TWO DOWNSTREAM REACHES BY THE MODIFIED PLUS METHOD. THE ASSUMED BREACH CONDITIONS:



1. THE BREACH BEGINS WHEN THE W.S. ELEV. 277.0 FT
2. TIME FOR BREACH TO DEVELOP MAX. SIZE 1.0 hr.
3. BREACH SECTION

BREACH RESULTS:

- | | | |
|--|---|-----------------|
| 1. Peak outflow | = | 2535.0 [cfs] |
| 2. Max. channel stage | = | 265.4 [FT] |
| Reach 2 | | inv. 260.0 [FT] |
| 3. Mill building inundated to a depth of approx. | = | 3.4 [FT] |

HYDROLOGY


SCALE 1" = 10' HORIZONTAL
1" = 10' VERTICAL



TYPICAL CROSS SECTION


REACH 1

SQUARE 4 X 4 TO THE INCH



STA. 3+50, FACING DOWNSTREAM

REACH 2



STA. 7+00, FACING DOWNSTREAM

HEC - 1 - DAM PRINTOUT

Overtopping Analysis

NATIONAL DAM SAFETY PROGRAM
 LAKE NODNAME #56 DAM, NEW JERSEY
 100 YEAR STORM ROUTING

JOB SPECIFICATION

NO	NHR	NMIN	IDAY	IHR	IMIN	MEIRC	IPLT	IFPT	NSTAN
300	0	15	0	0	0	0	0	4	0
			JOPEL	NWI	LRDEI	IRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRATIO= 1 LRATIO= 1

RIIOS= 1.00

***** ***** ***** ***** *****

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH TO LAKE NODNAME #56 DAM

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JFRT	INAME	ISTAGE	IAUTO
LAKE	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

IHYDQ	IUHG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
0	2	4.55	0.00	4.55	0.00	0.000	0	0	0

LOSS DATA

LRDEI	SIKRR	ULINK	RILOL	ERAIN	SIRKS	RILOK	SIRKL	CNSIL	ALSHX	RIIME
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.10	0.00	0.00

UNIT HYDROGRAPH DATA

IC= 0.00 LAG= 2.50

RECESSION DATA

STRTO= -1.00 ORCSN= -.05 RTIOR= 2.00

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP 0	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP 0

SUM 7.12 4.98 2.14 59877.
 (181.)(127.)(54.)(1695.53)

HYDROGRAPH ROUTING

ROUTE DISCHARGE THROUGH DAM

ISTAR 189.00 ICOMP 1 IECON 0 ITAPE 0 JFLT 0 JFRF 1 INAME 1 IAUTO 0
 DAM 0
 ROUTING DATA
 CLOSS 0.000 AVG 0.00 IRES 1 ISAME 1 IOFT 0 IPMP 0 LSTR 0
 0.0 0.000 0.00 1 1 0 0

NSIES 1 NSIML 0 LAG 0 AMSKN X ISK SIDRA ISERAI
 0 0.000 0.000 0.000 0.000 -275. -1

STAGE 275.00 276.00 277.00 278.00 280.00 282.00

FLOW 0.00 74.00 189.00 326.00 657.00 1042.00

SURFACE AREA= 0. 9. 572. 1013.

CAPACITY= 0. 15. 1100. 14241.

ELEVATION= 270. 275. 280. 300.

CREL SPWID COOW EXPW ELEV COOL CAREA EXPL
 275.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA

TOPEL 277.0
 COOD 2.6
 EXFO 1.5
 DAMWID 102.

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION STATION AREA PLAN RATIO 1
1.00

HYDROGRAPH AT LAKE 4.55 1 3183.
(11.78) (90.14)(
ROUTED TO DAN 4.55 1 1399.
(11.78) (38.21)(
ROUTED TO 1 4.55 1 1349.
(11.78) (38.20)(
ROUTED TO 2 4.55 1 1350.
(11.78) (38.22)(

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	275.00	275.00	277.00
ELEVATION STORAGE	15.	15.	128.
OUTFLOW	0.	0.	189.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	2.08	654.	1349.	18.00	22.75	0.00

PLAN 1 STATION 1

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
1.00	1349.	264.5	22.75

PLAN 1 STATION 2

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
1.00	1350.	263.1	22.75

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LOG MODIFICATION 24 FEB 79

HEC - 1 - DAM PRINTOUT

Breach Analysis

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPLECTIONS
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION STATION AREA PLAN RATIO 1
1.00

HYDROGRAPH AT LAKE	4.55	1	3183
(11.78)	(90.14)		
ROUTED TO DASH	4.55	1	2739
(11.78)	(77.57)		
ROUTED TO 1	4.55	1	2747
(11.78)	(77.78)		
ROUTED TO 2	4.55	1	2751
(11.78)	(77.98)		

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 INITIAL VALUE SPILLWAY CREST TOP OF DAM
 ELEVATION 275.00 275.00 277.00
 STORAGE 15. 15. 128.
 OUTFLOW 0. 0. 189.

RATIO OF PMF	MAXIMUM RESERVOIR DEPTH OVER DAM W.S. ELEV	MAXIMUM STORAGE OVER DAM AC-FT.	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF FAILURE HOURS
1.00	277.95	298.	2739.	5.00	21.00
					18.75

PLAN 1 STATION 1

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
1.00	2747.	266.7	21.00

PLAN 1 STATION 2

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
1.00	2754.	265.8	21.00

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

APPENDIX 5

Bibliography

- 1 1. "Recommended Guidelines for Safety Inspection of Dams," Department of the Army, Office of the Chief of Engineers, Washington, D.C. 20314.
2. Design of Small Dams, Second Edition, United States Department of the Interior, Bureau of Reclamation, United State Government Printing Office, Washington, D.C., 1973.
3. Holman, William W. and Jumikis, Alfreds R., Engineering Soil Survey of New Jersey, Report No. 11, Sussex County, Rutgers University, New Brunswick, N.J., 1953.
4. "Geologic Map of New Jersey," prepared by J. Volney Lewis and Henry B. Kummel, dated 1910-1912, revised by H.B. Kummel, 1931 and M. Johnson, 1950.
5. Chow, Ven Te., Ed., Handbook of Applied Hydrology, McGraw-Hill Book Company, 1964.
6. Herr, Lester A., Hydraulic Charts for the Selection of Highway Culverts, U.S. Department of Transportation, Federal Highway Administration, 1965.
7. Safety of Small Dams, Proceedings of the Engineering Foundation Conference, American Society of Civil Engineers, 1974.
8. King, Horace Williams and Brater, Ernest F., Handbook of Hydraulics, Fifth Edition, McGraw-Hill Book Company, 1963.
9. Urban Hydrology for Small Watersheds, Technical Release No. 55, Engineering Division, Soil Conservation Service, U.S. Department of Agriculture, January 1975.

DATE
FILMED
-8