


AD-A104 029

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON --ETC F/G 13/13
NATIONAL DAM SAFETY PROGRAM, BEATTIES MILL DAM (NJ00821), PASSA--ETC(U)
AUG 81 W A GUINAN DACW61-79-C-0011

UNCLASSIFIED

DEAN/NAP-53842/NJ00821-81/ ML

1 of 1
00A
10/16/78



END
DATE
FILMED
10-81
DTIC



AD A104029

PASSAIC RIVER BASIN,
PASSAIC RIVER, PASSAIC COUNTY,
NEW JERSEY.

Historical Dam's Safety Program

BEATTIES MILL DAM

(NJ 00821)

PHASE I INSPECTION REPORT.
NATIONAL DAM SAFETY PROGRAM

Department of the Army, Corps of Engineers, Philadelphia District



APPROVED FOR PUBLIC RELEASE
DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY
Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

FILE COPY

REPT. NO.: DAEN/NAP-53842/NJ00821-81/08
AUGUST 1981

DTI
S

D

81 9 09 038



IN REPLY REFER TO
NAPEN-N

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT CORPS OF ENGINEERS
CUSTOM HOUSE - 2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

31 AUG 1981

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

Dear Governor Byrne:

Inclosed is the Phase 1 Inspection Report for Beatties Mill Dam in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Beatties Mill Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 30 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood.) However, more detailed hydraulic and hydrologic studies are not recommended due to the limited site condition and the intended purpose of the dam. To ensure the adequacy of the structure, the following actions as a minimum, are recommended:

a. Within one year from the date of approval of this report the owner should engage a qualified professional consultant to perform the following:

(1) Design and oversee repair procedures for the replacement of the large masonry blocks which have been dislodged from the north side of the training wall which is at the left center of the dam.

(2) Evaluate the potential for undermining of the foundation support at the downstream end of the masonry spillway training wall at the left center of the dam caused by the loss of several large bedrock blocks, and design and oversee corrective measures as needed.

(3) Investigate measures to assure the stability of the dam under severe overtopping conditions.

NAPEN-N

Honorable Brendan T. Byrne

b. Within one year from the date of approval of this report the owner should repair the eroded construction joints.

c. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam, within one year from the date of approval of this report.

d. An emergency action plan and warning system should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Minish of the Eleventh District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



ROGER L. BALDWIN
Lieutenant Colonel, Corps of Engineers
Commander and District Engineer

Incl
As stated

Copies furnished:

Mr. Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief
Bureau of Flood Plain Regulation
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

BEATTIES MILL DAM (NJ00824)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 23 April 1981 by Anderson-Nichols and Co. Inc., under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Beatties Mill Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 30 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood.) However, more detailed hydraulic and hydrologic studies are not recommended due to the limited site condition and the intended purpose of the dam. To ensure the adequacy of the structure, the following actions as a minimum, are recommended:

a. Within one year from the date of approval of this report the owner should engage a qualified professional consultant to perform the following:

(1) Design and oversee repair procedures for the replacement of the large masonry blocks which have been dislodged from the north side of the training wall which is at the left center of the dam.

(2) Evaluate the potential for undermining of the foundation support at the downstream end of the masonry spillway training wall at the left center of the dam caused by the loss of several large bedrock blocks, and design and oversee corrective measures as needed.


(3) Investigate measures to assure the stability of the dam under severe overtopping conditions.

b. Within one year from the date of approval of this report the owner should repair the eroded construction joints.

c. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam, within one year from the date of approval of this report.

d. An emergency action plan and warning system should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

APPROVED:



ROGER L. BALDWIN
Lieutenant Colonel, Corps of Engineers
Commander and District Engineer

DATE:

4. Aug 81

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam:	Beatties Mill
Identification No.:	Fed ID No. NJ00821
State Located:	New Jersey
County Located:	Passaic
Stream:	Passaic River
River Basin:	Passaic
Date of Inspection	April 23, 1981

ASSESSMENT OF GENERAL CONDITIONS

Beatties Mill Dam is a 19-foot high concrete run-of-the-river dam with 267 feet of its 287 foot crest serving as a spillway. A 3-foot wide, 1-foot deep notch in the spillway crest carries low flows. The dam is 85 years old and underwent major reconstruction in 1945-1946. It is of intermediate size and in fair condition, and serves to create a pool allowing diversion of 75 mgd from the Passaic River to the Passaic Valley Water Commission's water treatment plant for treatment and municipal use.

Several stones are missing from the upstream end of a stone masonry training wall at the left center of the dam. This has caused vertical and horizontal displacement of other stones in the training wall, and could lead to seepage and undermining of the spillway. In addition, some erosion and undermining of the rock foundation at the downstream end of the training wall has occurred.

The spillway would pass 29% of the Spillway Design Flood, which is one-half of the PMF. Failure of the dam would cause interruption of raw water supply (75 mgd) to the Passaic Valley Water Commission's water treatment plant. This interruption of a public utility would entail economic losses but would cause little, if any, threat of loss of life. Therefore the hazard classification of Beatties Mill Dam is significant.

It is recommended that the owner retain the services of a professional engineer, qualified in the design and construction of dams, to accomplish the following tasks in the near future: Design and oversee repairs to the training wall at the left center of the dam, evaluate the potential for undermining of the foundation at the downstream end of the training wall and design and oversee corrective measures as needed, and investigate measures to assure the stability of the dam under severe overtopping conditions.

It is further recommended that the owner accomplish the following in the near future as part of operating and maintenance procedures: repair construction joints on the dam and develop a written operation and maintenance schedule to ensure the safety of the dam.

ANDERSON-NICHOLS & COMPANY, INC.

A handwritten signature in cursive script, reading "Warren A. Guinan".

Warren A. Guinan, P.E.
Project Manager
New Jersey No. 16848



April 23, 1981

OVERVIEW PHOTO
BEATTIES MILL DAM

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonable possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

CONTENTS

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY REPORT

BEATTIES MILL DAM FED ID NO. NJ00821

		<u>Page</u>
SECTION 1	PROJECT INFORMATION	
	1.1 <u>General</u>	1
	1.2 <u>Project Description</u>	1
	1.3 <u>Pertinent Data</u>	3
SECTION 2	ENGINEERING DATA	
	2.1 <u>Design</u>	6
	2.2 <u>Construction</u>	6
	2.3 <u>Operation</u>	6
	2.4 <u>Evaluation</u>	6
SECTION 3	VISUAL INSPECTION	7
SECTION 4	OPERATIONAL PROCEDURES	
	4.1 <u>Procedures</u>	8
	4.2 <u>Maintenance of Dam</u>	8
	4.3 <u>Maintenance of Operating Facilities</u>	8
	4.4 <u>Warning System</u>	8
	4.5 <u>Evaluation of Operational Adequacy</u>	8
SECTION 5	HYDRAULIC/HYDROLOGIC	9
SECTION 6	STRUCTURAL STABILITY	10
SECTION 7	ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES	
	7.1 <u>Assessment</u>	11
	7.2 <u>Recommendations/Remedial Measures</u>	11
FIGURES	1. Regional Vicinity Map	
	2. Essential Project Features	
	3. Essential Project Features	
APPENDICES	1. Engineering and Experience Data	
	2. Check List Visual Inspection	
	3. Photographs	
	4. Hydrologic Computations	
	5. HEC 1 Output	
	6. References	

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY INSPECTION PROGRAM
BEATTIES MILL DAM
FED ID NO. #NJ00821

SECTION 1
PROJECT INFORMATION

1.1 General

a. Authority. Authority to perform the Phase I Safety Inspection of Beatties Mill Dam was received from the State of New Jersey, Department of Environmental Protection, Division of Water Resources by letter dated 12 December 1980 under Basic Contract No. FPM-39 and Contract No. A01093 dated 10 October, 1979. This Authority was given pursuant to the National Dam Inspection Act, Public Law 92-367 and by agreement between the State and the U.S. Army Engineers District, Philadelphia. The inspection discussed herein was performed by Anderson-Nichols & Company, Inc.

b. Purpose: The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to the safety of Beatties Mill Dam and appurtenances. Conclusions are based upon available data and visual inspection. The results of this study are used to determine any need for emergency measures and to conclude if additional studies, investigations, and analyses are necessary and warranted.

1.2 Project Description

a. Description of Dam and Appurtenances. Beatties Mill Dam is a concrete run-of-the-river dam with a structural and hydraulic height of 19.3 feet. Most of the dam's crest is a 267 foot long broad-crested overflow spillway in three sections - an arched 152-foot center section (concave upstream), a 55-foot right wingwall tying into a factory building which serves as the right abutment, and a 60-foot left wingwall tying into the left abutment. There is a 3-foot wide, 1-foot deep notch in the right wingwall for low flows. The dam's crest width is about 5 feet, the upstream face is 2H:1V (4 feet) and then nearly vertical, and the downstream face slopes 1H:1-1/2V.

The pond created by Beatties Mill Dam serves to create a diversion pool for a canal leading to a water treatment plant. This canal is controlled from a gate house about 300 feet upstream of the left abutment.

b. Location. The dam is located in Little Falls, New Jersey, on the Passaic River. It is at 40°53.1' north latitude and 74°14.1' west longitude on the Paterson Quadrangle. To reach Beatties Mill Dam, take exit 53 from U.S. Interstate Highway 80 to Riverview Drive South. After about 0.7 miles, turn right on Union Avenue. The gate leading to Beatties Dam is 0.2 miles south on Union Avenue on the right.

c. Size Classification. Beatties Mill Dam is classified as being intermediate in size on the basis of storage at the dam crest of 4,870 acre-feet, which is less than 50,000 acre-feet but more than 1,000 acre-feet, in accordance with criteria given in the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. The failure of Beatties Mill Dam would cause a threat of loss to few, if any, lives. However, the hazard classification is considered to be significant because failure of the dam would interrupt inflow to the Passaic Valley Water Commission's water treatment plant, which is an important public utility.

e. Ownership. The dam is owned by the Passaic Valley Water Commission. Information may be obtained by writing the Commission at P.O. Box 230, Clifton, New Jersey, or by calling (201)772-3900.

f. Purpose. Beatties Mill Dam creates a pond from which an average of 75 mgd of Passaic River water is diverted to Passaic Valley Water Commission water treatment plant for treatment and use as water supply.

g. Design and Construction History. The cornerstone of the gatehouse controlling diversions to the water treatment plant indicates that Beatties Mill Dam was originally constructed in 1896. The dam was damaged by flooding in 1945, and major reconstruction designed by Bogert-Childs Engineering Associates was carried out in 1945-1946.

h. Normal Operational Procedure. Water for the Passaic Valley Water Commission is diverted to treatment as needed by canal. The average rate of diversion is 75 mgd. No other operational procedures were disclosed for this dam.

i. Site Geology. No boring information was available at the time the dam was inspected. Information derived from the Geologic Map of New Jersey (Kummel and Johnson, 1912) and the Glacial Drift Map of New Jersey (Salisbury, Kummel, Peet and Whitson, 1902) indicates that soils within the immediate site area consist of stratified drift which may include sand and gravel in plains, deltas, eskers, kames, and terraces.

Bedrock of igneous origin was observed in massive outcrops along the entire foundation during the inspection of this dam. The previously mentioned map (Kummel and Johnson) indicates that bedrock in this area consists of shale and sandstone with igneous intrusives of Triassic age.

1.3 Pertinent Data

a. Drainage Area

762 square miles

b. Discharge at Damsite (cfs)

Maximum flood at damsite - For USGS Gage 013895000, Passaic River at Little Falls, N.J., the maximum discharge from 1897 to the present is 28,000 cfs on October 10, 1903. The gage is 0.6 miles downstream of the dam, and has a drainage area of 762 square miles.

Total ungated spillway capacity at maximum pool elevation (at top of dam) - 12,701 cfs

c. Elevation (ft. above NGVD)

Top of dam - 164.1

Test flood (1/2 PMF) - 171.6

Recreation pool (at time of inspection) - about 157.2

Spillway crest - 156.8

Streambed at centerline of spillway - low point 144.8

Maximum tailwater - (F.l.S. 500 year flood) - 156

d. Reservoir (length in feet)

Length of maximum pool - (at 164.1' NGVD) - 117,000 (estimated)

Spillway crest - 76,000 (estimated)

e. Storage (acre-feet)

Spillway crest - 1,435

Test Flood (1/2 PMF) - 9,218

Top of dam - 4,870

f. Reservoir Surface (acres)

Top of dam - 536

Spillway crest - 350

g. Dam

Type - concrete gravity

Length - 287 feet

Height - 19.3 feet (hydraulic)

- 19.3 feet (structural)

Top width - about 5 feet

Side slopes - upstream 2H:1V for four feet then nearly vertical; downstream 1H:1-1/2V

Zoning - Not applicable

Impervious core - Not applicable

Cutoff - unknown

Grout curtain - unknown

h. Spillway

Type - Concrete overflow

Length of weir - 267 feet

Crest elevation - 157.8' NGVD - 3 foot notch at 156.8' NGVD

Low level outlet - None

U/S Channel - Passaic River

D/S Channel - Passaic River

i. Regulating Outlets

Type - Diversion canal controlled by gate located in gate house; seven 10' x 12' liftgates. Trash racks located at edge of reservoir outside gate house.

Width - Canal about 75 feet wide

Access - From left (north) bank through gate house to gates. Trash racks accessible from walkway upstream of gate house. Debris collected are passed downstream through trash flume and connecting 30-inch pipe.

SECTION 2
ENGINEERING DATA

2.1 Design

No hydraulic or hydrologic engineering data were disclosed. The plans for the 1945-1946 reconstruction were obtained.

2.2 Construction

Extensive correspondence exists between the Passaic Valley Water Commission and the New Jersey Department of Conservation concerning the 1945-1946 reconstruction of the dam. This correspondence is reproduced in Appendix 1.

2.3 Operation

No written operational data were found.

2.4 Evaluation

a. Availability. A search of the New Jersey Department of Environmental Protection files revealed the information discussed above.

b. Adequacy. The data obtained combined with the visual inspection are deemed adequate to complete this Phase 1 Inspection Report

SECTION 3
VISUAL INSPECTION

3.1 Findings

a. Dam. Some erosion and undermining of the large rock outcrop downstream of the left abutment of the dam has occurred. Several large masonry blocks are missing at the junction of the spillway and the masonry block training wall which is perpendicular to the spillway at the left center of the dam. The existence of former root systems was observed behind several of the adjacent blocks which had remained in place. Several of the top cap stones on the training wall had been displaced up to 3 inches vertically downward adjacent to the intersection with the spillway. Horizontal separations up to 5 inches wide were measured between blocks located in the spillway and the adjacent center masonry block training wall. Some undermining of the large stones was observed near the downstream end of the masonry training wall. The toe of the concrete spillway is undermined 2-4 inches along its entire length. The downstream face of the dam is eroded, exposing the coarse aggregate, with deeper erosion at the construction joints and apparent cold joints.

b. Appurtenant Structures. The trash racks, walkway, and gate house all appeared to be in good condition. The trash flume and connecting pipe were free of debris. Some debris had collected on the trash racks. The diversion canal was essentially free of debris; however, brush and small trees line the canal banks.

c. Reservoir Area. The watershed above the lake is gently sloping and urbanized with numerous mill buildings and homes. Slopes on the shore appear to be stable. Some sedimentation was observed in the reservoir.

d. Downstream Channel. Bedrock channel with some displacement of large blocks of massive rock outcrop has occurred along the right and left sides of the channel downstream of the dam. Trees are growing along the top of the rock outcrops along the left side of the channel downstream of the dam.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedures

No written operating procedures were revealed. Acceptable procedures are followed for operation of the diversion to the water treatment plant.

4.2 Maintenance of Dam

No formal maintenance procedures for the dam were found.

4.3 Maintenance of Operating Facilities

No formal maintenance procedures for the operating facilities were discovered. However, maintenance is adequate for continual use.

4.4 -Warning System

No description of any warning system was found.

4.5 Evaluation of Operational Adequacy

The remedial measures described in Section 7.2 should be implemented as described to improve operation and maintenance for the dam.

SECTION 5
HYDROLOGIC/HYDRAULIC

5.1 Evaluation of Features

a. Design Data. Because no original hydrologic design data were revealed, an evaluation of such data could not be performed.

b. Experience Data. The water surface elevation caused by the flood of record for the dam, in October 1903, is shown on a stone in the diversion structure controlling the canal to the water treatment plant. The peak elevation was about 169 feet above NGVD, 11 feet above the present spillway crest. The peak flow from the October 1903 flood at the USGS gage 0.6 miles downstream of the dam was 28,000 cfs. Since the dam was rebuilt in 1945, the stage-discharge relationship in the 1903 flood cannot be compared to the stage discharge curve developed in this report. In 1945, the dam was damaged by high waters. No record of the peak stage in the reservoir from this flood could be found.

c. Visual Inspection. At the time of the inspection, all flow was through the 3-foot wide notch in the main spillway, allowing a clear view of the spillway crest and downstream face.

d. Beatties Mill Dam Overtopping Potential. The hydraulic/hydrologic evaluation for this dam is based on a selected Spillway Design Flood (SDF) equal to one-half the Probable Maximum Flood (PMF) in accordance with the range of test floods given in the evaluation guidelines for dams classified as significant hazard and intermediate size. The PMF was obtained from Passaic River Basin - New Jersey and New York - Survey Report for Water Resources by the New York District of the Corps of Engineers. The half-PMF inflow to the pond is 44,000 cfs, with a peak outflow of 43,785 cfs causing a stage of 171.6 feet above NGVD. (Hydrologic/hydraulic computations are attached as Appendix 4.)

Water could rise 7.3 feet above the crest of the low flow notch in the spillway, to 164.1 feet above NGVD, before overtopping the left abutment of the dam. Under this head the spillway capacity is 12,701 cfs, 29% of the selected SDF. Flood routing calculations indicate that Beatties Mill Dam would be overtopped for 91 hours to a maximum elevation of 171.6 feet NGVD, 7.5 feet above the crest of the left abutment, under half-PMF conditions.

e. Draw-down Capacity. Water could be diverted from Beatties Mill Dam at times of low flow through the canal leading to the water treatment plant. The time required to draw the reservoir down would depend on inflow and on the capacity of the canal.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

The displacement of large masonry blocks at the junction of the spillway and center masonry block training wall may lead to seepage and undermining of the spillway. The dislodgment of several large blocks of bedrock at the downstream end of the masonry block training wall may cause stability problems to the training wall if allowed to continue.

6.2 Design and Construction Data.

No design or construction data pertinent to the structural stability of the dam are available.

6.3 Operating Records.

No operating records pertinent to the structural stability of the dam are available.

6.4 Post-Construction Changes.

Plans and sections from the 1945-1946 reconstruction of the dam are available; however no computational data pertinent to the structural stability of the dam are available.

6.5 Seismic Stability

This dam is in Seismic Zone 1. According to the Recommended Guidelines, dams located in Seismic Zone 1 "may be assumed to present no hazard from earthquake, provided static stability conditions are satisfactory and conventional safety margins exist". None of the visual observations made during the inspection are indicative of unstable conditions. However, because no data are available concerning the engineering properties of the foundation materials for this dam, it is not possible to make an engineering evaluation of the stability of the structure or the factor of safety under static conditions.

SECTION 7
ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. Beatties Mill Dam is 85 years old and is in fair condition.

b. Adequacy of Information. The information available is such that the assessment of the dam must be based primarily on the results of the visual inspection.

c. Urgency. The recommendations made in 7.2.a and 7.2.b should be implemented by the owner as prescribed.

d. Necessity for Additional Data/Evaluation. The information available from the visual inspection is adequate to identify the potential problems which are listed in 7.2.a. These problems require the attention of a professional engineer who will have to make additional engineering studies to design or specify remedial measures to rectify the problems. If left unattended, the problems could lead to failure of the dam.

7.2 Recommendation/Remedial Measures


a. Recommendations. The owner should retain a professional engineer qualified in the design and construction of dams to accomplish the following in the near future:

- (1) Design and oversee repair procedures for the replacement of the large masonry blocks which have been dislodged from the north side of the training wall which is at the left center of the dam.
- (2) Evaluate the potential for undermining of the foundation support at the downstream end of the masonry spillway training wall at the left center of the dam caused by the loss of several large bedrock blocks, and design and oversee corrective measures as needed.
- (3) Investigate measures to assure the stability of the dam under severe overtopping conditions.


b. Alternatives. None recommended.

c. Operating and Maintenance Procedures. The owner should accomplish the following in the near future:

- (1) Repair the eroded construction joints.
- (2) Develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.




PLAN



ELEVATION

Anderson-Nichols & Co, Inc		U.S. ARMY ENGINEER DIST PHILADELPHIA	
BOSTON	MASSACHUSETTS	CORPS OF ENGINEERS PHILADELPHIA, PA	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
BEATTIE'S MILL DAM			
PASSAIC RIVER		NEW JERSEY	
		SCALE NOT TO SCALE	
		DATE: JUNE 1981	



MAP BASED ON STATE OF NEW JERSEY OFFICIAL MAP & GUIDE.

Anderson-Nichols & Co., Inc.		U.S. ARMY ENGINEER DIST. PHILADELPHIA	
BOSTON MASSACHUSETTS		CORPS OF ENGINEERS PHILADELPHIA, PA.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
<h1>BEATTIES MILL DAM LOCATION MAP</h1>			
PASSAIC RIVER		NEW JERSEY	
		SCALE: 1" = 4 Miles Approx.	
		DATE: JUNE 1981	

APPENDIX 1
ENGINEERING AND EXPERIENCE DATA
BEATTIES MILL DAM

Borough of West Paterson

Department of Administration

ALFRED A. REDA
Municipal Clerk
Administrator



PASSAIC COUNTY, N. J.

833 McBRIDE AVENUE,
WEST PATERSON, N. J. 07649
(201) 378 0909

RECEIVED

AUG 23 10 25 AM '72

DEPT. OF ENVIRONMENTAL PROTECTION
DIV. OF WATER RESOURCES
August 21, 1972

414

Mr. Asis
State Department of Environmental Protection,
Division of Water Resources
Trenton, NJ

RE: Beattie Dam Little Falls
Township Passaic County NJ

Dear Mr. Asis:


With respect to the above noted matter please be advised that on August 15, 1972 Mr. Wendell Inhofer, General Superintendent of the Passaic Valley Water Commission, made a visual inspection of the Beattie Dam and was accompanied by Mr. Robert P. Schilling, Municipal Engineer, for the Borough of West Paterson.

For your information I am enclosing herewith a copy of Mr. Schilling's report dated August 15th wherein it is indicated the aforementioned found no evidence of cracks or other structural defects etc.

Please note that at the time of this inspection Mayor Alfred H. Baumann of West Paterson was away on vacation and has just returned. Upon his direction I am forwarding this report to you.

Should you desire any additional information on this matter, please do not hesitate to call my office. Thanking you for your cooperation, I wish to remain,

Sincerely yours,


Alfred A. Reda
Municipal Clerk
Administrator

AAR:gd
Enc.

CC: Mayor Alfred H. Baumann
Robert P. Schilling
Municipal Engineer



July 3AA

PASSAIC VALLEY WATER COMMISSION

1888 MAIN AVENUE

CLIFTON, NEW JERSEY

P. O. BOX 823

August 14, 1972

DEPT. OF ENVIRONMENTAL PROTECTION
DIV. OF WATER RESOURCES

WENDELL R. INHOFFER
General Superintendent
and Chief Engineer

Mr. Dirk C. Hofman, P.E.
Chief - Bureau of Water Control
State of New Jersey
Department of Environmental Protection
Division of Water Resources
Trenton, New Jersey 08625

Dear Mr. Hofman:

Re: Hestties Dam, Application No. 404

This is to inform you that on Saturday, August 12, 1972, the writer personally inspected Hestties Dam after all overflow had been diverted to the Commission's intake canal.

You are hereby advised that cracks and leaks reported in the Herald News on June 26, 1972, were not apparent during this inspection.

A number of photographs were taken and will be forwarded to your office in the near future.

Very truly yours,

PASSAIC VALLEY WATER COMMISSION

Wendell R. Inhoff
Wendell R. Inhoff
General Superintendent
and Chief Engineer

WRI:grt



Honorable Mayor and Council
Borough of West Paterson, N.J.

Re: Battie Dam
Little Falls Township,
Passaic County, N.J.

Gentlemen:


This is to advise that on this date I met with Mr. Wendell Inhoffer, General Supervisor and Chief Engineer, Passaic Valley Water Commission, in connection with an earlier report received regarding possible structural defects in the Battie Dam, in Little Falls, N.J.

At the present time there is no overflow occurring at the dam and we were able to observe the entire top and external face of the structure during this inspection. We found no evidence of any deterioration, cracks or other structural defects and in Mr. Inhoffer's opinion the dam appears to be in a sound condition. Mr. Inhoffer also stated that he has had photographs taken of the dam and has submitted a report of his findings to the New Jersey Dept. of Environmental Protection, Division of Water Resources.

Respectfully submitted,

Robert P. Schilling
Robert P. Schilling
Municipal Engineer

RPS/cc



Morris County Mosquito Extermination Commission

2 Franklin Place

COMMISSIONERS

A. RICHARD STOTT, President
WILLIAM V. FRANK, Vice President
DR. JOHN E. WALKER, Secretary
FRANCIS E. MATHIAS, Treasurer
DR. JOHN I. BISHOPSON
GEORGE E. LAIBACH

JAMES E. HART, Jr.
Superintendent
Telephone No. 4-1228

ROBERT L. VANNOTE, M. A.
October 28, 1946.

N. J. State Water Policy Commission
28 West State Street
Trenton, New Jersey.

Attention, Mr. Howard T. Critchlow

Gentlemen:

I am writing to inquire whether the State Water Policy Commission has checked the work completed at Beattie Dam, Little Falls, by the Passaic Valley Water Commission with respect to the following:

1. Elevation of the re-capped spillway.
2. Length of present spillway including wall on the mill side.

I have been informed by my associates in Little Falls that great secrecy surrounded the work, with watchmen, etc. All were forbidden to discuss the work; however, information is abroad that the spillway was raised a few inches in the re-capping process and the portion of the dam paralleling the mill side was cut off so that it can be no longer considered a spillway area. This may be rumor as most reports are; however, we must be prepared to answer.


Our position is one opposing even a fraction of an inch rise in the elevation of the spillway and the curtailment of any spillway area. If your Department has checked the work by running levels from the B.M. established by the Riparian Stream and Waterway Survey to the points on the spillway as shown on the plan of that survey and found no increase we will be more than pleased. If this was not done in the course of approving the final work we will take the steps necessary to make the survey in order to answer the rumors.

With best regards to you and your assistants, I remain,

Yours truly,

Robert L. Vannote
Robert L. Vannote, Exec. Sec'y
Four County Committee for Mosquito Control in the Passaic Valley

RLV:sa



Report on Dam Inspection

HEWITT'S DAM
PAROLEE RIVER, PAROLEE COUNTY

APPLICATION NO. 104

DAM NO. 26-30

On August 23, 1946 inspection was made in company with Richard E. Seay, Superintendent, Parolee Valley Water Commission, of the spillway about which has been completed recently under repairs approved November 1, 1945 for the sub-joint dam. Inspection disclosed that the work on the spillway has been completed in accordance with the approved drawings and is an excellent job. Inspections were taken from three angles. It is recommended that the approved letter accepting the repairs to the spillway be sent to Mr. Seay.

At the time of inspection, the contractor was removing the earth dike which had been constructed upstream of the spillway to permit repairs and was being that material to build a dike along the left bank to permit construction of the skimming flume.

This dike is being removed to below the original stream bed level where rock permits.

Ernest E. J.
August 23, 1946


George R. Shanklin
George R. Shanklin
Acting Chief Engineer

Suburban and Office
2 Washington Avenue
Mountain View, N. J.
Telephone 2-2227

Suburban and Office
2 Washington Avenue
Mountain View, N. J.
Telephone 2-2227

Law Office
SIDNEY H. KAMENITZ
126 WASHINGTON STREET
MOUNTAIN VIEW, N. J.

AKS



Dear Sirs:
Reference is made to your letter of the 11th instant regarding the modification of the deed of the property in Lincoln Park, N. J., owned by the late Mr. J. H. ...

Gentlemen:

Several weeks ago, I wrote to you regarding the modification of the deed of the property in Lincoln Park, N. J., owned by the late Mr. J. H. ... result of the alteration of the deed of the property mentioned, his property has been rendered worthless. Accordingly, would you be kind enough to communicate with me regarding this matter.

Sincerely yours,

SERVICES

Application No. 14
Date July 25, 1916

On July 25, 1916, the undersigned, in accordance with Richard W. Dunnington, the work in the vicinity of the station in Littleton, Colorado, has a line of 2 feet or more of water in the time of the high tide that the water will be just prior to the time of the film from the station of construction of a dam on the site by the U.S. Army. The undersigned has the honor to acknowledge the receipt of the certificate of the said railway agents.

George R. Shanklin
George R. Shanklin
Asst. Chief Engineer

Trenton, N. J.
July 25, 1916



Report on Site Inspection

STATE OF MISSISSIPPI

AFFIDAVIT NO. 70, 104

DEN NO. E6-50

On May 17, 1946 inspection was made of the work in progress on the project to this dam on the Little River in Little Falls, Paroche County. The inspection disclosed that the new spillway crest had been completed to the center of the crest section in the middle of the dam. At the time of the inspection all work had been interrupted by high flows. The board observed that the new section was approximately 8 inches.

Trenton, E. J.
May 27, 1946

George R. Shanklin
George R. Shanklin
Asst. Chief Engineer

Superior Aircraft

May 9, 1944

Mr. Richard E. Boyatz, General Superintendant
Boeing Aircraft Company
19741th Avenue
Boeing Field, Wash. D.C.

Boeing Aircraft Company

Dear Mr. Boyatz:

In reply to your letter of May 7, 1944 suggesting that the top of the wing wall on the left side of Battle's dam on the landing base at Little Falls, be raised 2 inches higher than the exact elevation 197.0 of the main dam, we can advise you that this change has no objection to this change in the design, provided however by 197.0. If this change is adopted, please file in duplicate revised drawings showing same.

Yours very truly,

H. F. Critchlow
Chief Engineer

CH:LM

Blis



PASSAIC VALLEY WATER COMMISSION

137 ELLISON STREET

PATERSON, 1
NEW JERSEY

May 3, 1946

JOHN F. BENTON, President
DAVID W. BENTON, Vice President
JOHN J. BENTON, Secretary
JOHN J. BENTON, Treasurer
BENTON & BENTON
INCORPORATED 1917



ERS

Department of Conservation
Division of Water Policy and Supply
28 West State Street
Trenton, N.J.

Attention: H.T. Critchlow, Chief Engineer

Re: Repair "Beattie's Dam"

Gentlemen:

It has just been suggested that the top of the wing-wall on the Beattie's mill side of the above captioned structure, be held at an elevation 8 inches higher than the crest of the main dam. This would materially improve the operating appearance when a small amount of water is flowing over the dam, and would confine the flow to the main section.

The plans, as approved, call for holding the same crest level throughout, namely, elevation 167.80.

Would you approve of the change suggested above?

Very truly yours,
PASSAIC VALLEY WATER COMMISSION

Richard K. Bonyun
Richard K. Bonyun
General Superintendent

REB:G



Report on the Dam

ARTICLE'S IAN

LITTLE FALLS, PASSAIC RIVER

APPLICATION NO. 401

RRM NO. 26-30

On October 10, 1945 inspection was made and conference was held with Richard E. Bogert, General Superintendent Passaic Valley Water Commission and Mr. Bogert of the Passaic Valley Water Commission, Consulting Engineer, regarding the repair and construction of a skimming flume at Little Falls on the Passaic River at Little Falls.

The inspection disclosed that the crest of the main dam had been severely damaged by the July 1943 flood, wherein two courses of the stone masonry had been washed off the top of the dam for a distance of 12 feet near the right end and for a distance of 6 feet near the left end of the main spillway. The left wing wall was in good condition with a concrete apron. However, the right wing wall is somewhat obstructed at the left end by an outcrop of ledge rock on the downstream face. The right wing wall, opposite the Hattie Manufacturing Company plant, is in very poor condition and leaks badly.

The preliminary drawings filed October 1 were discussed with Messrs. Boynton and Bogert, who were advised (1) that no approval to start construction could be granted before the next Council meeting on November 1; (2) that approval of the repairs and the skimming flume would be recommended without the provisions for flashboards; (3) that the outlet of the skimming flume be modified to reduce its obstruction of the left wing wall. Mr. Bogert agreed to eliminate the two concrete sills shown on the spillway for future flashboards, but requested that the pipe sockets and eye-bolts shown on the final drawings for use with flashboards at some future date be approved, since the cost of installing these items at the future date would be large as compared with the cost of installing them at this time. In order to avoid a serious obstruction to the left wing wall and heavy rock excavation below this wing wall, it was decided to end the skimming flume 20 feet above the dam and discharge through a concrete pipe, the top of which would be located below the crest of the dam. In support of the flashboard provisions Mr. Bogert was requested to file a letter with his application substantiating the need of the flashboards.

Trenton, New Jersey
October 25, 1945

George F. Shanklin
George F. Shanklin
Asst. Chief Engineer

Dam Application No. 1091

(26-90)

State of New Jersey
State Water Policy Commission

REPORT ON DAM APPLICATION

To the State Water Policy Commission,
State of New Jersey.

Gentlemen:

The application of Passaic Valley Water Commission, 137 Hillison St., Paterson, N.J.,

filed October 22, 1945 for approval of plans and for a permit to repair a dam
construct a skimming flume above this dam
known as Beattie's Dam and to raise in Little Falls on Passaic River

tributary to Newark Bay in Passaic County, New Jersey,

has been examined by George B. Shanklin, Chief
Assistant Mining Engineer.

PRINCIPAL FEATURES

Location 26.1.6.6-6	Site inspected Oct. 10, '45 - G.B.S.
Purpose of dam Potable public water supply	Length of dam 160 feet
Drainage area 772.9 sq. mi.	Elevation of top of dam 157.8 Applicant's datum
Area of Lake natural channel	Capacity of lake 1100 gals.
Type of dam Stone masonry dam capped with concrete	Downstream slope 1 to 1-1/2
Upstream slope 2-1/2 to 1 of batter	Max. height 8 1/2 feet
Foundation material Trap rock ledge	Length of spillway 285 feet
Type of spillway Freefall overflow, spillway dam	Max. head on spillway 11.12 feet See other side.
Spillway capacity 31,075 sec. ft.	Estimated maximum flood flow 41 sec. ft. per sq. mi. Oct. 10, 1903
Estimated maximum flood flow 41 sec. ft. per sq. mi. Oct. 10, 1903	Outlets other than spillway Intake canal and gate house for Passaic Valley Water Comm. plant on left bank upstream of dam and intake works for Beattie's Mfg. plant on right bank at dam.
Drawings filed	

It has been found that the site for the dam is suitable and the plans adequate to ensure the construction of a structure which will not be a menace to life or property. It is therefore recommended that the plans be approved and that a permit be issued, subject, however, to the following terms and conditions:—

1. That this permit does not give any property rights, either in real estate or material, nor any exclusive privileges; neither does it authorize any injury to private property nor invasion of private rights, nor any infringement of Federal, State or local laws or regulations, nor does it waive the obtaining of Federal assent, when necessary.

PASSAIC VALLEY WATER COMMISSION

157 ELLISON STREET
PATTERSON, 1
NEW JERSEY



DAM APPLICATION No. 4044
October 16, 1933

N. J. Dept. of Conservation
Division of Water Policy & Supply
28 West State Street
Trenton 8, New Jersey

Attention: W. T. Critchley,
Chief Engineer

Re: Dam #26, 30 Passaic County

Gentlemen:

We are enclosing herewith application forms for permission to repair this Commission's Dam, known as "Beattie's Dam", across the Passaic River at Little Falls. Also enclosed is a complete set of plans and specifications for the project.

Following our conference on the site with Mr. Shanklin on October 10th, we have revised the design of the outlet end of the skimming flume in accordance with your suggestions to eliminate any obstruction at the crest of the dam. The proposed elevation of the new crest is the same as that of the existing crest of the arched section. This elevation of crest will be held throughout the entire spillway and will effect a betterment in discharge capacity, since the crests of the existing wing walls on either side of the arched section are now and have been some three to four inches higher than the crest of the arched section.

You will note on the drawings that we are requesting approval for the installation of pipe sockets in the new dam crest for the future installation of flashboards, if and when applied for and approved by your Board.

We submit the following arguments to justify our request:

- (1) The pipe sockets would be flush with the top of the dam, filled and sealed with material of a

removable nature, and would offer no resistance to free discharge.

- (2) Flashboards would not be installed unless formal approval were granted by your Board. This policy would be confirmed by the Commission by formal resolution, if you request such action.
- (3) The design of the flashboard supports, if and when applied for and approval granted, would consist of stainless steel pins with a calibrated cut-away section at crest level, and designed and tested to fail at a predetermined elevation of water level above the permanent crest of the dam. The flashboards would then fall to the downstream face of the dam and be held there by chains fastened to the eye bolts set in the face of the dam. Such a design for flashboards would cause no hardship to upstream property owners during times of low flow conditions and would fail and create no obstruction to the free discharge over the dam during times of high water.

We are anticipating, at this time, the need for flashboards on this dam at some time in the future for the following reasons:

- (1) The Little Falls Purification Plant on this Commission's Passaic River source of potable water supply is designed on gravity flow of water from the river through intake canal, screen house, coagulation basins, influent piping and on to the filters. It is estimated that the present maximum gradient

PASSAIC VALLEY WATER COMMISSION

with water level at the river of 157.8 (crest level of the dam) will not permit production of potable water from this source 'a excess of 50 m.g.d. The future installation of flashboards to permit the carrying of 1 ft. higher elevation of water at the river intake, during times of low flow, would materially increase the potable water yield from this source of supply.

(2) The future installation of the flashboards would provide certain other advantages such as increased hydro-electric generation, which might be vital in our ability to pump water during failure of our auxiliary source of power.

As stated in our letter of September 23th, the Commission considers the repair of the dam urgent, and time to be of the essence, For this reason we have explained at length our present and future plans in anticipation of your deliberation on the application. The work has been advertised and bids will be received by the Commission on October 24th, and we respectfully request your approval of the project by that date or shortly after, in order that the contract may be awarded without delay.

Very truly yours,
 PACIFIC VALLEY WATER COMMISSION
Richard E. Boygun
 Richard E. Boygun
 General Superintendent

REB:VM

c

PACIFIC VALLEY WATER COMMISSION



PASSAIC VALLEY WATER COMMISSION

137 ELLISON STREET

PATERSON, I
NEW JERSEY

September 20, 1948



H.T. Grishlow, Chief Engineer
New Jersey Department of Conservation
Division of Water Policy and Supply
20 West State Street
Trenton 6, New Jersey

Pat. Dam No. 27-20 Passaic County

Gentlemen:

In response to your letter of September 11th, regarding repairs to our Paterson Dam, at Little Falls, we hereby make formal application for approval to proceed with this construction.

Enclosed herewith is a copy of a preliminary report of Bogert-Childs Engineering Associates, together with preliminary drawings of the work to be undertaken. It is proposed to do the following work:

- (1) Reconstruct the crest and down stream slope of the curved section of the dam and the straight section on gate house side, with poured concrete of typical cross-section as shown on scheme L of the drawing.
- (2) To reinforce the existing side wall on the Peattie Manufacturing side with poured concrete typical section L-R as shown on the drawing.
- (3) To hold the elevation of the new concrete crest of the main dam and side wall, at the same elevation as the crest of the present dam.
- (4) To construct a "skimming flume" from the floating boom at the gate house to and through the dam as shown on the drawings.
- (5) To provide in the new crest of the dam and side wall, slots for the future installation of flash boards if and when approved by your department.

*Not approved
for flash boards*

This application does not include a request for any change in elevation of the crest of the existing dam, or for the installation of flash boards previously mentioned in our letter of September 6th, but is merely a request for approval to proceed with the permanent

New Jersey Department of Conservation -D- September 25, 1940

rebuilding of the existing structure, the maintenance of which is vital to the operation of this Commission's Passaic River water supply.

Since the flood of July 22nd, recent high water over the dam has caused more damage to the structure and for this reason it is imperative that work on the repairs be placed under way as soon as possible.

Will you therefore kindly give this matter your prompt consideration so that there may be no undue delay in proceeding with the project.

Very truly yours,
PASSAIC VALLEY WATER COMMISSION

Richard K. Bonyun
Richard K. Bonyun
General Superintendent

END:G

PASSAIC VALLEY WATER COMMISSION

PASSAIC VALLEY WATER COMMISSION

157 ELLISON STREET

PATERSON, 1 -
NEW JERSEY

COMMUNICATIONS SECTION
TELEPHONE ROOM
MAIL ROOM
RECORDS SECTION
GENERAL OFFICE

Per Passaic Co.

September 6, 1945

EPB

R. T. Critchlow, Chief Engineer
N. J. Dept. of Conservation
Division of Water Policy & Supply
10 West State Street
Trenton 0, New Jersey



Rem. 26-30

Dear Mr. Critchlow

During the recent flood of July 22nd and 23rd, material damage was done to this Commission's dam across the Passaic River at Little Falls. The dam is known as "Beattie's Dam". Several of the coping stones forming the crest of the stone masonry dam were washed away.

We are starting with the preparation of plans and specifications for the work of making a permanent repair to this structure. To be included in this project is a new sluiceway from the floating boom at our River Intake, to and through the dam to facilitate removal of debris which collects at the intake. Also contemplated is the installation of collapsible filterboards on the top of the dam which would permit the carrying of approximately 1 ft. higher elevation of water in the pond above the dam during dry flow conditions, but which would collapse at time of high water and not interfere with the free discharge over the dam.

It is my understanding that such work is subject to the approval of your department and for this reason I am advising you of the project. We have engaged the services of Hovart-Childs Engineering Associates in the preparation of design, plans and specifications.

Please advise if I am correct in assuming that your approval is necessary, and if so please inform us of the procedure to follow.

Very truly yours,
PASSAIC VALLEY WATER COMMISSION

Richard E. Bonyun

(over)

Richard E. Bonyun
General Superintendent

APPENDIX 2

CHECK LIST

VISUAL INSPECTION

BEATTIES MILL DAM

Check List
Visual Inspection
Phase I

Name Dam Beatties Mill Dam County Passaic State NJ (00821) Coordinators NJDEP
Date(s) Inspection 2/17/81 Weather Clear Temperature 52°
4/23/81 Rain 55°
Pool Elevation at Time of Inspection 157.2' NGVD Tailwater at Time of Inspection 152' NGVD

Inspection Personnel:

<u>W. Guinan</u>	<u>C. Plaud</u>	<u>D. Deane</u>
<u>S. Gilman</u>	<u>J. Stone</u>	<u>K. Stuart</u>
<u>R. Murdock</u>		

R. Murdock/K. Stuart/S. Gilman Recorder

Mr. L. O'Brien - Owner's Representative

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEEPAGE OR LEAKAGE	None observed	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Considerable loss of stone support at junction of spillway and buttress and underneath downstream end of buttress.	Repair training wall and downstream support.
DRAINS	N/A	
WATER PASSAGES	N/A	
FOUNDATION	Entire structure is founded on bedrock.	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Surface of dam is eroded exposing the coarse aggregate	
STRUCTURAL CRACKING	Evidence of horizontal cracks or cold construction joints in d/s right end face.	Repair joint
VERTICAL AND HORIZONTAL ALIGNMENT	No indication of horizontal or vertical movement	
MONOLITH JOINTS	N/A	
CONSTRUCTION JOINTS	Vertical joints are eroded to 1-inch deep. No leakage noted. Bottom of weir is undermined at base approximately 2-4 inches all along toe of concrete dam.	

OUTLET WORKS

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT
Canal diversion for Passaic Valley Water Commission.
Canal - good condition

INTAKE STRUCTURE
Building over intake channel
Diversion to canal controlled from gate house.
Channel in good condition.
Channel with cut stone walls

OUTLET STRUCTURE
N/A

OUTLET CHANNEL
Canal to water treatment plant

EMERGENCY GATE
N/A

UNGATED SPILLWAY

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONCRETE WEIR

Good shape

APPROACH CHANNEL

Passaic River

DISCHARGE CHANNEL

Passaic River - open channel, bedrock
channel bottom.

Beattie Mill building adjacent to
right bank d/s

BRIDGE AND PIERS
OVER SPILLWAY

N/A

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

SLOPES

Gradually to moderately sloped. Mill buildings on right side of reservoir; wooded.

SEDIMENTATION

Some sedimentation observed in the reservoir.

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Rocky, well-defined channel	
--	-----------------------------	--

SLOPES	Stable, steep slopes	
--------	----------------------	--

APPROXIMATE NO. OF HOMES AND POPULATION	None threatened	
---	-----------------	--

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Plans from 1945-1946 reconstruction on file at NJDEP, Post Office Box CN-029, Trenton, N.J. 08625
REGIONAL VICINITY MAP	Prepared for this report
CONSTRUCTION HISTORY	No information available on the original construction in 1896 (est.). General information is available, however, in the NJDEP files on the 1945-1946 reconstruction. Copies of this information are included in Appendix 1 of this report.
TYPICAL SECTIONS OF DAM	Dam sections pertinent to the 1945-1946 reconstruction are on file at NJDEP; see "PLAN OF DAM" above.
HYDROLOGIC/HYDRAULIC DATA	84 years of discharge record at U.S.G.S. gage, 0.6 miles downstream of dam. 28,000 cfs in October 1903 is flood of record. No other information disclosed.
OUTLETS - PLAN	Not available
- DETAILS	Not available
- CONSTRAINTS	Not available
- DISCHARGE RATINGS	Not available
RAINFALL/RESERVOIR RECORDS	Not available. Peak stage from 1903 storm 11.1 feet above spillway crest.

ITEM

REMARKS

DESIGN REPORTS

Letters regarding 1945-1946 reconstruction available at NJDEP. See "PLAN OF DAM" on page 2-8.

GEOLOGY REPORTS

Not available

DESIGN COMPUTATIONS
HYDROLOGY & HYDRAULICS
DAM STABILITY
SEEPAGE STUDIES

Not available

2-9

MATERIALS INVESTIGATIONS
BORING RECORDS
LABORATORY
FIELD

Not available

POST-CONSTRUCTION SURVEYS OF DAM

Not available

BORROW SOURCES

Not applicable

ITEMS

REMARKS

SPILLWAY PLAN

SECTIONS

DETAILS

On file at NJDEP. See "PLAN OF DAM" on page 2-8 of this report.

OPERATING EQUIPMENT
PLANS & DETAILS

Not available

REMARKS

ITEM

MONITORING SYSTEMS

None

MODIFICATIONS

Plans for 1945-1946 reconstruction at NJDEP. See "PLAN OF DAM" on page 2-8 of this report.

HIGH POOL RECORDS

October 1903, 11.1 feet over crest of dam. (1945 reconstruction changed stage-discharge relationship.)

POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS

None

PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS

Damaged by high flows in 1945 (see Engineering Data, Appendix 1)

MAINTENANCE OPERATION RECORDS

Not available

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 762 square miles, wetlands,
urban areas, wooded areas

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 156.8 feet NGVD
(1,435 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY) _____
Not applicable

ELEVATION MAXIMUM TEST FLOOD POOL: 171.6 feet NGVD

ELEVATION TOP DAM: 164.1 feet NGVD (4,870 acre-feet)

SPILLWAY CREST: free overflow concrete spillway

- a. Elevation 157.8 feet NGVD (3 foot notch at 156.8)
- b. Type broad-crested
- c. Width 5 feet
- d. Length 267 feet
- e. Location Spillover entire top of dam
- f. Number and Type of Gates None

OUTLET WORKS: gated canal

- a. Type lift gates
- b. Location 300 feet upstream of left abutment
- c. Entrance Invert unknown
- d. Exit Invert unknown

HYDROMETEOROLOGICAL GAGES: None

MAXIMUM NON-DAMAGING DISCHARGE: 12,701 cfs

APPENDIX 3

PHOTOGRAPHS

BEATTIES MILL DAM



April 23, 1981

View along axis of dam from left (north) abutment




April 23, 1981

View of dam and pool area from downstream left bank



April 23, 1981

View of left wingwall and abutment



April 23, 1981

View of right wingwall and abutment. Note low level flow notch.




February 17, 1981

Small overflow spillway in right side, straight section of dam. Note large log in notch.




April 23, 1981

Erosion of training wall adjacent to spillway.




April 23, 1981

Root system visible behind missing stones. Stone block at crest (top of photo) is displaced three inches downward.



April 23, 1981

View of five-inch separation between masonry blocks near the base of the intersection between the training wall and the spillway.



April 23, 1981

Upstream side of intake building for canal to water treatment plant. Note high water mark from 1903 flood to the right of and below the right window.



April 23, 1981

View of canal to water treatment plant from intake building.




April 23, 1981

View of loss of rock support below downstream end
of training wall.

APPENDIX 4

HYDROLOGIC COMPUTATIONS

BEATTIES MILL DAM



NATIONAL PROGRAM OF INSPECTION OF
NON-FED. DAMS
BETTIES MILL DAM

REGIONAL VICINITY MAP
JUNE 1981

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
PHILADELPHIA, PENNSYLVANIA

Anderson-Nichols & Company, Inc.

BOSTON, MA

SCALE IN MILES



MAP BASED ON U.S.G.S. 1:250,000 SERIES SHEET
NK 18-8 SCRANTON, PA., N.Y., N.J. 1962, REVISED
1976, AND NK 18-11 NEWARK, N.J., PA., N.Y. 1944,
REVISED 1969.

JOB NO. _____
 SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 1/4 IN. SCALE


PMF

The PMF is from Passaic River Basin Survey Report for State Resources, Volume 2, Appendix A, Figure A-64. (Report by New York District, Corps of Engineers).


Time (hours) PMF flow at Beatties Dam

13	0	2,300
14	6	2,300
15	12	2,300
16	18	2,300
17	24	2,300
18	30	2,300
19	36	3,000
20	42	7,700
21	48	21,000
22	54	40,000
23	60	60,000
24	66	73,500
25	72	83,500
26	78	88,000
27	84	87,000
28	90	83,500
29	96	77,500
30	102	69,000
31	108	62,000
32	114	54,500
33	120	47,500
34	126	40,500*
35	132	34,000*
36	138	28,000*
37	144	22,000*
38	150	16,000*
39	156	11,000*
	162	6,000*

* Estimates of recession values



ANDERSON - NICHOLS			
VERNON	BOSTON	CONCORD	
<i>Beathies Mill Dam</i>			
<i>Hydraulic Profile</i>			
DATE 7/6/81	SCALE 1" = 20' H 1" = 2' V	JOB NO.	SHEET NO. 23 of 8




JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 1/4 IN. SCALE

Stage Vs Storage

The Passaic River upstream of Beatties Mill Dam is very flat.
 From U.S.G.S. maps, the 160' contour line is 106,000 feet upstream of the dam, and the 180' contour is 158,000 feet upstream. The lowpoint in the reservoir pool is shown to be 148.6' MGD on the plans, with the lowpoint on the low flow weir at 156.8'. Top of dam is 164.1'



Stationing, 1000 ft U/S of dam.

at normal pool (156.8)

Surface area = length x Avg. width
 Length = $\frac{156.8 - 148.6}{160 - 148.6} (106,000) = 76,246$ ft.
 Avg. width = 700 ft
 Area = $(76,246)(700) \text{ ft}^2 = 350.1$ acres

Storage = Area (Avg Depth) = $350.1 \left(\frac{156.8 - 148.6 + 0}{2} \right) = 1,435$ Ac-ft

JOB NO.

SQUARES
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39

at top of dam

$$\begin{aligned} \text{Surface area} &= \text{length} \times \text{Avg. width} \\ \text{Length} &= 106,000 + \frac{4.1}{20} (52,000) \\ &= 116,660 \text{ ft} \\ \text{Avg. width} &= 200 \text{ ft} \\ \text{area} &= 116,660 (200) \left(\frac{1}{43,560} \right) = 536 \text{ ac.} \end{aligned}$$

$$\begin{aligned} \text{Storage} &= \text{Surface area to 160 (Avg. Depth)} + \text{S.A. to 164.1 (Avg. Depth)} \\ &= \frac{106,000 (200) \left(\frac{(164.1-148.6) + (164.1-160)}{2} \right)}{43,560} + \frac{116,660 (200) \left(\frac{(164.1-160) + 0}{2} \right)}{43,560} \\ &= (486.7) (9.8) + 48.9 (2.05) = 4,870 \text{ ac. ft.} \end{aligned}$$


at 175' NGVD

$$\begin{aligned} \text{Storage} &= \frac{106,000 (200) \left(\frac{(175-148.6) + (175-160)}{2} \right)}{43,560} \\ &\quad + \frac{52,000 \left(\frac{15}{20} \right) 200 \left(\frac{(175-160) + 0}{2} \right)}{43,560} \\ &= 486.7 (20.7) + 179.1 (7.5) = 11,418 \text{ ac. ft.} \end{aligned}$$

Stage vs. Storage is plotted on page to HCC-1.

The following points are in:

<u>E (ft NGVD)</u>	<u>Stor (Ac. Ft.)</u>
148.6	0
156.8	1,435
157.8	1,820
160	2,790
162	3,740
164.1	4,870
167	6,410
169	7,600
171	8,830
172	10,160




JOB NO.

SQUARES
7/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29

Overtopping Analysis



1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39

APPENDIX 5

HEC 1 OUTPUT

BEATTIES MILL DAM

HEC-1 INPUT

LINE	ID	1	2	3	4	5	6	7	8	9	10
	ID	BEATTIES MILL DAM	OVERTOPPING ANALYSIS	JOM GOOCH	AMCO						
	IT	0.1	0.25	0.5	1.0	2.0	4.0	8.0	16.0	32.0	64.0
	JR	0.1	0.25	0.5	1.0	2.0	4.0	8.0	16.0	32.0	64.0
		FLOW	0.1	0.25	0.5	1.0	2.0	4.0	8.0	16.0	32.0
7	KK	A1	BEATTIES MILL POND INFLOW HYDROGRAPH								
8	KN	INFLOW FROM PASSAIC RIVER BASIN SURVEY REPORT FOR WATER RESOURCES									
9	KN	360									
10	CI	2300	2300	2300	2300	2300	2300	2300	2300	2300	2300
11	CI	60000	73500	83500	88000	87000	83500	77500	69000	62000	54500
12	CI	47500	40500	34000	28000	22000	16000	11000	6000	2300	4000
13	KS	A2	ROUTE INFLOW HYDROGRAPH THROUGH BEATTIES MILL POND								
14	SV	1	51.8	143.5	279.0	374.0	487.0	641.0	760.0	883.0	1016.0
15	SV	0	148.6	156.8	157.8	162	167	169	171	173	173
16	SV	0	156.8	157.8	160	162	167	169	171	173	173
17	SV	0	156.8	157.8	160	162	167	169	171	173	173
18	SV	0	156.8	157.8	160	162	167	169	171	173	173
19	SV	0	156.8	157.8	160	162	167	169	171	173	173
20	SV	0	156.8	157.8	160	162	167	169	171	173	173
21	SV	0	156.8	157.8	160	162	167	169	171	173	173
22	SV	0	156.8	157.8	160	162	167	169	171	173	173

BEATTIES MILL DAM OVERTOPPING ANALYSIS - TOM GOOCH ANCO
 NEW JERSEY DAM NO. 821 - PASSAIC COUNTY - LITTLE FALLS
 0.1, 0.25, 0.5 MULTIPLES OF THE PMF

8 IO OUTPUT CONTROL VARIABLES PRINT CONTROL
 IPLOT 0 PLOT CONTROL
 IPCAL 0 HYDROGRAPH PLOT SCALE
 DMSC YES PRINT DIAGNOSTIC MESSAGES

9 HYDROGRAPH TIME DATA 60 MINUTES IN COMPUTATION INTERVAL
 IDATE 1 0000 STARTING DATE
 ITIME 200 NUMBER OF HYDROGRAPH ORDINATES
 RDATE 9 0700 ENDING DATE
 RTIME COMPUTATION INTERVAL 1.00 HOURS
 TOTAL TIME BASE 199.00 HOURS

ENGLISH UNITS SQUARE MILES
 DRAINAGE AREA INCHES
 PRECIPITATION DEPTH FEET
 LENGTH, ELEVATION CUMULIC FEET PER SECOND
 SURFACE VOLUME ACRES FEET
 SURFACE AREA ACRES
 TEMPERATURE DEGREES FAHRENHEIT

JP MULTI-PLAN OPTION 1 NUMBER OF PLANS
 JK MULTI-RATIO OPTION 0.50
 RATIOS OF RUNOFF 0.25

7 XK *****
 * A1 *

 BEATTIES MILL POND INFLOW HYDROGRAPH

9 IN INFLOW FROM PASSAIC RIVER BASIN SURVEY REPORT FOR WATER RESOURCES
 TIME DATA FOR INPUT TIME SERIES
 JXMIN 360 TIME INTERVAL IN MINUTES
 JXDATE 1 0 STARTING DATE
 JXTIME STARTING TIME

SUB-BASIN: RUNOFF DATA
 SUBBASIN CHARACTERISTICS 0.0 SUBBASIN AREA ***
 AREA
 PEAK FLOW TIME MAXIMUM AVERAGE FLOW
 (CFS) (HS) (CFS) 24-HR 72-HR 199.00-HR
 8800. 78.00 (INCHES) 87550. 85027. 68854. 31383.
 (AC-F) 43423. 168648. 409707. 516137.
 CUMULATIVE AREA = 0.0 SQ MI

HYDROGRAPH AT STATION = 0.10 A1
FOR PLAN 1, RATIO = 0.10

PEAK FLOW (CFS) 8400.	TIME (HR) 70.00	6-HR 8759.	MAXIMUM AVERAGE FLOW 24-HR 8503.	72-HR 6885.	199.00-HR 3138.
(INCHES) (AC-FT)		0.000 4383.	0.000 16865.	0.000 46974.	0.000 51614.
CUMULATIVE AREA = 0.0 SQ MI					

*** **

HYDROGRAPH AT STATION = 0.25 A1
FOR PLAN 1, RATIO = 0.25

PEAK FLOW (CFS) 22000.	TIME (HR) 78.00	6-HR 21897.	MAXIMUM AVERAGE FLOW 24-HR 21257.	72-HR 17213.	199.00-HR 7865.
(INCHES) (AC-FT)		0.000 10859.	0.000 42162.	0.000 102425.	0.000 129029.
CUMULATIVE AREA = 0.0 SQ MI					

*** **

HYDROGRAPH AT STATION = 0.50 A1
FOR PLAN 1, RATIO = 0.50

PEAK FLOW (CFS) 44000.	TIME (HR) 78.00	6-HR 43714.	MAXIMUM AVERAGE FLOW 24-HR 42514.	72-HR 34426.	199.00-HR 15691.
(INCHES) (AC-FT)		0.000 21717.	0.000 84325.	0.000 204852.	0.000 258062.
CUMULATIVE AREA = 0.0 SQ MI					

*** **

* A2 *

13 KK ROUTE INFLOW HYDROGRAPH THROUGH BEATTIES MILL POND

HYDROGRAPH ROUTING DATA

14 PS	STORAGE ROUTING HYDROTYPE RSVRIC X	1435.00	NUMBER OF SUBREACHES TYPE OF INITIAL CONDITION INITIAL CONDITION WORKING R AND D COEFFICIENT	1820.0	2790.0	3740.0	4870.0	7600.0	8830.0	10160.0
15 SV	STORAGE	0.0	1435.0	156.80	160.00	162.00	164.10	167.00	171.00	173.00
16 SE	ELEVATION	0.0	0.0	9.0	2636.0	6924.0	12701.0	22822.0	40701.0	51286.0
17 SC	DISCHARGE	148.60	156.80	157.80	160.00	162.00	164.10	167.00	171.00	173.00
18 SE	ELEVATION	148.60	156.80	157.80	160.00	162.00	164.10	167.00	171.00	173.00
19 SS	SPILLWAY CREL SPWID CROW EXPW	156.80 267.00 3.00 1.50	SPILLWAY CREST ELEVATION SPILLWAY WIDTH WEIR COEFFICIENT EXPONENT OF HEAD	1820.0	2790.0	3740.0	4870.0	7600.0	8830.0	10160.0
20 ST	TOP OF DAM TOP OF TUNNEL DAM WID CROW EXPW	164.10 287.00 0.0 1.50	ELEVATION AT TOP OF DAM DAM WIDTH WEIR COEFFICIENT EXPONENT OF HEAD	1820.0	2790.0	3740.0	4870.0	7600.0	8830.0	10160.0

COMPUTED STORAGE-OUTFLOW CURVE
 STORAGE 0.0 1435.00 1820.00 2790.00 3740.00 4870.00 6410.00 7600.00 8830.00 10160.00
 OUTFLOW 0.0 0.0 9.00 2636.00 6924.00 12701.00 22822.00 31210.00 40701.00 51286.00

HYDROGRAPH AT STATION A2
 FOR PLAN 1, RATIO = 0.10

PEAK OUTFLOW IS 8730. AT TIME 82.00 HOURS

PEAK FLOW (CFS) 8730.	6-HR 8716 0.000 4322.	MAXIMUM AVERAGE FLOW 24-HR 8471. 72-HR 6859. 0.000 40816.	199.00-HR 3110. 0.000 51146.
PEAK STORAGE (AC-FT) 4(93).	6-HR 4091.	MAXIMUM AVERAGE STORAGE 24-HR 4042. 72-HR 3710.	199.00-HR 2705.
PEAK STAGE (FEET) 162.66	6-HR 162.65	MAXIMUM AVERAGE STAGE 24-HR 162.56 72-HR 161.90	199.00-HR 159.73

CUMULATIVE AREA = 0.0 SQ MI

HYDROGRAPH AT STATION A2
 FOR PLAN 1, RATIO = 0.25

PEAK OUTFLOW IS 21669. AT TIME 81.00 HOURS

PEAK FLOW
 (CFS)
 1169.

TIME
 (HR)
 81.00

(INCHES)
 (AC-FT)

6-HR
 21834.
 0.000
 10827.

MAXIMUM AVERAGE FLOW
 24-HR
 21208.
 0.000
 42065.

199.00-HR
 7809.
 0.000
 128436.

PEAK STORAGE
 (AC-FT)
 6725.

TIME
 (HR)
 81.00

6-HR
 6220.

MAXIMUM AVERAGE STORAGE
 24-HR
 6164.
 5540.

199.00-HR
 3635.

PEAK STAGE
 (FEET)
 166.73

TIME
 (HR)
 91.00

6-HR
 166.72

MAXIMUM AVERAGE STAGE
 24-HR
 166.54
 165.56

199.00-HR
 161.56

CUMULATIVE AREA = 0.0 SQ MI

*** **

HYDROGRAPH AT STATION A2
 FOR PLAN 1, RATIO = 0.50

PEAK OUTFLOW IS 43785. AT TIME 81.00 HOURS

PEAK FLOW
 (CFS)
 43785.

TIME
 (HR)
 81.00

(INCHES)
 (AC-FT)

6-HR
 43700.
 0.000
 21669.

MAXIMUM AVERAGE FLOW
 24-HR
 42444.
 0.000
 84187.

199.00-HR
 15642.
 0.000
 257257.

PEAK STORAGE
 (AC-FT)
 9214.

TIME
 (HR)
 81.00

6-HR
 9207.

MAXIMUM AVERAGE STORAGE
 24-HR
 9049.
 7982.

199.00-HR
 4876.

PEAK STAGE
 (FEET)
 171.56

TIME
 (HR)
 81.00

6-HR
 171.56

MAXIMUM AVERAGE STAGE
 24-HR
 171.52
 169.59

199.00-HR
 163.82

CUMULATIVE AREA = 0.0 SQ MI

*** **

PEAK FLOW AND STAGE (END-OF-PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND, AREA IN SQUARE MILES
 TIME TO PEAK IN HOURS

OPERATION	STATION	AREA	PLAN	FLOW TIME	RATIOS APPLIED TO FLOWS		
					RATIO 1 0.10	RATIO 2 0.25	RATIO 3 0.50
HYDROGRAPH AT	A1	0.0	1	800 78.00	22000 78.00	4000 78.00	
ROUTED TO	A2	0.0	1	820 81.00	21862 81.00	43785 81.00	
			** PEAK STAGES IN FEET **				
			1	162.68	166.73	171.58	
				82.00	81.00	81.00	

SUMMARY OF DAM OVERTOPPING/BREACH ANALYSIS FOR STATION A2

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM					
		156.80	156.80	164.10					
		1435.0	1435.0	4870.0					
				12701.0					
	RATIO OF P.H.F	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS		
	0.10	0.0	4093.	8730.	0.0	82.00	0.0		
	0.25	2.63	6265.	21829.	60.00	81.00	0.0		
	0.50	7.48	9218.	43765.	91.00	81.00	0.0		

*** NORMAL END OF JOB ***

 * U.S. ARMY CORPS OF ENGINEERS *
 * THE HYDROLOGIC ENGINEERING CENTER *
 * 609 SECOND STREET *
 * DAVIS, CALIFORNIA 95616 *
 * (916) 440-3285 DR (FTS) 448-3285 *

 * FLUGG HYDROGRAPH PACKAGE (HEC-1) *
 * FEBRUARY 1981 *
 * RUN DATE 07/07/81 TIME 13.07.24 *

BEATTIES MILL DAM OVERTOPPING ANALYSIS TOM GOOCH ANCO
 NEW JERSEY DAM NO. R21 - PASSAIC COUNTY - LITTLE FALLS
 0.5 MULTIPLE OF THE PMF

5 IO OUTPUT CONTROL VARIABLES PRINT CONTROL
 IPRINT 1 PLOT CONTROL
 IPLOT 1 HYDROGRAPH PLOT SCALE
 QSCALE 0 PRINT DIAGNOSTIC MESSAGES
 DMSG YES

IT HYDROGRAPH TIME DATA 60 MINUTES IN COMPUTATION INTERVAL
 ICAFE 1 0000 STARTING DATE
 ITIME 200 NUMBER OF HYDROGRAPH ORDINATES
 NDDATE 9 0700 ENDING DATE
 NDTIME COMPUTATION INTERVAL 1.00 HOURS
 TOTAL TIME BASE 199.00 HOURS

ENGLISH UNITS
 DRAINAGE AREA SQUARE MILES
 PRECIPITATION DEPTH INCHES
 LENGTH, ELEVATION FEET
 FLOW CUBIC FEET PER SECOND
 STORAGE VOLUME ACRES-FEET
 SURFACE AREA ACRES
 TEMPERATURE DEGREES FAHRENHEIT

JP MULTI-PLAN OPTION 1 NUMBER OF PLANS
 JR MULTI-RATIO OPTION
 RATIOS OF RUNOFF 0.50

 * A1 *

 BEATTIES MILL POND. INFLOW HYDROGRAPH

INFLOW FROM PASSAIC RIVER BASIN SURVEY REPORT FOR WATER RESOURCES

9 IN TIME DATA FOR INPUT TIME SERIES
 JXMIN 360 TIME INTERVAL IN MINUTES
 JXDATE 1 0 STARTING DATE
 JXTIME 0 STARTING TIME

0 BA SUBBASIN CHARACTERISTICS SUBBASIN AREA
 AREA 0.0

HYDROGRAPH AT STATION AI

DA	MON	HRMN	ORD	FLOW	DA	MON	HRMN	ORD	FLOW	DA	MON	HPMN	ORD	FLOW
1	1	000	1	2300	5	5	050	10	7333	7	7	060	15	1633
1	1	000	2	2300	5	5	050	11	5000	7	7	070	16	1900
1	1	000	3	2300	5	5	070	12	3689	7	7	090	17	2900
1	1	000	4	2300	5	5	070	13	3683	7	7	100	18	4300
1	1	000	5	2300	5	5	080	14	4000	7	7	110	19	6667
1	1	000	6	2300	5	5	080	15	4333	7	7	120	20	6433
1	1	000	7	2300	5	5	090	16	4667	7	7	130	21	6200
1	1	000	8	2300	5	5	090	17	5000	7	7	140	22	6200
1	1	000	9	2300	5	5	100	18	5667	7	7	150	23	6200
1	1	000	10	2300	5	5	110	19	6200	7	7	160	24	6200
1	1	000	11	2300	5	5	110	20	6200	7	7	170	25	6200
1	1	000	12	2300	5	5	120	21	6200	7	7	180	26	6200
1	1	000	13	2300	5	5	130	22	6200	7	7	190	27	6200
1	1	000	14	2300	5	5	140	23	6200	7	7	200	28	6200
1	1	000	15	2300	5	5	150	24	6200	7	7	210	29	6200
1	1	000	16	2300	5	5	160	25	6200	7	7	220	30	6200
1	1	000	17	2300	5	5	170	26	6200	7	7	230	31	6200
1	1	000	18	2300	5	5	180	27	6200	7	7	240	32	6200
1	1	000	19	2300	5	5	190	28	6200	7	7	250	33	6200
1	1	000	20	2300	5	5	200	29	6200	7	7	260	34	6200
1	1	000	21	2300	5	5	210	30	6200	7	7	270	35	6200
1	1	000	22	2300	5	5	220	31	6200	7	7	280	36	6200
1	1	000	23	2300	5	5	230	32	6200	7	7	290	37	6200
1	1	000	24	2300	5	5	240	33	6200	7	7	300	38	6200
1	1	000	25	2300	5	5	250	34	6200	7	7	310	39	6200
1	1	000	26	2300	5	5	260	35	6200	7	7	320	40	6200
1	1	000	27	2300	5	5	270	36	6200	7	7	330	41	6200
1	1	000	28	2300	5	5	280	37	6200	7	7	340	42	6200
1	1	000	29	2300	5	5	290	38	6200	7	7	350	43	6200
1	1	000	30	2300	5	5	300	39	6200	7	7	360	44	6200
1	1	000	31	2300	5	5	310	40	6200	7	7	370	45	6200
1	1	000	32	2300	5	5	320	41	6200	7	7	380	46	6200
1	1	000	33	2300	5	5	330	42	6200	7	7	390	47	6200
1	1	000	34	2300	5	5	340	43	6200	7	7	400	48	6200
1	1	000	35	2300	5	5	350	44	6200	7	7	410	49	6200
1	1	000	36	2300	5	5	360	45	6200	7	7	420	50	6200
1	1	000	37	2300	5	5	370	46	6200	7	7	430	51	6200
1	1	000	38	2300	5	5	380	47	6200	7	7	440	52	6200
1	1	000	39	2300	5	5	390	48	6200	7	7	450	53	6200
1	1	000	40	2300	5	5	400	49	6200	7	7	460	54	6200
1	1	000	41	2300	5	5	410	50	6200	7	7	470	55	6200
1	1	000	42	2300	5	5	420	51	6200	7	7	480	56	6200
1	1	000	43	2300	5	5	430	52	6200	7	7	490	57	6200
1	1	000	44	2300	5	5	440	53	6200	7	7	500	58	6200
1	1	000	45	2300	5	5	450	54	6200	7	7	510	59	6200
1	1	000	46	2300	5	5	460	55	6200	7	7	520	60	6200
1	1	000	47	2300	5	5	470	56	6200	7	7	530	61	6200
1	1	000	48	2300	5	5	480	57	6200	7	7	540	62	6200
1	1	000	49	2300	5	5	490	58	6200	7	7	550	63	6200
1	1	000	50	2300	5	5	500	59	6200	7	7	560	64	6200
1	1	000	51	2300	5	5	510	60	6200	7	7	570	65	6200
1	1	000	52	2300	5	5	520	61	6200	7	7	580	66	6200
1	1	000	53	2300	5	5	530	62	6200	7	7	590	67	6200
1	1	000	54	2300	5	5	540	63	6200	7	7	600	68	6200
1	1	000	55	2300	5	5	550	64	6200	7	7	610	69	6200
1	1	000	56	2300	5	5	560	65	6200	7	7	620	70	6200
1	1	000	57	2300	5	5	570	66	6200	7	7	630	71	6200
1	1	000	58	2300	5	5	580	67	6200	7	7	640	72	6200
1	1	000	59	2300	5	5	590	68	6200	7	7	650	73	6200
1	1	000	60	2300	5	5	600	69	6200	7	7	660	74	6200
1	1	000	61	2300	5	5	610	70	6200	7	7	670	75	6200
1	1	000	62	2300	5	5	620	71	6200	7	7	680	76	6200
1	1	000	63	2300	5	5	630	72	6200	7	7	690	77	6200
1	1	000	64	2300	5	5	640	73	6200	7	7	700	78	6200
1	1	000	65	2300	5	5	650	74	6200	7	7	710	79	6200
1	1	000	66	2300	5	5	660	75	6200	7	7	720	80	6200
1	1	000	67	2300	5	5	670	76	6200	7	7	730	81	6200
1	1	000	68	2300	5	5	680	77	6200	7	7	740	82	6200
1	1	000	69	2300	5	5	690	78	6200	7	7	750	83	6200
1	1	000	70	2300	5	5	700	79	6200	7	7	760	84	6200
1	1	000	71	2300	5	5	710	80	6200	7	7	770	85	6200
1	1	000	72	2300	5	5	720	81	6200	7	7	780	86	6200
1	1	000	73	2300	5	5	730	82	6200	7	7	790	87	6200
1	1	000	74	2300	5	5	740	83	6200	7	7	800	88	6200
1	1	000	75	2300	5	5	750	84	6200	7	7	810	89	6200
1	1	000	76	2300	5	5	760	85	6200	7	7	820	90	6200
1	1	000	77	2300	5	5	770	86	6200	7	7	830	91	6200
1	1	000	78	2300	5	5	780	87	6200	7	7	840	92	6200
1	1	000	79	2300	5	5	790	88	6200	7	7	850	93	6200
1	1	000	80	2300	5	5	800	89	6200	7	7	860	94	6200
1	1	000	81	2300	5	5	810	90	6200	7	7	870	95	6200
1	1	000	82	2300	5	5	820	91	6200	7	7	880	96	6200
1	1	000	83	2300	5	5	830	92	6200	7	7	890	97	6200
1	1	000	84	2300	5	5	840	93	6200	7	7	900	98	6200
1	1	000	85	2300	5	5	850	94	6200	7	7	910	99	6200
1	1	000	86	2300	5	5	860	95	6200	7	7	920	100	6200
1	1	000	87	2300	5	5	870	96	6200	7	7	930	101	6200
1	1	000	88	2300	5	5	880	97	6200	7	7	940	102	6200
1	1	000	89	2300	5	5	890	98	6200	7	7	950	103	6200
1	1	000	90	2300	5	5	900	99	6200	7	7	960	104	6200
1	1	000	91	2300	5	5	910	100	6200	7	7	970	105	6200
1	1	000	92	2300	5	5	920	101	6200	7	7	980	106	6200
1	1	000	93	2300	5	5	930	102	6200	7	7	990	107	6200
1	1	000	94	2300	5	5	940	103	6200	7	7	1000	108	6200
1	1	000	95	2300	5	5	950	104	6200	7	7	1010	109	6200
1	1	000	96	2300	5	5	960	105	6200	7	7	1020	110	6200
1	1	000	97	2300	5	5	970	106	6200	7	7	1030	111	6200
1	1	000	98	2300	5	5	980	107	6200	7	7	1040	112	6200
1	1	000	99	2300	5	5	990	108	6200	7	7	1050	113	6200
1	1	000	100	2300	5	5	1000	109	6200	7	7	1060	114	6200
1	1	000	101	2300	5	5	1010	110	6200	7	7	1070	115	6200
1	1	000	102	2300	5	5	1020	111	6200	7	7	1080	116	6200
1	1	000	103	2300	5	5	1030	112	6200	7	7	1090	117	6200
1	1	000	104	2300	5	5	1040	113	6200	7	7	1100	118	6200
1	1	000	105	2300	5	5	1050	114	6200	7	7	1110	119	6200
1	1	000	106	2300	5	5	1060	115	6200	7	7	1120	120	6200
1	1	000	107	2300	5	5	1070	116	6200	7	7	1130	121	620

PEAK FLOW
(CFS)
86006.

TIME
(HR)
78.00

MAXIMUM AVERAGE FLOW
24-HR
87590.
6-HR
85027.
16R64R.
0.000
43433.

199.00-HR
31383.
0.000
516137.

CUMULATIVE AREA = 0.0 SQ MI

HYDROGRAPH AT STATION = 0.50
PLAN 1,

DA	MON	HRMN	GRD	FLOW (INCHES) (AC-FT)	DA	MON	HRMN	GRD	FLOW	DA	MON	HRMN	GRD	FLOW	DA	MON	HRMN	GRD	FLOW
1	1	000	1	1150.	5	5	0400	101	13667.	7	7	0600	151	8000.					
2	1	100	3	1150.	5	5	0500	102	15250.	7	7	0700	152	7583.					
3	1	200	3	1150.	5	5	0600	103	16433.	7	7	0800	153	7167.					
4	1	300	3	1150.	5	5	0700	104	18417.	7	7	0900	154	6337.					
5	1	400	3	1150.	5	5	0800	105	20000.	7	7	1000	155	5504.					
6	1	500	3	1150.	5	5	0900	106	22333.	7	7	1100	156	5047.					
7	1	000	3	1150.	5	5	1000	107	25000.	7	7	1200	157	4667.					
8	1	100	3	1150.	5	5	1100	108	28667.	7	7	1300	158	4337.					
9	1	200	3	1150.	5	5	1200	109	33000.	7	7	1400	159	4067.					
10	1	300	3	1150.	5	5	1300	111	38333.	7	7	1500	160	3837.					
11	1	400	3	1150.	5	5	1400	111	41250.	7	7	1600	161	3637.					
12	1	500	3	1150.	5	5	1500	111	45000.	7	7	1700	162	3437.					
13	1	000	3	1150.	5	5	1600	111	49750.	7	7	1800	163	3237.					
14	1	100	3	1150.	5	5	1700	111	55000.	7	7	1900	164	3037.					
15	1	200	3	1150.	5	5	1800	111	60750.	7	7	2000	165	2837.					
16	1	300	3	1150.	5	5	1900	111	67000.	7	7	2100	166	2637.					
17	1	400	3	1150.	5	5	2000	111	73750.	7	7	2200	167	2437.					
18	1	500	3	1150.	5	5	2100	111	81000.	7	7	2300	168	2237.					
19	1	000	3	1150.	5	5	2200	111	89750.	7	7	2400	169	2037.					
20	1	100	3	1150.	5	5	2300	112	99000.	8	8	0100	170	1837.					
21	1	200	3	1150.	5	5	2400	112	109750.	8	8	0200	171	1637.					
22	1	300	3	1150.	5	5	2500	112	121000.	8	8	0300	172	1437.					
23	1	400	3	1150.	5	5	2600	112	133750.	8	8	0400	173	1237.					
24	1	500	3	1150.	5	5	2700	112	148000.	8	8	0500	174	1037.					
25	1	000	4	1150.	5	5	2800	112	163750.	8	8	0600	175	837.					
26	1	100	4	1150.	5	5	2900	112	181000.	8	8	0700	176	637.					
27	1	200	4	1150.	5	5	3000	112	199750.	8	8	0800	177	437.					
28	1	300	4	1150.	5	5	3100	112	220000.	8	8	0900	178	237.					
29	1	400	4	1150.	5	5	3200	113	241750.	8	8	1000	179	37.					
30	1	500	4	1150.	5	5	3300	113	265000.	8	8	1100	180	37.					
31	2	000	4	1150.	5	5	3400	113	290750.	8	8	1200	181	37.					
32	2	100	4	1150.	5	5	3500	113	318000.	8	8	1300	182	37.					
33	2	200	4	1150.	5	5	3600	113	346750.	8	8	1400	183	37.					
34	2	300	4	1150.	5	5	3700	113	377000.	8	8	1500	184	37.					
35	2	400	4	1150.	5	5	3800	113	409750.	8	8	1600	185	37.					
36	2	500	4	1150.	5	5	3900	113	445000.	8	8	1700	186	37.					
37	2	000	4	1150.	5	5	4000	113	482750.	8	8	1800	187	37.					
38	2	100	4	1150.	5	5	4100	113	523000.	8	8	1900	188	37.					
39	2	200	4	1150.	5	5	4200	114	565750.	8	8	2000	189	37.					
40	2	300	4	1150.	5	5	4300	114	611000.	8	8	2100	190	37.					
41	2	400	4	1150.	5	5	4400	114	658750.	8	8	2200	191	37.					
42	2	500	4	1150.	5	5	4500	114	709000.	8	8	2300	192	37.					
43	2	000	4	1150.	5	5	4600	114	762750.	8	8	2400	193	37.					
44	2	100	4	1150.	5	5	4700	114	819000.	8	8	2500	194	37.					
45	2	200	4	1150.	5	5	4800	114	878750.	8	8	2600	195	37.					
46	2	300	4	1150.	5	5	4900	114	941000.	8	8	2700	196	37.					
47	2	400	4	1150.	5	5	5000	114	1006750.	8	8	2800	197	37.					
48	2	500	4	1150.	5	5	0100	114	1077000.	8	8	2900	198	37.					
49	2	000	5	10500.	5	5	0200	114	1150000.	8	8	3000	199	37.					
50	2	100	5	12083.	5	5	0300	115	1230000.	8	8	0100	200	37.					

HYDROGRAPH AT STATION A2
PLAN 1, RATIO = 0.50

A	PEN	HRMN	ORD	OUTFLOW	STORAGE	STAGE	DA	MON	HRMN	ORD	OUTFLOW	STORAGE	STAGE	DA	MON	HRMN	ORD	OUTFLOW	STORAGE	STA
000	1	1000	68	36017.	8223.	170.4	0	0	1400	135	16946.	515.	165	6	0	1400	135	16946.	515.	165
000	2	2000	69	36976.	8347.2	170.2	0.2	0.2	1500	136	16435.	54364.	165	6	0.2	1500	136	16435.	54364.	165
000	3	2100	70	37874.	8467.6	170.6	0.6	0.6	1600	137	15929.	55284.	165	6	0.6	1600	137	15929.	55284.	165
000	4	2200	71	38741.	8576.0	170.8	0.8	0.8	1700	138	14922.	56202.	165	6	0.8	1700	138	14922.	56202.	165
000	5	2300	72	39591.	8686.2	170.9	0.9	0.9	1800	139	14421.	57117.	165	6	0.9	1800	139	14421.	57117.	165
000	6	0100	73	40433.	8799.1	171.1	1.2	1.2	0200	140	13921.	58029.	165	6	1.2	0200	140	13921.	58029.	165
000	7	0300	74	41171.	8916.2	171.3	1.3	1.3	0400	141	13421.	58947.	165	6	1.3	0400	141	13421.	58947.	165
000	8	0500	75	422207.	9031.9	171.4	1.4	1.4	0600	142	12921.	59862.	165	6	1.4	0600	142	12921.	59862.	165
000	9	0400	76	43030.	9142.4	171.5	1.5	1.5	0700	143	12421.	60774.	165	6	1.5	0700	143	12421.	60774.	165
000	10	0600	77	43747.	9251.3	171.6	1.6	1.6	0800	144	11921.	61683.	165	6	1.6	0800	144	11921.	61683.	165
000	11	0700	78	443685.	9359.7	171.7	1.7	1.7	0900	145	11421.	62589.	165	6	1.7	0900	145	11421.	62589.	165
000	12	0800	79	450775.	9467.5	171.8	1.8	1.8	1000	146	10921.	63492.	165	6	1.8	1000	146	10921.	63492.	165
000	13	0900	80	45778.	9574.5	171.9	1.9	1.9	1100	147	10421.	64392.	165	6	1.9	1100	147	10421.	64392.	165
000	14	1000	81	46477.	9681.1	172.0	2.0	2.0	1200	148	9921.	65289.	165	6	2.0	1200	148	9921.	65289.	165
000	15	1100	82	47178.	9787.7	172.1	2.1	2.1	1300	149	9421.	66183.	165	6	2.1	1300	149	9421.	66183.	165
000	16	1200	83	47877.	9893.9	172.2	2.2	2.2	1400	150	8921.	67074.	165	6	2.2	1400	150	8921.	67074.	165
000	17	1300	84	48576.	10000.	172.3	2.3	2.3	1500	151	8421.	67962.	165	6	2.3	1500	151	8421.	67962.	165
000	18	1400	85	49274.	10106.	172.4	2.4	2.4	1600	152	7921.	68847.	165	6	2.4	1600	152	7921.	68847.	165
000	19	1500	86	50000.	10212.	172.5	2.5	2.5	1700	153	7421.	69729.	165	6	2.5	1700	153	7421.	69729.	165
000	20	1600	87	50748.	10319.	172.6	2.6	2.6	1800	154	6921.	70608.	165	6	2.6	1800	154	6921.	70608.	165
000	21	1700	88	51510.	10427.	172.7	2.7	2.7	1900	155	6421.	71484.	165	6	2.7	1900	155	6421.	71484.	165
000	22	1800	89	52286.	10536.	172.8	2.8	2.8	2000	156	5921.	72357.	165	6	2.8	2000	156	5921.	72357.	165
000	23	1900	90	53077.	10646.	172.9	2.9	2.9	2100	157	5421.	73227.	165	6	2.9	2100	157	5421.	73227.	165
000	24	2000	91	53883.	10757.	173.0	3.0	3.0	2200	158	4921.	74094.	165	6	3.0	2200	158	4921.	74094.	165
000	25	2100	92	54704.	10869.	173.1	3.1	3.1	2300	159	4421.	74958.	165	6	3.1	2300	159	4421.	74958.	165
000	26	2200	93	55540.	10983.	173.2	3.2	3.2	2400	160	3921.	75819.	165	6	3.2	2400	160	3921.	75819.	165
000	27	2300	94	56391.	11099.	173.3	3.3	3.3	2500	161	3421.	76677.	165	6	3.3	2500	161	3421.	76677.	165
000	28	2400	95	57257.	11217.	173.4	3.4	3.4	2600	162	2921.	77532.	165	6	3.4	2600	162	2921.	77532.	165
000	29	2500	96	58138.	11337.	173.5	3.5	3.5	2700	163	2421.	78384.	165	6	3.5	2700	163	2421.	78384.	165
000	30	2600	97	59034.	11459.	173.6	3.6	3.6	2800	164	1921.	79233.	165	6	3.6	2800	164	1921.	79233.	165
000	31	2700	98	59945.	11583.	173.7	3.7	3.7	2900	165	1421.	80079.	165	6	3.7	2900	165	1421.	80079.	165
000	32	2800	99	60871.	11709.	173.8	3.8	3.8	3000	166	921.	80922.	165	6	3.8	3000	166	921.	80922.	165
000	33	2900	100	61812.	11837.	173.9	3.9	3.9	3100	167	421.	81762.	165	6	3.9	3100	167	421.	81762.	165
000	34	3000	101	62768.	11967.	174.0	4.0	4.0	3200	168	0.	82599.	165	6	4.0	3200	168	0.	82599.	165
000	35	3100	102	63740.	12099.	174.1	4.1	4.1	3300	169	0.	83433.	165	6	4.1	3300	169	0.	83433.	165
000	36	3200	103	64727.	12233.	174.2	4.2	4.2	3400	170	0.	84264.	165	6	4.2	3400	170	0.	84264.	165
000	37	3300	104	65729.	12369.	174.3	4.3	4.3	3500	171	0.	85092.	165	6	4.3	3500	171	0.	85092.	165
000	38	3400	105	66746.	12507.	174.4	4.4	4.4	3600	172	0.	85917.	165	6	4.4	3600	172	0.	85917.	165
000	39	3500	106	67778.	12647.	174.5	4.5	4.5	3700	173	0.	86739.	165	6	4.5	3700	173	0.	86739.	165
000	40	3600	107	68825.	12789.	174.6	4.6	4.6	3800	174	0.	87558.	165	6	4.6	3800	174	0.	87558.	165
000	41	3700	108	69887.	12933.	174.7	4.7	4.7	3900	175	0.	88374.	165	6	4.7	3900	175	0.	88374.	165
000	42	3800	109	70964.	13079.	174.8	4.8	4.8	4000	176	0.	89187.	165	6	4.8	4000	176	0.	89187.	165
000	43	3900	110	72056.	13227.	174.9	4.9	4.9	4100	177	0.	89997.	165	6	4.9	4100	177	0.	89997.	165
000	44	4000	111	73163.	13377.	175.0	5.0	5.0	4200	178	0.	90804.	165	6	5.0	4200	178	0.	90804.	165
000	45	4100	112	74285.	13529.	175.1	5.1	5.1	4300	179	0.	91608.	165	6	5.1	4300	179	0.	91608.	165
000	46	4200	113	75422.	13683.	175.2	5.2	5.2	4400	180	0.	92409.	165	6	5.2	4400	180	0.	92409.	165
000	47	4300	114	76574.	13839.	175.3	5.3	5.3	4500	181	0.	93207.	165	6	5.3	4500	181	0.	93207.	165
000	48	4400	115	77741.	13997.	175.4	5.4	5.4	4600	182	0.	94002.	165	6	5.4	4600	182	0.	94002.	165
000	49	4500	116	78923.	14157.	175.5	5.5	5.5	4700	183	0.	94794.	165	6	5.5	4700	183	0.	94794.	165
000	50	4600	117	80120.	14319.	175.6	5.6	5.6	4800	184	0.	95583.	165	6	5.6	4800	184	0.	95583.	165
000	51	4700	118	81332.	14483.	175.7	5.7	5.7	4900	185	0.	96369.	165	6	5.7	4900	185	0.	96369.	165
000	52	4800	119	82559.	14649.	175.8	5.8	5.8	5000	186	0.	97152.	165	6	5.8	5000	186	0.	97152.	165
000	53	4900	120	83801.	14817.	175.9	5.9	5.9	5100	187	0.	97932.	165	6	5.9	5100	187	0.	97932.	165
000	54	5000	121	85058.	14987.	176.0	6.0	6.0	5200	188	0.	98709.	165	6	6.0	5200	188	0.	98709.	165
000	55	5100	122	86330.	15159.	176.1	6.1	6.1	5300	189	0.	99483.	165	6	6.1	5300	189	0.	99483.	165
000	56	5200	123	87617.	15333.	176.2	6.2	6.2	5400	190	0.	100254.	165	6	6.2	5400	190	0.	100254.	165
000	57	5300	124	88919.	15509.	176.3	6.3	6.3	5500	191	0.	101022.	165	6	6.3	5500	191	0.	101022.	165
000	58	5400	125	90236.	15687.	176.4	6.4	6.4	5600	192	0.	101787.	165	6	6.4	5600	192	0.	101787.	165
000	59	5500	126	91568.	15867.	176.5	6.5	6.5	5700	193	0.	102549.	165	6	6.5	5700	193	0.	102549.	165

EAK OUTFLOW IS 43785. AT TIME 81.00 HOURS

PEAK FLOW (CFS) 43785.	TIME (HR) 81.00	(INCHES) (AC-FT)	6-HR 43700. 0.000 21669.	MAXIMUM AVERAGE FLOW 24-HR 42444. 0.000 84187.	72-HR 34374. 0.000 204538.	199.00-HR 15642. 0.000 257257.
EAK STORAGE (AC-FT) 5218.	TIME (HR) 81.00		6-HR 9207.	MAXIMUM AVERAGE STORAGE 24-HR 9049.	72-HR 7982.	199.00-HR 4876.
PEAK STAGE (FEET) 171.58	TIME (HR) 81.00		6-HR 171.56	MAXIMUM AVERAGE STAGE 24-HR 171.32	72-HR 169.59	199.00-HR 163.82

CUMULATIVE AREA = 0.0 SQ MI

PEAK FLOW AND STAGE (LONG-TERM PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND, AREA IN SQUARE MILES
 TIME TO PEAK IN HOURS

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO
HYDROGRAPH AT	A1	0.0	1	0.50
				44000
				78.00
ROUTED TO	A2	0.0	1	43785
				81.00

** PEAK STAGES IN FEET **
 1 171.58
 1 81.00

APPENDIX 6

REFERENCES

BEATTIES MILL DAM

APPENDIX 6
REFERENCES

BEATTIES MILL DAM

Chow, Ven Te, Open Channel Hydraulics, McGraw Hill Book Company, New York, 1959.

King, H.W. and E.F. Brater, Handbook of Hydraulics, McGraw Hill Book Company, New York, Fifth Edition 1963.

Lewis, J.V. and H.B. Kummel (1910-1912) Geologic Map of New Jersey, revised by H.B. Kummel, 1931, and by M.E. Johnson, 1950. New Jersey Department of Conservation of Economic Development Atlas.

Schway, G.O., R.K. Frevert, T.W. Edmister, and K.K. Barnes, Soil and Water Conservation Engineering, The Ferguson Foundation Agricultural Engineering Series, John Wiley and Sons, Inc., New York, 1966, 683 pp.

U.S. Army Corps of Engineers, Hydrologic Engineering Center, Flood Hydrograph Package (HEC-1) Users Manual, (Preliminary), Davis, California, March 1981.

U.S. Army Corps of Engineers, New York District, Passaic River Basin, New Jersey and New York, Survey Report for Water Resources, June, 1972.

U.S. Department of Agriculture, Soil Conservation Service, Urban Hydrology for Small Watersheds, Technical Release No. 55, Washington, 1975.

U.S. Department of Commerce, Weather Bureau, "Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1000 Square Miles and Durations of 6, 12, 24, and 48 Hours", Hydrometeorological Report No. 33, Washington.

United States Department of Interior, Bureau of Reclamation, Design of Small Dams, U.S. Government Printing Office, Washington, 1977, 816 pp.

U.S. Department of the Interior, Geological Survey, Water Resources Data for New Jersey, Volume 1, Atlantic Slope Basins, Hudson River to Cape May, Water Year 1979.

U.S. Department of Interior, Geological Survey, 7.5-Minute Series (topographic) maps, scale 1:24000, Contour Interval 10 feet: New Brunswick, New Jersey, (1954), Photorevised 1970.

Viessman, Warren, Jr., J.W. Knapp, G.L. Lewis, T.E. Harbaugh, Introduction to Hydrology, Harper and Row, Publishers, New York, Second Edition 1977, 704 pp.

DATE
ILME