

AD-A105 743

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM SAFETY PROGRAM, EARL RESERVOIR DAM (INVENTORY NUMB--ETC(U)
JUN 81 G KESTER

F/G 13/13

DACW51-81-C-0010

NL

UNCLASSIFIED

1 of 2

ALL RIGHTS RESERVED



LEVEL #



P.S

DTIC FILE COPY

AD A 1 0 5 7 4 3


LOWER HUDSON RIVER BASIN

EARL RESERVOIR DAM

ORANGE COUNTY, NEW YORK

INVENTORY NO. N.Y. 203

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED

DTIC
ELECTE
OCT 19 1981

D

NEW YORK DISTRICT CORPS OF ENGINEERS

JUNE 1981

10 10 19

DTIC FILE COPY

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A105743	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Earl Reservoir Dam Lower Hudson River Basin, Orange County, NY Inventory No. 203		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) GRANVILLE KESTER, JR.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Michael Baker, Jr. Inc. 4301 Dutch Ridge Road Box 280 Beaver, PA 15009 (10) Granville		8. CONTRACT OR GRANT NUMBER(s) DACW51-81-C-0010
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287 (11)		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
13. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287 (10) 138		12. REPORT DATE 30 June 1981
14. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		13. NUMBER OF PAGES
17. DISTRIBUTION STATEMENT (of the abstract only) (6) National Dam Safety Program, Earl Reservoir Dam, (Inventory Number Y.Y. 203), Lower Hudson River Basin, Orange County, New York. Phase I Inspection Report.		15. SECURITY CLASS. (of this report) UNCLASSIFIED
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability		Earl Reservoir Dam Orange County Lower Hudson River Basin
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Examination of available documents and a visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.		

Using the Corps of Engineers' screening criteria, it has been determined that the dam will pass 100 percent of the Probable Maximum Flood (PMF) without overtopping the dam. The spillway is, therefore, adjudged as "adequate." No signs of embankment instability were observed; therefore, no stability analysis will be required.

Current inspection and maintenance procedures by the owner are adequate, but need to be documented. Monitoring of the reservoir levels should be expanded to include readings during peak flow periods.

The following remedial measures must be completed within one year:

1. Add riprap to the spillway discharge channel downstream of the plunge pool to prevent further undercutting of the right wing wall.
2. Point the deteriorated joints in the dam masonry core wall and spillway discharge channel wing wall.
3. Riprap or pave the eroded channel along the toe of the embankment with the right abutment to prevent further erosion.
4. Cut the small trees, near the junction of the left and right abutments with the dam, off at ground level and mow the embankment regularly.

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DTIC
ELECT
S OCT 19 1981 D
D

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
EARL RESERVOIR DAM
I.D. No. NY 203
DEC DAM No. 195C-453 LOWER HUDSON RIVER BASIN
ORANGE COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	3
2 ENGINEERING DATA	5
2.1 GEOLOGY	5
2.2 SUBSURFACE INVESTIGATION	5
2.3 DAM AND APPURTENANT STRUCTURES	6
2.4 CONSTRUCTION RECORDS	6
2.5 OPERATION RECORDS	7
2.6 EVALUATION OF DATA	7
3 VISUAL INSPECTION	9
3.1 FINDINGS	9
3.2 EVALUATION	10
4 OPERATION AND MAINTENANCE PROCEDURES	11
4.1 PROCEDURES	11
4.2 MAINTENANCE OF THE DAM	11
4.3 WARNING SYSTEM	11
4.4 EVALUATION	11
5 HYDRAULIC/HYDROLOGIC	13
5.1 DRAINAGE AREA CHARACTERISTICS	13
5.2 ANALYSIS CRITERIA	13
5.3 SPILLWAY CAPACITY	13
5.4 RESERVOIR CAPACITY	13
5.5 FLOODS OF RECORD	14
5.6 OVERTOPPING POTENTIAL	14
5.7 RESERVOIR EMPTYING POTENTIAL	14
5.8 EVALUATION	14

	<u>PAGE NO.</u>	
6	STRUCTURAL STABILITY	15
	6.1 EVALUATION OF EMBANKMENT STABILITY	15
	6.2 STABILITY ANALYSIS	16
	6.3 SEISMIC STABILITY	16
7	ASSESSMENT/RECOMMENDATIONS	17
	7.1 ASSESSMENT	17
	7.2 RECOMMENDED MEASURES	17

APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC DATA AND COMPUTATIONS
- D. REFERENCES
- E. DRAWINGS AND ENGINEER'S REPORT
- F. BACKGROUND DOCUMENTS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Earl Reservoir Dam (I.D. No. NY 203)
State: New York
County: Orange
Stream: Tributary of Woodbury Creek
Dates of Inspection: 9 January 1981
9 March 1981

ASSESSMENT

Examination of available documents and a visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.

Using the Corps of Engineers' screening criteria, it has been determined that the dam will pass 100 percent of the Probable Maximum Flood (PMF) without overtopping the dam. The spillway is, therefore, adjudged as "adequate." No signs of embankment instability were observed; therefore, no stability analysis will be required.

Current inspection and maintenance procedures by the owner are adequate, but need to be documented. Monitoring of the reservoir levels should be expanded to include readings during peak flow periods.


The following remedial measures must be completed within one year:

1. Add riprap to the spillway discharge channel downstream of the plunge pool to prevent further undercutting of the right wing wall.
2. Point the deteriorated joints in the dam masonry core wall and spillway discharge channel wing wall.
3. Riprap or pave the eroded channel along the toe of the embankment with the right abutment to prevent further erosion.
4. Cut the small trees, near the junction of the left and right abutments with the dam, off at ground level and mow the embankment regularly.

5. Install a staff gage to monitor reservoir levels above normal pool.

SUBMITTED: 

Granville Kester, Jr., P.E.
Vice President
MICHAEL BAKER, JR. of New York, INC.

APPROVED: 

Colonel W.M. Smith, Jr.
New York District Engineer

DATE: 30 JUN 1981



Overall View of Dam
Earl Reservoir Dam
I.D. No. NY 203
9 March 1981

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
EARL RESERVOIR DAM
I.D. No. NY 203
DEC DAM No. 453
HUDSON RIVER BASIN
ORANGE COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

- a. Authority - The Phase I Inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.
- b. Purpose of Inspection - This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances - Earl Reservoir Dam is an earthfill embankment with a masonry core wall and a 2-foot thick concrete facing on the upstream side of the masonry wall. The core wall, which has been capped with concrete, extends above the earth embankment and forms the crest of the dam. The core wall is founded a minimum of 5 feet below original ground. There is no internal drainage system for the dam.

The dam is 460 feet long and 26.3 feet high, measured from tailwater to the top of dam. The crest width varies from 3.6 feet at the left¹ side of the dam to 7.1 feet at the center to 4.2 feet at the right side of the dam. A three sided, rectangular shaped, concrete spillway is located at the center of the dam. The crest of the spillway is a concrete broad-crested weir, 110 feet long and

¹Looking downstream left to right.

8 inches wide, with an inclined upstream face and vertical downstream face. Water passing over the weir cascades down a series of concrete steps to a concrete apron. Water then flows over the apron through the dam via a culvert, 15 feet wide by 15.5 feet high. Upon leaving the culvert, water drops about 11 feet into a masonry plunge pool provided for energy dissipation and then passes into a riprapped channel and natural stream channel.

The outlet works consist of a 12-inch cast iron pipe and a 20-inch cast iron pipe placed through the right side of the dam. Slide gate controls for the pipes are located in a manhole on the downstream side of the dam, right side of the spillway discharge channel. The 20-inch cast iron pipe exits into the masonry plunge pool underneath the concrete spillway discharge channel. The 12-inch cast iron pipe exits into the natural stream channel downstream of the dam and has an additional slide gate at the outlet.

- b. Location - Earl Reservoir Dam is located in the Town of Woodbury, Orange County, New York, on an unnamed tributary of Woodbury Creek. The coordinates of the dam are N 41° 21.8' and W 74° 8.2'. The dam and reservoir are located on the USGS 7.5 minute topographic quadrangle, Monroe, New York. A Location Plan is included in Appendix E.
- c. Size Classification - Earl Reservoir Dam is 26.3 feet high and the reservoir storage capacity at the top of the dam is 172 acre-feet. Therefore, the dam is in the "small" size category as defined by the Recommended Guidelines for Safety Inspection of Dams.
- d. Hazard Classification - Ridge Road is located about 800 feet downstream of the dam. Six homes are situated just downstream of Ridge Road. There is danger of loss of human life from large flows downstream of the dam. Therefore, Earl Reservoir Dam is considered to be in the "high" hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.
- e. Ownership - The dam and reservoir are owned by the Town of Woodbury, Albany Turnpike (Route 32), Highland Mills, New York 10930. The contact person is Mr. Richard Wilson (Telephone 914-928-6707).

- 10
- f. Purpose of the Dam - The dam was originally used for water supply but now is used for recreational purposes by the Town of Woodbury.
- g. Design and Construction History - The dam was originally constructed in 1912 by the Town of Woodbury. The dam was reconstructed in 1980 by Raimondi Associates, Monroe, New York 10950. The designer for the reconstruction was A.G. Lichtenstein and Associates, Teaneck, New Jersey 07666.
- h. Normal Operating Procedures - The reservoir is normally maintained at the elevation of the spillway weir crest at elevation 1005.1 T.B.M.² There are no written, formal operational procedures for Earl Reservoir Dam.

1.3 PERTINENT DATA

a.	<u>Drainage Area (Acres)</u> -	450
b.	<u>Discharge at Dam (c.f.s.)</u> -	
	Spillway at Top of Dam (Minimum)	1928
	Reservoir Drain at Normal Pool	
	Elevation = 1005.1 Feet T.B.M.	55.1
c.	<u>Elevations (Feet T.B.M.)</u> -	
	Top of Dam (Concrete Cap)	1008.9
	Top of Dam (Minimum on Left Abutment)	1007.9
	Spillway Crest	1005.1
	Reservoir Drain Inlet Invert	
	12-Inch Cast Iron Pipe	986.9
	20-Inch Cast Iron Pipe	986.9
d.	<u>Reservoir Surface Area (Acres)</u> -	
	Top of Dam (Minimum)	19.8
	Spillway Crest	16.0
e.	<u>Reservoir Storage Capacity (Acre-Feet)</u> -	
	Top of Dam (Minimum)	172.0
	Spillway Crest	122.0

²Temporary Bench Mark (T.B.M.) is top of manhole on the right side of the spillway, downstream side of the embankment. The assumed elevation is 1000.0 feet.

f. Dam -

Type: Earthfill embankment with a masonry and concrete core wall capped with concrete.

Length (Feet) 460
Slopes (Vertical:Horizontal)
Upstream - Embankment submerged 1:4
Downstream - 1:2.5

Crest Width (Feet)
Concrete cap at center of dam 7.1
Concrete cap at left abutment 3.6
Concrete cap at right abutment 4.2
Concrete cap and flat portion of earth embankment at center of dam 13.5

g. Spillway -

Type: Uncontrolled, three sided, rectangular shaped concrete weir

Length of Crest Perpendicular to Direction of Flow (feet) 110
Width of Crest Parallel to Direction of Flow (inches) 8

h. Reservoir Drain -

Type: A 12-inch cast iron pipe and a 20-inch cast iron pipe.

Control: Slide gate controls for both pipes are located in a manhole on the downstream side of the dam, right side of the spillway discharge channel. A second slide gate is present at the outlet of the 12-inch pipe.

i. Appurtenant Structures - An abandoned pump house is located downstream of the toe of the dam above the outlet of the 12-inch cast iron pipe.

SECTION 2: ENGINEERING DATA

2.1 GEOLOGY

Earl Reservoir Dam is located in a small eastern remnant of the "Appalachian Uplands" physiographic province of New York State. The province was formed by dissection of the uplifted but generally flat lying sandstones of the Middle Devonian Catskill Delta. Relief is high to moderate. Bedrock occurring in the immediate vicinity of the dam consists of undifferentiated sedimentary strata of the Hamilton Group, Middle Devonian Period (approximately 380 million years old), according to available geologic maps for New York State by J.G. Broughton and others (1970). Float exposed in the stream bed immediately below the dam indicates that the Skunnekunk Formation, consisting of sandstone and conglomerate, may actually underlie the dam. In-place bedrock was not exposed locally for examination. Faulting is not indicated in the vicinity of the dam, according to available information. The region has been repeatedly glaciated by the major ice sheet advances which occurred during the Pleistocene Epoch. The most recent ice advance ended approximately 11,000 years ago.

2.2 SUBSURFACE INVESTIGATION

According to the available (preliminary) soils report for Orange County prepared by the USDA Soil Conservation Service, local materials consist of "Bath Silt Loam" soils. These soils are described as deep (6+ feet), well drained, yellowish brown, strongly to medium acid, medium textured soils having a firm fragipan and formed in deep glacial till derived mainly from slates, shales and sandstone. Bath soils reportedly have 2 to 2-1/2 feet of moderately permeable gravelly loam overlying 1-1/2 to 4 feet of slowly permeable, very firm gravelly silt loam.

Nine borings were completed in 1977 immediately adjacent to the dam to facilitate plans for its rehabilitation. The boring logs are included in the engineering report included in Appendix E. The locations of these borings are shown on rehabilitation plans which are included in Appendix E. The borings did not encounter bedrock and extended typically through 16 to 31 feet of clay silt having small amounts of sand and gravel.

2.3 DAM AND APPURTENANT STRUCTURES

The dam was originally constructed in 1912 by the Town of Woodbury for water supply purposes. The impoundment has not been used since approximately 1940 for water supply, but has been subsequently used for recreational purposes by the town. The original construction reportedly consisted of an earth dam with a masonry core wall and centrally located masonry spillway (refer to documentation in Appendix E). The core wall extended from 5 to 15 or 20 feet below original ground according to best available information (refer to letter of 17 October 1912 in Appendix F). A 24-inch diameter reservoir drain and 12-inch diameter water supply pipe, each with slide gate controls on the upstream side of the dam, were available.

Because of the occurrence of several significant leaks during the 1970's, apparent piping of embankment materials, and plugging of the 24-inch drain, the dam was recently rehabilitated, principally for recreational purposes. Rehabilitation consisted of installation of a larger three-sided concrete spillway (110 feet total length) on the upstream side of the dam to act as a discharge "culvert" (Photo 3). The upstream side and crest of the original core wall were faced with 2 feet of concrete bonded to the masonry work with epoxy cement to reduce leakage (Photo 3). In addition, a clay blanket was placed on most of the upstream side of the rehabilitated structure and adjacent impoundment area. New intake structures were constructed for the existing 24-inch reservoir drain and 12-inch water supply pipe. A new 20-inch pipe was placed within the 24-inch pipe. The original slide gate controls were eliminated and new slide gate controls were placed in a manhole on the right downstream side of the spillway discharge channel. A Field Sketch, which illustrates present dam conditions, is included as Plate 1 in Appendix E.

The design engineer for the rehabilitation project was A.G. Lichtenstein and Associates of Teaneck, New Jersey. The construction engineer was Raimondi Associates of Monroe, New York.

2.4 CONSTRUCTION RECORDS

A single letter is available, dated 17 October 1912, which describes features related to original construction of the dam. Specifically, the letter discusses excavation of the masonry core wall trench. The letter

is included in Appendix F. The original construction is also discussed generally in the March 1978 Engineer's Report for the Rehabilitation of Earl Reservoir. The engineering report and accompanying engineering drawings are included in Appendix E.

2.5 OPERATION RECORDS

No operation records were found during this investigation.

2.6 EVALUATION OF DATA

Engineering data were obtained from files of the New York State Department of Environmental Conservation and from Mr. Ron Rothenburg of Raimondi Associates. The available data are considered adequate and reliable for Phase I Inspection purposes.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

- a. General - The inspection of Earl Reservoir Dam was conducted on 9 January 1981. The weather was cloudy and cold with temperatures ranging from 10°F to 15°F. At the time of inspection, approximately 3 inches of snow covered the ground. The reservoir was frozen over and the elevation of the ice was 1005.1 T.B.M. Deficiencies found during the inspection will require remedial treatment. A Field Sketch of conditions found during the inspection is included in Appendix F. The complete Visual Inspection Checklist is presented as Appendix B. Because there was a snow cover on the dam during the initial inspection, a follow-up inspection was carried out on 11 March 1981.
- b. Spillway - At the time of inspection, the spillway, described in Section 1.2a., was found to be in excellent condition. There was no cracking or spalling observed in the concrete of the spillway and spillway apron as shown in Photos 2 and 3. However, the spillway was covered by ice and snow. The spillway discharge channel, as described in Section 1.2a., was found to be in good condition. The sides of the discharge channel are masonry wing walls which connect with the masonry core wall of the dam. Some masonry joints in the upper portion of the wing walls, near the core wall, are deteriorated. The right wing wall, downstream of the plunge pool is slightly undercut.
- c. Embankment - The embankment was covered by about 3 inches of snow at the time of inspection. Overall, the dam, as described in Section 1.2a., appears to be in good condition. The horizontal and vertical alignments are good and no surface cracks were observed. Some joints in the masonry core wall, exposed on the downstream side of the dam, are deteriorated, as shown in Photo 6. A few small trees, as shown in Photo 7, were found near the junctions of the left and right abutments with the dam. A seep of about 3 gallons per minute occurs from a 15-foot wide area located near the toe of the embankment, right of the spillway discharge channel. A drainage culvert outlets at the far right downstream side of the dam. Drainage from the culvert has eroded a 2-foot deep ditch along the junction of the right abutment with the downstream embankment.

- d. 9 March 1981 Inspection - The reservoir had risen to the spillway crest at the time of the second inspection. The only additional observation made during this inspection was that there is a saturated area covering approximately 30 square feet at the downstream toe of the dam. This area is approximately 25 feet to the right of the spillway discharge channel. There was no discernable flow from the area. This is the same area of seepage observed in the original inspection.
- e. Outlet Works - The outlet works, as described in Section 1.2a., appear to be in good condition. The inlets for the 12-inch and 20-inch pipes, although not directly observed, are new. The piping system and gates located in the manhole are newly constructed. The additional gate on the outlet of the 12-inch pipe is rusty (see Photo 5).
- f. Downstream Channel - The downstream channel is a natural stream channel which flows in a narrow valley. The side slopes of the valley are steep and wooded. The stream slope is steep, approximately 9 percent.
- g. Reservoir - The slopes immediately adjacent to the reservoir are shallow and largely covered with grass. Steep wooded slopes are present at the upper end of the reservoir. There were no reservoir monitoring instruments observed.

3.2 EVALUATION

Visual inspection revealed several deficiencies in this structure. The following items were noted:)

- 1. A seep is located near the toe of the embankment, right of the spillway discharge channel,)
- 2. (The right wing wall is undercut downstream of the plunge pool,)
- 3. (Some of the joints in the masonry core wall are deteriorated,)
- 4. (Some of the joints in the upper portion of the wing walls are deteriorated,)
- 5. (Drainage from a culvert at the far right downstream side of the dam has eroded a 2-foot deep ditch along the downstream toe of the dam, 002)
- 6. A few small trees are near the junctions of the left and right abutments with the dam. ←

SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

The operation of the dam is an automatic function controlled by the crest of the spillway.

4.2 MAINTENANCE OF THE DAM

Maintenance of the dam is the responsibility of the owner. There are no formal inspection and maintenance procedures for Earl Reservoir Dam.

4.3 WARNING SYSTEM

There is no warning procedure or emergency action plan in the event of dam failure.

4.4 EVALUATION

It is recommended that formal inspection and maintenance procedures be developed and implemented. Maintenance items should be corrected annually. A warning system and emergency action plan should be developed and implemented.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 DRAINAGE AREA CHARACTERISTICS

Delineation of the watershed above Earl Reservoir Dam was made using the Monroe and Maybrook, New York USGS 7.5 minute quadrangles. The drainage basin is wooded. Slopes near the reservoir are moderate, approximately 13%, and are steep, approximately 33%, in the upper reaches of the watershed. The total drainage area is 450 acres (0.70 square miles).

5.2 ANALYSIS CRITERIA

An hydrologic analysis of the watershed and hydraulic analysis of the dam was conducted using the U.S. Army Corps of Engineers' Flood Hydrograph Package HEC-1 DB computer program (Reference 12, Appendix D). The unit hydrograph was defined using the Snyder Unit Hydrograph Method. Estimates of Snyder hydrograph coefficients were based upon average coefficients from the Hydrologic Flood Routing Model for Lower Hudson River Basin (Reference 16, Appendix D). Precipitation data was taken from Hydrometeorological Report No. 33 (Reference 8, Appendix D). Rainfall losses were estimated at an initial loss of 1.0 inch and a constant loss rate of 0.1 inch per hour thereafter. The hydraulic capacity of the dam, reservoir, and spillway was determined by incorporating the Modified Puls Routing Method. All flood routings were begun with the reservoir at normal pool level. Outlet discharge capacity was computed by hand. The Probable Maximum Flood (PMF) and 1/2 Probable Maximum Flood (1/2 PMF) were developed and routed through the reservoir.

5.3 SPILLWAY CAPACITY

With the reservoir level at the minimum top of dam, the spillway capacity was determined to be 1928 cubic feet per second (c.f.s.).

5.4 RESERVOIR CAPACITY

The storage capacity of Earl Reservoir at normal pool is 122 acre-feet. The storage capacity of the reservoir at the minimum top of dam is 172 acre-feet. Therefore, flood control storage of the reservoir between the spillway crest and top of dam is 50 acre-feet. This volume represents a total of 1.34 inches of runoff from the watershed.

PRECEDING PAGE BLANK-NOT FILLED

5.5 FLOODS OF RECORD

No records concerning the effects of significant floods on the dam and spillway are available.

5.6 OVERTOPPING POTENTIAL

The maximum capacity of the spillway is 1928 c.f.s. before overtopping would occur. The peak outflow of the PMF is 1778 c.f.s. and the 1/2 PMF is 883 c.f.s. Therefore, the spillway is capable of passing 100% of the PMF.

5.7 RESERVOIR EMPTYING POTENTIAL

The reservoir can be drawn down by means of a 12-inch and a 20-inch cast iron pipe, as described in Section 1.2a. Neglecting inflow, the reservoir can be drawn down from normal pool in approximately 35 hours. This is equivalent to an approximate drawdown rate of 0.5 feet per hour, based on the hydraulic height measured from normal pool divided by the time to dewater the reservoir.

5.8 EVALUATION

Earl Reservoir Dam is a "small" size - "high" hazard dam requiring the spillway to pass a flood in the range of the 1/2 PMF to PMF. The PMF and 1/2 PMF were routed through the watershed and dam. It was determined that the spillway is capable of passing 100% of the PMF without overtopping the dam. The spillway is, therefore, judged to be "adequate".

Conclusions pertain to present conditions and the effect of future development on the hydrology has not been considered.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF EMBANKMENT STABILITY

- a. Visual Observations - No signs of instability were noted during the visual inspection. Minor problems observed which could potentially affect the stability of the dam include:
 1. A ditch approximately 2 feet deep has been eroded along a portion of the junction of the right abutment and downstream embankment (see Photo 7). This steepening of the foundation for the embankment could result in slumping if erosion is allowed to continue.
 2. A seep totalling approximately 3 gallons per minute occurs from a 15-foot wide area located just downstream of the left end of the right downstream embankment.
- b. Design and Construction Data - Design and rehabilitation information concerning the stability of the embankment was not available.
- c. Operating Records - Operating records are not available.
- d. Post Construction Changes - The dam was recently rehabilitated as discussed in Section 2. Rehabilitation measures that are related to the stability of the dam include:
 1. The spillway was totally reconstructed and its capacity increased, thereby reducing the possibility of overtopping.
 2. Leakage through the dam was reduced by facing the original masonry core wall with concrete and installing a clay blanket along the upstream slope of the dam and immediate reservoir area.
 3. Reconstructed embankment slopes are gentle (flatter than 1V:2.5H).
 4. The original 24-inch reservoir drain pipe, which had become inoperable, was replaced with a new 20-inch cast iron pipe grouted into the old one, thereby re-establishing the capability of rapid drawdown as necessary.

6.2 STABILITY ANALYSIS

The results of a previous stability analysis were not available for reference during this evaluation. The dam might technically be considered a diaphragm type, but is considered to be more comparable to a zoned earthfill dam. The dam is 26.3 feet high, as measured from the crest of the dam to the tailwater in the plunge pool between the wing walls. The width of the crest varies; it is widest in the center and narrower at each end. The width near the center is approximately 13.5 feet, including the width of the exposed core wall plus the flat top portions of the upstream and downstream embankments. The most narrow width is 3.6 feet at the left end of the dam where only the concrete faced masonry core wall is present, and there is virtually no embankment on either side. The core of the dam is founded in a positive cut-off trench.

The upstream embankment slope is 1V:4H, as shown on the rehabilitation plans in Appendix E. The downstream embankment slope was measured at 1V:2.5H, although it is shown as 1V:2H on the rehabilitation plans. The dam is subject to rapid drawdown (greater than 0.5 feet per day) due to the availability of the 12- and 20-inch outlets.

The slopes of the embankments are not overly steep and appeared to be stable at the time of inspection. Therefore, a stability analysis of the structure is not considered necessary at this time.

6.3 SEISMIC STABILITY

Earl Reservoir Dam is located in Seismic Zone 1 which presents no hazard from earthquakes, according to the Recommended Guidelines for Safety Inspection of Dams. This determination is contingent on the requirements that static stability conditions are satisfactory and conventional safety margins exist.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

- a. Safety - Examination of available documents and visual inspections of Earl Reservoir Dam did not reveal any hazardous conditions.

Using the Corps of Engineers' screening criteria for initial review of spillway adequacy, it has been determined that the spillway is capable of passing 100% of the PMF without overtopping the dam. The spillway is therefore adjudged as "adequate". A stability analysis of the dam is not considered necessary at this time.

- b. Adequacy of Information - The engineering information reviewed is considered adequate for a Phase I Inspection.
- c. Need for Additional Investigation - Considering the present condition of the dam and reservoir, there is no need for additional investigation at this time.
- d. Urgency - The owner must complete the recommended corrective measures within one year of notification.

7.2 RECOMMENDED MEASURES

It is recommended that formal inspection and maintenance procedures be developed and implemented. Maintenance items should be corrected annually. A warning system and emergency action plan should be developed and implemented.

The seep near the toe of the embankment should be examined at regular intervals and after periods of heavy rain for turbidity and increase in flow, which may indicate the potential for piping of embankment material. If turbidity and increased flows are noted, a qualified geotechnical engineering firm should be retained to perform a stability check of the dam and plan remedial measures.

The following remedial measures must be completed within one year of notification:

1. Add riprap to the spillway discharge channel downstream of the plunge pool to prevent further undercutting of the right wing wall.

2. Point the deteriorated joints in the dam masonry core wall and spillway discharge channel wing wall.
3. Riprap or pave the eroded channel along the toe of the embankment with the right abutment to prevent further erosion.
4. Cut the small trees, near the junction of the left and right abutments with the dam, off at ground level and mow the embankment regularly.
5. Install a staff gage to monitor reservoir levels above normal pool.

APPENDIX A
PHOTOGRAPHS

CONTENTS

- Photo 1: Spillway Crest and Upstream Face of Dam -
9 March 1981
- Photo 2: Energy Dissipators (Steps) in Spillway -
9 March 1981
- Photo 3: Notch Through Masonry Core for Spillway -
9 March 1981
- Photo 4: 20-Inch Outlet Beneath Spillway Apron -
9 January 1981
- Photo 5: 12-Inch Outlet and Slide Gate, Abandoned
Pump House - 9 March 1981
- Photo 6: Condition of Masonry Core Wall Exposed on
Downstream Side of Dam - 9 March 1981
- Photo 7: Eroded Channel at Junction of Downstream
Embankment with Right Abutment - 9 March 1981
- Photo 8: Downstream Hazard Area - 9 March 1981

EARL RESERVOIR DAM



Photo 1. Spillway Crest and Upstream Face of Dam
9 March 1981



Photo 2. Energy Dissipators (Steps) in Spillway
9 March 1981

EARL RESERVOIR DAM



Photo 3. Notch Through Masonry Core for Spillway
9 March 1981



Photo 4. 20-Inch Outlet Beneath Spillway Apron
9 January 1981

EARL RESERVOIR DAM



Photo 5. 12-Inch Outlet and Slide Gate,
Abandoned Pump House
9 March 1981



Photo 6. Condition of Masonry Core Wall Exposed
on Downstream Side of Dam
9 March 1981

EARL RESERVOIR DAM



Photo 7. Eroded Channel at Junction of Downstream
Embankment with Right Abutment
9 March 1981




Photo 8. Downstream Hazard Area
9 March 1981

APPENDIX B
VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Earl Reservoir Dam

Fed. I.D. # NY 203 DEC Dam No. 195C-453

River Basin Hudson

Location: Town Woodbury County Orange

Stream Name Unnamed

Tributary of Woodbury Creek

Latitude (N) 41°21.8' Longitude (W) 74°08.2'

Type of Dam Earth dam with a masonry/concrete core wall

Hazard Category High

Date(s) of Inspection 9 January 1981

Weather Conditions Partly cloudy, 10°F. to 15°F., 3 in. snow cover on dam

Reservoir Level at Time of Inspection Elevation 1005.1 ft. T.B.M.*

b. Inspection Personnel Jeffrey Quay, Larry Diday, David Hupe

c. Persons Contacted (Including Address & Phone No.) _____

Richard Wilson Raimondi Associates, P.C.

3 Ridge Place 110 Stage Road

Highland Mills, NY 10930 Monroe, NY 10950

914/928-6707 (home phone) 914/782-8681

d. History:

Date Constructed 1912 Date(s) Reconstructed 1980

Designer (Reconstruction) A.G. Lichtenstein & Assoc., Teaneck, NJ 07666

Re-Constructed By (Construction Eng.) Raimondi Assoc., Monroe, NY.10950

Owner Town of Woodbury

*Temporary Bench Mark (T.B.M.) is top of manhole on the right side of the spillway, downstream side of the embankment. Assumed elevation is 1000.0 ft.

2) Embankment

a. Characteristics

- (1) Embankment Material Clayey silt.
- (2) Cutoff Type Core founded a minimum of 5 ft. below natural ground line.
- (3) Impervious Core Original masonry core with new 2 ft. thick upstream concrete facing bonded to masonry with epoxy cement.
- (4) Internal Drainage System None observed
- (5) Miscellaneous _____

b. Crest - Masonry core wall capped with concrete extends higher than the embankment and forms the crest.

- (1) Vertical Alignment Satisfactory
- (2) Horizontal Alignment Satisfactory
- (3) Surface Cracks None observed
- (4) Miscellaneous The concrete construction joints are tight. Expansion joint material was not used.

c. Upstream Slope

- (1) Slope (Estimate) (V:H) Could not measure; reservoir frozen over.
Design plans for dam rehabilitation indicate slope is 1V:4H.
- (2) Undesirable Growth or Debris, Animal Burrows None anticipated. The upstream slope is entirely inundated at normal pool level.

(3) Sloughing, Subsidence, or Depressions Unknown

(4) Slope Protection The design plans for dam rehabilitation indicate
6 in. of gravel in the vicinity of the spillway.

(5) Surface Cracks or Movement at Toe Unknown

d. Downstream Slope

(1) Slope (Estimate - V:H) 1V:2.5H measured during the field
inspection.

(2) Undesirable Growth or Debris, Animal Burrows None observed

(3) Sloughing, Subsidence or Depressions The embankments appear to be
in good condition. Some joints in the masonry core exposed on the
downstream side of the dam are deteriorated.

(4) Surface Cracks or Movement at Toe Refer to 2)e of this checklist

(5) Seepage No seepage was observed on the downstream slopes.

(6) External Drainage System (Ditches, Trenches, Blanket) None

(7) Condition Around Outlet Structure The masonry core wall beneath the
concrete spillway apron encases the 20 in. outlet adequately.

(8) Seepage Beyond Toe Seepage (total flow approx. 3 g.p.m.) occurs
from a 15 ft. wide area located near the toe of the embankment right
of the spillway.

e. Abutments - Embankment Contact A few small trees are located near the
junctions of the left and right abutments with the dam.

(1) Erosion at Contact A drainage culvert outlets at the far right end
of the dam on the downstream side. The drainage has eroded a 2 ft.
deep ditch along the junction of the right abutment with the down-
stream embankment.

(2) Seepage Along Contact None observed

3) Drainage System

a. Description of System None observed

b. Condition of System _____

c. Discharge from Drainage System _____

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs,
Piezometers, Etc.) None observed

5) Reservoir

- a. Slopes The slopes are very gentle and largely grass covered near the dam. Very steep wooded slopes are present at the upper end of the watershed.
- b. Sedimentation Unknown. The reservoir was frozen over.
- c. Unusual Conditions Which Affect Dam _____

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) Ridge Road is situated 800 ft. downstream. A large masonry arch culvert carries stream flow beneath the road. Just downstream of Ridge Road are six homes which are likely to be affected in the event of dam failure.
- b. Seepage, Unusual Growth None was observed.
- c. Evidence of Movement Beyond Toe of Dam None observed
- d. Condition of Downstream Channel The immediate downstream channel is narrow with steep sides.

7) Spillway(s) (Including Discharge Conveyance Channel)

Material: Good

Joints: Unknown Alignment Unknown

Structural Integrity: Structural integrity should be satisfactory. The 20 in. pipe is a new pipe grouted into the original 24 in. pipe. The existing 12 in. pipe upstream of the core wall has been encased in concrete.

Hydraulic Capability: _____

Means of Control: Gate both outlets Valve _____ Uncontrolled _____

Operation: Operable _____ Inoperable _____ Other Unknown

Present Condition (Describe): The gate at the discharge of the 12 in. outlet is rusty. The condition of the gate for the 20 in. outlet is unknown. The control is in the manhole immediately right of the spillway. The gate is new. A second gate for the 12 in. outlet is shown on the rehabilitation drawings as being controlled from the manhole.

9) Structural See Spillway

a. Concrete Surfaces _____

b. Structural Cracking _____

c. Movement - Horizontal & Vertical Alignment (Settlement) _____

d. Junctions with Abutments or Embankments _____

e. Drains - Foundation, Joint, Face _____

f. Water Passages, Conduits, Sluices _____

g. Seepage or Leakage _____

h. Joints - Construction, etc. _____

i. Foundation _____

j. Abutments _____

k. Control Gates _____

l. Approach & Outlet Channels _____

m. Energy Dissipators (Plunge Pool, etc.) _____

n. Intake Structures _____

o. Stability _____

p. Miscellaneous _____

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition An abandoned pump house is located above
the outlet of the 12 in. drain.

APPENDIX C
HYDROLOGIC/HYDRAULIC ENGINEERING
DATA AND COMPUTATIONS

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject EARL RESERVOIR DAM S.O. No. _____
APPENDIX C - HYDROLOGIC AND Sheet No. _____ of _____
HYDRAULIC COMPUTATIONS Drawing No. _____
Computed by _____ Checked by _____ Date _____

<u>SUBJECT</u>	<u>PAGE</u>
CHECK LIST FOR DAMS	1
DRAINAGE AREA MAP	5
HYDROLOGIC AND HYDRAULIC DATA	6
TOP OF DAM PROFILE	8
CROSS SECTION OF DAM	9
CROSS SECTION AT SPILLWAY	10
SPILLWAY	11
SPILLWAY RATING	12
OUTLET WORKS RATING	14
OUTLET WORKS SUMMARY RATING	23
HEC-1 ANALYSIS	24

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>1007.9 T.B.M.*</u>	<u>19.8</u>	<u>172.</u>
2) Design High Water (Max. Design Pool)	<u>1007.6 T.B.M.</u>	<u>19.7</u>	<u>167.</u>
3) Auxiliary Spillway Crest	<u>-</u>	<u>-</u>	<u>-</u>
4) Pool Level with Flashboards	<u>-</u>	<u>-</u>	<u>-</u>
5) Service Spillway Crest	<u>1005.1 T.B.M.</u>	<u>16.0</u>	<u>122.</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>30</u>
2) Spillway @ Maximum High Water - Top of Dam -	<u>1,928.</u>
3) Spillway @ Design High Water	<u>1,392.</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>-</u>
5) Low Level Outlet	<u>-</u>
6) Total (of all facilities) @ Maximum High Water	<u>1,928.</u>
7) Maximum Known Flood	<u>-</u>
8) At Time of Inspection	<u>25</u>

*Temporary Bench Mark (T.B.M.) is top of manhole on the right side of the spillway, downstream side of the embankment. Assumed elevation is 1,000.0 ft.

CREST:

ELEVATION: 1005.1 T.B.M.

Type: Masonry core wall capped with concrete.

Width: Varies from 3.6 to 7.1 ft. Length: 460 ft.

Spillover Uncontrolled rectangular concrete weir.

Location Center of dam.

SPILLWAY:

SERVICE

AUXILIARY

1005.1 T.B.M. Elevation None

Concrete weir Type

Width = 8 in. length = 110 ft. Width

Type of Control

X Uncontrolled

Controlled:

None Type

(Flashboards; gate)

- Number

- Size/Length

Invert Material

Anticipated Length
of Operating Service

16.5 ft. Chute Length

- Height Between Spillway Crest

& Approach Channel Invert

(Weir Flow)

HYDROMETEROLOGICAL GAGES:

Type: None were observed.

Location: _____

Records:

Date: _____

Max. Reading: _____

FLOOD WATER CONTROL SYSTEM:

Warning System: None

Method of Controlled Releases (mechanisms):

Gate valves in a manhole, located on the downstream side of the embankment,
control a 12 in. cast iron pipe and a 20 in. cast iron pipe.

DRAINAGE AREA: 0.70 sq. mi.

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: Wooded

Terrain - Relief: Moderate (13%) slopes near reservoir. Steep (33%) slopes in upper reaches of watershed.

Surface - Soil: Poor permeability.

Runoff Potential (existing or planned extensive alterations to existing surface or subsurface conditions)

None

Potential Sedimentation problem areas (natural or man-made; present or future)

Sedimentation is not expected to be a problem due to the natural wooded undeveloped watershed.

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

There are no potential backwater problem areas.

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter: None



Location: _____

Elevation: _____

Reservoir:

Length @ Maximum Pool (Top of dam) 1,700 ft.

Length of Shoreline (@ Spillway Crest) 3,900 ft.



EARL RESERVOIR DAM
DRAINAGE AREA MAP

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS


Box 280
Beaver, Pa. 15009

Subject N.Y. Dam Ins. S.O. No. 13088-00-ARA-09
EARL RESERVOIR DAM Sheet No. 6 of 37
Drawing No. _____
Computed by NCK/EE Checked by EE/WLS Date 1/12/01

DRAINAGE AREA - $3.80 + 1.97 \text{ mi}^2 = 447.26 \text{ AC} = 0.70 \text{ mi}^2$
LAKE AREA (elev 833±) - $0.13 \text{ mi}^2 = 11.94 \text{ ac} = \text{EL. } 1005.1$ 16 Ac. from Design Report
elev 840 - $0.27 \text{ mi}^2 = 24.79 \text{ ac} = \text{EL. } 1012.1$
860 - $0.54 \text{ mi}^2 = 49.59 \text{ ac} = \text{EL. } 1032.1$

L = 3.5 in - 7000' ft - 1.33 mi
L₄₀ = 1.4 in - 2800' ft - 0.53 mi

to convert Quad datum
to Field note datum
el. 833 ± el. 1005.1
or + 172.1 ±



From Const. Plans -
Lake bottom @ 810 ± 982.1

PRECIPITATION DATA

HMR-33 - ZONE 1

PMP 24 hr. - 200 mi² - 21.6 in.
D.A. - Less than 10 mi²

Duration	%	Inches
6 hr. PMP	111	= 23.98
12 hr PMP	123	= 26.57
24 hr PMP	133	= 28.73
48 hr PMP	142	= 30.67

TP-40

100 YR - 24 hr. Rainfall = 7.5 inches
" 12 hr " 6.4 "
" 6 hr " 5.3 "

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 7 of 37
Snyders Coeff. & Storage Drawing No. _____
Computed by LAD Checked by JAQ Date 2/4/81

Snyders Unit Hydrograph Coefficients

$$C_p = 0.63$$

$$C_T = 2.0$$

$$L = 1.33 \text{ Mi.}$$

$$L_{CA} = 0.53 \text{ Mi.}$$

$$T_p = C_T (L \times L_{CA})^{0.3}$$
$$= 2.0 (1.33 \times 0.53)^{0.3}$$
$$= 1.80$$

Reservoir Storage

	Design Plans	Survey (T.B.M) for HEC I
Top of Dam (conc.)	El. 832.0	El. 1008.9
Crest of spillway	El. 828.2	El. 1005.1
Bottom of Res. (Invert of 12" & 20" Pipe Inlet)	El. 810.0	El. 986.9

From Design Report - Res. Surface Area at
Crest of spillway = 16.0 Acres, 16 Ft.
Below crest surface area 90% reduced. = 1.6 Acres.
3.8 Ft. Above crest Area = 21.5 Acres

Therefore: Bottom of Res. (0 Acres) = El. 986.9

1.6 Acres = El. 989.1

*Acreage from U.S.G.S,
Quadrangle

16 Acres = El. 1005.1

21.5 Acres = El. 1008.9

*24.8 Acres = El. 1012.1


*49.6 Acres = El. 1032.1

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 8 of 37
Drawing No. _____
Computed by LAD Checked by KAR Date 1/15/91

TOP OF DAM PROFILE




MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 9 of 37
Drawing No. _____
Computed by GAD Checked by KAR Date 1/15/81

CROSS SECTION STA. 2+50



MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Earl Reservoir Dam

Cross-Section at Spillway

S.O. No. _____


Sheet No. 10 of 37

Drawing No. _____

Computed by DWH

Checked by _____

Date 1/19/81




CROSS SECTION AT SPILLWAY
NOTCH THROUGH CORE WALL
Scale: 1" = 5'

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS


Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 11 of 37
Spillway Drawing No. _____
Computed by LAD Checked by KAR Date 1/15/81

Concrete Spillway - Plan, Scale 1" = 10'



Concrete Spillway - Profile, Scale 1" = 10'



Total Weir Length = 110' Breadth of Crest = 8"
Size of Culvert = 15' x 15.5'

MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams

S.O. No. _____

Earl Reservoir Dam

Sheet No. 12 of 37

Spillway Rating

Drawing No. _____

Computed by LAD

Checked by ~~JE~~

~~JE~~
JAG

Date 1/15/81

Weir Flow over Concrete Weir

$$Q = CLH^{3/2}$$

$$L = 110 \text{ Ft.}$$

H varies from 0.5 Ft to 8.0 Ft.

C varies with H, King and Brater
Handbook Pg 5-44 Table 5-11

Elevation (Ft.)	H (Ft.)	L (Ft.)	C	Q (cfs)
1005.1	0	110.	0.	0
1006.1	1.0	110.	3.41	375.1
1007.1	2.0	110.	3.65	1135.6
1008.1	3.0	110.	3.72	2126.3
1009.1	4.0	110.	3.73	3282.4
1010.1	5.0	110.	3.73	4587.3
1011.1	6.0	110.	3.73	6030.2
1012.1	7.0	110.	3.73	7598.9
1013.1	8.0	110.	3.73	9284.0

↓ CONTROLS

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaumont, Pa. 15009

Subject New York Dams S.O. No. _____

Earl Reservoir Dam Sheet No. 13 of 37

Spillway Setting Drawing No. _____

Computed by LAD Checked by JHQ Date 1/15/61

Orifices Flow for Culvert

$$Q = CA (2gH)^{1/2}$$

$$= (.55)(232.5)(64.4H)^{1/2}$$

$$= 1026.2 (H)^{1/2}$$

$A = 15 \times 15.5 = 232.5 \text{ Sq. Ft.}$

$g = 32.2 \text{ Ft./sec}^2$

$C = 0.55$ Pg 4-11 King and
Brater Handbook

H varies from 7.75 + 12.75
Ft. and is measured from
the center of the culvert.

Elevation (Ft.)	H (Ft.)	Q (cfs)
1008.1	7.75	2856.8 ✓
1009.1	8.75	3035.5 ✓
1010.1	9.75	3204.3 ✓
1011.1	10.75	3364.6 ✓
1012.1	11.75	3517.6 ✓
1013.1	12.75	3664.2 ✓


↓ CONTROLS

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dam S.O. No. _____
Earl Reservoir Dam Sheet No. 14 of 37
Outlet Works Drawing No. _____
Computed by LAD Checked by JAS Date 2/9/81

Profile of Outlet Works



	20" Cast Iron Pipe	12" Cast Iron Pipe
Entrance Invert	El. 986.9	El. 986.9
Outlet Invert	El. 982.4	El. 976.9
Length	63 Ft.	170 Ft.
Slope	0.0714 ✓	0.0588 ✓


MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 15 of 37
20" Pipe Rating Drawing No. _____
Computed by LED Checked by JHQ Date 2/9/81

Flow in Pipes Partly Full

"Design of Small Dams" Pages 558 and 559



$D = \text{Pipe Dia} = 20" = 1.67 \text{ Ft.}$

$d = \text{Depth of Flow}$

$s = \text{Slope} = 0.0714$

Pipe is Cast Iron

$n = 0.014$

$\frac{d}{D} = \frac{.5}{1.67} = 0.30$

$0.5225 = \frac{Q_c}{D^{5/2}} = \frac{Q_c}{(1.67)^{5/2}} \quad Q_c = \underline{1.9 \text{ cfs}} \checkmark$

$\frac{d}{D} = \frac{.5}{1.67} = 0.30$

$0.0907 = \frac{Q n}{D^{4.75} s^{1/2}} = \frac{Q(0.014)}{(1.67)^{4.75} (.0714)^{1/2}} \quad Q = \underline{6.8 \text{ cfs}} \checkmark$

$\frac{d}{D} = \frac{1.0}{1.67} = 0.60$

$1.9773 = \frac{Q_c}{D^{5/2}} = \frac{Q_c}{(1.67)^{5/2}} \quad Q_c = \underline{7.1 \text{ cfs}} \checkmark$

$\frac{d}{D} = \frac{1.0}{1.67} = 0.60$

$0.311 = \frac{Q n}{D^{4.75} s^{1/2}} = \frac{Q(0.014)}{(1.67)^{4.75} (.0714)^{1/2}} \quad Q = \underline{23.3 \text{ cfs}} \checkmark$

Critical Depth Controls

El. 986.9 $Q = 0 \checkmark$

El. 987.4 $Q = 1.9 \text{ cfs} \checkmark$

El. 987.9 $Q = 7.1 \text{ cfs} \checkmark$

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl C. Veir Dam Sheet No. 16 of 37
20" Pipe Rating Drawing No. _____
Computed by LAD Checked by JAG Date 2/9/21

Pipe Flow

$$Q = \frac{A (2gH)^{1/2}}{[1 + K_0 + K_p(L)]^{1/2}}$$

$$= \frac{2.16 (64.4 H)^{1/2}}{[1 + 0.78 + .0185(63)]^{1/2}}$$

$$= 10.10 (H)^{1/2}$$

Pipe = 20" Dia. Cast Iron
 $A = \pi r^2 = \frac{2.16}{2.16} \text{ Sq. Ft.}$
 $g = 32.2 \text{ Ft./sec.}$
 $L = 63 \text{ Ft.}$
 Pipe Losses

Entrance Loss (K_0) = 0.78
 Pg 5.5-6 SCS NEH-5
 Head Loss (K_p) = 0.0185
 $n = 0.014$ Pg 5.5-4
 SCS NEH-5

H varies from 4.9 Ft. to
 21.0 Ft. and is measured
 from the Top of Pipe
 at Outlet = El. 984.1

Elevation (Ft.)	H (Ft.)	Q (cfs)
989.0	4.9	22.4
990.0	5.9	24.5
991.0	6.9	26.5
992.0	7.9	28.4
993.0	8.9	30.1
994.0	9.9	31.8
995.0	10.9	33.3
996.0	11.9	34.8
997.0	12.9	36.3
998.0	13.9	37.7
999.0	14.9	39.0
1000.0	15.9	40.3
1001.0	16.9	41.5
1002.0	17.9	42.7
1003.0	18.9	43.9
1004.0	19.9	45.1
1005.1	21.0	46.3

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 17 of 37
20" Pipe Rating Drawing No. _____
Computed by LAD Checked by JAQ Date 2/9/81

Orifice Flow

$$Q = CA(2gH)^{.5}$$

$$= (0.6)(2.16)(64.4 H)^{.5}$$

$$= 10.40 (H)^{.5}$$

Pipe = 20" Cast Iron

$$A = \pi r^2 = 2.16 \text{ Sq. Ft.}$$

$$g = 32.2 \text{ Ft./sec}$$

C = 0.6 King and Brater
Handbook Pg 4-32 Table 4-6

H varies from 1.3 Ft. to
17.4 Ft. and is measured
from the center of pipe
at inlet = El. 987.7


Elevation (Ft.)	H (Ft.)	Q (cfs)
989.0	1.3	11.9
990.0	2.3	15.8
991.0	3.3	18.9
992.0	4.3	21.6
993.0	5.3	23.9
994.0	6.3	26.1
995.0	7.3	28.1
996.0	8.3	30.0
997.0	9.3	31.7
998.0	10.3	33.4
999.0	11.3	35.0
1000.0	12.3	36.5
1001.0	13.3	37.9
1002.0	14.3	39.3
1003.0	15.3	40.7
1004.0	16.3	42.0
1005.1	17.4	43.4

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 18 of 37
20" Pipe Rating Drawing No. _____
Computed by LAD Checked by JMQ Date 2/9/81

RATING CURVE




MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 19 of 37
12" Pipe Rating Drawing No. _____
Computed by LAD Checked by JAQ Date 2/9/81

Flow in Pipes Partly Full

"Design of Small Dams" Pages 558 and 559



D = Pipe Dia. = 12" = 1 Ft.
d = Depth of Flow
S = Slope = 0.0588
Pipe is Cast Iron
n = 0.014

$$\frac{d}{D} = \frac{.4}{1.0} = .4 \quad 0.9103 = \frac{Q_c}{D^{5/2}} = \frac{Q_c}{(1)^{5/2}} \quad \underline{Q_c = 0.9 \text{ cfs}} \checkmark$$

$$\frac{d}{D} = \frac{.4}{1.0} = .4 \quad 0.1561 = \frac{Q_n}{D^{4/3} S^{1/2}} = \frac{Q(0.014)}{(1)^{4/3} (0.0588)^{1/2}} \quad Q = 2.7 \text{ cfs} \checkmark$$

$$\frac{d}{D} = \frac{.7}{1.0} = .7 \quad 2.6656 = \frac{Q_c}{D^{5/2}} = \frac{Q_c}{(1)^{5/2}} \quad \underline{Q_c = 2.7 \text{ cfs}} \checkmark$$

$$\frac{d}{D} = \frac{.7}{1.0} = .7 \quad 0.388 = \frac{Q_n}{D^{4/3} S^{1/2}} = \frac{Q(0.014)}{(1)^{4/3} (0.0588)^{1/2}} \quad Q = 6.7 \text{ cfs} \checkmark$$

Critical Depth Controls

El. 986.9 $Q = 0$ ✓

El. 987.3 $Q = 0.9 \text{ cfs}$ ✓

El. 987.6 $Q = 2.7 \text{ cfs}$ ✓

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 20 of 37
12" Pipe Rating Drawing No. _____
Computed by LAD Checked by JAQ Date 2/9/81

Pipe Flow

$$Q = \frac{A(2gH)^{1/2}}{[1 + K_0 + K_p(L)]^{1/2}}$$

$$= \frac{(0.79)(64.4 H)^{1/2}}{[1 + .78 + 0.0363(170)]^{1/2}}$$

$$= 2.25 (H)^{1/2} \checkmark$$

Pipe = 12" Dia. Cast Iron

$$A = \pi r^2 = 0.79 \text{ Sq. Ft.}$$

$$g = 32.2 \text{ Ft./sec.}$$

$$L = 170 \text{ Ft.}$$

Pipe Losses

$$\text{Entrance Loss } (K_0) = 0.78$$

Pg. 5.5-6 SCS NEH-5

$$\text{Head Loss } (K_p) = 0.0363$$

n = 0.014 Pg. 5.5-4
SCS NEH-5

H varies from 10.1 Ft. to 27.2 Ft. and is measured from the Top of Pipe at Outlet = El. 977.9

Elevation (Ft.)	H (Ft.)	Q (cfs)
988.0	10.1	7.2
989.0	11.1	7.5
990.0	12.1	7.8
991.0	13.1	8.1
992.0	14.1	8.4
993.0	15.1	8.7
994.0	16.1	9.0
995.0	17.1	9.3
996.0	18.1	9.6
997.0	19.1	9.8
998.0	20.1	10.1
999.0	21.1	10.3
1000.0	22.1	10.6
1001.0	23.1	10.8
1002.0	24.1	11.0
1003.0	25.1	11.3
1004.0	26.1	11.5
1005.1	27.2	11.7

MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams

Earl Reservoir Dam

12" Pipe Rating

Computed by LAD

Checked by JAO

S.O. No. _____

Sheet No. 21 of 37

Drawing No. _____

Date 2/9/81

Orifice Flow

$$\begin{aligned}
 Q &= CA (2gH)^{.5} \\
 &= (.6)(0.79)(64.4 H)^{.5} \\
 &= 3.80 (H)^{.5}
 \end{aligned}$$

Pipe = 12" Cast Iron

$$A = \pi r^2 = 0.79 \text{ Sq. Ft.}$$

$$g = 32.2 \text{ Ft./sec.}$$

C = 0.6 King and Brater Handbook Pg 4-32 Table 4-6

H varies from 0.6 Ft. to 17.7 Ft. and is measured from the center of pipe at inlet = El. 987.4


Elevation (Ft.)	H (Ft.)	Q (cfs)
988.0	0.6	2.9
989.0	1.6	4.8
990.0	2.6	6.1
991.0	3.6	7.2
992.0	4.6	8.2
993.0	5.6	9.0
994.0	6.6	9.8
995.0	7.6	10.5
996.0	8.6	11.2
1005.1	17.7	16.0

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____
Earl Reservoir Dam Sheet No. 22 of 37
12" Pipe Rating Drawing No. _____
Computed by LAD Checked by JAQ Date 2/9/81

RATING CURVE



MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject New York Dams S.O. No. _____

Earl Reservoir Dam Sheet No. 23 of 37

Outlet Summary Rating Drawing No. _____

Computed by LAD Checked by _____ Date 2/9/81

Elevation (Ft.)	20" Pipe Q (cfs)	12" Pipe Q (cfs)	Total Q (cfs)
986.9	0	0	0
987.4	1.9	1.4	3.3
987.8	4.5	2.4	6.9
988.0	7.0	2.9	9.9
989.0	11.9	4.8	16.7
990.0	15.8	6.1	21.9
991.0	18.9	7.2	26.1
992.0	21.6	8.2	29.8
993.0	23.9	8.7	32.6
994.0	26.1	9.0	35.1
995.0	28.1	9.3	37.4
996.0	30.0	9.6	39.6
997.0	31.7	9.8	41.5
998.0	33.4	10.1	43.5
999.0	35.0	10.3	45.3
1000.0	36.5	10.6	47.1
1001.0	37.9	10.8	48.7
1002.0	39.3	11.0	50.3
1003.0	40.7	11.3	52.0
1004.0	42.0	11.5	53.5
1005.1	43.4	11.7	55.1

 FLOOD HYDROGRAPH PACKAGE LDEC-11
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 48J UPDATE 04 JUL 79

1 A1 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
 2 A2 HYDRAULIC AND HYDRAULIC ANALYSIS OF EARL RESERVOIR DAM
 3 A3 UNIT HYDROGRAPH BY SNYDER'S METHOD
 4 B 5J
 5 B1 3
 6 J 1
 7 J1 1.0 0.75 0.5 0.25
 8 K 1
 9 K1 RUNOFF HYDROGRAPH TO DAM
 10 M 1 0.70
 11 P 21.6 111 123 133 162 1.0 0.1
 12 P 1
 13 W 1.8J 0.6J
 14 X -1.5 -0.05 2
 15 K 1
 16 K1 ROUTING FOR EARL RESERVOIR DAM
 17 Y 1
 18 Y1 1
 19 Y41005.1 1J06.1 1007.1 1008.1 1009.1 1010.1 1011.1 1012.1 1013.1
 20 Y5 0 375.1 1135.6 2126.3 3035.5 3208.3 3364.6 3517.0 3684.2
 21 SA J 1.6 16.0 21.5 24.8 49.6
 22 SE 986.7 789.1 1005.1 1008.9 1012.1 1032.1
 23 S81005.1
 24 S01007.7 2.0 1.5
 25 S1 J 17 36 489 549 651 750
 26 S1007.7 1J08.2 1008.5 1009.0 1010.0 1012.0 1014.0
 27 K 99

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIOS APPLIED TO FLOWS
 1.00 0.75 0.50 0.25

HYDROGRAPH AT 1 1810. 1357. 905. 454.
 (1.01) (51.25) (38.43) (25.62) (12.81)
 ROUTED TO 2 1778. 1323. 883. 435.
 (1.01) (50.35) (37.75) (24.99) (12.31)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE	INITIAL VALUE	SPILLWAY GUEST	TUP OF DAM	TIME OF FAILURE		
	OUTFLOW				HOURS		
		1003.10	1005.10	1007.90			
		122.	122.	172.			
		0.	0.	1928.			
RATIO OF PWF	MAXIMUM AC SERVOIR 4-S-ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FI	MAXIMUM OUTFLOW CFS	URATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	1007.75	0.0	169.	1778.	0.0	41.20	0.0
0.75	1007.30	0.0	161.	1433.	0.0	41.50	0.0
0.50	1006.77	0.0	151.	883.	0.0	41.58	0.0
0.25	1006.18	0.0	140.	435.	0.0	41.87	0.0

11

11

SHEET 34 of 37

1	1.01	2.00	2	2.00	0.	59.	113.	1009.2
2	1.01	3.00	3	3.00	0.	59.	109.	1009.4
3	1.01	4.00	4	4.00	0.	53.	104.	1003.5
4	1.01	5.00	5	5.00	0.	53.	100.	1003.6
5	1.01	6.00	6	6.00	0.	52.	92.	1003.3
6	1.01	7.00	7	7.00	0.	51.	87.	1002.0
7	1.01	8.00	8	8.00	0.	51.	82.	1002.3
8	1.01	9.00	9	9.00	0.	50.	78.	1002.0
9	1.01	10.00	10	10.00	0.	50.	74.	1001.6
10	1.01	11.00	11	11.00	0.	49.	70.	1001.3
11	1.01	12.00	12	12.00	0.	49.	66.	1000.9
12	1.01	13.00	13	13.00	0.	48.	62.	1000.5
13	1.01	14.00	14	14.00	0.	47.	58.	1000.4
14	1.01	15.00	15	15.00	0.	47.	54.	999.7
15	1.01	16.00	16	16.00	0.	46.	50.	999.3
16	1.01	17.00	17	17.00	0.	45.	47.	998.5
17	1.01	18.00	18	18.00	0.	45.	43.	998.0
18	1.01	19.00	19	19.00	0.	44.	39.	997.5
19	1.01	20.00	20	20.00	0.	44.	36.	997.0
20	1.01	21.00	21	21.00	0.	42.	32.	996.5
21	1.01	22.00	22	22.00	0.	41.	29.	996.0
22	1.01	23.00	23	23.00	0.	40.	26.	995.0
23	1.02	0.0	24	24.00	0.	38.	22.	995.4
24	1.02	1.00	25	25.00	0.	37.	19.	994.8
25	1.02	2.00	26	26.00	0.	36.	16.	994.2
26	1.02	3.00	27	27.00	0.	35.	13.	993.6
27	1.02	4.00	28	28.00	0.	32.	11.	992.8
28	1.02	5.00	29	29.00	0.	30.	8.	992.1
29	1.02	6.00	30	30.00	0.	27.	6.	991.3
30	1.02	7.00	31	31.00	0.	26.	4.	990.4
31	1.02	8.00	32	32.00	0.	20.	2.	989.5
32	1.02	9.00	33	33.00	0.	16.	1.	988.6
33	1.02	10.00	34	34.00	0.	0.	0.	988.0
34	1.02	11.00	35	35.00	0.	0.	0.	986.9
35	1.02	12.00	36	36.00	0.	0.	0.	986.9
36	1.02	13.00	37	37.00	0.	0.	0.	986.9
37	1.02	14.00	38	38.00	0.	0.	0.	986.9
38	1.02	15.00	39	39.00	0.	0.	0.	986.9
39	1.02	16.00	40	40.00	0.	0.	0.	986.9
40	1.02	17.00	41	41.00	0.	0.	0.	986.9
41	1.02	18.00	42	42.00	0.	0.	0.	986.9
42	1.02	19.00	43	43.00	0.	0.	0.	986.9
43	1.02	20.00	44	44.00	0.	0.	0.	986.9
44	1.02	21.00	45	45.00	0.	0.	0.	986.9
45	1.02	22.00	46	46.00	0.	0.	0.	986.9
46	1.02	23.00	47	47.00	0.	0.	0.	986.9
47	1.03	0.0	48	48.00	0.	0.	0.	986.9
48	1.03	1.00	49	49.00	0.	0.	0.	986.9
49	1.03	2.00	50	50.00	0.	0.	0.	986.9
50	1.03	3.00	51	51.00	0.	0.	0.	986.9
51	1.03	4.00	52	52.00	0.	0.	0.	986.9
52	1.03	5.00	53	53.00	0.	0.	0.	986.9
53	1.03	6.00	54	54.00	0.	0.	0.	986.9
54	1.03	7.00	55	55.00	0.	0.	0.	986.9
55	1.03	8.00	56	56.00	0.	0.	0.	986.9
56	1.03	9.00	57	57.00	0.	0.	0.	986.9
57	1.03	10.00	58	58.00	0.	0.	0.	986.9
58	1.03	11.00	59	59.00	0.	0.	0.	986.9
59	1.03	12.00	60	60.00	0.	0.	0.	986.9
60	1.03	13.00	61	61.00	0.	0.	0.	986.9
61	1.03	14.00	62	62.00	0.	0.	0.	986.9
62	1.03	15.00	63	63.00	0.	0.	0.	986.9
63	1.03	16.00	64	64.00	0.	0.	0.	986.9
64	1.03	17.00	65	65.00	0.	0.	0.	986.9
65	1.03	18.00	66	66.00	0.	0.	0.	986.9
66	1.03	19.00	67	67.00	0.	0.	0.	986.9

LINE NO.	DATE	TIME	55. AT TIME	0.0 HOURS	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1	1.01	21.00	55.	53.	48.	20.	1922.	
2	1.03	21.00	55.	53.	48.	20.	1922.	
3	1.03	22.00	2.	2.	1.	1.	40.	
4	1.03	23.00	0.71	18.00	2.55	3.15	3.15	
5	1.04	0.00	18.00	64.69	79.98	79.98	79.98	
6	1.04	1.00	26.	95.	117.	117.	117.	
7	1.04	2.00	33.	117.	145.	145.	145.	
8	1.04	3.00						
9	1.04	4.00						
10	1.04	5.00						
11	1.04	6.00						
12	1.04	7.00						
13	1.04	8.00						
14	1.04	9.00						
15	1.04	10.00						
16	1.04	11.00						
17	1.04	12.00						
18	1.04	13.00						
19	1.04	14.00						
20	1.04	15.00						
21	1.04	16.00						
22	1.04	17.00						
23	1.04	18.00						
24	1.04	19.00						
25	1.04	20.00						
26	1.04	21.00						
27	1.04	22.00						
28	1.04	23.00						
29	1.05	0.00						
30	1.05	1.00						
31	1.05	2.00						
32	1.05	3.00						
33	1.05	4.00						
34								
35								
36								
37								
38								
39								
40								
41								
42								
43								
44								
45								
46								
47								
48								
49								
50								
51								
52								
53								
54								
55								
56								
57								
58								
59								
60								
61								
62								
63								
64								
65								
66								
67								
68								
69								
70								
71								
72								
73								
74								
75								
76								
77								
78								
79								
80								
81								
82								
83								
84								
85								
86								
87								
88								
89								
90								
91								
92								
93								
94								
95								
96								
97								
98								
99								
100								
101								
102								
103								
104								
105								
106								
107								
108								
109								
110								
111								
112								
113								
114								
115								
116								
117								
118								
119								
120								
121								
122								
123								
124								
125								
126								
127								
128								
129								
130								
131								
132								
133								
134								
135								
136								
137								
138								
139								
140								
141								
142								
143								
144								
145								
146								
147								
148								
149								
150								
151								
152								
153								
154								
155								
156								
157								
158								
159								
160								
161								
162								
163								
164								
165								
166								
167								
168								
169								
170								
171								
172								
173								
174								
175								
176								
177								
178								
179								
180								
181								
182								
183								
184								
185								
186								
187								
188								
189								
190								
191								
192								
193								
194								
195								
196								
197								
198								
199								
200								

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLUWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE FEET (SQUARE METER)

RATIOS APPLIED TO FLUWS

OPERATION STATION AREA PLAN RATIO 1
 1.00

HYDROGRAPH AT 1 0.70 1 0.
 1.811 0.071

ROUTED TO 2 0.70 1 55.
 1.811 1.5511

APPENDIX D
REFERENCES

REFERENCES

1. University of the State of New York, Geology of New York, Education Leaflet 20, 1966.
2. Broughton, John G. and others, "Geologic Map of New York - Lower Hudson Sheet," New York State Museum and Science Service, Map and Chart Series No. 15, 1970.
3. Soil Conservation Service, Soil Interpretations Inventory Analysis and Erosion Control - Orange County, New York, U.S. Dept. of Agriculture, January 1972.
4. Dunbar, Carl O. and Waage, Karl M., Historical Geology, John Wiley and Sons, Inc., New York, 1969.
5. Bureau of Reclamation, U.S. Dept. of the Int., Design of Small Dams, A Water Resources Technical Publication, 1977.
6. Chow, Ven Te, Handbook of Applied Hydrology, McGraw - Hill Book Company, New York, 1964.
7. Chow, Ven Te, Open Channel Hydraulics, McGraw - Hill Book Company, New York, First Edition, 1959.
8. HMR 33, "Seasonal Variations of Probable Maximum Precipitation, East of the 105th Meridian for Areas 10 to 1000 Square Miles and Durations of 6 to 48 Hours," (1956).
9. King, Horace Williams and Brater, Ernest F., Handbook of Hydraulics, Fifth Edition, McGraw - Hill Book Company, New York, 1963.
10. Soil Conservation Service, "National Engineering Handbook - Section 4, Hydrology," U.S. Department of Agriculture, 1964.
11. Soil Conservation Service, "National Engineering Handbook - Section 5, Hydraulics," U.S. Department of Agriculture.
12. U.S. Army, Hydrological Engineering Center, "Flood Hydrograph Package (HEC-1), Dam Safety Investigations, Users Manual," Corps of Engineers, Davis, California, September 1978.
13. U.S. Army, Hydrological Engineering Center, "HEC-2 Water Surface Profiles, Users Manual," Corps of Engineers, Davis, California, October 1973.

14. U.S. Army, "Inventory of United States Dams," Corps of Engineers, 9 September 1978.
15. U.S. Army, Office of the Chief of Engineers, "Appendix D, Recommended Guidelines for Safety Inspection of Dams," National Program of Inspection of Dams, Volume 1, Corps of Engineers, Washington, D.C., May 1975.
16. George, Thomas S. and Taylor, Robert S., Hydrologic Flood Routing Model For Lower Hudson River Basin, Water Resources Engineers, Inc., 8001 Forbes Place, Suite 312, Springfield, Virginia, January 1977.
17. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-163 (Draft Engineering Manual), "Spillway and Freeboard Requirements for Dams, Appendix C, Hydrometeorological Criteria and Hyetograph Estimates," (August 1975).
18. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-188, "Engineering and Design, National Program of Inspection of Non-Federal Dams," Corps of Engineers, Washington, D.C., 30 December 1977.
19. U.S. Army, Office of the Chief of Engineers, Engineer Technical Letter No. ETL 1110-2-234, "Engineering and Design, National Program of Inspection of Non-Federal Dams, Review of Spillway Adequacy," Corps of Engineers, Washington, D.C., 10 May 1978.
20. U.S. Department of Commerce, "Technical Paper No. 40, Rainfall Frequency Atlas of the United States for Durations from 30 Minutes to 24 Hours and Return Periods from 1 to 100 Years," Weather Bureau, Washington, D.C., May 1961.
21. U.S. Department of Commerce, National Oceanic and Atmospheric Administration, "Hydrometeorological Report No. 51, Probable Maximum Precipitation Estimates, United States East of the 105th Meridian," Washington, D.C., June 1978.

APPENDIX E
DRAWINGS AND ENGINEER'S REPORT

CONTENTS

Location Plan

Watershed Map

Plate 1: Field Sketch

Plate 2: Plan of Dam

Plates 3,4,5: Dam Cross Sections

Plate 6: General Plan & Elevation of Spillway


Plate 7: Clay Blanket

Plate 8: Mudgate Structure Details

Plate 9: Construction Details (Control Manhole)

Engineer's Report

- Not to Scale -




FIELD SKETCH

EARL RESERVOIR DAM, NEW YORK

Michael Baker, Jr., Inc.


9 January 1981

PLATE 1



REFERENCES:
 1. U.S.G.S. 7.5' MAYBROOK, N.Y.
 QUADRANGLE. 1957
 2. U.S.G.S. 7.5' MONROE, N.Y.
 QUADRANGLE. 1957

LOCATION PLAN
EARL RESERVOIR DAM



LEGEND MARK:

- ① R. R. Sp. in Pole No. 7
El. 824.04 (Assumed Datum)
- ② R. R. Sp. in Pole No. 8
El. 823.00 (Assumed Datum)



EARL RESER

EXISTING WATER SUPPLY STRUCTURE
TO BE MODIFIED (SEE SPECS)

PROPOSED LAKE MUDGATE ST

PROPOSED PEDE
OVERWASH TO
EXISTING CORE W

CONST. STA. 1
CHANNEL & ST

PRO
STR

TOE OF

BEGIN CURTAIN WALL
STA. 1+11

CONSTR. E

S. APPROACH WALK
(TYP.)

PROP. CONTROL MANHOLE

EXISTING BRIDGE TO BE
REMOVED TO EL. 807.0

CONSTRUCT
36 L.F. 24" C.B.P. (23" x 2") 16 GA
1" UNITS, TYPE A.

CONSTRUCT
88 L.F. BEAM GUIDE RAIL

PCC STA. 4+30

EXIST. 12" Ø OUT-
FLOW PIPE TO
REMAIN

EXIST. PUMP HOUSE TO
REMAIN

EXISTING BLOW OFF
GATE VALVE TO REMAIN

MEET EXISTING
& BANKS STA. 1

EXIST
TO R

CHANNEL SECTION

EL. 822.0

Channel 8

Approx. Exist. Ground


Dry in 100 lb. truck
with 1000 gal. of water.

CHANNEL SECTION

PLAN

1" = 20'

800



⊙ INDICATES SOIL BORING TAKEN 9/77
LOGS AVAILABLE FOR INSPECTION
AT TOWN HALL

Notes:
 1. Existing information is not guaranteed to be correct. Bidders shall visit the site to determine the extent of the work. Dimensions shall be field verified.
 2. For Details of Clay Blanket, see Sheet 11.


PLATE 2


REHABILITATION OF EARL RESERVOIR

TOWN OF WOODBURY ORANGE COUNTY, N.Y.

PLAN

RAIMONDI ASSOC., P.C. A.G. LICHTENSTEIN, P.E. CONSULTING ENGINEERS	SCALE	DATE	SHEET NO.
	AS SHOWN	MAR., '78	2 OF 18





EXISTING DAM

PROPOSED EXCAVATION

FROM DAM SECTIONS
 FROM DAM SECTIONS
 TOTAL EXCAVATION
 LESS SHRINKAGE
 TOTAL EXCAVATION FOR DAM

BACKFILL


FROM DAM SECTIONS
 TOTAL BACKFILL

REHABILITATION OF
EARL RESERVOIR
 TOWN OF WOODBURY

DAM CROSS SECTIONS

RAYMOND ASSOC. P.C.
 A. GLONSTEIN, P.E.
 CONSULTING ENGINEERS

1" = 5' SHEET NO. 3 OF 19




PLAN OF BRIDGE
FOR APPROX. SEE SHEET 1
ELEVATION OF BRIDGE
SEE SHEET 1

2+00

2+30

2+60

SCALE 1" = 10'




2

REHABILITATION OF
 EARL RESERVOIR
 TOWN OF WOODBURY ORANGE COUNTY, N.Y.


DAM CROSS SECTIONS

RAMOND ASSOC., P.C.
 A.G. LICHTENSTEIN, P.E.
 CONSULTING ENGINEERS

SCALE	DATE	SHEET NO.
1" = 5'	MAR, '78	4 OF 18



CONST



SCARIFY TOPSOIL, SEED & MULCH EXISTING
ROADWAY WHERE ABANDONED (TYP)

CONST. 2

2

REHABILITATION OF
EARL RESERVOIR
TOWN OF WOODBURY ORANGE COUNTY, N.Y.

DAM CROSS SECTIONS

RAIMONDI ASSOC., P.C.
AGLICHTENSTEIN, P.E.
CONSULTING ENGINEERS

SCALE	DATE	SHEET NO
1" = 5'	MAR. '78	5 OF 18

Proposed Spillway

Prop. Curtain Wall

Exist. Core Wall to remain

Prop. Curtain Wall Sta. 1+44

Const. @ Sta 2+64.5
Chairs @ Sta 2+50

PT Sta 1+44

PLAN

10'

Note to locate nearby Exist. Core Wall between abutments. Include cost in Item 2

SECTION A-A

1" = 10'

ELEVATIO

1" = 10'

EL. 814.5

Prop. Abutment

Crest EL. 818.20

Prop. Spillway

EL. 816.0

EL. 813.5

Prop. Clay Blanket

Cravel overlay

Approx. Exist. Ground

Unclassified Escar. Full Length of Spillway
Select Fill

Exit Bridge to be
EL. 817.0
Clear in Water

EL. 814.0

EL. 814.2

Const. @

50' varies

EL. 822.0

50' varies

EL. 828.0

EL. 828.0

Topsoiling & Seeding

Prop. Clay Blanket

Level Berm


EL. 828.0

SECTION B-B

1" = 10'

Prop. Spillway - per the Note

EARL RESERVOIR



PLAN

POSSIBLE SEQUENCE OF CONSTRUCTION

1. Divert water thru existing 12" outflow pipe. Cut notch thru corewall. Excavate unnecessary material under proposed spillway. Remove existing mudgate valve. Partially backfill excavation. Construct & encase new mudgate structure.
2. Divert water thru mudgate structure. Reconstruct & raise 12" Main. (A cap for the 12" Main will be kept available in place of right in case of heavy rain.)
3. Divert water thru both the 12" Main & the mudgate & complete backfill under proposed spillway.
4. Construct Spillway, Apron & Surface Wall.
5. Construct Pedestrian Bridge & Railing.
6. Complete Embankment, Clay Blanket & Channel work. Remove existing bridge.
7. Complete Miscellaneous Work.

Notes:


1. This sequence of construction is suggested but does not in any way limit the contractor to his selected method of construction. Contractor shall be responsible for the sequence of construction to the extent of the start of construction for each item.
2. Pedestrian & Vehicular Traffic to be detoured.

ELEVATION


PLATE 3

REHABILITATION OF EARL RESERVOIR		
DATE OF PREPARATION: _____		
GENERAL PLAN & ELEVATION		
RAINBOW ASSOC. P.C. Arlington P. E. CONSULTING ENGINEERS	SCALE: DATE: _____	

2



SECTION C-C
1"=5'




SECTION B-B
1"=5'

Note:
All exposed clay blanket shall be covered covering of gravel 3" thick. Care to be taken to prevent clay blanket.


PLATE 7

WENDEL T. ...		
EARL ...		
CLAY BLANKET		
RANDOLPH ASSOC., P.C.
A.E. LICHTENBERG, P.E.
CONSULTING ENGINEER


2





PLAN
N.T.S.




PLAN




ELEVATION






21 - 3/8" dia
4-1/2" dia
concrete

B
PLAN




ELEVATION



SECTION B-B

INTAKE HEADWALL DETAILS

3'-10"





Note:
 1) Shop Drawings for MUDGATE STRUCTURE
 2) Water Supply Structure
 3) Retention Structure
 4) Foundation Structure
 5) All structures to be constructed with concrete

PLATE

SECTION A-A
4'-11"-0"


2



SECTION C-C



SECTION A-A




SECTION B-B


Minimum Weights

Weight of Grate	385 ⁰
Weight of Frame	372 ⁰
Weight of Back	169 ⁰
Weight of Curb piece	6'-225 ⁰
	8'-255 ⁰
	10'-265 ⁰
	12'-322 ⁰


FRAME-BACK-CURB
PIECE AND GRATE
FOR
INLET TYPE B
CATCH BASIN TYPE C
Scale 1/8"=1'-0"





SECTION A-A



SECTION A-A




SECTION A-A



UNDERSIDE OF COVER


Weight of Grate: 372⁰
Weight of Cover: 169⁰



DETAIL OF SEAT
Half Size



DETAIL OF NON-ROD LUG
Half Size




Set curb piece in
direction of adjacent
curb

Concrete Curb - 1/2" MIN. THK
WHERE CURB PIECE


**INLET TYPE B
WITH O.I. CURB PIECE-BACK-FRAME
AND GRATE**

Scale 1/2" = 1'-0"

This inlet may be constructed of brick, concrete or concrete block. If brick or concrete block is used the bottom shall be as shown for concrete.




SECTION B-B



SECTION B-B

INLETS TYPE B1 & B2

Inlets Type B1 or Type B2 shall be constructed as shown for Type B except as shown.




INLET TYPE	DIMENSION A
B1	4'-0"
B2	5'-0"

No Scale

GENERAL NOTES

1. Corbeling of inlet walls shall be done at the rate of 1/2" per 6" of height of wall. Maximum corbel 6" per wall.
2. When the item of manholes, catch basins, or catch basins, additional depth is shown in the proposal and the depth of a drainage manhole is as measured from top of edge of grate to top of drainage structure, the top of the manhole below a depth of 6' shall be 12" from wall. The overall horizontal dimensions of manholes shall be increased 12" and shall to rest the depth increased to 12".
3. Except for catch basins and traps, all manhole footings and manholes shall be constructed in two stages, and the bottom of the footing shall be 6" below the curb top of the manhole in laterals and 10" in manholes.
4. The item of steel head casting, raising or lowering the head casting of brick and catch basins, or the raising of manhole base castings, for a maximum of 6" in other changes in position of head casting shall be considered as reconstructed manholes or reconstructed basins or catch basins.
5. When curb pipe height specified is greater than curb face height, adjust the grade of grate so that the top of curb shall be at the same elevation as the top of curb (SEE DETAILS).




SECTION B-B

CONTROL


**CATCH BASIN TYPE C
WITH C.I. CURB PIECE-BACK-FRAME
AND GRATE**

Scale 1/2" = 1'-0"

This basin may be constructed of brick, concrete or concrete block. If brick or concrete block is used the bottom shall be as shown for concrete. Alternate vertical joints of brick or block in five lower courses shall be left open. When constructed of concrete a leaching basin 18" x 18" x 2'-0" deep of 2" trap rock or approved field stone shall be constructed.



SECTION B-B



SECTION B-B

O.D. OF SETTING BASE FOR TYPE B1 OR B2 HEIGHT IS 6" GREATER THAN CURB FACE

3

PLU

ENGINEER'S REPORT
REHABILITATION OF EARL RESERVOIR

TOWN OF WOODBURY
COUNTY OF ORANGE
STATE OF NEW YORK

RAIMONDI ASSOCIATES, P.C.
110 STAGE ROAD
MONROE, NEW YORK 10950

A. G. LICHTENSTEIN & ASSOCIATES
1298 TEANECK ROAD
TEANECK, N.J. 07666

MARCH 1978

GENERAL

The Earl Reservoir is a 16 + acre pond located in the Town of Woodbury just north of Ridge Road about one mile west of the intersection of Ridge Road and New York State Route 32 (see Exhibit A). The pond is presently used as a recreational area for the residents of the Town. Up until 30 + years ago the water in the pond was used for water supply purposes although the Town still maintains the right to use the water for said use in case of emergency need.

Water is contained in the pond by a masonry and earth dam constructed 65 years ago. The dam is approximately 425 feet in length with a maximum height above the old stream bed of some 26 feet. The existing spillway is divided into three (3) parts:

1. 15' long - 0.3' deep
2. 16' long - 1.0' deep
3. 15' long - 0.8' feet (total capacity 80+ cfs)

The dam has a gated 24" emergency outlet (non-operative) as well as a 12" diameter intake for water supply purposes now used to drain most of the lake if needed.

Over the past few years several leaks in the outside face of the dam have been noted. During the summer of 1977 with little or no inflow for extended periods the lake level dropped more than 5 feet. Verification of location and magnitude of these leaks have been made by an underwater examination of the upstream face of the dam.

NOTE: A 2' diameter sinkhole near the spillway necessitated lowering of the lake beginning October, 1977. Lake level down 16' +, lake surface reduced by 90% +.

DESCRIPTION OF WATERSHED

The pond is located in a bowl shaped basin with the northern limit being the ridge of the Schunnemunk Mountains. Upstream ground slopes are quite severe, in some areas being well in excess of 30%. The predominant land use in the upstream watershed is forest with a small percent of swamp and an even smaller percent (1+) of suburban lands. Due to the shape of the basin there are several main tributaries to the pond. In developing the hydrology the drainage basin was divided into six (6) significant areas to better establish the Q100 at the spillway.

Below the dam the stream flows through a fairly steep reach for a distance of some 3000 + feet. Below this point the channel flattens and broadens considerably into a wide flood plain. There are two road crossings in the first reach namely Ridge Road about 1000 + feet downstream of the dam and Jones Road about 1700 + feet downstream. At Ridge Road the roadway is about 15 feet above the stream bed. Any flood surge should be substantially attenuated at this point. The upstream easterly bank at Ridge Road is approximately 12 feet higher than the stream. During a surge water could flow down Ridge Avenue in an easterly direction. However, this possible overflow

should not have a significant downstream effect. Between Ridge Road and Jones Road there are five dwellings in the vicinity of the channel. However, these homes are 12-15 feet higher than the stream. At Jones Road the road bed is more than 10 feet above the stream. There is one dwelling below Jones Road, however, any possible overflow should not present a serious hazard to same. Below Jones Road, there are no dwellings until the channel broadens considerably. The remaining downstream basin has scattered dwellings. Based upon our inspection of the area, it is our opinion that a hazard rating of "b" as defined by the SCS should be adequate for the design of the spillway. A review of the attached calculations should reveal that design of the proposed spillway is quite conservative with a substantial factor of safety built-in.

HYDROLOGY

The Q100 for the project was developed using the Soil Conservation Service "Soil Complex Method" as explained in Technical Release # 55. As indicated the shape of the basin necessitated dividing it up into six areas. This procedure produced a fairly high Q100 of 1258 cfs for a total tributary area of 464 acres. The general data input included a 100 year, 24 hour rainfall of 7.20", a Type II rainfall distribution, a hydrologic soil Group of C based upon 5 different soil types within the basin and a general land use conforming to woods (see calculations).

A copy of our calculations were submitted to the SCS office in Middletown. Attached and labelled Exhibit S is an endorsement by the SCS of our evaluations.

HYDRAULICS

To preserve the beauty of the existing structure it is intended to rebuild a portion of the dam upstream of the existing face. The drawings indicate the new dam to be rectangular in shape having a single spillway 110 feet in length. The spillway overflow will cascade down over a series of steps provided as an energy dissipator as well as for its aesthetics. Below the spillway an opening will be made in the existing dam to allow the flow to continue downstream. The existing bridge shown on the plans will be removed with access to the recreation site being provided from a different source.

Using 150% of Q100 for design of the spillway and a spillway length of 110 feet a routed discharge of 1392cfs has been computed. The maximum elevation of the upstream pool is 830.65 or some 2.45 feet above the spillway crest. Total storage above the spillway crest is approximately 44.82 acre feet. The existing top of the dam (elevation 829.8) to be raised to elevation 832.00 to provide necessary freeboard.

To check if the single spillway can evacuate 75% of the storage between maximum high water and the spillway crest within 48 hours we may calculate as follows. Using the falling head equation (no inflow assumed)

$$dt = A \cdot dy / C \cdot y^{3/2}$$

* - A assumed constant

Integrate between $y=H$ (2.45 ft) and $Y=0$ (Spillway Crest)

$$t = 2A / CHL^{1/2}$$

$$A = \text{Average Lake Area} = \frac{\text{Total Storage at Q Peak}}{\text{Depth of Flood Above Crest}} = \frac{44.82}{2.45} = 18.29 \text{ Acres}$$

$$18.29 \text{ Acres} = 796,712 \text{ Square Feet}$$

$$C = \text{Weir Coefficient} = 3.3$$

$$L = \text{Length of Spillway} = 110 \text{ feet}$$

$$t = \text{time to empty} = \frac{2(796,712)}{3.3(110)(2.45)^{1/2}} = 2805 \text{ Seconds} = 47 \text{ + Minutes}$$

No Problems to evaluate all flow above spillway Crest within 48 hours.

Similarly the criteria of being able to evacuate 90% of the storage below the lowest spillway crest within 14 days may be checked as follows:

First it must be noted that when it was decided to lower the water in the lake for safety, the existing 12" intake was utilized for this purpose. With normal inflow, it took approximately 4 to 5 days to lower the lake some 16 feet. It has already been noted that at this elevation more than 90% of the lake area is gone.

The present proposal is to reactivate the mud gate. The plans indicate that a 20 inch outlet is proposed for this purpose. It is obvious from the discussion above that the new mud gate facility would be more than adequate to meet the criteris of discharging 90% of the lake volume below the spillway crest within a 14 day period. However, to tie it down more exactly, we may calculate the following:

$$dt = A \cdot dy / C \cdot a \cdot \sqrt{2gy}$$

Integrate between $y=H$ (H_t of Spillway Crest Above ϕ of 20" outlet) and $y=H_2$ (Selected at 1' above ϕ of 20" outlet)

$$t = \frac{2A}{C \cdot a} \left(\frac{\sqrt{H_1}}{\sqrt{2g}} - \frac{\sqrt{H_2}}{\sqrt{2g}} \right)$$

A = Average Lake Area between Spillway Crest (16+) and Lake @ El.810 (2 Ac) or 9 Ac (392,040 Sq. Ft.)

$$C = \text{Orifice Constant} = \text{Say } 0.6$$

$$a = \text{Area of } 20" \text{ } \phi \text{ outlet pipe} = 2.18 \text{ Sq. Ft.}$$

$$H_1 = 17 \quad H_2 = 1$$

$$t = \frac{2(392,040)}{0.6(2.18)} \left(\frac{\sqrt{17}}{\sqrt{8.01}} - \frac{\sqrt{1}}{\sqrt{8.01}} \right) = 2.71 \text{ Days} \quad \text{NO PROBLEM}$$

Upon cascading down the spillway the flood will pass through an opening to be cut into the old dam. Said opening will be 15 feet wide conforming to the width between buttresses below the present spillway. Considering the opening as a culvert with inlet control, the total depth of flow using procedures in BPR (HEC # 5) would be 11.0 feet. With an invert proposed of 815.0 this depth converts to 826.0. The opening proposed still allows for lake control at the spillway.

Upon passing through the opening in the old dam the water drops about 10-1/2 feet into a plunge pool which is aided by a three foot high check dam located immediately below the drop. This installation will aid in the dissipation of energy created by the flood. The entire channel below the dam will be rip-rapped a distance of some 125 feet.

STRUCTURAL CONSIDERATIONS

Earl Reservoir was constructed circa 1912 as an earth dam with a masonry core wall. In recent years, there have developed various forms of leaks through the dam masonry with the water level dropping several feet below the spillway, particularly in the summer season. Also, the stone masonry has been damaged by wave and ice action on its upper portions. These concerns combined with aesthetic considerations and a need to improve the hydraulic capacity of the spillway led to the development of the proposed structure.

Soil Borings were taken for the proposed project. The underlying soils for the structure were found to be dense and sandy soils containing varying proportions of silty clay. These materials were deemed to be of a suitable bearing and permeability capacity to meet the needs of the project. A copy of the Boring Logs are included elsewhere in this Report.

An underwater inspection of the existing structure made by certified divers and several sink holes were discovered along and near the upstream face of the core wall. One sink hole in particular was approximately two (2') feet in diameter and appeared to be causing a migration of fine materials, through the dam, to an outflow area discovered 75'+ downstream. Concern for the progressive nature of this type of failure led to the lowering of the reservoir.

In light of the accumulated data, the proposed structure was selected to incorporate a steel sheeting cut-off wall capped by a reinforced concrete curtain wall along the existing core wall. This is tied into a reinforced concrete spillway with a designed crest length of 110'.

Various other architectural and aesthetic treatments were included in the proposed projects to compliment the recreational nature of the site.

Re: Our File # 77-1170
Earl Reservoir

ESTIMATE OF QUANTITIES

<u>Item Number</u>	<u>Item</u>	<u>Unit</u>	<u>Quan.</u>	<u>Unit Price</u>	<u>Total</u>
1.	Clearing & Grubbing	L.S.	L.S.	\$5,000.	\$ 5,000.00
2.	Removal of Bridge & Core-wall Section	L.S.	S.S.	10,000.	\$ 10,000.00
3.	Unclassified Excavation and Disposal	C.Y.	1900	\$ 3	\$ 5,700.00
4.	Select Fill	C.Y.	1250	\$ 6	\$ 7,500.00
5.	Class B Concrete For Structures	C.Y.	900	\$ 160.	\$144,000.00
6.	Bar Eninforcement for Structures	LBS.	24,500	\$.65	\$ 15,925.00
7.	Corrugated Steel Pipe 24 inch diameter	L.F.	375	\$ 20.	\$ 7,500.00
8.	Mudgate Structure	L.S.	L.S.	\$ 5,000.	\$ 5,000.00
9.	Water Supply Structure Modification	L.S.	L.S.	\$ 3,000.	\$ 3,000.00
10.	Inlets, Type A	Unit	3	\$ 1,000.	\$ 3,000.00
11.	Manholes	Unit	1	\$ 1,500.	\$ 1,500.00
12.	Beam Guide Rail (Timber Faced)	L.F.	125	\$ 10.	\$ 1,250.00
13.	Pipe Railing	L.F.	510	\$ 20.	\$ 10,200.00
14.	Topsoil (4" TH.) and Seeding	S.Y.	1100	\$ 3.	\$ 3,300.00
15.	Dry, Rip-Rap	C.Y.	170	\$ 30.	\$ 5,100.00
16.	Permanent Steel Sheet Piling	S.F.	8700	\$ 12.	<u>\$104,400.00</u>
		Total			\$332,375.00

HYDROLOGIC EVALUATION
Earl Reservoir - Town of Woodbury

Total Drainage Area - 464 acres (0.725 Sq. Mi.) Exhibit A
Storm Precipitation - 7.20" (100 year rainfall) Exhibit B
Use SCS Type II Rainfall Distribution

- A) Divide basin into 6 drainage areas.
- B) Use procedures SCS TR#55.

Drainage Area #1

- a) D.A.=110 acres (0.172 SQ. Mi.)
- b) $T_t \sim 1$) Overland Flow 40' in 600' (fig. 3-1) also Exhibit C
2) Channel Flow 650' in 3700 (see exhibit attached)
Exhibit D
 $T_t(1) = 600/0.66(60) = 15$ minutes
 $T_t(2) = 9$ minutes
 $T_c \sim 24$ minutes, Use 0.4 hour
- c) Hydrologic Soil Group - Use C (soil types, bath, swartz-wood & Lacka wanna, Scribia-Sun, Arnot-Oqaqua Rocky and Arnot Rock Outcrop)
- d) Land Use - Good Woods - Exhibit E
- e) Curve Number - 70 - Exhibit E
- *f) Run-off (precipitation) - 3.79" = d, Note: From SCS TP 149.
- g) Travel Time to Lake - T_t 14' in 700' = 5+minutes (say 0.10 hour)

*May obtain directly from SCS National Engineering Handbook.

Drainage Area #2

- a) D.A. = 107 acres (0.167 Sq. Mi.)
- b) $T_t \sim 1$) O.F. 20' in 400' $T_t = 13$ minutes
2) C.F. 670' in 4500' $T_t = 12$ minutes
 $T_c \sim 25$ minutes Use 0.4 hour
- c) Hydrologic Soil Group - C
- d) Land Use - Good Woods
- e) Curve Number - 70
- f) R.O. = 3.79"
- g) T_t to Lake - 0.10 hour

Drainage Area #3

- a) D.A. = 144 acres (0.225 Sq. Mi.)
- b) $T_t \sim 1$) O.F. 80' in 800' $T_t = 19$ minutes
 - 2) C.F. 400' in 1200' - (swamp) - 180' in 2200'
 $T_t = 11$ minutes $T_c = 30$ minute or 0.50 hour
- Note: A swampy area consisting of 10+ acres exists mid-way up basin. Based upon methods in TR-55 peak flow could be reduced by some 25%. The new peak (using table 5-3) coincides with a T_c in excess of 0.8 hour (see Exhibit F). Use $T_c \sim 0.75$ hour.
- c) Hydrologic Soil Group - C
- d) Land Use - Good Woods
- e) Curve Number - 70
- f) Run-off - 3.79"

Drainage Area #4

- a) D.A. = 20 acres (0.031 Sq. Mi.)
- b) $T_t = T_c =$ O.F. = 100' in 1000' ~ 21 minutes, use 0.3 hour
- c) Hydrologic Soil Group - 5 acres D and 15 acres C
- d) Land Use - Good Woods
- e) Curve Number - $5(77) + 15(70)/20 = 71.8$
- f) Run-off - 3.97"

Drainage Area #5

- a) D.A. = 25 acres (0.039 Sq. Mi.)
- b) $T_t = T_c =$ O.F. = 140' in 1100' ~ 20 minutes, use 0.3 hour
- c) Hydrologic Soil Group - C
- d) Land Use - Good Woods
- e) Curve Number - 70
- f) Run-off ~ 3.79 "

Drainage Area #6

- a) D.A. = 58 acres (0.091 Sq. Mi.)
- b) $T_t = T_c =$ O.F. = 110' in 1250' ~ 28 minutes, use 0.5 hour

- c) Hydrologic Soil Group - 43 acres C and 15 acres pond
- d) Land Use - Good Woods
- e) Curve Number - $43(70) + 15(100)/58 = 77.8$
- f) Run-off $\sim 4.64"$

See Exhibit G-3

FLOOD ROUTING (STEP METHOD)

A) Stage vs. Discharge

- 1) Select spillway length to keep lake depth to within 3.0 of normal during flood flow.
- 2) Provide additional freeboard - Require at least 1.0' above flood level.
- 3) Use trapezoidal weir section - inclined upstream face vertical downstream face - Exhibit H
- 4) Select weir length 110 feet - use C=3.3 (conservative)

<u>Stage (ft)</u>	<u>Discharge (cfs)</u>	<u>Stage (ft)</u>	<u>Discharge(cfs)</u>
0	-	2.3	1342
0.3	63	2.8	1804
0.8	275	3.3	2176
1.3	570	3.8	2689
1.8	930		

Datum Elevation 828.2

B) Stage vs. Storage

<u>Stage (ft)</u>	<u>Elevation</u>	<u>Lake Area (ac)</u>	<u>Storage (Ac-ft)</u>
0	828.2	16.00	
0.3	828.5	16.82	4.92
0.8	829.0	17.65	13.54
1.3	829.5	18.47	22.57
1.8	830.0	19.30	32.01
2.3	830.5	19.85	41.80
2.8	831.0	20.40	51.86
3.3	831.5	20.95	62.20
3.8	832.0	21.50	72.81

FLOOD ROUTING CHART A

* $\Delta t = 0.10$ hour - 360 seconds

Stage (ft)	A(Acres)	Q(cfs-out)	Q/2	Storage (Ac-ft)	S/ Δt *	S/ $\Delta t - Q/2$	S/ $\Delta t + Q/2$
0	16.00	-	-	0	0	--	-
0.3	16.82	63	32	4.92	595	563	627
0.8	17.65	275	138	13.54	1638	1500	1776
1.3	18.47	570	285	22.57	2731	2446	3016
1.8	19.30	930	465	32.01	3873	3408	4338
2.3	19.85	1342	671	41.80	5058	4387	5729
2.8	20.40	1804	902	51.86	6275	5373	7177

FLOOD ROUTING CHART B - See Exhibit J

Hour	Inflow(cfs)	Iav	150% Iav	S/ $\Delta t - Q/2$	S/ $\Delta t + Q/2$	H(ft)	Qout-cfs
11.0	47	-	-	-	-	.15	20(est)
11.1	55	51	77	285	362	.17	25
11.2	64	60	90	325	415	.20	32
11.3	74	69	104	385	489	.24	43
11.4	84	79	119	465	584	.29	56
11.5	95	90	135	550	685	.33	69
11.6	145	120	180	630	810	.39	88
11.7	217	181	272	740	1012	.48	121
11.8	442	330	495	905	1400	.65	190
11.9	799	621	932	1225	2157	.98	352
12.0	1107	953	1430	1850	3280	1.41	608
12.1	1258	1183	1774	2670	4444	1.85	913
12.2	1211	1235	1853	3540	5393	2.19	1176
12.3	1084	1148	1722	4200	5922	2.38	1333
12.4	922	1003	1509	4600	6109	2.45	1392
12.5	759	841	1262	4725	5987	2.41	1358





EXHIBIT A
EARL RESERVOIR
TOWN OF WOODBURY

West Pk
Girls Cal
Central
Valley
Golf
Course

CONTINENTAL UNITED STATES

100-YEAR 24-HOUR RAINFALL (INCHES)



Prepared by U. S. Weather Bureau

EXHIBIT B

**EARL RESERVOIR
TOWN OF WOODBURY**

then ... by dividing the total overland flow length by the average
velocity

EXHIBIT C




Figure 3-1.--Average velocities for estimating travel time for overland flow.

Storm sewer or road gutter flow

Travel time through the storm sewer or road gutter system to the main open channel is the sum of travel times in each individual component of the system between the uppermost inlet and the outlet. In most cases, average velocities can be used without a significant loss of accuracy. During major storm events, the sewer system may be fully taxed and additional overland flow may occur, generally at a significantly lower velocity than the flow in the storm sewers. By using average conduit sizes and an average slope (excluding any vertical drops in the system), the average velocity can be estimated using Manning's formula.


Since the hydraulic radius of a pipe flowing half full is the same as when flowing full, the respective velocities are equal. Travel time may

**EARL RESERVOIR
TOWN OF WOODBURY**

Nomograph For The Calculation Of "T"

EXHIBIT D

For use with
Rational Formula
to find "Q"




Example

Given $H = 900'$

$L = 3$ Miles

By Calc. $T = 40$ Min.

$$Q = CIA$$



EARL RESERVOIR
TOWN OF WOODBURY

EXHIBIT ETable 2-2. Runoff curve numbers for selected agricultural, suburban, and urban land use. (Antecedent moisture condition II, and $I_a = 0.2S$)

LAND USE DESCRIPTION	HYDROLOGIC SOIL GROUP			
	A	B	C	D
Cultivated land ^{1/} : without conservation treatment	72	81	88	91
: with conservation treatment	62	71	78	81
Pasture or range land: poor condition	68	79	86	89
good condition	39	61	74	80
Meadow: good condition	30	58	71	78
Wood or Forest land: thin stand, poor cover, no mulch	45	66	77	83
good cover ^{2/}	25	55	70	77
Open spaces, lawns, parks, golf courses, cemeteries, etc.				
good condition: grass cover on 75% or more of the area	39	61	74	80
fair condition: grass cover on 50% to 75% of the area	49	69	79	84
Commercial and business areas (85% impervious)	89	92	94	95
Industrial districts (72% impervious).	81	88	91	93
Residential: ^{3/}				
Average lot size				
Average % Impervious ^{4/}				
1/8 acre or less	65			
1/4 acre	38	77	85	90
1/3 acre	30	61	75	83
1/2 acre	25	57	72	81
1 acre	20	54	70	80
		51	68	79
				84
Paved parking lots, roofs, driveways, etc. ^{5/}	98	98	98	98
Streets and roads:				
paved with curbs and storm sewers ^{6/}	98	98	98	98
gravel	76	85	89	91
dirt	72	82	87	89

^{1/} For a more detailed description of agricultural land use curve numbers refer to National Engineering Handbook, Section 4, Hydrology, Chapter 9, Aug. 1972.

^{2/} Good cover is protected from grazing and litter and brush cover soil.

^{3/} Curve numbers are computed assuming the runoff from the house and driveway is directed towards the street with a minimum of roof water directed to lawns where additional infiltration could occur.

^{4/} The remaining pervious areas (lawn) are considered to be in good pasture condition for these curve numbers.

^{5/} In some warmer climates of the country a curve number of 95 may be used.

**EARL RESERVOIR
TOWN OF WOODBURY**

EXHIBIT F

Table E-3.---Adjustment factors where ponding and swampy areas are spread throughout the watershed or occur in central parts of the watershed

Ratio of drainage area to ponding and swampy area	Percentage of ponding and swampy area	Storm frequency (years)					
		2	5	10	25	50	100
500	0.2	0.94	0.95	0.96	0.97	0.98	0.99
200	.5	.88	.89	.90	.91	.92	.94
100	1.0	.83	.84	.86	.87	.88	.90
50	2.0	.78	.79	.81	.83	.85	.87
40	2.5	.73	.74	.76	.78	.81	.84
30	3.3	.69	.70	.71	.74	.77	.81
20	5.0	.65	.66	.68	.72	.75	.78
15	6.7	.62	.63	.65	.69	.72	.75
10	10.0	.58	.59	.61	.65	.68	.71
5	20.0	.53	.54	.56	.60	.63	.68
4	25.0	.50	.51	.53	.57	.61	.66

Table E-4.---Adjustment factors where ponding and swampy areas are located only in upper reaches of the watershed

Ratio of drainage area to ponding and swampy area	Percentage of ponding and swampy area	Storm frequency (years)					
		2	5	10	25	50	100
500	0.2	0.96	0.97	0.98	0.98	0.99	0.99
200	.5	.93	.94	.94	.95	.96	.97
100	1.0	.90	.91	.92	.93	.94	.95
50	2.0	.87	.88	.88	.90	.91	.93
40	2.5	.85	.85	.86	.88	.89	.91
30	3.3	.82	.83	.84	.86	.88	.89
20	5.0	.80	.81	.82	.84	.86	.88
15	6.7	.78	.79	.80	.82	.84	.86
10	10.0	.77	.77	.78	.80	.82	.84
5	20.0	.74	.75	.76	.78	.80	.82

These conditions may occur in a proposed or existing urban or suburban area and the adjustment factors from tables E-2, E-3, or E-4 should be applied after the peaks have been adjusted for the effects of urbanization as described in chapter 4.

Example E-3

A 5-acre pond is located at the downstream end of a 100-acre watershed in which a housing development is proposed. The average watershed slope is 4 percent and the present-condition curve number is 75. After the installation of the housing development, 30 percent of the watershed will be impervious and 50 percent of the hydraulic length will be modified. The future-condition curve number is estimated to be 80. For a rainfall

**EARL RESERVOIR
TOWN OF WOODBURY**

EXHIBIT G-1

Table 5-3.--Tabular discharges for type-II storm distribution (csm/in)--Continued Sheet 2 of 5

5
1
03

T ₂	TIME OF CONCENTRATION = 0.3 hours Hydrograph time in hours																							
	11.0	11.5	11.7	11.8	11.9	12.0	12.1	12.2	12.3	12.4	12.5	12.6	12.7	12.8	12.9	13.0	13.2	13.5	14.0	14.5	15.0	16.0	18.0	20.0
0	21	43	141	324	586	658	535	372	251	184	148	124	102	86	77	71	61	51	41	34	30	24	18	14
0.25	17	31	43	67	134	279	461	558	530	428	318	234	179	143	116	97	76	59	45	37	32	25	18	15
0.50	13	22	29	34	42	65	124	238	78	479	499	447	363	281	216	168	110	74	51	41	34	26	19	15
0.75	10	17	21	24	27	32	41	63	114	203	316	413	457	443	389	319	198	105	60	45	37	28	20	15
1.00	8	13	16	18	20	23	26	31	40	60	103	176	269	358	415	426	344	182	77	51	41	30	20	16
1.50	5	8	10	11	12	13	15	16	18	21	24	28	36	52	82	132	272	382	192	81	52	34	22	17
2.00	3	5	6	7	8	8	9	10	11	12	14	15	17	19	21	25	44	151	351	198	85	41	24	18
2.50	1	3	4	4	5	5	6	6	7	8	9	10	11	12	14	17	28	162	328	200	54	27	19	14
3.00	0	1	2	2	3	3	3	4	4	5	5	6	6	7	8	9	10	14	33	169	309	94	30	20
3.50	0	0	1	1	1	1	2	2	2	3	3	3	4	4	5	5	6	9	14	38	172	294	35	22
4.00	0	0	0	0	0	0	1	1	1	1	1	2	2	2	3	3	4	5	9	15	43	281	42	24

T ₂	TIME OF CONCENTRATION = 0.4 hours Hydrograph Time in Hours																								
	11.0	11.5	11.7	11.8	11.9	12.0	12.1	12.2	12.3	12.4	12.5	12.6	12.7	12.8	12.9	13.0	13.2	13.5	14.0	14.5	15.0	16.0	18.0	20.0	
0	20	39	103	224	419	558	575	451	331	247	190	155	127	105	90	80	66	53	42	35	30	24	18	14	
0.25	15	28	38	54	98	196	343	467	508	464	380	295	228	180	145	119	87	64	47	38	32	26	19	15	
0.50	12	20	26	30	37	53	92	172	286	395	462	453	402	332	266	211	137	84	54	42	35	27	19	15	
0.75	10	16	19	22	25	29	36	51	85	150	242	338	407	429	406	356	241	128	65	47	38	29	20	16	
1.00	8	12	15	17	19	21	24	28	34	49	78	132	208	292	362	403	368	220	88	55	42	30	21	16	
1.50	5	8	9	10	11	12	14	15	17	19	22	25	31	43	65	102	220	365	224	93	56	35	22	17	
2.00	3	5	6	6	7	8	9	9	10	11	13	14	16	17	20	23	37	119	338	225	99	43	24	18	
2.50	1	3	3	3	4	4	5	5	6	6	7	8	9	10	11	12	13	16	25	132	317	225	58	27	19
3.00	0	1	2	2	2	3	3	3	4	4	5	5	6	6	7	8	10	13	28	140	300	107	31	21	
3.50	0	0	1	1	1	1	1	2	2	2	3	3	3	4	4	5	6	8	13	32	146	286	36	22	
4.00	0	0	0	0	0	0	0	1	1	1	1	1	2	2	2	3	3	5	8	14	36	275	44	24	

EARL RESERVOIR
TOWN OF WOODBURY

EXHIBIT G-2

Table 5-3.--Tabular discharges for type-II storm distribution (csm/in)--Continued Sheet 3 of 5

T _p	TIME OF CONCENTRATION = 0.5 hours by equal time in hours																							
	11.0	11.5	11.7	11.8	11.9	12.0	12.1	12.2	12.3	12.4	12.5	12.6	12.7	12.8	12.9	13.0	13.2	13.5	14.0	14.5	15.0	16.0	18.0	20.0
0	10	26	50	166	321	433	496	474	395	309	242	194	158	120	109	94	75	57	43	36	31	25	18	15
0.25	15	35	37	52	94	172	277	372	425	424	353	286	270	221	182	150	107	73	49	39	33	26	19	15
0.50	12	20	25	30	33	58	101	169	252	327	374	385	366	329	285	241	169	103	59	44	36	27	19	15
0.75	9	15	19	22	25	30	41	63	103	162	229	272	335	354	348	325	255	157	77	50	39	29	20	16
1.00	7	12	15	17	19	21	25	31	43	66	103	153	210	264	304	327	217	231	109	61	44	31	21	16
1.50	5	8	9	10	11	12	14	15	17	20	24	31	43	63	92	129	214	295	224	115	65	36	23	17
2.00	3	5	6	6	7	8	9	10	11	12	13	14	16	19	23	30	50	143	271	216	120	46	25	18
2.50	1	3	3	4	4	5	5	6	7	7	8	9	10	11	12	14	18	39	150	253	209	71	28	19
3.00	0	1	2	2	2	3	3	4	4	4	5	5	6	7	7	8	10	15	48	154	239	126	32	21
3.50	0	0	1	1	1	1	2	2	2	2	3	3	4	4	5	5	6	8	16	56	155	227	38	23
4.00	0	0	0	0	0	1	1	1	1	1	1	2	2	2	3	3	4	5	9	19	63	217	52	25

TIME OF CONCENTRATION = 0.75 hours
by equal time in hours

T _p	TIME OF CONCENTRATION = 0.75 hours by equal time in hours																							
	11.0	11.5	11.7	11.8	11.9	12.0	12.1	12.2	12.3	12.4	12.5	12.6	12.7	12.8	12.9	13.0	13.2	13.5	14.0	14.5	15.0	16.0	18.0	20.0
0	15	29	57	58	163	248	329	375	328	359	325	276	232	195	165	142	107	76	51	39	33	26	19	15
0.25	12	21	29	29	61	100	158	227	291	336	355	348	321	285	247	212	156	103	62	44	36	27	19	15
0.50	10	16	21	24	29	41	63	100	150	208	253	305	327	329	314	268	226	147	79	52	40	29	20	16
0.75	8	13	16	18	20	24	29	43	65	98	122	152	239	270	303	311	286	208	107	63	45	31	21	16
1.00	6	10	13	14	15	17	20	24	31	44	65	95	134	177	220	256	294	264	149	81	53	33	21	16
1.50	4	6	9	9	10	11	12	13	14	16	19	23	31	42	60	83	147	269	248	152	85	40	23	17
2.00	2	4	5	5	6	7	7	8	9	10	11	12	14	16	18	23	39	97	251	235	153	56	26	19
2.50	1	2	3	3	4	4	5	5	6	7	7	8	9	10	10	11	15	28	107	218	236	91	29	20
3.00	0	1	1	2	2	2	2	3	3	4	4	5	5	6	6	7	8	12	33	113	225	153	34	22
3.50	0	0	1	1	1	1	1	1	2	2	2	3	3	3	4	4	5	7	13	29	217	215	44	24
4.00	0	0	0	0	0	0	0	1	1	1	1	1	1	2	2	2	3	4	7	15	45	207	63	26

**EARL RESERVOIR
TOWN OF WOODBURY**

CALC. UNIT 63

(ESTIMATED)

11 11.3 11.3 11.4 11.6

PEAK DISCHARGE CALCULATIONS (BY TRIANGULAR METHOD - EXHIBIT C)


SUB. AREA TC T_r DA. RAIN CN RO. HOUR

1	0.4	0.1	0.172	7.20"	70	3.79	12	23	50	102	189	269	314	298	262	218	173	138	109	88	73	62
2	0.4	0.1	0.167	"	70	3.79	11	22	48	99	183	261	305	289	254	211	167	133	105	85	70	60
3	0.75	-	0.225	"	70	3.79	12	24	48	83	138	211	281	320	331	314	277	235	197	166	140	121
4	0.3	-	0.031	"	71.8	3.97	2	5	17	39	72	81	66	46	31	22	18	15	12	10	9	8
5	0.3	-	0.039	"	70	3.79	3	6	21	49	90	102	83	58	39	27	22	18	15	12	11	10
6	0.5	-	0.091	"	77.8	4.64	7	15	33	70	127	183	208	200	167	130	102	81	66	54	46	39

47 95 217 442 799 1107 1258 1211 1084 922 757 610 504 415 349 300 55 64 74 84 145

EARL RESERVOIR
TOWN OF WOODBURY

Q_{100} (PEAK) = 1258 C.F.S.



30
EXHIBIT J
EARL RESERVOIR
TOWN OF WOODBURY

EXHIBIT H

5-26 HANDBOOK OF HYDRAULICS

weirs of this type, each 4.9 ft high, were performed by the U.S. Deep Waterways Board.

Coefficients covering the range of Bazin's experiments are given in Table 5-9. Table 5-10 gives coefficients resulting from the experiments by the U.S. Deep Waterways Board.

For weirs of trapezoidal cross section with sloping upstream and vertical downstream face

(Fig. 5-10) there are five series of experiments by the U.S. Deep Waterways Board. All the models for these experiments were approximately 4.9 ft high, and the breadth of crest *AB* was either 0.33 or 0.66 ft. The length of all weirs was 6.53 ft. Table 5-11 gives coefficients derived from these experiments.

TYPICAL




Fig. 5-10. Trapezoidal weir.



Fig. 5-11

Weirs of Irregular Section. Figures 5-11 to 5-15 represent models of weirs experimented on by the U.S. Deep Waterways Board, under the direction of G. W. Rafter, at the hydraulic laboratory of Cornell University. From four to seven experiments were run on each model, the range of head varying approximately from 1 to 5.5 ft. Values of *C* tabulated from these experiments are given in Table 5-12.




Fig. 5-13



Fig. 5-14

Experiments for the U.S. Geological Survey, under the direction of Robert E. Horton, were performed in 1903 at the hydraulic laboratory of Cornell University to determine the coefficients of discharge of weirs modeled after various types

WEIRS

5-27

of dams. Figures 5-16 to 5-25 show forms of crests of models experimented on. The weirs were all 11.25 ft high and either 8 or 15 ft long. The purpose of the experiments was to enable the Geological Survey to determine more accurately discharges




Fig. 5-16



Fig. 5-17




Fig. 5-18



Fig. 5-19



Fig. 5-20




Fig. 5-21




Fig. 5-22




Fig. 5-23




Fig. 5-24




Fig. 5-25

over weirs at gauging stations. Coefficients obtained from these experiments are given in Table 5-13.

Figure 5-24 is a cross section of the old dam at Austin, Tex. Five series of gagings of flow over this dam were made with a current meter by Taylor¹ in 1900. The range of head was from 0.42 to 1.44 ft.

¹T. G. Taylor, The Austin Dam, U.S. Geol. Survey Water Supply and Irrigation Paper 40, 1900.

EARL RESERVOIR TOWN OF WOODBURY

W. M. WALSH COMPANY, INC.
Crosskill, New Jersey

TEST BORING DATA

TEST HOLE NO. W-1

Project Earl's Lake

Location Woodbury, N.Y.

Drillings made by: A. Ecke

Arch. Engr. A.G. Lichtenstein

Date Started 9/21

Completed 9/27/77

Dr. of Ground Water

Raimondi Assoc.

Length of Casing Driven

Depth in Feet	Ground Line Elevation	Lake Surface	Materials Encountered	Blows on Spoon			
				0-6	6-12	12-18	18-24
0							
5			Water				
10							
15	15'		Mud & Clay				
18	18'		F/M Gray Sand, Silty Clay & Gravel				
20				1	22	25	33
23	23'						
25							
25			Brn. Clayey Silt, little fine Sand & Gravel				
29				2	50	71	75
30							
31	31'						
30			Bottom of boring	3	29	31	46
35							
40							
45							

Inside Dia. of Casing 2 1/2"
" " " Spoon 1 3/8"
Weight of Hammer on Casing 300 lbs.
" " " " Spoon 140 lbs.
Drop of Hammer on Casing 24"
" " " " Spoon 30"

DRY SAMPLE DATA			
Sample No.	Elevation bottom of Spoon	Total Penetration	Length of Sample
1	21'6"	18"	
2 *	26'6"	"	
3 #	31'0"	24"	
* Used 300# Hammer to drive Spoon.			

CORE DATA				
Sample No.	Elevation		Core Recovered	Boring Feet Per Hour
	Top	Bot.		

Type of Core Drill _____
Core Diameter _____

EXHIBIT T-1
EARL RESERVOIR
TOWN OF WOODBURY

W. M. WALSH COMPANY, INC.
Cresskill, New Jersey

TEST BORING DATA

TEST HOLE NO. W-2

Project Earl's Lake Woodbury, N. Y.

Location

Borings made by: A. Ecke

Archl. Engr. A. G. Lichtenstein

Date Started 9/22

Completed 9/22/77

Level of Ground Water Lake Surface

Raimondi Assoc.

Length of Casing Driven 30'

Depth in Feet	Ground Line Elevation	Materials Encountered	Blows on Spoon			
			0-6	6-12	12-18	18-24
0-14		Water				
14-15	29	F/C Gray Sand, Silty Clay, gravel & Boulders				
15-16	240					
16-17	57					
17-18	69					
18-19	114					
19-20	121	Brn. Silt, some fine sand & gravel	1	32	22	24
20-21	85					
21-22	72					
22-23	77	Red-brn. Silt, trc. fine sand & gravel				
23-24	112					
24-25	105					
25-26	79					
26-27	92	Red-brn. Silt & Sandstone				
27-28	121					
28-29	137					
29-30	145	Bottom of boring	3	69	100+	100+

Inside Dia. of Casing 2 1/2"
" " " Spoon 1 3/8"
Weight of Hammer on Casing 300 lbs.
" " " " Spoon 140 lbs.
Drop of Hammer on Casing 24"
" " " " Spoon 30"

DRY SAMPLE DATA			
Sample No.	Elevation bottom of Spoon	Total Penetration	Length of Sample
1 *	21'6"	18"	
2 *	26'6"	"	
3 *	31'6"	"	
* Used 300# Hammer to drive Spoon			

CORE DATA				
Sample No.	Elevation		Core Recovered	Boring Feet Per Hour
	Top	Bot.		

Type of Core Drill _____
Core Diameter _____

EXHIBIT T-2
EARL RESERVOIR
TOWN OF WOODBURY

DO NOT WRITE ON BACK OF SHEET

W. M. WALSH COMPANY, INC.
Crosskill, New Jersey

TEST BORING DATA

TEST HOLE NO. W-3

Project Earl's Lake

Location Woodbury, N.Y

Borings made by: A. Ecke

Arch. Engr. A.G. Lichtenstein
Raimondi Assoc.

Date Started 9/21 Completed 9/21/77

of Ground Water

Length of Casing Driven

Depth in Feet	Materials Encountered	Blows on Spoon			
		0-6	6-12	12-18	18
0	Ground Line Elevation Lake Surface				
1	3'6" Water				
5	6'0 Mud				
10	11' Gray Silty Clay, little fine sand	1	3	4	14
15	16' Gray Silty Clay, little to some fine sand	2	1	2	2
20	17' Black Organic Silt				
25	19' Gray Silty Clay trc. sand				
28	24' Brn. Silt, little fine sand & gravel	3	23	62	24
30	28' Brn. Silt,	4	28	130	100+
35	Chopped to 27'6" Drove rod to 28'				

Inside Dia. of Casing 2 1/2"
" " " Spoon 1 3/8"
Weight of Hammer on Casing 300 lbs.
" " " " Spoon 140 lbs.
Drop of Hammer on Casing 24"
" " " " Spoon 30"

DRY SAMPLE DATA			
Sample No.	Elevation bottom of Spoon	Total Penetration	Length of Sample
1	11'6	18"	
2	16'6	"	
3	21'6	"	
4 *	26'6	"	
* Used 300# Hammer			

CORE DATA				
Sample No.	Elevation		Core Recovered	Boring Feet Per Hour
	Top	Bot.		

Type of Core Drill _____
Core Diameter _____

EXHIBIT T-3

EARL RESERVOIR
TOWN OF WOODBURY

W. M. WALSH COMPANY, INC.
Crosskill, New Jersey

EST HOLE NO. W-4

Project Earl's Lake

Location Woodbury, N.Y.

borings made by: A. Ecke

Arch. Engr. A.G. Lichtenstein

Date Started 9/22

Completed 9/22/77

El. of Ground Water

Raimondi Assoc.

Length of Casing Driven

Depth in Feet	Blows Per Foot of Casing Penetration	Materials Encountered	Blows on Spoon				
			0-6	6-12	12-18	18-24	
0		Water					
5	5'						
3		F/M Gray Sand, Silty Clay, some Gravel					
4							
4							
6							
10	14'		1	4	8	15	
7		Brn. Clayey Silt, little fine Sand & Gravel (Boulder at 17')					
19							
38							
49							
15	14'			2	19	24	42
10							
300							
28			3	No Rec.			
56			3	32	34	39	
20							
14							
C							
H							
O							
P							
P							
F							
D							
30	30'		4	70	88	65	
	31'6"	Brn. Silt, trc. Sandstone					
		Bottom of boring					
35							
40		Casing Bent at 17-18' Unable to drive casing below 20' Washed & Chopped to 30'0					
45							
50							

Inside Dia. of Casing 2 1/2"
" " " Spoon 1 3/8"
Weight of Hammer on Casing 300 lbs.
" " " " Spoon 140 lbs.
Drop of Hammer on Casing 24"
" " " " Spoon 30"

DRY SAMPLE DATA			
Sample No.	Elevation bottom of Spoon	Total Penetration	Length of Sample
1	11'6	18"	
2	16'6	"	
3	23'6	"	
4 *	31'6	"	
* Used 300# Hammer on Spoon			

CORE DATA				
Sample No.	Elevation		Core Recovered	Boring Feet Per Hour
	Top	Bol.		

Type of Core Drill _____
Core Diameter _____

EXHIBIT T-4

**EARL RESERVOIR
TOWN OF WOODBURY**

DO NOT WRITE ON BACK OF SHEET

W. M. WALSH COMPANY, INC.
Crosskill, New Jersey

TEST BORING DATA

TEST HOLE NOL-5

Project Earl's Lake

Location Woodbury, NY.

Borings made by: A. Ecke

Arch. Engr. A.G. Lichtenstein

Date Started 8/31

Completed 9/1/77

El. of Ground Water

Raimondi Assoc.

Length of Casing Driven

Depth in Feet	Ground Line Elevation	Materials Encountered	Blows on Spoon			
			0-6	6-12	12-18	18-24
4						
4						
6		Fill, Silt, Clay				
16		Gravel, Boulders				
5	23	5'				
29			1	10	27	42
47		Gray Clayey Silt, gravel, boulders, little Sand				
158						
73						
10	69					
63			2	28	37	44
97						
158						
182						
15	197	15'				
149			3	25	24	21
189		Gray Clayey Silt, little fine sand				
117						
135						
185						
20	145	Trc. fine gravel	4	35	48	56
157						
151						
162						
25	118	26'6" Bottom of boring	5	35	40	50+
30						
35						
40						
45						

Inside Dia. of Casing 24"
" " " Spoon 1 3/8"
Weight of Hammer on Casing 300 lbs.
" " " " Spoon 140 lbs.
Drop of Hammer on Casing 24"
" " " " Spoon 30"

DRY SAMPLE DATA			
Sample No.	Elevation bottom of Spoon	Total Penetration	Length of Sample
1	6'6"	18"	
2	11'6"	"	
3 *	16'6"	"	
4 *	21'6"	"	
5 *	26'6"	"	
* Used 300# Hammer			

CORE DATA				
Sample No.	Elevation		Core Recovered	Boring Feet Per Hour
	Top	Bot.		

Type of Core Drill _____

Core Diameter _____

EXHIBIT T-3

EARL RESERVOIR
TOWN OF WOODBURY

W. M. WALSH COMPANY, INC.
Crosskill, New Jersey

TEST BORING DATA

TEST HOLE NO. L-7

Project Earl's Lake

Location Woodbury, NY

Drillings made by: A. Ecke

Arch. Engr. A.G. Lichtenstein

Date Started 9/23

Completed 9/23/77

Level of Ground Water 1'6" below grade

Raimondi Assoc.

Length of Casing Driven 25'0"

Depth in Feet	Ground Line Elevation	Materials Encountered	Blows on Spoon			
			6	8	12	18
4		Gray Silty Clay, some Gravel				
3						
4						
5						
7						
3				1	3	5
5						
10						
29						
43	10'		Brn. Silty Clay, some gravel, little fine sand			
47		2		3	18	20
58						
62						
60						
77	15'	Red-Brn. Silt, trc. fine sand, trc. fine gravel				
52			3	22	19	23
57						
59						
70						
103						
71			4	23	21	24
87						
119						
231						
300						
	26'6"	Bottom of boring	5	90	103	100+

Inside Dia. of Casing 2 1/2"
" " " Spoon 1 3/8"
Weight of Hammer on Casing 300 lbs.
" " " " Spoon 140 lbs.
Drop of Hammer on Casing 24"
" " " " Spoon 30"

DRY SAMPLE DATA			
Sample No.	Elevation bottom of Spoon	Total Penetration	Length of Sample
1	6'6"	18"	
2	11'6"	"	
3 *	16'6"	"	
4 *	21'6"	"	
5 *	26'6"	"	
* Used 300# Hammer			

CORE DATA				
Sample No.	Elevation		Core Recovered	Boring Feet Per Hour
	Top	Bot.		

Type of Core Drill _____

Core Diameter _____

EXHIBIT T-7

EARL RESERVOIR
TOWN OF WOODBURY

W. M. WALSH COMPANY, INC.
Crosskill, New Jersey

TEST BORING DATA

TEST HOLE NO. L-9

Project Earl's Lake

Location Woodbury, NY

Drings made by: A. Ecke

Arch. Eng. A. G. Lichtenstein

Date Started 9/1

Completed 9/2/77

Level of Ground Water

Raimondi Assoc.

Length of Casing Driven

Depth in Feet	Ground Line Elevation	Materials Encountered	Blows on Spoon				
			0-6	6-12	12-18	18+	
25		Brn. Clayey Silt some fine Sand, Gravel, Boulders					
70							
52							
73							
69							
38				1	47	38	29
42							
97							
90							
76							
10		15' Red-Brn. Silt trc. fine Sand trc. fine gravel	2	29	48	33	
68							
57							
79							
55							
48							
73				3	31	62	110
85							
141							
189							
20		23' Brn. Silt & Rock Fragments trc. fine sand	4	84	100+		
276							
75							
71							
73							
300							
300				5	150+		
25							
30			30' 31' Silt & Broken Rock Bottom of boring	6	60	100+	
35							
40							
45							

Inside Dia. of Casing 2 1/2"
" " " Spoon 1 3/8"
Weight of Hammer on Casing 300 lbs.
" " " " Spoon 140 lbs.
Drop of Hammer on Casing 24"
" " " " Spoon 30"

DRY SAMPLE DATA			
Sample No.	Elevation bottom of Spoon	Total Penetration	Length of Sample
1	0'6"	18"	
2	11'6"	"	
3	16'6"	"	
4 *	21'0"	12"	
5 *	25'6"	6"	
6 *	31'0"	12"	
* Used 300# Hammer			

CORE DATA				
Sample No.	Elevation		Core Recovered	Boring Feet Per Hour
	Top	Bot.		

Type of Core Drill _____
Core Diameter _____

EXHIBIT T-9

EARL RESERVOIR
TOWN OF WOODBURY

APPENDIX F
BACKGROUND DOCUMENTS

W. M. IMBRIE, PRESIDENT
MARVYN SCUDDER, TREASURER

COMMONWEALTH WATER COMPANY OF NEW YORK
46 BROADWAY, NEW YORK

10/17/12
114

October 17, 1912.

Mr. Alexander Rice McKim, C. E.,
New York Conservation Committee,
Albany, N. Y.

Dear Sir:

Your telegram of Tuesday unfortunately reached me too late to allow my being able to meet you at 8:45 yesterday morning at Highland Mills. I instructed my assistant engineer, however, to show you every courtesy and expedite as far as possible any investigation or inspection which you might wish to make, and I trust that this was done.

A rather meagre telephone message this morning informed me that you visited the site and inspected the trench which is being put in for the foundation.

I was also informed that you deemed it necessary to carry the footings of the extreme easterly wing of the dam down about five feet and that you further thought it would be necessary to go fifteen or twenty feet in depth at the center, that is, under the heaviest portion of the dam, unless rock should be encountered at a higher level.

These views coincide entirely with my own and I feel that the footings should be carried to the levels suggested by you, unless indeed rock is encountered. Personally I feel that rock will be encountered at a higher level under

Mr. Alexander Rice McKim -2-

the deeper portion of the dam.


The soundings taken by us across the Valley showed rock at about the level shown on the plans, or rather on sections, but the formation is so treacherous and the ground is larded with broken boulder formation that it is more than possible that some of our soundings reached boulder rather than ledge rock; in fact the trench as open to date seems to indicate this.

My feeling is that if we go to the depths suggested by you and concurred in by me and find at those levels a very heavy dense clay which would seem impervious to water action we would be abundantly safe in establishing such levels for our lower footings.

I would be extremely obliged to you, when writing me on the subject, if you will be as full as possible as you have time. Of course, I realize that you are a very busy man, and have many demands upon your time, but I want you to feel that it is the desire of the Company, as well as its engineer, to embody and carry out your views as far as it is possible.

With kind personal regards, I am

Very truly yours,



FST/T

Engineer

Woodbury Field + Stream Inc.

DAM INSPECTION REPORT
(By Visual Inspection)

Dam Number	River Basin	Town	County	Hazard Class*	Date & Inspector
453	L. Hudson	Woodbury	Orange	A	6-19-74 GHE-KDH

Type of Construction

- Earth w/concrete spillway
- Earth w/drop inlet pipe
- Earth w/stone or riprap spillway
- Concrete
- Stone
- Timber

Use

- Water Supply
- Power
- Recreation
- Fish and Wildlife
- Farm Pond
- No Apparent Use-Abandoned

Estimated Impoundment Size

- 1-5 acres
- 5-10 acres
- Over 10 acres

Estimated Height of Dam above Streambed

- Under 10 feet
- 10-25 feet
- Over 25 feet

Condition of Spillway

- Service satisfactory
- In need of repair or maintenance
- Auxiliary satisfactory
- In need of repair or maintenance

Explain: Leakage thru stone

Condition of Non-Overflow Section

- Satisfactory
- In need of repair or maintenance

Explain: _____

Leakage thru stone

Condition of Mechanical Equipment

- Satisfactory
- In need of repair or maintenance

Explain: _____

Evaluation (From Visual Inspection)

- No defects observed beyond normal maintenance
- Repairs required beyond normal maintenance

*Explain Hazard Class, if Necessary _____

EARL DESERDOR

SH-10113

APPLICATION FOR PERMIT

FOR THE CONSTRUCTION, RECONSTRUCTION OR REPAIR OF A DAM OR OTHER IMPOUNDMENT STRUCTURE

FOR DEPARTMENT USE ONLY	
APPLICATION NO.	<i>336-24-0051</i>
DAM NO.	
WATERSHED	

Read instructions on reverse side of last sheet before completing this application. PLEASE TYPE OR PRINT CLEARLY IN INK

PROJECT DESCRIPTION

1. LOCATION ON U.S. GEOLOGICAL SURVEY MAP Name of Map Monroe	Latitude 41°-21'-48"	Longitude 74°-08'-10"	2. PROPOSED USE FOR IMPOUNDED WATER Recreation & Aux. Water Supply	3. STATE THE HEIGHT ABOVE SPILLCREST OF THE LOWEST PART OF THE IMMEDIATE UPSTREAM ADJOINING PROPERTY OR PROPERTIES * All surrounding prop feet
---	--------------------------------	---------------------------------	--	--

4. IS THIS PROPOSED POND OR LAKE PART OF A PUBLIC WATER SUPPLY? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If not, where is nearest downstream public water supply intake?	5. SIZE OF AREA DRAINING INTO POND OR LAKE (Acres or Square Miles) 464 Acres	HEIGHT OF DAM ABOVE STREAM BED? 28 (proposed) feet
--	--	--

6. THE DRAINAGE AREA IS COMPOSED OF: (Total = 100%)
 ___ 95 % Forest ___ % Cropland ___ % Pasture ___ % Other **4** % Swamp **1** % Suburban Lands ___ % Urban Lands

7. TYPE OF SPILLWAY <input type="checkbox"/> Service Spillway - Auxiliary <input type="checkbox"/> Pipe Riser ONLY Spillway Combination <input type="checkbox"/> Other <input checked="" type="checkbox"/> Single Spillway w/ mud gate	8. DESIGNER'S ESTIMATE OF CLASS OF HAZARD (As described in "Guidelines for Small Earth Dam Designs") <input type="checkbox"/> Class "A" <input checked="" type="checkbox"/> Class "B" <input type="checkbox"/> Class "C" NOTE: Provide descriptive information on character of downstream area.
--	--

9a. SPILLWAY INFLOW DESIGN FLOOD 1500 X 100 yr.* Frequency ___ Flood Peak 1087 cfs Runoff Volume 5.86 in.	9b. SERVICE SPILLWAY INFLOW DESIGN FLOOD Frequency ___ Flood Peak ___ cfs Runoff Volume ___ in.
---	--

10. THE SINGLE SPILLWAY OR AUXILIARY SPILLWAY IS COMPOSED OF:
 Vegetated Earth Concrete Timber Rock-filled Crib Masonry Other

11. MAXIMUM VELOCITY WITHIN THE SINGLE OR AUXILIARY SPILLWAY 2.5 fps	12. SINGLE OR AUXILIARY SPILLWAY DISCHARGE AT DESIGN HIGH WATER 1392 cfs	13. TYPE OF ENERGY DISSIPATER PROVIDED ON SINGLE SPILLWAY <input type="checkbox"/> Hydraulic Jump Basin <input checked="" type="checkbox"/> Drop Structure <input type="checkbox"/> Other
---	---	--

14. POND OR LAKE WILL BE DRAINED BY MEANS OF **20" mudgate**
 WATER WILL BE SUPPLIED TO RIPARIAN OWNERS DOWNSTREAM BY MEANS OF **normal overflow**

15. AREA-CAPACITY DATA Answer 1, 2 and 3, OR 1, 2, 4, 5	ELEVATION, Referred to Assumed Benchmark	SURFACE AREA	VOLUME STORED	16. TYPE OF ENERGY DISSIPATER AT OUTLET OF CONDUIT: <input type="checkbox"/> Impact Basin <input type="checkbox"/> Hydraulic Jump Basin <input checked="" type="checkbox"/> Plunge Pool <input type="checkbox"/> Other
1. Top of Dam	832 Feet	21.50 acres	72.81 Acre-Feet	IS PIPE RISER PROVIDED WITH AN ANTI-VORTEX DEVICE? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
2. Design High Water	830.65 Feet	20.02 acres	44.82 Acre-Feet	
3. Single Spillway Crest	828.40 Feet	160 Acres	*150.4 Acre-Feet	
4. Auxiliary Spillway Crest	___ Feet	___ Acres	___ Acre-Feet	
5. Service Spillway Crest	___ Feet	___ Acres	___ Acre-Feet	

17. DRAWDOWN TIMES: Answer 1 and 2, OR 1, 3 and 4* **See attached Engineer's report.**

1. Has provision been made to evacuate 90% of the storage below the lowest spillway crest within fourteen days? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	3. Can the Service Spillway evacuate 75% of the storage between the auxiliary spillway and the Service Spillway crest within seven days? <input type="checkbox"/> Yes <input type="checkbox"/> No
2. Can the single spillway evacuate 75% of the storage between the maximum design high water and the spillway crest within 48 hours? <input type="checkbox"/> Yes <input type="checkbox"/> No	4. Can the Service Spillway and the Auxiliary Spillway in combination evacuate the storage between the design high water and the auxiliary spillway crest within 12 hours? <input type="checkbox"/> Yes <input type="checkbox"/> No

18. SOIL DATA - State the character of the bed and banks in respect to natural types of soil materials, hardness, perviousness, water bearing, effect of exposure to air and water, uniformity, etc.

See Boriny logs

If an earth dam, describe the material to be used in the embankment.

See Specifications

What is the source of embankment fill material(s)?

Contractors option

***erties owned by APPLICANT**

Are there porous seams or fissures beneath the foundation of the proposed dam? Yes No
 Method used to obtain the above soil data Soil Borings Test Pits

19. DESIGN ENGINEER Name of Agency or Individual A.G. Lichtenstein & Ass.	P.E. License No. of Individual 28317	20. CONSTRUCTION ENGINEER Name of Agency or Individual Raimondi Assoc. P.C.	P.E. License No. of Individual 40,212
Address 1258 Teaneck Road, Teaneck, N.J. 07666		Address 110 Stage Road, Monroe, N.Y. 10950	
Title resident	Telephone No. 201-837-4300	Title President	Telephone No. 914-782-8681

- Article 15 (STREAM PROTECTION) Environmental Conservation Law
 - For the construction, reconstruction or repair of a DAM or other impoundment structure.
 - For the construction, reconstruction or repair of any permanent DOCK, pier or wharf; and any dock, pier or wharf, built on open work supports, which has a top surface area of more than 200 square feet.
 - For the disturbance of a STREAM BED or excavation in or fill of navigable waters.
- Article 24 (FRESHWATER WETLANDS) Environmental Conservation Law
- Article 25 (TIDAL WETLANDS) Environmental Conservation Law

Read instructions on reverse side of last sheet before completing this application. PLEASE TYPE OR PRINT CLEARLY IN INK.

1. NAME AND ADDRESS OF APPLICANT		TELEPHONE NO.
First Town of Woodbury	M.I.	Last
Street Address		914-928-6829
Albany Turnpike (Route 32) Highland Mills, N.Y.		10930
Post Office		State
State		Zip Code
2. NAME AND ADDRESS OF OWNER (if different from Applicant)		
First M.I. Last		
Street Address		
Post Office		
State		
Zip Code		
3. AGENCY SUBMITTING APPLICATION		
Park Commission		
PROJECT DATA		
4. LOCATION OF WETLAND OR ADJACENT AREA, STREAM, OR BODY OF WATER		
Body of Water	Town	County
Earl Reservoir	Woodbury	Monroe
Locate by giving distance and direction from a commonly accepted and identifiable landmark or body of water or U.S.G.S. coordinates.		
5. SIZE OF WORK SECTION	6. SPECIFIC LOCATION	7. WILL PROJECT UTILIZE STATE OWNED LANDS?
500' +	D.E.C. Designation	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
H-89-7-6-P229a		
8. TYPE AND EXTENT OF WORK (Feet of new channel; yards of material to be removed, draining, dredging, filling, etc.)		
Reconstruction of Dam		
9. DOES PROJECT COMPLY WITH		8. Development Restrictions (If any)
A. Use Guidelines (If any)		
N.A.		
10. PURPOSE (Hardship)		
Emergency dam repair & municipal recreation		
11. IF A DAM OR OBSTRUCTION, INDICATE		12. PROPOSED STARTING DATE
Height 28	Size of Pond 16 + Acres	June 1, 1978
		13. APPROXIMATE COMPLETION DATE
		Nov. 1, 1978
14. NAME AND ADDRESS OF TWO OFFICIAL NEWSPAPERS IN LOCALITY WHERE PROPOSED ACTIVITY IS LOCATED		
Times Herald Record		Photo News
1 Stage Road		Warwick, N.Y.
Monroe, New York 10950		
15. CERTIFICATION		
I hereby affirm under penalty of perjury that information provided on this form and all attachments submitted herewith is true to the best of my knowledge and belief. False statements made herein are punishable as a Class A misdemeanor pursuant to Section 210.45 of the Penal Law. As a condition to the issuance of a permit, the applicant accepts full legal responsibility for all damage, direct or indirect, of whatever nature, and by whomever suffered, arising out of the project described herein and agrees to indemnify and save harmless the State from suits, actions, damages and costs of every name and description resulting from the said project.		
DATE		SIGNATURE

END

DATE
FILMED

11-81

DTIC