

AD-A108 671

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/8 13/13
NATIONAL DAM SAFETY PROGRAM. CORTLANDT LAKE DAM (INVENTORY NUMB--ETC(U)
AUG 81 G KOCH DACW51-79-C-0001

UNCLASSIFIED

ML


For
A. A.
Table

END

DATE

FILED

RTIC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

REPORT DOCUMENTATION PAGE

READ INSTRUCTIONS
BEFORE COMPLETING FORM

LEVEL 1

8

1. REPORT NUMBER		2. GOVT ACCESSION NUMBER		3. RECIPIENT'S CATALOG NUMBER	
4. TITLE (and Subtitle) Phase I Inspection Report Cortlandt Lake Dam Lower Hudson River Basin, Westchester County, N.Y. Inventory No. 85		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program			
7. AUTHOR(s) GEORGE KOCH		6. PERFORMING ORG. REPORT NUMBER			
9. PERFORMING ORGANIZATION NAME AND ADDRESS New York State Department of Environmental Conservation 50 Wolf Road Albany, New York 12233		8. CONTRACT OR GRANT NUMBER(s) DACW51-79-C-0001			
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS			
12. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 26 August 1981			
		13. NUMBER OF PAGES			
		13. SECURITY CLASS. (of this report) UNCLASSIFIED			
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE			
15. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.					
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Rep.)					
18. SUPPLEMENTARY NOTES					
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Cortlandt Lake Dam Westchester County Lower Hudson River Basin					
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Visual inspection of this dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which require further engineering investigations and remedial work.					

AD A108671

DTIC
S
DEC 17 1981
A

DTIC FILE COPY


The structural stability analysis performed for this report indicated that the stability of the spillway section of the dam is questionable. The analysis indicated that the dam was unstable for all conditions studied. The analysis performed was based on available information and assumptions made may not reflect actual conditions. However, the analysis does indicate that there are serious questions about the stability of this structure and further investigations are required.

The inspection revealed a semicircular wet area just beyond the downstream end of the left wingwall. There was active clear seepage in this area which had caused some sloughing.

It is recommended that within 3 months of the date of notification of the owner, investigations into the structural stability and seepage problems on this dam be commenced. The structural stability investigations should include subsurface explorations and concrete cores to obtain information about the structure and its foundation conditions. This data should then be incorporated into a detailed stability evaluation and, if necessary, modifications to the structure should then be designed. The investigation into the wet area should attempt to determine the cause of the wet area and devise methods of treatment. Remedial measures which are required based on these investigations should be completed within 18 months.

The hydrologic/hydraulic analyses performed indicate that the outflows from all storms exceeding 50% of the Probable Maximum Flood (PMF) will result in flows over the top of the dam. The dam can pass one-half the PMF with a computed freeboard of 0.03 feet. Therefore, the spillway capacity is rated as inadequate.

**LOWER HUDSON RIVER BASIN
CORTLANDT LAKE DAM
WESTCHESTER COUNTY, NEW YORK
INVENTORY NO. N.Y. 85
PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



**APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED**

NEW YORK DISTRICT CORPS OF ENGINEERS

JULY, 1981

10 10 19

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

A

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
CORTLANDT LAKE DAM
I.D. NO. NY85
LOWER HUDSON RIVER BASIN
WESTCHESTER COUNTY, NEW YORK

TABLE OF CONTENTS

		<u>PAGE NO.</u>
-	ASSESSMENT	-
-	OVERVIEW PHOTOGRAPH	-
1	PROJECT INFORMATION	1
1.1	GENERAL	1
1.2	DESCRIPTION OF PROJECT	1
1.3	PERTINENT DATA	2
2	ENGINEERING DATA	4
2.1	GEOTECHNICAL DATA	5
2.2	CONSTRUCTION RECORDS	4
2.3	OPERATION RECORDS	4
2.4	EVALUATION OF DATA	4
2.5	DESIGN RECORDS	4
3	VISUAL INSPECTION	5
3.1	FINDINGS	5
3.2	EVALUATION OF OBSERVATIONS	6
4	OPERATION AND MAINTENANCE PROCEDURES	8
4.1	PROCEDURE	8
4.2	MAINTENANCE OF DAM	8
4.3	WARNING SYSTEM IN EFFECT	8
4.4	EVALUATION	8

	<u>PAGE NO.</u>	
5	HYDROLOGIC/HYDRAULIC	9
5.1	DRAINAGE AREA CHARACTERISTICS	9
5.2	ANALYSIS CRITERIA	9
5.3	SPILLWAY CAPACITY	10
5.4	RESERVOIR CAPACITY	10
5.5	FLOODS OF RECORD	10
5.6	OVERTOPPING POTENTIAL	10
5.7	EVALUATION	10
6	STRUCTURAL STABILITY	11
6.1	EVALUATION OF STRUCTURAL STABILITY	11
7	ASSESSMENT/RECOMMENDATIONS	13
7.1	ASSESSMENT	13
7.2	RECOMMENDED MEASURES	14

APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- D. STABILITY COMPUTATIONS
- E. REFERENCES
- F. DRAWINGS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Cortlandt Lake Dam
(I.D. No. NY 85)

State Located: New York

County: Westchester

Watershed: Lower Hudson River Basin

Stream: Canopus Creek

Date of Inspection: May 27, 1981

ASSESSMENT

Visual inspection of this dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which require further engineering investigations and remedial work.

The structural stability analysis performed for this report indicated that the stability of the spillway section of the dam is questionable. The analysis indicated that the dam was unstable for all conditions studied. The analysis performed was based on available information and assumptions made may not reflect actual conditions. However, the analysis does indicate that there are serious questions about the stability of this structure and further investigations are required.


The inspection revealed a semicircular wet area just beyond the downstream end of the left wingwall. There was active clear seepage in this area which had caused some sloughing.

It is recommended that within 3 months of the date of notification of the owner, investigations into the structural stability and seepage problems on this dam be commenced. The structural stability investigations should include subsurface explorations and concrete cores to obtain information about the structure and its foundation conditions. This data should then be incorporated into a detailed stability evaluation and, if necessary, modifications to the structure should then be designed. The investigation into the wet area should attempt to determine the cause of the wet area and devise methods of treatment. Remedial measures which are required based on these investigations should be completed within 18 months.


The hydrologic/hydraulic analyses performed indicate that the outflows from all storms exceeding 50% of the Probable Maximum Flood (PMF) will result in flows over the top of the dam. The dam can pass one-half the PMF with a computed freeboard of 0.03 feet. Therefore, the spillway capacity is rated as inadequate.

Several other deficiencies were noted on this structure. These deficiencies should be corrected within 12 months of the date of notification of the owner. Among the actions required are the following:

1. Replace the missing backfill behind the left wingwall.
2. Repair deteriorated and spalling concrete on the spillway section and wingwalls.
3. Seal the joints on both the spillway section and the wingwalls to eliminate leakage through these joints.
4. Develop an emergency action plan for the notification of downstream residents.


George Koch
Chief, Dam Safety Section
New York State Department
of Environmental Conservation
NY License No. 45927

Approved by:


Col. W. M. Smith, Jr.
New York District Engineer

Date:





OVERVIEW
CORTLANDT LAKE DAM
I.D.NO. NY85

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
CORTLANDT LAKE DAM
I.D.NO. NY-85 #213-858
LOWER HUDSON RIVER BASIN
WESTCHESTER COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam

The Cortlandt Lake Dam (formerly known as Canopus Dam) is a concrete dam with an ogee near the center of the dam. The dam is 225 feet long and a maximum of 37 feet high. The concrete gravity spillway is 120 feet long and has a crest elevation 6 feet below the top of the dam. Concrete wingwalls separate the spillway section from the remainder of the dam. Beyond the ends of the spillway, the dam is a wall section which has been backfilled both upstream and downstream of the dam.

There are two 3 foot square openings through the dam which serve as low level outlets. Flow through the openings is controlled by sluice gates. One of the openings is near the right end of the dam and has an inlet elevation 6 feet below the spillway crest. This shall be referred to as the mid-level gate. The control mechanism for this gate is on the upstream face of the dam. The other opening is at the base of the dam, 22 feet below the spillway crest, and shall be referred to as the reservoir drain. The control mechanism for this gate is supposedly on the upstream face of the spillway.

b. Location

This dam is located on Canopus Creek (which becomes Sprout Brook downstream of the dam) in the Town of Cortlandt, Westchester County. It is one quarter mile west of Sprout Brook Road. The county boundary passes through the reservoir, with half of the reservoir in Westchester County and the other half in Putnam County.

c. Size Classification

This dam is 37 feet high and has a storage capacity of 244 acre feet. Therefore, the dam is in the small size category as defined by the "Recommended Guidelines for Safety Inspection of Dams".

d. Hazard Classification

The dam is classified as "high" hazard due to the presence of substantial residential development immediately downstream of the dam.

e. Ownership

The dam is owned by the Continental Village Park District Commission, which consists of the Towns of Cortlandt, Putnam Valley and Phillipstown, New York. The district chairmanship rotates among the towns. This year's chairman is Supervisor Charles DiGiacomo. His address is Town of Cortlandt Municipal Building, Croton-on-Hudson, New York 10520.

f. Purpose of Dam

This dam is used to create an impoundment for recreational purposes.

g. Design and Construction History

This dam was designed in 1929 by Nicholas S. Hill, Jr., Consulting Engineer, from New York City. H.D. Hynds Inc., builders from New York City constructed the dam in late 1929.

h. Normal Operating Procedures

There are no prescribed operating procedures for this structure. Water flows over an ungated spillway.

1.3 PERTINENT DATA

a. Drainage Area (sq.mi.) 15.15

b. Discharge at Dam (cfs)

Spillway at Maximum High Water	6754
Mid-level Outlet (gate fully open); water @ spillcrest	92
Reservoir Drain (gate fully open); water @ spillcrest	196

c. Elevation

	DATUM	
	(USGS)	(PLAN)
Top of Dam	102	108
Spillway Crest	96	102
<u>INVERT ELEVATIONS</u>		
Mid-level Outlet:		
Inlet	90	96
Outlet	84	90
Reservoir Drain:		
Inlet	74	80
Outlet	68	74

d. Reservoir - Surface Area (acres)

Top of Dam 17.4+
Spillway Crest 17.4

e. Storage Capacity (acre-feet)

Top of Dam 244
Spillway Crest 140

f. Dam

Type - Concrete gravity spillway segment; backfilled concrete core walls at either end.

Dam Length (ft) 225
Crest Width - Wall Segment (ft) 3

g. Spillway

Type: Ungated, concrete ogee section in center of dam.

Length (ft) 120

h. Mid-Level Outlet

Type: 3 foot square opening on right abutment

Control: Vertical sluice gate with trash rack
ID plate on gate floorstand:

Wilcox Sluice Gates & Roller Bearing Standards
Coldwell- Wilcox Company
Newburgh, New York

i. Reservoir Drain

Type: 3 foot square opening through spillway

Control: Unknown

SECTION 2: ENGINEERING DATA

2.1 GEOTECHNICAL DATA

a. Geology

The Cortlandt Lake Dam is located in the Hudson Hills segment of the New England Uplands physiographic province of New York State. These hills, commonly known as the "Highlands of the Hudson", are composed of crystalline rocks similar to those in the Adirondacks. The highlands, which trend northeast-southwest, have been eroded to form very rugged terrain with summit levels reaching 1000 feet above sea level. Bedrock in the area consists of gneiss, quartzite and marble from the Precambrian era (more than 570 million years ago). A review of the "Brittle Structures Map of New York" indicates that there is a fault trace approximately 1/2 mile east of the dam. In addition, there is a shear zone of mylonite, ultramylonite or mylonite gneiss within the reservoir, several hundred feet northwest of the dam.

b. Subsurface Investigations

No records of any subsurface investigations performed for this structure could be located. The permit application for the original construction of this dam indicates that the natural soils in the vicinity of this dam are clay, sand and gravel. It also stated that the dam would be founded on bedrock.

2.2 DESIGN RECORDS

The only design records available consisted of two sheets of plans prepared by Nicholas S. Hill, Jr., Consulting Engineer, of New York City. Copies of these plans have been included in Appendix F. Some additional design information was included in the 1929 application for construction submitted to the New York State Department of Public Works.

2.3 CONSTRUCTION RECORDS

This dam is believed to have been constructed by H.D. Hynds, Inc., builders from New York City. The only construction records available was a letter from Mr. H.W. Bressler of H.D. Hynds, Inc. to the Department of Public Works which outlined the specifications which were to be used for the construction of this dam.

2.4 OPERATION RECORDS

There are no operation records available for this structure.

2.5 EVALUATION OF DATA

Data used for the preparation of this report was obtained from the Department of Environmental Conservation files. The information available appeared to be reasonably accurate.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of the Cortlandt Lake Dam was conducted on May 27, 1981. The weather was clear and the temperature was in the seventies. The water level at the time of the inspection was at the spillway crest.

b. Spillway

The spillway section comprises the biggest part of the dam. There are provisions for flashboards on the spillway although at the time of the inspection, there were no flashboards or support pins in place. Visual inspection revealed some concrete deterioration on the spillway. There was minor spalling and some concrete removal along each of the construction joints. The deterioration had also resulted in slightly irregular crest with a low area at the left end of the spillway. Water was flowing over the spillway in two low areas at the time of the inspection. Photos which were taken during an inspection in 1959 (several of these photos have been included in Appendix A), indicate that the concrete on the crest was similarly deteriorated at that time. The condition of the concrete does not appear to have worsened substantially since 1959. Photos from the 1959 inspection also showed that there was some leakage through one of the horizontal construction joints at the left end of the spillway. This was not observed during the Phase I inspection due to the water flowing over that portion of the spillway.

c. Wingwalls

There is a wingwall at either end of the spillway. The concrete forming these wingwalls was in satisfactory condition. There was some minor cracking and deterioration along the construction joints. Near the downstream end of each wall, the top surface was spalling. Several weep holes through the walls were flowing at the time of the inspection. Discoloration of the concrete below these weep holes indicated that they flow frequently.

There were several other deficiencies noted in this area. The most serious of these was a wet area just beyond the downstream end of the left wingwall. There was a semi-circular area about 12 feet wide which had sloughed by as much as a foot. Clear seepage was emerging from this area at a rate of approximately one gallon per minute. It could not be determined whether this water was coming from the reservoir or if it was flowing out of the hillside. The water then flowed over a low wall and into the downstream channel. There was also some seepage noted at the downstream end of the right wingwall.

The quantity of seepage on this side was less than at the left side. Another deficiency noted was missing backfill behind the left wingwall. The problem was most severe at the upstream end of the wingwall where there was as much as 5 feet of backfill missing. The hole extended down the wall for approximately half of its length.

Also observed during the visual inspection was a submerged circular hole in the wingwall just upstream of the spillway crest. The function of this hole could not be determined. The plans make no reference to this opening. The 1959 photos show that, at that time, there was a wood cover over this hole.

d. Low Level Outlets

There are two, 3 foot square openings through the concrete on this dam which can release impounded water below the normal pool level. The control mechanism for one of these outlets is located just beyond the right end of the spillway. It appeared to be in satisfactory condition and operable although it was not operated at the time of inspection. There was minor leakage noted along the base of the outlet opening on the downstream face of the dam.

The other outlet serves as a reservoir drain. Only the top of the outlet was visible in the plunge pool area. The gate and control mechanism is reportedly on the upstream face of the spillway. It was submerged at the time of the inspection. Photos from the 1959 inspection indicate that the drain was opened at that time.

e. Reservoir

There were no signs of soil instability in the reservoir area.

f. Downstream Channel

The channel downstream of the dam was filled with rocks with occasional bedrock outcrops. There were some trees growing in the channel as well.

3.2 EVALUATION OF OBSERVATIONS

Visual observations revealed several deficiencies on this structure. The following items were noted:

1. A wet area beyond the downstream end of the left wingwall;
2. A substantial quantity of missing backfill behind the left wingwall;
3. Minor seepage beyond the downstream end of the right wingwall;
4. Deterioration and spalling of concrete on the spillway section, especially along the crest;

5. Leakage through horizontal construction joints both on the spillway and on the wingwalls;
6. Spalling of the concrete on the top surface of the wingwalls, near the downstream end.

SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

There are no formal operation procedures on this dam. Water flows over an ungated spillway. There are provisions for flashboards on the spillway, but at the time of the inspection, there were no flashboards or support pins in place. It appeared that flashboards are no longer used.

4.2 MAINTENANCE OF DAM

There was no formal maintenance plan for this structure.

4.3 WARNING SYSTEM IN EFFECT

No apparent warning system for the evacuation of downstream residents is present.

4.4 EVALUATION

The operation procedures for this dam are satisfactory. Increased maintenance efforts are needed to repair the deficiencies noted in Section 3.

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

The delineation of the contributing watershed to this dam is indicated on the map titled "Drainage Area Map-Cortlandt Lake Dam" (Appendix C). The irregular, long and narrow, northeast-southwest oriented watershed of some 15.15 square miles (9696 acres) is comprised of relatively undeveloped lands, primarily forests and woodlands.

No significant land development exists except for two moderate-density residential areas, one surrounding Cortlandt Lake and the other surrounding Indian Lake. Several sizeable lakes lie within the watershed, these being Canopus Lake and Pelton Pond in the upper end of the drainage basin and Indian Lake and Lake Celeste in the lower third of the basin. Numerous smaller, unnamed ponds are also interspersed throughout the watershed.

Slopes along the primary drainage paths are flat to moderate (less than 8%). However, the adjacent hillsides have steep and rocky slopes, with those hilltops forming the watershed divide ranging from 200 feet to 1200 feet in elevation above the reservoir.

There are no known flow diversions either into or out of this watershed. The inlet stream to Cortlandt Lake is known as Canopus Creek, whereas the outlet stream from the dam site is known as Sprout Brook.

5.2 ANALYSIS CRITERIA

No hydrologic/hydraulic information was available regarding the original design for this dam. Therefore, the analysis of the flood-water retarding capability of the dam was performed using the Corps of Engineer's HEC-1 computer program, Dam Safety version. The computer program develops an inflow hydrograph using the "Snyder Unit Hydrograph" method and then reservoir routes the hydrograph using the "Modified Puls" flood routing procedure. The spillway design flood selected for analysis was the Probable Maximum Flood (PMF), in accordance with the Recommended Guidelines of the U.S. Army Corps of Engineers. The PMF event is that hypothetical storm event resulting from the most critical combination of rainfall, minimum soil retention, and direct runoff to a specific site that is considered reasonably possible for a particular watershed.

The Corps of Engineers Lower Hudson River Basin study (ref. #1) was used to obtain hydrograph parameters, rainfall loss rate values of 1.5 inches (initial) and 0.1 inches per hour (constant) and base flow values. Precipitation values used in the analysis were obtained from the Weather Bureau publication, HMR 33.

5.3 SPILLWAY CAPACITY

The single, ungated, concrete ogee spillway was analyzed for weir flow using a discharge coefficient, C, varying from 3.2 to 3.83. Near the center of the spillway crest is an open slot which can provide 8 cfs additional discharge capacity. This capacity was included in the analysis. The additional discharge capacity of the 3 foot square, mid-level outlet located in the right abutment was not included in the floodwater analysis although access to the sluice gate control mechanism is possible during the occurrence of a large storm event.

The floodwater analysis performed for this dam indicates that the spillway does not have sufficient capacity for discharging the PMF. For this storm event, the peak inflow and the peak outflow are 13421 cfs. The one-half PMF peak inflow and peak outflow are 6708 cfs. The computed discharge capacity of the spillway is 6754 cfs.

5.4 RESERVOIR CAPACITY

The normal water surface is at or near the spillway crest (elevation 96-USGS). The impounded capacity at this elevation is 140 acre-feet. Surcharge storage capacity to the top-of-dam (elevation 102) adds 104 acre feet which is equivalent to a direct runoff depth of 0.13 inches over the watershed. The total storage capacity is 244 acre feet.

5.5 FLOODS OF RECORD

No data was available regarding the occurrence of the maximum known flood at this dam site.

5.6 OVERTOPPING POTENTIAL

Analyses using the PMF storm event indicates that the spillway does not have sufficient discharge capacity. The peak outflow from the PMF event will overtop the dam to a computed depth of 2.83 feet. The peak outflow from the one-half PMF event will not overtop the dam, having a computed freeboard of 0.03 feet. All storm events exceeding 50% of the PMF will result in the dam being overtopped.

5.7 EVALUATION

The spillway does not have sufficient capacity for discharging the peak outflow from the PMF. However, the spillway does have sufficient discharge capacity for passing the peak outflow from one-half the PMF. Therefore, the spillway is assessed as inadequate.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Visual inspection of the dam revealed several deficiencies on this structure. The most serious of these deficiencies was a wet area just beyond the downstream end of the left wingwall. There was a semi-circular area about 12 feet wide which had sloughed. Clear seepage was emerging from this area. Another deficiency noted was missing backfill behind the left wingwall. Other problems noted were related to the deterioration of concrete both on the spillway and on the wingwalls.

b. Data Review and Stability Evaluation

A stability analysis was performed for this report in accordance with the "Recommended Guidelines for the Safety Inspection of Dams." The analysis was based on a cross section of the concrete gravity spillway shown on the 1929 plans prepared by Nicholas S. Hill, Jr., Consulting Engineer, of New York City. The results of the analysis are as follows:

<u>Case</u>	<u>Overturning Safety Factor</u>	<u>Resultant in Middle Third</u>	<u>Sliding Safety Factor</u>
a. Normal conditions, water surface at spillway crest	1.31	No	0.85
b. Case a. plus ice load of 5000 lb/ft	1.10	No	0.74
c. 1/2PMF flows; water surface at top of dam	1.04	No	0.62
d. Seismic Loading, water surface at spillway crest	1.23	No	0.64

The analysis indicates that the dam is unstable. The fact that the factors of safety are below 1.0 for normal loading conditions shows that actual loading and uplift conditions are less severe than those which were assumed for the analysis. The analysis, in accordance with the Corps of Engineers' "Recommended Guidelines", assumed full uplift pressure under the upstream toe decreasing to tailwater pressure under the downstream toe. However, safety factors were below recommended values even when zero uplift pressure was assumed. Therefore, the structure must be considered to be marginally stable at best.

Further investigations are required to better assess the stability of the dam. Subsurface explorations and concrete cores are required to obtain information about the uplift forces acting on the dam and about the condition of the dam and its foundation. Revised stability analyses

should then be performed using this data. Based on the results of these analyses, required modifications to the structure should be made.

c. Seismic Stability

This structure is located in Seismic Zone 1. However, since there was a fault trace in the vicinity of the dam, a seismic stability analysis was performed assuming a seismic coefficient of 0.1. The results of this analysis (shown on page 11) indicate that the safety factors are below recommended values when seismic considerations are included.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase I inspection of the Cortlandt Lake Dam revealed several deficiencies on the structure. One of the most serious deficiencies was a semicircular wet area just beyond the downstream end of the left wingwall. There was active clear seepage in this area which had caused some sloughing.

The inspection also revealed that the stability of this structure is questionable. Analyses performed indicated that the dam was unstable for all conditions studied. While the uplift conditions assumed for this report may have been more severe than actually exist, the analysis does indicate that a serious stability deficiency exists on this structure.

The dam does not have sufficient spillway capacity to pass the Probable Maximum Flood (PMF). The outflows from one-half the PMF will not overtop the non-overflow segment of the dam. Therefore, the spillway capacity has been rated as inadequate.

b. Adequacy of Information

The information available for the preparation of this report was fairly complete and appeared to be reasonably accurate. The condition of the rock forming the dam's foundation was unknown, so conservative assumptions about it were made for the stability analyses performed for this report.

c. Need for Additional Investigations

Further investigation of the structural stability and seepage problems on this dam are required. The structural stability investigations should include subsurface explorations and concrete cores to obtain information about the structure and its foundation conditions. This data should then be incorporated into a detailed stability evaluation and, if necessary, modifications to the structure should then be designed.

Investigations into the causes of the wet area beyond the downstream end of the left wingwall are required. As a result of these investigations, methods of treatment should be devised and implemented.

d. Urgency


Investigations of the structural stability and seepage problems should be commenced within 3 months of the date of notification of the owner. Remedial measures deemed necessary as a result of these investigations should be completed within 18 months. Other deficiencies noted on the structure should be corrected within 12 months.

7.2 RECOMMENDED MEASURES

1. Modify the structure as necessary, based on the stability analysis.
2. Devise and implement a method to treat the wet area beyond the downstream end of the left wingwall.
3. Replace the missing backfill behind the left wingwall.
4. Repair the deteriorated and spalling concrete on the spillway section and wingwalls.
5. Seal the joints on both the spillway section and the wingwalls to eliminate leakage through these joints.
6. Develop and implement an emergency action plan for the notification of downstream residents.

APPENDIX A

PHOTOGRAPHS



MISSING BACKFILL BEHIND WINGWALL AT LEFT END OF DAM



AREA OF MISSING BACKFILL FROM DOWNSTREAM TOE
ALSO, CONCRETE DETERIORATING ON WINGWALL



WET AREA AT DOWNSTREAM END OF LEFT WINGWALL



AREA OF SLOUGH RESULTING FROM THE WET AREA



FORMED HOLE IN CONCRETE ON LEFT
WINGWALL IN RESERVOIR




FLOW THROUGH WEEP HOLE IN
WINGWALL AT RIGHT END OF DAM




SPILLWAY SECTION
NOTE THE DETERIORATED CREST ON RIGHT SIDE



SPILLWAY SECTION
NOTE DETERIORATED CONCRETE



1959 PHOTO
CREST OF SPILLWAY WITH FLASHBOARD PINS IN PLACE
NOTE WOOD COVER OVER CIRCULAR HOLE IN WINGWALL



1959 PHOTO
LEAKAGE THROUGH THE HORIZONTAL CONSTRUCTION JOINTS



1959 PHOTO
GATE ON LOW LEVEL OUTLET OPENED



1959 PHOTO
DOWNSTREAM VIEW BOTH LOW LEVEL OUTLETS FLOWING

APPENDIX B

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam CORTLANDT LAKE DAM (FORMERLY CANOPUS DAM)

Fed. I.D. # NY 85 DEC Dam No. 213-858 LOWER HUDSON

River Basin LOWER HUDSON

Location: Town CORTLANDT County WESTCHESTER

Stream Name CANOPUS CREEK

Tributary of SPROUT BROOK

Latitude (N) 41° 19.6' Longitude (W) 73° 55.2'

Type of Dam CONCRETE

Hazard Category HIGH

Date(s) of Inspection 5/27/81

Weather Conditions SUNNY 70°

Reservoir Level at Time of Inspection SPILLWAY CREST

b. Inspection Personnel R. WARRENDER W. LYNICK

c. Persons Contacted (Including Address & Phone No.) _____

JAMES IRISH-TOWN OF CORTLANDT ENGINEER 914-737-3713

d. History:

Date Constructed 1929 Date(s) Reconstructed _____

Designer NICHOLAS HILL

Constructed By _____

Owner CONTINENTAL VILLAGE PARK COMMISSION

2) EMBANKMENT - NO EMBANKMENT SECTION - EARTH FILL IS
SIMPLY BACKFILL FOR CONCRETE SECTIONS

3) Drainage System

- a. Description of System WEEP HOLES THROUGH CONCRETE
WINGWALLS AT EITHER END OF SPILLWAY SECTION
- b. Condition of System SATISFACTORY
- c. Discharge from Drainage System FLOW THROUGH SEVERAL OF THE WEEP
HOLES AT TIME OF INSPECTION - DISCOLORATION OF CONCRETE BELOW
SOME OF THE WEEP HOLES INDICATES FREQUENT DISCHARGE

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs,
Piezometers, Etc.)

NONE

5) Reservoira. Slopes FAIRLY STEEP BUT SATISFACTORYb. Sedimentation NONE APPARENTc. Unusual Conditions Which Affect Dam NONE6) Area Downstream of Dama. Downstream Hazard (No. of Homes, Highways, etc.) SUBSTANTIAL
DOWNSTREAM DEVELOPMENT & 1 ROAD (TOWN)b. Seepage, Unusual Growth NONEc. Evidence of Movement Beyond Toe of Dam NONEd. Condition of Downstream Channel SOME TREES GROWING IN CHANNEL
GENERALLY ROCK LINED & SATISFACTORY7) Spillway(s) (Including Discharge Conveyance Channel)MAIN SPILLWAY SECTION IS CONCRETE OGEE SECTION IN
CENTER OF DAM. 2 LOW LEVEL OUTLET OPENINGS FOR RELEASE
BELOW SPILLCREST

a. General

OGEE SECTION HAS HOLES IN CREST FOR FLASHBOARD
PINS - HOWEVER NONE WERE IN PLACE AT TIME OF THE
INSPECTIONb. Condition of ^{OGEE}~~Service~~ Spillway SOME DETERIORATION OF CONCRETE
SLIGHTLY IRREGULAR CREST - FLOW OVER TWO DETERIORATED
AREAS OF CREST AT TIME OF INSPECTIONSOME DETERIORATION OF CONCRETE ALONG EACH
CONSTRUCTION JOINT AS WELL

MID LEVEL OUTLET

- c. Condition of ~~Spillway~~ Spillway CONTROL MECHANISM AT RIGHT END OF SPILLWAY - DID NOT APPEAR TO HAVE BEEN OPERATED RECENTLY BUT APPEARED TO BE OPERABLE. THERE WAS SLIGHT SEWAGE LEAKAGE ALONG BASE OF THE 3' SQUARE OPENING - NOTED AT OUTLET OF CHANNEL
- d. Condition of Discharge Conveyance Channel SATISFACTORY

8) Reservoir Drain/Outlet - (LOWER LOW LEVEL OUTLET)

Type: Pipe _____ Conduit _____ Other 3' SQUARE OPENNING

Material: Concrete Metal _____ Other _____

Size: 3' SQUARE Length 25'

Invert Elevations: Entrance 80 Exit 74

Physical Condition (Describe): _____ Unobservable

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate Valve _____ Uncontrolled _____

Operation: Operable _____ Inoperable _____ Other _____

Present Condition (Describe): CONTROL MECHANISM IN RESERVOIR UNOBSERVABLE - OUTLET PARTIALLY SUBMERGED

9) Structural

- a. Concrete Surfaces SOME DETERIORATION OF CONCRETE ON SPILLWAY CREST
ALSO SOME SPALLING ON DOWNSTREAM ENDS OF WINGWALLS,
SOME SPALLING & DETERIORATION IN VICINITY OF ~~WINGWALLS~~
JOINTS BOTH ON WINGWALLS & SPILLWAY SECTION
- b. Structural Cracking NO MAJOR CRACKING
- c. Movement - Horizontal & Vertical Alignment (Settlement) ALIGNMENT
SATISFACTORY
- d. Junctions with Abutments or Embankments AT ENDS OF SPILLWAY CONCRETE
WINGWALLS SEPARATE SPILLWAY & RETAIN BACKFILL - SUBSTANTIAL
AMOUNT OF BACKFILL MISSING BEHIND LEFT WINGWALL - UP TO 5' DEEP AT CREST
GOING DOWN ABOUT $\frac{1}{2}$ WAY ALONG WINGWALL
- e. Drains - Foundation, Joint, Face WEEP HOLES THROUGH WINGWALLS
SOME OF WHICH ARE FLOWING
- f. Water Passages, Conduits, Sluices SLUICES FOR LOW LEVEL OUTLETS
APPEAR SATISFACTORY
- g. Seepage or Leakage SATURATED AREA AT BASE OF LEFT WINGWALL
AREA - SEEPAGE & SLOUGHING - SEMI-CIRCULAR AREA ABOUT 12' ACROSS
HAS SLOUGHED UP TO 1' - SEEPAGE COMING OUT AT RATE OF ABOUT
1 GAL/MINUTE. - WATER FLOWS OVER THE LOW WALL AT THE BASE OF
THE WINGWALL.
SOME SEEPAGE ALSO NOTED AT DOWNSTREAM END OF RIGHT
WINGWALL AT ORIGINAL GROUND CONTACT

- h. Joints - Construction, etc. SOME DETERIORATION & SPALLING
ALONG A NUMBER OF CONSTRUCTION JOINTS - ESPECIALLY
ALONG VERTICAL CONSTRUCTION JOINTS
- i. Foundation SATISFACTORY
- j. Abutments GOOD
- k. Control Gates MIDLEVEL GATE APPEARED SATISFACTORY
LOW LEVEL OUTLET UNOBSERVABLE
- l. Approach & Outlet Channels SATISFACTORY
- m. Energy Dissipators (Plunge Pool, etc.) NONE
- n. Intake Structures FORMED CIRCULAR CONCRETE HOLE IN LEFT
ABUTMENT - PURPOSE OF HOLE IS UNKNOWN
- o. Stability _____
- p. Miscellaneous _____

APPENDIX C

HYDROLOGIC/HYDRAULIC
ENGINEERING DATA AND COMPUTATIONS

CORTLAND LAKE DAM
NY-85

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

AREA-CAPACITY DATA:

	<u>[USGS]</u> Elevation (ft.)	Surface Area (acres)	Storage Capacity (acre-ft.)
1) Top of Dam	<u>102</u>	<u>17.4 +</u>	<u>244</u>
2) Design High Water (Max. Design Pool)	<u>N/A</u>	<u>-</u>	<u>-</u>
3) Auxiliary Spillway Crest	<u>N/A</u>	<u>-</u>	<u>-</u>
4) Pool Level with Flashboards	<u>N/A</u>	<u>-</u>	<u>-</u>
5) <u> </u> Spillway Crest	<u>96</u>	<u>17.4</u>	<u>140</u>
6) SLOT ON CREST	<u>95.25</u>	<u>-</u>	<u>-</u>

DISCHARGES

	<u> </u> (cfs)
1) Average Daily	<u>N/A</u>
2) Spillway @ Maximum High Water	<u>6754</u>
3) Spillway @ Design High Water	<u>N/A</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>N/A</u>
5) Low Level Outlet (WATER @ SPILLCREST ELEV.) (FULL OPEN)	<u>288</u>
6) Total (of all facilities) @ Maximum High Water	<u>7117</u>
7) Maximum Known Flood	<u>N/A</u>
8) At Time of Inspection	<u>±10</u>

CREST: USGS ELEVATION: 100

Type: CONCRETE WALL w/ EARTH BACKFILL

Width: WALL = 3' TOTAL ≈ 10'-15' Length: LT = 55' RT = 50' L = 105'

Spillover SPILLWAY (WEIR)

Location @ CENTER OF DAM

SPILLWAY:

SERVICE

96 Elevation

CONC. Ogee WEIR Type

± 6' Width

Type of Control

✓ Uncontrolled

Controlled:

N/A Type
(Flashboards; gate)

N/A Number

120' Size/Length

Invert Material

Anticipated Length
of operating service

Chute Length

> 10' Height Between Spillway Crest
& Approach Channel Invert
(Weir Flow)

HYDROMETEROLOGICAL GAGES:

Type : USGS GAGE # 1374150

Location: 1.075 MI. UPSTREAM FROM LAKE @ CONTINENTAL VILLAGE

* Records: LOW FLOW / PARTIAL RECORD STA.

Date - 12/7/60 - 7/26/66

 Readings: 0.22 - 17.9 cfs

FLOOD WATER CONTROL SYSTEM:

Warning System: NONE

Method of Controlled Releases (mechanisms):

TWO 3'x3' OUTLETS THRU DAM ; ONE @ RT. ABUTMENT (MID-LEVEL GATE)
OTHER THRU SPILLWAY (RESV. DRAIN)

* GAGE DATA:

#1374150 (USGS)

Canopus Creek @ Continental Village
Low-flow, partial record station

<u>DATE</u>	<u>DISCHARGE</u>
7/26/66	10.3
8/5/65	6.55
9/17/64	0.22
7/1/64	1.98
3/1/63	10.9
7/18/62	0.93
6/19/62	3.63
12/7/60	17.9

DRAINAGE AREA: 9693 ACRES 15.15 SQ MILES

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: FORESTS ; WOODLANDS ; SOME RESIDENTIAL DEVELOPMENT
OF MEDIUM TO LIGHT DENSITY

Terrain - Relief: HILLY ; STEEP SLOPES

Surface - Soil: ROCKY

Runoff Potential (existing or planned extensive alterations to existing
(surface or subsurface conditions)

NONE APPARENT

Potential Sedimentation problem areas (natural or man-made; present or future)

NONE APPARENT

Potential Backwater problem areas for levels at maximum storage capacity
including surcharge storage:

NONE APPARENT

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the
Reservoir perimeter:

Location: NO

Elevation: _____

Reservoir:

Length @ Maximum Pool 1850' ±0.35 (Miles)

Length of Shoreline (@ Spillway Crest) 4200' ±0.8 (Miles)

PROJECT GRID

JOB		SHEET NO.		CHECKED BY	DATE
CORTLAND LAKE DAM		1/			
SUBJECT		COMPUTED BY		DATE	
WATERSHED PARAMETERS		WCL		7/3/51	
DRAINAGE AREA: - PLANIMETERED (1 SQ. IN. = 91.827 ACRES)					
VEGS 7.5 MIN.					
QUAD.	SUBBASIN	SQ. INS.	ACRES		
OSCAWANA LAKE	CANOPUS LAKE	DA = 2.33	214		
	NORTH END - DAM	SURE A = 0.37	34		
	OUTLET - CANOPUS LAKE	DA = 3.51	322		
	(LOWER POND)	+ PELTON POND	SUBBASIN		
		SURE A = 0.67	61.5		
	PELTON POND DAM	DA = 1.46	134		
		SURE A = 0.09	8.26		
	JOHN ALLEN POND DAM	DA = 10.29	945		
		SURE A = 0.02	1.84		
	MAIN STEM - CANOPUS CREEK	13.69			
MOHEGAN →	↑	18.35			
LAKE		3.27			
WEST POINT →		10.88			
PEEKSKILL →	↓	34.52			
		80.71	7411		
WEST POINT →	DAM # 469 LH	DA = 4.90	450		
WEST POINT	INDIAN LAKE	DA = 0.67	217		
PEEKSKILL		1.70			
		SURE A = 0.13	41.3		
		0.39			

PROJECT GRID

JOB		SHEET NO.		CHECKED BY		DATE	
CORTLAND LAKE DAM		2/					
SUBJECT				COMPUTED BY		DATE	
WATERSHED PARAMETERS				WCL		7/6/81	
DRAINAGE AREA HAVING CONTROLLED RUNOFF :							
DAM	DRAINAGE AREA (ACRES)	% TOTAL	RESERVOIR SURFACE (ACRES)	H	SURCHARGE STORAGE (AC-FT)		
CANOPUS LAKE	214	2.21	34	5'	170		
NORTH END DAM			(50)		(250)		
PELTON POND	134	1.38	8.26	5.5'	45.4		
			(8.72)		(48)		
CANOPUS LAKE LOWER	322	3.32	61.5	-	UNKNOWN		
(NATURAL OUTLET?)	---	---					
SUBTOTAL :	670	6.91					
JOHN ALLEN POND	945	9.75	1.84	1.5'	2.76		
			(20)		(30)		
DAM #469LH	450	4.64	-	-	UNKNOWN		
INDIAN LAKE	217	2.24	41.3	-	UNKNOWN		
TOTAL :	<u>2282</u>	<u>23.54</u>					
AREA DRAINING DIRECTLY INTO CANOPUS CREEK	7411						
TOTAL WATERSHED :	<u>9693</u>				→ 15.15 SQ MILES ←		

PROJECT GRID

JOB		SHEET NO.	CHECKED BY	DATE
CORTLAND LAKE DAM		3/		
SUBJECT			COMPUTED BY	DATE
WATERSHED PARAMETERS			WCL	7/6/81
SNYDER UNIT HYDROGRAPH :				
LAG TIME : $t_p = C_e (L \times L_{CA})^{0.3}$				
		$L = 12.60$ MILES (66650')		
		$L_{CA} = 5.95$ MILES (31400')		
		$C_e = 2.0$		
$t_p = (2.0)(12.60 \times 5.95)^{0.3}$				
$t_p = 7.31$ HRS				
UNIT RAINFALL DURATION : $t_r = \frac{t_p}{5.5}$				
$t_r = 1.33$				
USE $t_r = 1.0$ HR				
ADJUSTED LAG TIME :				
$TP = t_p + 0.25(t_p - t_r)$				
$= 7.31 + 0.25(7.31 - 1.33)$				
$TP = 7.24$ HRS				
PEAKING COEFFICIENT :				
640 CP = 3.59				
CP = 0.56				
REF: CORPS ENGRS LOWER HUDSON BASIN STUDY				

PROJECT GRID

JOB CORTLAND LAKE DAM		SHEET NO. 4/	CHECKED BY	DATE
SUBJECT		COMPUTED BY WCL		DATE 7/6/81
PMP - RAINFALL : HRR # 33				
ZONE 1 200 SQ MI / 24 HR INDEX P = 21.4"				
ADJUSTMENT FOR AREA / DURATION : (HRS) 6 12 24 48				
% OF INDEX → 100 119 128 137				
SOIL RETENTION - RAINFALL LOSS RATES :				
INITIAL = 1.5 INS		REF: CORPS ENGRS		
CONSTANT = 0.1 INS/HR		LOWER HUDSON BASIN STUDY		
BASE FLOW :				
INITIAL @ 1 cfs / 30 MI → 15 cfs		REF: ↑		
ORCSN = 0.25		RTICR = 3.0		

PROJECT GRID

JOB		SHEET NO.	CHECKED BY	DATE
CORTLAND LAKE DAM		5/		
SUBJECT			COMPUTED BY	DATE
			WCL	7/7/81
STORAGE VOLUME :				
LAKE SURFACE - PLANIMETERED @ 0.19 SQ INS → 17.4 ACRES				
REF: 10/10/29 DAM APPLICATION → 16.9 ACRES				
VOLUME @ SPILLWAY → 140 AC-FT				
CREST				
DEGS	SURF. AREA	(AC-FT)		
ELEV		VOLUME		
±75		± 10		
96	17.4	140	SPILLCREST ←	
DIST. TO TOP DAM				
PLAN = 6'				
MEASURED @ 6.25' ΔVOL = 6 × 17.4 = 104.4				
102	17.4	244	TOP-OF-DAM ←	
PROJECTED				
ΔV = 4 × 17.4 = 69.6 AC-FT				
106 ↓		314		
DISCHARGE - SLOT IN SPILLCREST :				
WEIR FLOW } Q = CLH ^{3/2}			DAM OVERTOPPING :	
H = 0.75'			L = 105'	
L = 4.9'			RT ABUT = 50'	
C = 2.63			LT ABUT = 55' (±)	
EXCEEDS } Q = 8.37 cfs			C = 2.63	
BASE FLOW }				

PROJECT GRID

JOB		SHEET NO.		CHECKED BY		DATE	
CORTLAND LAKE DAM		6/					
SUBJECT				COMPUTED BY		DATE	
SPILLWAY DISCHARGES				WCL		7/7/81	
WEIR FLOW $Q = C L H^{3/2}$				WITHOUT END CONTRACTIONS			
FIELD MEASURED - 5/81							
CREST TO TOP DAM:		L = 120'		REF: HANDBOOK OF HYDRAULICS KING & BRATER 5TH ED. TABLE 5-13			
LT = 6.75'		C - VARIES w/ H					
RT = 6.25'							
USGS ELEV.	H	C	Q				
%	—	3.2	—	(+ SLOT @ 8 cfs)		SPILLCREST	
	0.5	3.22	136				
	1	3.38	405				
	1.5	3.46	762				
	2	3.51	1191				
	2.5	3.55	1684				
	3	3.58	2232				
	3.5	3.62	2844				
	4	3.68	3532				
	4.5	3.74	4284				
	5	3.83	5138				
	5.5		5928				
102	6		6754			TOP DAM	
	8		10400			PROJECTED	
	10		14533				

PROJECT GRID

JOB		SHEET NO.		CHECKED BY		DATE	
CORTLAND LAKE DAM		7/					
SUBJECT				COMPUTED BY		DATE	
DISCHARGES :				WCL		7/7/81	
<u>PLAN</u> DATUM:							
MID-LEVEL GATE :		3' X 3' CONC. BOX		ORIFICE FLOW			
INLET @ 96		INVERT H 6'		$Q = CA \sqrt{2gH}$			
OUTLET @ 90		12'		GATE CONTROL 7 ACCESSABLE		C = 0.6 A = 9	
WATER SURFACE @ SPILLCREST :		GATE FULLY OPEN		Q = 92 cfs		H = 4.5'	
* @ TOP DAM :		Q = 140 cfs		H = 10.5			
@ H = 12.5		Q = 153 cfs					
@ H = 14.5		Q = 165 cfs					
RESERVOIR DRAIN :		3' X 3' CONC. BOX		ORIFICE FLOW			
INLET @ 80		INVERT H 22'					
OUTLET @ 74		28'		GATE CONTROL 7 INACCESSABLE		C = 0.6 A = 9	
WATER SURFACE @ SPILLCREST :		GATE FULLY OPEN		Q = 196 cfs		H = 22.5	
@ TOP DAM :		Q = 223 cfs		H = 26.5			
* MID-LEVEL GATE OPENING (DURING PMF EVENT) :							
START GATE OPENING WHEN FLOW DEPTH ON SPILLWAY = 3'							
WATER ELEV.	GATE OPENING	Q	HEC-1 SPILLWAY Q	44/45	TOTAL Q		
99	CLOSED	0	2232		2232		
.5		23	2844		2867		
100		46	3532		3578		
.5		69	4284		4353		
101		93	5138		5231		
.5		116	5928		6044		
102	FULL OPEN	140	6754		6894		
104		153	10400		10553		
106		165	14533		14698		

FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 MODIFIED FOR HONEYWELL APR 79

NEW YORK STATE
 DEPT OF ENVIRONMENTAL CONSERVATION
 FLOOD PROTECTICH BUREAU

.....

A1 NY-85
 A2
 A3
 B 120
 B1 5

.....
 LOWER HUDSON RIVER BASIN
 WESTCHESTER COUNTY
 SNYDER UH
 0 0 0 0

CORTLAND LAKE DAM
 DEC 213-858 LH -- CANOPUS CR:EK
 CONTINENTAL VILL. PARK DISTR COMM.
 1 0 0 0

J1 0.50 0.51 0.52 0.53 0.54 0.55
 K 0 BASIN
 K1 INFLOW HYDROGRAPH - DAM

M 1 1 15.15 15.15
 P 21.4 106 119 128 137
 T 1.5 0.1

V 7.24 0.56
 X 15 -0.25 3
 K 1 DAM
 K1 ROUTEE OUTFLOW - DAM - SPILLCREST ELEV 96-USGS

Y 1 1
 Y1 1
 Y4 95.25 56 56.5 97 97.5 98 98.5 99 99.5 100
 Y4 100.5 101 101.5 102 104 106
 Y5 0 8 136 405 762 1191 1684 2232 2844 3532
 Y5 4284 5138 5928 6754 10400 14533
 S5 10 140 244 314
 SE 75 56 102 106
 S8 96
 SD 102 2.63 1.5 105
 X 99
 A
 A
 A

NO GATE OPEN

.....

.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 MODIFIED FOR HONEYWELL APR 79

.....
 NEW YORK STATE
 DEPT OF ENVIRONMENTAL CONSERVATION
 FLOOD PROTECTION BUREAU

.....
 LOWER HUDSON RIVER BASIN
 WESTCHESTER COUNTY
 SNYDER UH

.....
 CCRTLANC LAKE DAM
 DEC 23-858 LM -- CANCPUS CREEK
 CONTINENTAL VILL. PARK DISTR :CMH.

.....
 NY-85
 RUN DATE 07/13/81
 NO NHR NPJA IOAY IHR IMIN METRC IPLT IPRT INSTAN
 120 1 0 0 0 0 0 0 0 0 0
 JOPER 5 LRO'1 TRACE
 0 0 0 0

.....
 MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRATIO= 7 LRTIO= 1
 RTIOS= 0.50 0.51 0.52 0.53 0.54 0.55 1.00

.....
 SUB-AREA RUNOFF COMPUTATION
 INFLOW HYDROGRAPH - DAM
 ISTAT ICOMP IECCN ITAPE JPLT JPRT INAME ISTAGE IAUTO
 BASIN 0 0 0 0 0 0 0 0 0 0

.....
 HYDROGRAPH DATA
 IHYDG ILHG IAFEA SNAP TRSOA TRSPC RATIO ISNOW ISAME LOCAL
 1 1 15.15 0. 15.15 0. 0. 0 0 1 0 0
 PRECIP DATA
 SPFE PPS R6 R12 R24 R48 R72 R96
 0. 21.40 106.00 119.00 128.00 137.00 0. 0.
 TRSPC COMPUTED BY THE PROGRAM IS 0.814

.....
 LOSS DATA
 LROPT STRKR ULTKR FVIGL ERATN STRKS RTICK STRTL CNSIL ALSMX RTIMP
 0 0. 0. 1.00 0. 0. 1.00 1.50 0.10 0. 0.
 UNIT HYDROGRAPH DATA
 TP= 7.24 CP=0.56 NTA= 0

.....
 RECESION DATA
 STRTJE= 15.00 ORCSN= -0.25 RTIOE= 5.00
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 8.15 AND RE= 8.12 INTERVALS

.....
 UNIT HYDROGRAPH 48 END-OF-PERIOD ORIGINATES, LAG= 7.30 HOURS, CP= 0.56 VOL= 1.00
 34. 129. 258. 406. 554. 673. 745. 765. 718. 637.
 563. 498. 440. 389. 344. 304. 269. 237. 210. 186.
 164. 145. 128. 113. 100. 85. 78. 69. 61. 54.
 48. 42. 37. 33. 29. 26. 23. 20. 18. 16.
 14. 12. 11. 10. 9. 8. 7. 6. 5. 4.

END-OF-PERIOD FLOW

0

163. 498. 440. 349. 144. 304. 269. 217. 210. 186.
 168. 145. 128. 113. 100. 85. 78. 69. 61. 54.
 48. 42. 37. 33. 29. 26. 23. 20. 18. 16.
 14. 12. 11. 10. 9. 8. 7. 6. 5. 4.

END-OF-PERIOD FLOW

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
1.01	1.00	1	0.01	0.	0.01	13.	1.03	13.00	61	0.	0.	0.	2807.
1.01	2.00	2	0.01	0.	0.01	12.	1.03	14.00	62	0.	0.	0.	2515.
1.01	3.00	3	0.01	0.	0.01	11.	1.03	15.00	63	0.	0.	0.	2253.
1.01	4.00	4	0.01	0.	0.01	10.	1.03	16.00	64	0.	0.	0.	2019.
1.01	5.00	5	0.01	0.	0.01	9.	1.03	17.00	65	0.	0.	0.	1805.
1.01	6.00	6	0.01	0.	0.01	8.	1.03	18.00	66	0.	0.	0.	1621.
1.01	7.00	7	0.03	0.	0.03	7.	1.03	19.00	67	0.	0.	0.	1452.
1.01	8.00	8	0.03	0.	0.03	6.	1.03	20.00	68	0.	0.	0.	1301.
1.01	9.00	9	0.03	0.	0.03	6.	1.03	21.00	69	0.	0.	0.	1166.
1.01	10.00	10	0.03	0.	0.03	5.	1.03	22.00	70	0.	0.	0.	1044.
1.01	11.00	11	0.03	0.	0.03	4.	1.04	0.	71	0.	0.	0.	936.
1.01	12.00	12	0.03	0.	0.03	4.	1.04	1.00	72	0.	0.	0.	838.
1.01	13.00	13	0.13	0.	0.13	4.	1.04	2.00	73	0.	0.	0.	751.
1.01	14.00	14	0.16	0.	0.16	3.	1.04	3.00	74	0.	0.	0.	673.
1.01	15.00	15	0.19	0.	0.19	3.	1.04	4.00	75	0.	0.	0.	603.
1.01	16.00	16	0.49	0.	0.49	3.	1.04	5.00	76	0.	0.	0.	540.
1.01	17.00	17	0.18	0.	0.18	2.	1.04	6.00	77	0.	0.	0.	484.
1.01	18.00	18	0.14	0.	0.14	2.	1.04	7.00	78	0.	0.	0.	434.
1.01	19.00	19	0.01	0.	0.01	2.	1.04	8.00	79	0.	0.	0.	389.
1.01	20.00	20	0.01	0.	0.01	2.	1.04	9.00	80	0.	0.	0.	348.
1.01	21.00	21	0.01	0.	0.01	2.	1.04	10.00	81	0.	0.	0.	312.
1.01	22.00	22	0.01	0.	0.01	2.	1.04	11.00	82	0.	0.	0.	279.
1.01	23.00	23	0.01	0.	0.01	2.	1.04	12.00	83	0.	0.	0.	250.
1.02	0.	24	0.01	0.	0.01	2.	1.04	13.00	84	0.	0.	0.	224.
1.02	1.00	25	0.10	0.	0.10	2.	1.04	14.00	85	0.	0.	0.	201.
1.02	2.00	26	0.10	0.	0.10	2.	1.04	15.00	86	0.	0.	0.	180.
1.02	3.00	27	0.10	0.	0.10	3.	1.04	16.00	87	0.	0.	0.	161.
1.02	4.00	28	0.10	0.	0.10	5.	1.04	17.00	88	0.	0.	0.	145.
1.02	5.00	29	0.10	0.	0.10	7.	1.04	18.00	89	0.	0.	0.	130.
1.02	6.00	30	0.10	0.	0.10	10.	1.04	19.00	90	0.	0.	0.	116.
1.02	7.00	31	0.38	0.26	0.10	23.	1.04	20.00	91	0.	0.	0.	104.
1.02	8.00	32	0.38	0.28	0.10	61.	1.04	21.00	92	0.	0.	0.	93.
1.02	9.00	33	0.38	0.28	0.10	135.	1.04	22.00	94	0.	0.	0.	75.
1.02	10.00	34	0.38	0.28	0.10	248.	1.04	23.00	95	0.	0.	0.	67.
1.02	11.00	35	0.38	0.28	0.10	588.	1.05	0.	96	0.	0.	0.	60.
1.02	12.00	36	0.38	0.28	0.10	844.	1.05	1.00	97	0.	0.	0.	54.
1.02	13.00	37	1.85	1.75	0.10	1255.	1.05	2.00	98	0.	0.	0.	48.
1.02	14.00	38	2.22	2.12	0.10	1898.	1.05	3.00	99	0.	0.	0.	43.
1.02	15.00	39	2.77	2.67	0.10	2993.	1.05	4.00	100	0.	0.	0.	39.
1.02	16.00	40	7.02	6.52	0.50	4536.	1.05	5.00	101	0.	0.	0.	35.
1.02	17.00	41	2.59	2.49	0.10	6700.	1.05	6.00	102	0.	0.	0.	31.
1.02	18.00	42	2.03	1.53	0.50	8919.	1.05	7.00	103	0.	0.	0.	28.
1.02	19.00	43	0.15	0.06	0.10	10359.	1.05	8.00	104	0.	0.	0.	25.
1.02	20.00	44	0.16	0.06	0.10	12506.	1.05	9.00	105	0.	0.	0.	22.
1.02	21.00	45	0.16	0.06	0.10	13327.	1.05	10.00	106	0.	0.	0.	20.
1.02	22.00	46	0.16	0.06	0.10	13377.	1.05	11.00	107	0.	0.	0.	18.
1.02	23.00	47	0.16	0.06	0.10	12743.	1.05	12.00	108	0.	0.	0.	16.
1.03	0.	48	0.16	0.06	0.10	11642.	1.05	13.00	109	0.	0.	0.	14.
1.03	1.00	49	0.	0.	0.	9274.	1.05	14.00	110	0.	0.	0.	13.
1.03	2.00	50	0.	0.	0.	8037.	1.05	15.00	111	0.	0.	0.	12.
1.03	3.00	51	0.	0.	0.		1.05	15.00	112	0.	0.	0.	
1.03	4.00	52	0.	0.	0.		1.05	15.00	113	0.	0.	0.	

1.03	1.00	49	0.	0.	11,42.	1.05	13.00	105	U.	14.
1.03	2.00	50	0.	0.	10432.	1.05	14.00	110	0.	13.
1.03	3.00	51	0.	0.	9274.	1.05	15.00	111	0.	12.
1.03	4.00	52	0.	0.	8237.	1.05	16.00	112	0.	10.
1.03	5.00	53	0.	0.	7509.	1.05	17.00	113	0.	9.
1.03	6.00	54	0.	0.	6478.	1.05	18.00	114	0.	8.
1.03	7.00	55	0.	0.	5755.	1.05	19.00	115	0.	7.
1.03	8.00	56	0.	0.	5072.	1.05	20.00	116	0.	7.
1.03	9.00	57	0.	0.	4184.	1.05	21.00	117	0.	6.
1.03	10.00	58	0.	0.	3963.	1.05	22.00	118	0.	5.
1.03	11.00	59	0.	0.	3504.	1.05	23.00	119	0.	5.
1.03	12.00	60	0.	0.	3133.	1.06	0.	120	0.	4.

SUM 23.87 19.90 3.57 197992.
 (606.)(506.)(101.)(5606.51)

PEAK	13397.	7202.	2745.	197982.
6-HOUR	12386.	204.	78.	5606.
24-HOUR	7.61	17.63	20.22	20.26
72-HOUR	153.17	449.27	513.56	514.62
TOTAL VOLUME	6142.	14284.	16332.	16362.
	7576.	17619.	20145.	20182.

HYDROGRAPH AT STA BASIN FOR PLAN 1, RATIO 1

7.	5.	4.	4.	3.	3.	2.
2.	2.	1.	1.	1.	1.	1.
1.	1.	1.	1.	2.	2.	5.
11.	67.	201.	294.	422.	628.	1491.
2318.	4459.	5253.	6664.	6699.	6371.	5216.
4637.	3654.	2867.	2536.	2242.	1982.	1567.
1404.	1127.	904.	810.	726.	650.	522.
468.	376.	301.	270.	242.	217.	174.
156.	125.	100.	30.	81.	72.	65.
52.	42.	33.	30.	27.	24.	19.
17.	14.	11.	10.	9.	8.	6.
6.	5.	4.	3.	3.	2.	2.

PEAK	699.	3601.	1372.	98991.
6-HOUR	6193.	102.	39.	2803.
24-HOUR	175.	8.84	10.11	10.13
72-HOUR	3.80	224.61	256.83	257.31
TOTAL VOLUME	56.59	7142.	8166.	8131.
	3071.	8810.	10072.	10091.

HYDROGRAPH AT STA BASIN FOR PLAN 1, RATIO 2

7.	6.	5.	4.	4.	3.	3.
2.	2.	2.	1.	1.	1.	1.
1.	1.	1.	1.	2.	2.	5.
12.	65.	127.	205.	300.	430.	1521.
2335.	4548.	5594.	6378.	6797.	6833.	5938.
4730.	3721.	3304.	2925.	2587.	2287.	1787.
1432.	1145.	1030.	923.	741.	664.	594.
477.	383.	343.	308.	276.	247.	198.
159.	143.	114.	103.	92.	74.	66.
53.	42.	38.	34.	31.	27.	25.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
699.	6193.	3601.	1372.	98991.	
190.	175.	102.	39.	2803.	
	3.80	8.84	10.11	257.31	
	96.59	224.63	256.83	8181.	
	3071.	7142.	8166.	10091.	
	3788.	8810.	10072.		

HYDROGRAPH AT STA BASIN FOR PLAN 1, RTIO 2

	6.	5.	4.	4.	3.
7.	6.	5.	4.	4.	3.
2.	2.	2.	1.	1.	1.
1.	1.	1.	1.	2.	5.
12.	31.	69.	127.	430.	968.
2365.	3417.	4546.	5594.	3797.	5938.
4730.	4201.	3304.	2925.	2287.	1787.
1432.	1283.	1145.	923.	741.	594.
477.	428.	383.	308.	276.	198.
159.	143.	126.	103.	92.	66.
53.	48.	42.	38.	31.	22.
18.	16.	14.	11.	10.	7.
6.	5.	4.	3.	3.	2.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
6833.	6317.	3673.	1400.	100971.	
193.	179.	104.	40.	2859.	
	3.88	9.02	10.31	10.33	
	98.52	229.13	261.97	262.46	
	3132.	7285.	8329.	8345.	
	3864.	8986.	10274.	10293.	

HYDROGRAPH AT STA BASIN FOR PLAN 1, RTIO 3

	6.	5.	5.	4.	3.
7.	6.	5.	4.	4.	3.
6.	2.	2.	2.	1.	1.
1.	1.	1.	1.	2.	5.
12.	32.	70.	129.	306.	653.
2411.	3484.	4638.	5704.	5930.	6626.
4823.	4283.	3800.	2982.	2331.	2061.
1450.	1308.	1172.	941.	843.	677.
487.	436.	391.	350.	281.	226.
162.	145.	130.	117.	94.	75.
54.	48.	42.	39.	31.	25.
10.	16.	14.	13.	10.	8.
6.	5.	4.	4.	3.	2.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
6967.	6441.	3745.	1427.	102951.	
197.	182.	106.	40.	2915.	
	3.95	9.20	10.52	10.54	
	100.45	233.62	267.10	267.60	
	3194.	7428.	8492.	8508.	
	3939.	9162.	10475.	10495.	

HYDROGRAPH AT STA BASIN FOR PLAN 1, RTIO 4

	6.	5.	5.	4.	3.
7.	6.	5.	4.	4.	3.
6.	2.	2.	2.	1.	1.
1.	1.	1.	1.	2.	5.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
7369.	6812.	3961.	1510.	108870.
209.	153.	112.	43.	3083.
	4.18	9.73	13.12	11.14
	106.24	247.10	282.51	283.04
	3378.	7856.	8982.	8999.
	4167.	9691.	11080.	11100.

HYDROGRAPH AT STA BASIN FOR PLAN 1, RTIO 7

13.	11.	9.	8.	7.	6.	5.
4.	4.	3.	3.	2.	2.	2.
23.	2.	2.	2.	3.	7.	10.
	61.	402.	588.	844.	1898.	2963.
4636.	8915.	12506.	13327.	13397.	13642.	10432.
9274.	7305.	5735.	5072.	4484.	2509.	3133.
2807.	2253.	1809.	1621.	1452.	3166.	1044.
936.	838.	673.	540.	484.	389.	348.
312.	250.	201.	180.	161.	130.	116.
104.	83.	67.	60.	54.	43.	39.
35.	28.	22.	20.	18.	14.	13.
12.	9.	7.	7.	6.	5.	4.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
12397.	12386.	7202.	2745.	197982.
379.	351.	204.	78.	5606.
	7.61	17.69	20.22	20.26
	153.17	443.27	513.66	514.62
	6142.	14284.	16332.	16362.
	7576.	17619.	20145.	20182.

HYDROGRAPH ROUTING

ROUTED OUTFLOW - DAM - SPILLCREST ELEV 96-USGS NO GATE OPEN
 ISTATG ICOMP IECON ITAPE JPLI JPRJ INAME ISTAGE IAUTO
 DAM 1 0 0 0 0 1 0 0

	CLOSS	CLOSS	AVG	ROUTING DATA				LSTR
	0.	0.	0.	IRES	ISAME	IOPT	IPHP	0
				1	1	0	0	
	ASTPS	NSTOL	LAG	AMSKK	X	TSK	STORA	ISPRAT
	1	0	0	0.	0.	0.	96.	-1
STAGE	95.25	56.00	97.00	97.50	98.00	98.50	99.00	99.50
	100.50	101.00	102.00	104.00	106.00	106.00	106.00	106.00
FLOW	4284.00	5138.00	5528.00	6754.00	762.00	1191.00	2232.00	2844.00
	0.	8.00	136.00	405.00	10400.00	14533.00	1684.00	3522.00
CAPACITY=	10.	140.	244.	.14.				
ELEVATION=	75.	96.	102.	106.				

CREL SFMID COOH EXPW ELEV COOL CAREA EXPL

17. 8.	17. 8.	15. 7.	14. 7.	13. 7.	12. 6.	11. 5.	10. 5.	9. 5.
140.	140.	140.	140.	139.	139.	137.	137.	138.
138.	138.	138.	138.	137.	137.	137.	137.	137.
137.	137.	137.	136.	136.	136.	136.	136.	137.
137.	137.	141.	145.	149.	153.	161.	168.	179.
151.	205.	218.	229.	238.	244.	241.	235.	229.
222.	217.	211.	206.	202.	197.	189.	185.	182.
179.	176.	174.	172.	159.	167.	166.	162.	161.
159.	158.	157.	156.	154.	152.	152.	151.	150.
150.	149.	146.	148.	147.	146.	145.	144.	144.
143.	143.	142.	142.	142.	142.	141.	141.	141.
141.	141.	140.	140.	140.	140.	140.	140.	140.
140.	140.	140.	139.	139.	139.	138.	138.	138.

STORAGE

STAGE

96.0	96.0	96.0	95.9	95.9	95.8	95.8	95.8	95.7
95.7	95.7	95.6	95.6	95.5	95.5	95.5	95.5	95.5
95.5	95.5	95.4	95.4	95.4	95.4	95.4	95.4	95.4
95.5	95.8	96.1	96.3	96.5	96.7	96.9	97.6	98.2
98.9	99.7	100.5	101.1	101.6	101.9	102.0	101.8	101.1
100.7	100.4	100.1	99.8	99.6	99.3	99.0	98.8	98.4
98.3	98.1	98.0	97.8	97.7	97.6	97.5	97.4	97.2
97.1	97.0	97.0	96.9	96.8	96.8	96.7	96.6	96.6
96.6	96.5	96.5	96.4	96.4	96.4	96.3	96.2	96.2
96.2	96.2	96.1	96.1	96.1	96.1	96.1	96.1	96.1
96.0	96.0	96.0	96.0	96.0	96.0	96.0	96.0	96.0
96.0	96.0	95.9	95.9	95.9	95.8	95.8	95.8	95.7

PEAK OUTFLOW IS 6708. AT TIME 47.00 HOURS

RATIO 1

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
€708.	6195.	3598.	1372.	95028.
190.	175.	102.	33.	2804.
	3.80	8.84	10.11	10.13
	56.61	224.44	256.76	257.41
	3072.	7136.	8164.	8184.
	3789.	8802.	10070.	10095.

STATION DAM, PLAN 1, RATIO 2

END-OF-PERIOD HYDROGRAPH ORDINATES

8.	8.	8.	7.	6.	5.
5.	4.	4.	3.	3.	2.
2.	2.	2.	2.	2.	2.
3.	5.	27.	81.	150.	265.
2184.	3247.	4395.	5475.	6285.	6844.
4800.	4263.	3796.	3361.	2983.	2337.
1467.	1313.	1178.	1059.	948.	751.
493.	442.	397.	359.	321.	288.
166.	149.	124.	135.	112.	101.
58.	53.	47.	42.	38.	30.
20.	18.	16.	14.	13.	10.
8.	8.	7.	7.	7.	6.

PEAK FLOW AND STORAGE (LEAD OF PERIOD) SUMMARY FORMULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS						
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7
HYDROGRAPH AT	BASIN	15.15 (32089.28)	1	0.50	0.51	0.52	0.53	0.54	0.55	1.00
				6659.	6833.	6967.	7101.	7235.	7369.	13357.
			(189.69)	193.48)	197.27)	201.07)	204.86)	208.65)	379.37)
ROUTED TO	DAM	15.15 (32089.28)	1	0.50	0.51	0.52	0.53	0.54	0.55	1.00
				6708.	6844.	6978.	7111.	7244.	7378.	13421.
			(189.95)	193.81)	197.60)	201.37)	205.13)	208.91)	380.04)

WITH GATE CLOSED :

CORTLAND LAKE DAM
 NY-85

.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 CAN SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 MODIFIED FOR HONEYWELL APR 79

.....
 NEW YORK STATE
 DEPT OF ENVIRONMENTAL CONSERVATION
 FLOOD PROTECTION BUREAU

.....
 NY-85
 RUN DATE 07/13/81
 CCRTLAND LAKE DAM
 DEC 213-858 LM -- CAPOIUS CREEK
 CCNTINENTAL VILL. PARK DISTR COMM.
 LOWER HUDSON RIVER BASIN
 WESTCHESTER COUNTY
 SKYDER UH

.....
 JOB SPECIFICATION
 NQ NHR NPVA IDAY IHR ININ METRC IPLT IPRT NSTAN
 120 1 C 0 0 0 0 0
 JOPER NNT LRJPT TRACE
 5 0 0 0

.....
 MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRTIO= 7 LRTIO= 1
 RTIOS= 0.50 0.51 0.52 0.53 0.54 0.55 1.00

.....
 SUB-AREA RUNOFF COMPUTATION
 INFLOW HYDROGRAPH - CAM
 ISTAQ ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTC
 EASIN 0 0 0 0 0 0 1 0 0

.....
 HYDROGRAPH DATA
 IMYDG IUNG IAFEA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
 1 1 15.15 0. 15.15 0. 0. 0. 0. 0. 1 0

.....
 TRSPC COMPUTED BY THE PROGRAM IS 0.814
 SPFE PPS R6 R12 R24 R48 R72 R96
 0. 21.40 106.00 119.00 123.00 137.00 0. 0.

.....
 LOSS DATA
 LROPT STRKR DLIKR RTIOL ERAIN STRKS RTIOK STRIL CNSIL ALSHX RTIMP
 0 0. 0. 1.00 0. 0. 1.00 1.50 0.10 0. 0.

.....
 UNIT HYDROGRAPH DATA
 TP= 7.24 CP=0.56 NTA= 0
 RECESION DATA
 STRIC= 15.00 GRCSN= -0.25 RTIOR= 3.00
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE: TC= 8.15 AND R= 6.12 INTERVALS
 UNIT HYDROGRAPH 48 END-OF-PERIOD ORDINATES, LAG= 7.30 HOURS, CP= 0.56 VOL= 1.00
 34. 128. 258. 406. 554. 673. 745. 765. 718. 627.
 563. 458. 440. 389. 344. 304. 269. 237. 210. 186.
 164. 145. 128. 113. 100. 85. 69. 61. 54.
 48. 42. 37. 33. 29. 26. 23. 20. 18. 16.
 14. 12. 11. 10. 9. 8. 7. 6.

END-OF-PERIOD FLOW
 0

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS						
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7
HYDROGRAPH AT	BASIN	15.15	1	0.50	0.51	0.52	0.53	0.54	0.55	1.00
		(32089.37)	(699.)	(683.)	(696.)	(710.)	(723.)	(736.)	(757.)	
ROUTED TO	DAM	15.15	1	6706.	6842.	6977.	7112.	7246.	7379.	12418.
		(32089.37)	(189.69)((193.74)((197.52)((201.39)((205.18)((208.55)((375.55)(

WITH GATE OPEN :


CORTLAND LAKE DAM
 NY-85

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 56.00 140. 8.	SPILLWAY CREST 96.00 140. 8.	TOP OF DAM 102.00 244. 6894.	RATIO OF PMF	MAXIMUM RESERVOIR H.S.-ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.50	101.85	0.	242.	6706.	0.	47.00	0.					
0.51	101.97	0.	243.	6842.	0.	47.00	0.					
0.52	102.04	0.04	245.	6977.	2.00	47.00	0.					
0.53	102.11	0.11	246.	7112.	2.00	47.00	0.					
0.54	102.18	0.18	247.	7246.	3.00	47.00	0.					
0.55	102.25	0.25	248.	7379.	3.00	47.00	0.					
1.00	104.77	2.77	292.	13418.	11.00	47.00	0.					

CORTLAND LAKE DAM
NY-85

WITH GATE OPEN :



SCALE: UNKNOWN

DRAINAGE AREA MAP
 CORTLAND LAKE DAM
 NY-85

DISCHARGE AT PARTIAL-RECORD STATIONS AND MISCELLANEOUS SITES

Discharge measurements made at low-flow partial-record stations during water year 1966 -- Continued

Station No.	Station name	Location	Drainage Area (sq mi)	Period of record	Measurements	
					Date	Discharge (cfs)
Hudson River basin -- Continued						
3642	Saw Kill at Sawkill, N. Y.	Lat 41°58'46", long 74°00'52", at bridge on Kingston-Sawkill road, 1.0 mile east of Sawkill, Ulster County.	41.6	1951, 1954, 1956-61, 1964, 1966	7-14-66	2.55
*3644	Plattkill Creek at Mount Marion, N. Y.	Lat 42°02'22", long 73°59'50", 400 ft downstream from bridge on town road just off Glasco Rd., 0.5 mile west of Mt. Marion, Ulster County, and 2.5 miles upstream from mouth.	36.6	1962-64, 1966	11-26-65 6-30-66	28.0 8.9
3647	Saw Kill at Rock City, N. Y.	Lat 41°58'15", long 73°49'19", at bridge on State Highway 199, at Rock City, Dutchess County.	6.01	1956-62, 1965-66	7-14-66	1.04
3668	Vernooij Kill at Wawarsing, N. Y.	Lat 41°45'28", long 74°21'50", at abandoned pump house, just off State Highway 209, 0.5 mile northwest of Wawarsing, Ulster County.	23.5	1956-61, 1964-66	6-29-66	10.6
*3720.1	Landman Kill at Rhinebeck, N. Y.	Lat 41°55'22", long 73°54'46", at bridge on US Highway 9, at Rhinebeck, Dutchess County.	10.9	1956-62, 1964-66	7-12-66	1.11
3720.3	Fallsburg Creek near Rhinebeck, N. Y.	Lat 41°53'33", long 73°54'52", at highway bridge on Fox Hollow Road, 2.4 miles south of Rhinebeck, Dutchess County.	3.58	1956-62, 1964-66	7-12-66	0.03
*3720.4	Cross Elbow Creek at Hyde Park, N. Y.	Lat 41°47'24", long 73°59'53", at bridge on Hyde Park-East Park Road, at Hyde Park, Dutchess County, and 0.3 mile east of US Highway 9.	18.6	1956-58, 1961-62, 1964, 1966	8-1-66	.26
3726	Quassaic Creek near Newburgh, N. Y.	Lat 41°51'28", long 74°03'24", at bridge on Powder Mill Road, 0.4 mile northeast of State Highway 52 near Newburgh, Orange County.	13.5	1956-61, 1964-66	7-13-66	.26
3727	Gidneytown Creek at Newburgh, N. Y.	Lat 41°51'24", long 74°02'09", at bridge at junction of Gidney Avenue and Germantown Road, at Newburgh, Orange County.	10.1	1956-61, 1964-66	7-14-66	.28
3729.45	Clove Creek near Cold Spring, N. Y.	Lat 41°27'50", long 73°55'13", at bridge on east Mountain Road West, 50 ft east of US Highway 9, and 3.2 miles northeast of Cold Spring, Putnam County.	10.2	1962, 1964-66	7-26-66	.98
3740.98	Annaville Creek at Graymoor, N. Y.	Lat 41°20'23", long 73°55'27", at bridge on US Highway 9, 1 mile south of Graymoor, Putnam County, and 3.5 miles north of Peekskill.	1.97	1963, 1964-66	7-26-66	.04
→ 3741.5	Canopus Creek at Continental Village, N. Y.	Lat 41°20'15", long 73°54'15", at bridge on Gallows Hill Road, three-quarters of a mile upstream from Cortland Lake, at Continental Village, Putnam County.	14.5	1954, 1960, 1962-66	7-26-66	10.3
*3744.6	South Branch Minisceongo Creek at Letchworth Village, N. Y.	Lat 41°12'15", long 74°01'54", 200 ft downstream from Letchworth Village road and pond, and 1000 ft downstream from Palisades Interstate Parkway, at Letchworth Village, Rockland County.	5.85	1959-62, 1966	7-18-66	.12
3744.94	Haviland Hollow Brook near Putnam Lake, N. Y.	Lat 41°29'03", long 73°54'16", at bridge on Haviland Hollow-Putnam Lake Road, 0.6 mile upstream from mouth, and 2 miles northwest of Putnam Lake, Putnam County.	12.2	1962, 1964-66	7-26-66	.10
3745.4	Holly Stream near Brewster, N. Y.	Lat 41°22'17", long 73°58'16", at bridge on US Highway 202, 0.1 mile upstream from mouth, 1.9 miles southwest of Brewster, Putnam County, and 2.1 miles northeast of Croton Falls.	4.82	1962, 1964-66	7-26-66	.18
Streams on Staten Island						
3765.3	Sharrots Stream near Tottenville, N. Y.	Lat 40°32'50", long 74°14'16", at culvert on Arthur Kill Road, 150 ft north of Ellis Place, near Port Socony, and 2.2 miles north-northeast of Tottenville, Richmond County.	-	1962-66	5-15-66 6-16-66 7-29-66	.66 .12 .46
3765.35	Richmond Creek at Richmond, N. Y.	Lat 40°34'20", long 74°08'46", at downstream side of Richmond Hill Road (Arthur Kill Road) at end of Richmond Road, at Richmond, Richmond County, and 7 miles northeast of Tottenville.	-	1962-66	3-15-66 6-16-66 9-29-66	1.05 .51 .41
3765.4	Springville Creek at New Springville, N. Y.	Lat 40°35'36", long 74°09'49", at downstream side of Richmond Avenue at end of Travis Avenue at New Springville, Richmond County, and 7.5 miles northeast of Tottenville.	-	1962-66	3-15-66 6-16-66 9-29-66	.41 .16 .17
3765.5	Palmera Run at Port Richmond, N. Y.	Lat 40°38'14", long 74°07'41", at culvert on Richmond Terrace at end of Rector Street at Port Richmond, Richmond County.	-	1962-66	3-15-66 6-16-66	1.57 1.40
3765.6	Lemon Creek at Prince Bay, N. Y.	Lat 40°31'05", long 74°12'05", at downstream side of Ryan Boulevard at Prince Bay, Richmond County, and 2½ miles east of Tottenville.	-	1963-66	5-15-66 6-16-66	1.31 2.82

* Also a crest-stage partial-record station
 † Operated as a continuous-record gaging station
 ‡ Estimated

CORTLAND LAKE DAM
 NY-85

APPENDIX D
STABILITY COMPUTATIONS


CORTLANDT LAKE DAM

I.D. No. NY 85

SPILLWAY CROSS SECTION

SCALE 1" = 5'

SEGMENT	AREA (ft ²)	DISTANCE FROM CENTROID TO TOE (ft)
①	$(34)(2) = 68$	24
②	$\frac{1}{2}(28)(23) = 322$	15.3
③	$(4.5)(23) = 103.5$	11.5



STRUCTURAL STABILITY ANALYSIS

The analysis was based on a cross section shown on the plans. A normal analysis was performed including both overturning and sliding analysis. The analysis was performed according to Corps of Engineers guidelines and assumed full uplift pressure at the upstream toe, decreasing to tailwater pressure at the downstream toe.

ANALYSIS CONDITIONS

1. Normal conditions; water surface at spillway crest
2. Same as #1 plus ice load of 5,000 pounds per linear foot.
3. 1/2 PMF flows; water surface near or at top of dam (6.0 feet over spillway).
4. Seismic Conditions; water at spillway crest with seismic coefficient of 0.1.
5. Normal conditions but assuming Uplift Pressure = 0.

STABILITY ANALYSIS PROGRAM - WORK SHEET

<u>INPUT ENTRY</u>	<u>ANALYSIS CONDITION</u>				
	1	2	3	4	5
Unit Weight of Dam (K/ft ³)	0	0.15	0.15	0.15	0.15
Area of Segment No. 1 (ft ²)	1	68	68	68	68
Distance from Center of Gravity of Segment No. 1 to Downstream Toe (ft)	2	24	24	24	24
Area of Segment No. 2 (ft ²)	3	322	322	322	322
Distance from Center of Gravity of Segment No. 2 to Downstream Toe (ft)	4	15.3	15.3	15.3	15.3
Area of Segment No. 3 (ft ²)	5	103.5	103.5	103.5	103.5
Distance from Center of Gravity of Segment No. 3 to Downstream Toe (ft)	6	11.5	11.5	11.5	11.5
Base Width of Dam (Total) (ft)	7	25	25	25	0*
Height of Dam (ft)	8	34	34	34	34
Ice Loading (K/L ft.)	9	—	5.0	—	—
Coefficient of Sliding	10	0.65	0.65	0.65	0.65
Unit Weight of Soil (K/ft ³) (assumed to)	11	0.055	0.055	0.055	0.055
Active Soil Coefficient - Ka	12	0.27	0.27	0.27	0.27
Passive Soil Coefficient - Kp	13	3.69	3.69	3.69	3.69
Height of Water over Top of Dam or Spillway (ft)	14	—	—	6.0	—
Height of Soil for Active Pressure (ft)	15	2.5	2.5	2.5	2.5
Height of Soil for Passive Pressure (ft)	16	4.0	4.0	4.0	4.0
Height of Water in Tailrace Channel (ft)	17	6.0	6.0	8.0	6.0
Weight of Water (K/ft ³)	18	0.0624	0.0624	0.0624	0.0624
Area of Segment No. 4 (ft ²)	19	—	—	—	—
Distance from Center of Gravity of Segment No. 4 to Downstream Toe (ft)	20	—	—	—	—
Height of Ice Load or Active Water (ft) (does not include 14)	46	34	34	34	34
Seismic Coefficient (g)	50	—	—	0.1	—
<u>RESULTS OF ANALYSIS</u>					
Factor of Safety vs. Overturning		1.31	1.10	1.04	1.23
Distance From Toe to Resultant		6.47	2.50	1.23	5.18
Factor of Safety vs. Sliding		0.85	0.74	0.62	0.64

* ASSUMED 0 TO MAKE UPLIFT = ZERO

APPENDIX E

REFERENCES

APPENDIX E


REFERENCES

- 1) T. S. George and R. S. Taylor, Lower Hudson River Basin Hydrologic Flood Routing Model, for the Department of the Army, New York District, Corps of Engineers, Water Resources Engineers Inc. January 1977.
 - 2) H.W. King and E. F. Brater, Handbook of Hydraulics, 5th edition, McGraw-Hill, 1963
 - 3) R.K. Linsley, Jr., M.A. Kohler, and J.L.H. Paulhus; Hydrology for Engineers, 2nd edition, McGraw-Hill, 1975.
 - 4) University of the State of New York, Geology of New York, Education Leaflet 20, Reprinted 1973.
 - 5) U.S. Army Corps of Engineers:
HEC-1 Flood Hydrograph Package - Dam Safety Version, September 1978.
 - 6) Engineering Manual 1110-2-1405; Flood-Hydrograph Analyses and Computations, August 1959.
 - 7) U.S. Department of Agriculture, Soil Conservation Service; National Engineering Handbook; Section 4 - Hydrology, August 1972.
- US Department of Commerce; Weather Bureau:
- 8) Hydrometeorological Report No. 33:
Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24 and 48 Hours, April 1956.
 - 9) U.S. Department of Interior; BUREC, Design of Small Dams, 2nd edition (rev. reprint) 1977.
- US Geological Survey:
- | | | |
|-----|-----------------------------------|--------------------------------------|
| 10) | Water Resources Data for New York | - 1961: Part 1-Surface Water Records |
| 11) | " " " " " " | - 1962 |
| 12) | " " " " " " | - 1964 |
| 13) | " " " " " " | - 1966 |


APPENDIX F


DRAWINGS

CONNECTICUT



VICINITY MAP
 CORTLAND LAKE DAM
 NY-85






TOPOGRAPHIC MAP


CORTLAND LAKE DAM
NY-85

Fill above Dam to be made of
least porous material obtainable
at site

2





PLAN
Scale 1" = 20'
2+00 1+30 1+00




FRONT ELEVATION

Limits of Rock excavation
to be determined from
field inspections

3+00




3.



FRONT ELEVATION
Scale: 1"=20'


Limits of Rock excavation
to be determined from
field inspection




REAR ELEVATION
Scale: 1"=20'

4

Drawn by	IF	Check
Revisions:		



of Rock excavation
 determined from
 section



5

DRAWING NO. 328-1

H D HYNDS, INC.

DAM ACROSS CANOPUS CREEK
WESTCHESTER COUNTY, N.Y.


PLAN AND ELEVATIONS

Nicholas S. Hill, Jr.
 Consulting Engineer
 New York City

Scale: 1"=20'

October, 1929


Drawn by	if	Checked by	D'AMPT	Examined by	ama	Reviewed by	Approved by	D'AMPT
Revisions								




3' -

32'-6"


SECTION A-A
Scale - 1" = 5'



#16 Gage Copper Water Stop
in all vertical joints




TYPICAL CONSTRUCTION JOINT




SECTION B-B
Scale 1"=5'




3




SECTION B-B
Scale: 1"=5'






37°0'


SECTION B-B
Scale: 1" = 5'



SECTION D-D
Scale: 1" = 5'



SECTION E-E
Scale: 1" = 5'



SECTION F-F
Scale: 1" = 5'


Drawn by
Reviewed by

SECTION B-B

Scale: 1"=5'

37'0"


30"



Retaining Wall


Dam

3'0"



SECTION F-F

Scale: 1"=5'



SECTION H-H


Scale: 1"=10'

Elev 108.0

Elev 102.0

Slope 1 on 1 1/2

Slope 1 on 2 3/4



SECTION G-G

Scale: 1"=10'

DRAWING NO. 328-2

H.D. HYNDS, INC.

DAM ACROSS CANOPUS CREEK
WESTCHESTER COUNTY, N.Y.

SECTIONS

Nicholas S. Hill, Jr.
Consulting Engineer
New York City

October, 1929

Scale: As shown

Drawn by	HF	Checked by	DBK	Examined by	Ans.	Revised by	Approved by	o'Neil
Revised by								

**DATE
FILMED**

