

AD-A109 753


D'APPOLONIA CONSULTING ENGINEERS INC PITTSBURGH PA  
NATIONAL DAM SAFETY PROGRAM. ED PYLKAS DAM (INVENTORY NUMBER NY--ETC(U)  
AUG 81 L D ANDERSEN


F/G 13/13

DACW51-81-C-0011

NL

UNCLASSIFIED





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD A109753

| REPORT DOCUMENTATION PAGE   |                       | READ INSTRUCTIONS<br>BEFORE COMPLETING FORM  |
|---|-----------------------|--|
| 1. REPORT NUMBER  | 2. GOVT ACCESSION NO. | 3. RECIPIENT'S CATALOG NUMBER  |
|   | TD-4                  | DA9753   |
| 4. TITLE (and Subtitle)<br>Phase I Inspection Report<br>Ed Pylkas Dam<br>Seneca River Basin, Tioga County, NY<br>Inventory No. 355  |                       | 5. TYPE OF REPORT & PERIOD COVERED<br>Phase I Inspection Report<br>National Dam Safety Program |
| 7. AUTHOR(s)<br>LAWRENCE D. ANDERSEN  |                       | 6. PERFORMING ORG. REPORT NUMBER   |
| 9. PERFORMING ORGANIZATION NAME AND ADDRESS<br>D'Appolonia Consulting Engineers, Inc.<br>10 Duff Road<br>Pittsburgh, PA 15235 411001  |                       | 8. CONTRACT OR GRANT NUMBER(s)<br>DACW51-81-C-0011   |
| 11. CONTROLLING OFFICE NAME AND ADDRESS<br>Department of the Army<br>26 Federal Plaza New York District, CofE<br>New York, New York 10287   |                       | 10. PROGRAM ELEMENT, PROJECT, TASK<br>AREA & WORK UNIT NUMBERS                                 |
| 14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)<br>Department of the Army<br>26 Federal Plaza New York District, CofE<br>New York, NY 10287   |                       | 12. REPORT DATE<br>14 August 1981  |
|   |                       | 13. NUMBER OF PAGES  |
|   |                       | 15. SECURITY CLASS. (of this report)<br>UNCLASSIFIED   |
|   |                       | 15a. DECLASSIFICATION/DOWNGRADING<br>SCHEDULE  |
| 16. DISTRIBUTION STATEMENT (of this Report)<br>Approved for public release; Distribution unlimited.   |                       |  |
| 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)  |                       |  |
| 18. SUPPLEMENTARY NOTES   |                       |  |
| 19. KEY WORDS (Continue on reverse side if necessary and identify by block number)<br>Dam Safety<br>National Dam Safety Program<br>Visual Inspection<br>Hydrology, Structural Stability   |                       | Ed Pylkas Dam<br>Seneca River Basin<br>Tioga County  |
| 20. ABSTRACT (Continue on reverse side if necessary and identify by block number)<br>This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization.<br><br>Based on the evaluation of the existing conditions, the condition of the Ed Pylkas Dam is considered to be good. The examination of documents and visual observations did not reveal conditions which constitute a hazard to human life or property. |                       |  |

The spillway capacity was evaluated according to the recommended procedure and was found to pass the required spillway design flood of 100 percent of the Probable Maximum Flood (PMF). Therefore, the spillway capacity is rated as adequate.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

|                  |   |
|------------------|---|
| Prepared For     |   |
| Project Name     | X |
| Project Number   |   |
| Project Location |   |
| Project Status   |   |
| Prepared by      |   |
| Reviewed by      |   |
| Approved by      |   |
| Date             |   |
| Scale            |   |
| Sheet            |   |
| Total            |   |

A

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
ED PYLKAS DAM  
N.Y. 355  
DEC I.D. NO. 67-2067  
SUSQUEHANNA RIVER BASIN  
TIOGA COUNTY, NEW YORK

TABLE OF CONTENTS

|   | <u>PAGE NO.</u> |
|---|-----------------|
| ASSESSMENT                                      | iv              |
| DOWNSTREAM FACE PHOTOGRAPH                      | vi              |
| SECTION 1: PROJECT INFORMATION                  | 1               |
| 1.1 GENERAL                                     | 1               |
| 1.2 DESCRIPTION OF PROJECT                      | 1               |
| 1.3 PERTINENT DATA                              | 2               |
| SECTION 2: ENGINEERING DATA                     | 4               |
| 2.1 DATA AVAILABLE                              | 4               |
| 2.2 GEOLOGY                                     | 4               |
| 2.3 SUBSURFACE INVESTIGATION                    | 4               |
| 2.4 EMBANKMENT AND APPURTENANT STRUCTURES       | 5               |
| 2.5 CONSTRUCTION RECORDS                        | 5               |
| 2.6 OPERATING RECORDS                           | 5               |
| 2.7 EVALUATION OF DATA                          | 5               |
| SECTION 3: VISUAL INSPECTION                    | 6               |
| 3.1 FINDINGS                                    | 6               |
| 3.2 EVALUATION                                  | 7               |
| SECTION 4: OPERATION AND MAINTENANCE PROCEDURES | 8               |
| 4.1 PROCEDURES                                  | 8               |

TABLE OF CONTENTS  
(Continued)

|  | <u>PAGE NO.</u> |
|--|-----------------|
| 4.2 MAINTENANCE OF THE DAM             | 8               |
| 4.3 WARNING SYSTEM IN EFFECT           | 8               |
| 4.4 EVALUATION                         | 8               |
| SECTION 5: HYDRAULIC/HYDROLOGY         | 9               |
| 5.1 DRAINAGE AREA CHARACTERISTICS      | 9               |
| 5.2 ANALYSIS CRITERIA                  | 9               |
| 5.3 SPILLWAY CAPACITY                  | 9               |
| 5.4 RESERVOIR CAPACITY                 | 9               |
| 5.5 FLOODS OF RECORD                   | 9               |
| 5.6 OVERTOPPING POTENTIAL              | 10              |
| 5.7 EVALUATION                         | 10              |
| SECTION 6: STRUCTURAL STABILITY        | 11              |
| 6.1 EVALUATION OF STRUCTURAL STABILITY | 11              |
| SECTION 7: ASSESSMENT/RECOMMENDATIONS  | 12              |
| 7.1 ASSESSMENT                         | 12              |
| 7.2 RECOMMENDATIONS                    | 12              |
| <u>APPENDIX</u>                        |                 |
| A. PHOTOGRAPHS                         |                 |
| B. VISUAL INSPECTION CHECKLIST         |                 |
| C. ENGINEERING DATA CHECKLIST          |                 |
| D. HYDROLOGY AND HYDRAULIC ANALYSES    |                 |
| E. PLATES                              |                 |
| F. GEOLOGY MAP                         |                 |

TABLE OF CONTENTS  
(Continued)

- \*G. STABILITY ANALYSES
- \*H. PREVIOUS INSPECTION REPORTS/AVAILABLE DATA
- \*I REFERENCES

---

\*Not Included Due To Lack of Pertinent Data

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Ed Pylkas Dam  
N.Y. 355

State Located: New York

County Located: Tioga

Stream: Dean Creek (a tributary of  
Catonk Creek)

Date of Inspection: March 25, 1981 and April 30, 1981

ASSESSMENT


Based on the evaluation of the existing conditions, the condition of the Ed Pylkas Dam is considered to be good. The examination of documents and visual observations did not reveal conditions which constitute a hazard to human life or property.

The spillway capacity was evaluated according to the recommended procedure and was found to pass the required spillway design flood of 100 percent of the Probable Maximum Flood (PMF). Therefore, the spillway capacity is rated as adequate.

The following recommendations should be implemented within three months from issuance of this report.

1. The need for replacing the corroded downstream segment of the primary spillway outlet pipe and relocating the barbed wire fence across the discharge channel of the emergency spillway should be evaluated.
2. An emergency action plan should be developed including a formal warning system to alert the downstream residents in the event of an emergency.

Assessment - Ed Pylkas Dam



*Lawrence D. Andersen*

Lawrence D. Andersen, P.E.  
Vice President  
D'Appolonia Consulting Engineers, Inc.  
Pittsburgh, Pennsylvania

Approved by:

*W. M. Smith, Jr.*

Col. W. M. Smith, Jr.  
New York District Engineer

Date:

*17 Aug 81*

ED PYLKAS DAM  
N.Y. 355  
DEC I.D. 67-2067  
MARCH 25, 1981



Downstream Face

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
ED PYLKAS DAM  
N.Y. 355  
DEC I.D. NO. 67-2067  
SUSQUEHANNA RIVER BASIN  
TIOGA COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I Inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

The inspection was to evaluate the existing conditions of the subject dam to identify deficiencies and hazardous conditions, determine if they constitute hazards to life and property, and recommend remedial measures where necessary.

1.2 DESCRIPTION OF PROJECT

a. Dam and Appurtenances

The Ed Pylkas Dam consists of an earth embankment approximately 420 feet long with a maximum height of 37 feet from the downstream toe. The embankment has a crest width of 14 feet and an upstream slope of 3 horizontal to 1 vertical. The downstream slope is 2 horizontal to 1 vertical. A 10-foot-wide berm was provided on the upstream slope at the level of the primary spillway crest.

The spillways for the dam consist of a vegetated earth emergency channel located on the left abutment and a drop inlet pipe primary spillway located at the center of the dam. The primary spillway structures are comprised of a concrete drop inlet structure which discharges into a 24-inch corrugated metal pipe terminating at a plunge pool at the downstream toe. The drop inlet structure is equipped with a trash rack. The outlet pipe is encased in concrete and has been provided with antiseep collars. The emergency spillway is a trapezoidal earth channel with a base width of 54 feet and side slopes of 3 horizontal to 1 vertical.

The primary spillway intake level is located near the upstream toe level of the dam. Therefore, the primary spillway also functions as a reservoir drainpipe.

b. Location

The dam is located on Dean Creek, a tributary of Catatunk Creek approximately three miles southwest of the village of Spencer in Tioga County, New York. Plate 1 illustrates the location of the dam.

c. Size Classification

The dam is classified as a small dam based on 37-foot height and maximum storage capacity of 206 acre-feet.

d. Hazard Classification

The dam is classified to be in high hazard category. A house is located immediately downstream from the dam and two farms, located about one-half mile and two miles downstream from the dam, are considered to be within the potential floodplain of Dean Creek.

It is estimated that failure of the dam under maximum pool level would cause loss of more than a few lives and appreciable property damage in this area.

e. Ownership

The dam is owned by Mr. Sidney Lincoln, R.D. #1, Box 42, Lockwood, NY 14859, (607) 589-6817, and operated by Tioga County Soil and Water Conservation District.

f. Purpose of Dam

The dam is a floodwater retarding structure.

g. Design and Construction History

The dam was designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS) in 1954. Construction of the dam was completed in 1955.

h. Normal Operating Procedure

The reservoir is normally maintained at the crest level of the uncontrolled primary spillway at Elevation 1265 (USGS Datum). The emergency spillway crest is located at Elevation 1279.9.

1.3 PERTINENT DATA

Elevations referred to in this section and subsequent sections of the report were calculated based on field measurements assuming the primary spillway crest level at be at Elevation 1265.0 (USGS Datum) which was interpolated as normal pool level from the USGS 7.5-minute Van Etten quadrangle. Elevations shown in the design drawings appear to be relative to an arbitrary site datum.

|                                  |     |
|----------------------------------|-----|
| <u>a. Drainage Area</u> (acres)  | 440 |
| <u>b. Discharge at Dam</u> (cfs) |     |
| Principal spillway at top of dam | 65  |

|   |  |
|---|--|
| Auxiliary spillway at top of dam            | 2060   |
| Total spillway capacity at top of dam       | 2125   |
| <u>c. Elevation (USGS Datum) (feet)</u>     |  |
| Top of dam                                  | 1284.4   |
| Auxiliary spillway crest                    | 1279.9   |
| Principal spillway crest                    | 1265.0   |
| <u>d. Reservoir (acres)</u>                 |  |
| Surface area at top of dam                  | 24.2   |
| Surface area at crest of auxiliary spillway | 14.7   |
| Surface area at crest of principal spillway | 2.3  |
| <u>e. Storage Capacity (acre-feet)</u>      |  |
| Top of dam                                  | 206  |
| Auxiliary spillway crest                    | 125  |
| Principal spillway crest                    | 12   |
| <u>f. Dam</u>                               |  |
| Type  | Earth embankment                                   |
| Length                                      | 420 feet   |
| Height                                      | 35 feet  |
| Top width                                   | 14 feet  |
| Side slopes                                 | Downstream: 2H:1V<br>Upstream: 3H:1V               |
| Zoning                                      | No   |
| Impervious core                             | No   |
| Cutoff                                      | No   |
| Grout curtain                               | No   |
| <u>g. Primary Spillway</u>                  |  |
| Type  | 3-foot-square drop inlet                           |
| Length                                      | 9-foot perimeter                                   |
| Crest elevation                             | 1265   |
| <u>h. Emergency Spillway</u>                |  |
| Type  | Vegetated trapezoidal earth channel                |
| Length                                      | 54 feet (as measured)                              |
| Crest elevation                             | 1279.9   |
| <u>i. Reservoir Drain</u>                   |  |
| Type  | 8-inch-steel pipe                                  |
| Length                                      | 30 <sup>±</sup> feet                               |
| Access                                      | Inaccessible                                       |
| Regulating facilities                       | None (plugged with concrete as required by design) |

## SECTION 2: ENGINEERING DATA

### 2.1 DATA AVAILABLE

Available information was obtained from New York State Department of Environmental Conservation, Dam Safety Division files, and from the files of the SCS in Syracuse, New York. Available information includes design and as-built drawings, limited engineering reports, and dam inspection reports conducted by the SCS.

### 2.2 GEOLOGY

The Ed Pylkas Dam is located in the glaciated Allegheny Plateau section of the Appalachian Plateau Province. A regional geology map is included in Appendix F. This section is characterized as a maturely dissected plateau with the features modified by continental glaciation, including deposition of glacial till in the valleys.

The dam site is near the axis of a northeast trending syncline (approximately north 70 degrees east). The folding is gentle with the maximum dip of the limbs one to two degrees. The strata at the dam are nearly horizontal and the dip of the strata are affected locally by the folding; however, regionally, the rock strata dip south to southwest at approximately 100 to 150 feet per mile. Regional discontinuities trend approximately north-south with the east-west trend less predominant.

The rock strata in the area consist of unconsolidated Pleistocene glacial till (Wisconsin Drift) underlain by strata of the Lower West Falls Group (Upper Devonian Age). The glacial till consists of a mixture of clay and silt with varying quantities of gravel. The glacial till is relatively thin on hilltops and slopes and thicker in the valleys. The bedrock consists of a thick sequence of interbedded very dark gray to black shale and siltstone which may be up to 2,000 feet thick. The upper portion of the hills west of the dam consists of interbedded very dark gray shales and thin gray siltstone.

The abutment slopes are relatively gentle and not susceptible to landslide slope movement.

### 2.3 SUBSURFACE INVESTIGATION

A review of available information indicates the subsurface investigation for the dam consisted of shallow test pits. Plate 2 illustrates a subsurface profile included in the design drawings. A SCS Soils Analysis Report indicates the soils in the area generally consist of silty clays.

#### 2.4 EMBANKMENT AND APPURTENANT STRUCTURES

Plates 3, 4, and 5 show the plan and details of the dam and appurtenant structures. To the extent that can be determined, the dam appears to be a homogeneous embankment. No references were found to indicate whether the embankment incorporated an impervious core, a cutoff trench, or internal drainage system. As shown in Plate 4, the dam was designed to have a slope of 2 horizontal to 1 vertical downstream, and 3 horizontal to 1 vertical upstream with a crest width of 14 feet. A berm was provided on the upstream slope in the vicinity of the primary spillway crest level. Plates 4 and 5 show the details of the primary spillway. The primary spillway structures are comprised of a concrete drop inlet structure discharging into a 24-inch corrugated metal pipe encased in concrete, terminating at a plunge hole at the downstream toe. The outlet pipe is equipped with antiseep collars.

Hydrology and hydraulic analyses conducted for the design are summarized in a SCS report entitled, "Dean Creek Watershed Project, Project NY-WP-3, Ed Pylkas Dam," dated May 21, 1954. The report indicates that the dam was designed to pass a 100-year flood with a freeboard of three feet. The design inflow and outflow hydrographs are shown in Plate 6. Plate 7 shows the design high water elevation.

#### 2.5 CONSTRUCTION RECORDS

None available. Based on visual observation, it appears that no major postconstruction changes were instituted.

#### 2.6 OPERATING RECORDS

Because the dam is an ungaged flood-retarding structure, no operating records are maintained for the dam.

#### 2.7 EVALUATION OF DATA

The information obtained from the state and SCS files is considered to be adequate for Phase I inspection purposes.

## SECTION 3: VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

Visual inspections of the dam were conducted on March 25 and April 30, 1981. On both dates, the pool level was approximately at the invert level of the primary spillway riser.

#### b. Embankment

In general, the condition of the dam is considered to be good. No signs of distress, seepage, or misalignment were observed. The faces of the dam and the crest are covered with grass and found to be adequately maintained. The top of the dam was surveyed relative to the emergency spillway crest elevation and found to be reasonably in conformance with the design elevations with camber.

#### c. Primary Spillway

The primary spillway facilities consist of a concrete drop inlet structure discharging into a 24-inch corrugated metal pipe encased in concrete and terminating at a riprapped plunge pool at the downstream toe. Visible components of the primary spillway were found to be in satisfactory condition except the bottom of the last uncased segment of the primary spillway outlet pipe which was found to be corroded, releasing flow from its bottom. The need for replacing this pipe should be evaluated.

#### d. Emergency Spillway

The emergency spillway is a trapezoidal vegetated earth channel located on the left abutment. The emergency spillway channel was found to be in good condition. The grass cover is well established and adequately maintained. While the approach channel was found to be free of brush and trees or debris which may pose a potential for blockage of the spillway, a barbed wire fence across the emergency spillway discharge channel, a short distance downstream of the control section, may pose a potential for partial blockage of the channel by debris. The need for relocating this fence further downstream should be evaluated.

#### e. Reservoir Drain

The primary spillway intake is located near the upstream toe of the dam and can drain approximately 90 percent of the 125 acre-foot storage at the emergency spillway crest level. The remaining 12 acre-feet of storage below the primary spillway crest cannot be drained. The design drawing included in Plate 4 indicates that the reservoir drainpipe which extends from the upstream toe of the dam to the primary spillway drop inlet structure was to be plugged by concrete in the completion of the dam.

f. Downstream Channel

The downstream channel below the primary spillway plunge pool is the natural stream bed. The channel appears to be stable in the near vicinity of the dam.

g. Reservoir

There are no visible signs of instability or sedimentation problems within the reservoir area.

3.2 EVALUATION

The dam was found to be in good condition. It is considered advisable that the need for replacing the corroded segment of the primary spillway outlet pipe and relocating the barbed wire fence across the emergency spillway discharge channel should be evaluated.

SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

The reservoir is normally maintained at the primary spillway crest level with excess inflow discharging through the primary spillway. The dam is a flood retarding structure and has no formal operating procedure.

4.2 MAINTENANCE OF THE DAM

The dam is maintained by Tioga County Soil and Water Conservation District and the maintenance condition of the dam is considered to be satisfactory.

4.3 WARNING SYSTEM IN EFFECT

No formal warning system exists for the dam.

4.4 EVALUATION

The maintenance condition of the dam is considered to be good. Development of a formal warning system is considered to be advisable.

## SECTION 5: HYDRAULIC/HYDROLOGY

### 5.1 DRAINAGE AREA CHARACTERISTICS

Ed Pylkas Dam has a watershed of 0.7 square mile. The drainage area is comprised of woodlands and farmlands. Relief ranges from moderate to steep.

### 5.2 ANALYSIS CRITERIA

As previously stated, Ed Pylkas Dam is classified as a small dam in the high-hazard category. Under the recommended criteria for evaluating emergency spillway discharge capacity, such impoundments are required to pass one-half to full PMF. In view of the high downstream damage potention, full PMF was selected as the spillway design flood.

The PMF inflow hydrograph for the reservoir was determined using the dam safety version of the HEC-1 computer program developed by the hydrologic engineering center of the U.S. Army Corps of Engineers. The data used for the computer input are presented in Appendix D. The PMF inflow hydrograph was found to have a peak flow of 2247 cfs. Computer outputs are also included in Appendix D.

### 5.3 SPILLWAY CAPACITY

The flood discharge facilities for the dam consist of primary and emergency spillways. The emergency spillway on the left abutment is a trapezoidal earth channel with a base width of 54 feet and side slopes of 3 horizontal to 1 vertical. The PMF inflow hydrograph was routed through the reservoir and it was found that the dam can pass 100 percent of the PMF without overtopping the embankment. Based on the available head relative to a low spot on the crest of the dam, the capacities of the primary and emergency spillways are calculated to be 65 cfs and 2060 cfs, respectively. Primary and emergency spillway rating calculations are also included in Appendix D.

### 5.4 RESERVOIR CAPACITY

The dam impounds a reservoir with a storage capacity of 12 acre-feet at the primary spillway crest level, 129 acre-feet at the emergency spillway crest level, and 206 acre-feet at the top of dam.

### 5.5 FLOODS OF RECORD

Not available.

### 5.6 OVERTOPPING POTENTIAL

The dam can pass 100 percent of the PMF without overtopping the embankment. Maximum pool level was computed to be at Elevation 1284.45, which is slightly above the measured low spot on the crest of the dam at Elevation 1284.4. The low spot is located at the junction of the dam crest and the side slope of the emergency spillway. The remaining portion of the dam crest is between Elevations 1885.3 and 1886.5.

| <u>PMF Ratio</u> | <u>Maximum Outflow<br/>(cfs)</u> | <u>Maximum Depth<br/>of Overtopping<br/>(feet)</u> |
|------------------|----------------------------------|--|
| 100              | 2091                             | 0.05   |

### 5.7 EVALUATION

The spillway can pass the recommended spillway design flood of full PMF without overtopping the embankment; therefore, spillway capacity is classified to be adequate according to the recommended criteria.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

As discussed in Section 3, the field observations did not reveal any signs of distress that would significantly affect the stability of the dam at this time. However, it should be understood that the dam is a flood control facility and was at normal pool level at the time of inspection. Therefore, it was not under maximum loading conditions which would occur only during the passage of major floods.

#### b. Design and Construction Data

Available information does not include any design and construction data. Further, no reference was found to indicate whether laboratory soils testing, stability, and seepage analysis were conducted for the design of the embankment. Therefore, the structural stability of the dam could not be assessed. However, based on visual observations, static stability of the dam appears to be satisfactory.

#### c. Postconstruction Changes

None reported.

#### d. Seismic Stability

The dam is located in Seismic Zone 1. Based on the recommended criteria for evaluation of seismic stability of dams, the structure is presumed to present no hazard from earthquakes.

## SECTION 7: ASSESSMENT/RECOMMENDATIONS

### 7.1 ASSESSMENT

#### a. Safety

Visual observations indicate that Ed Pylkas Dam is in good condition. No conditions were observed that would significantly affect the overall performance of the structure at this time. However, as previously noted, the dam was not inspected under its maximum load condition which would occur when the reservoir is filled during major storms.

The spillway capacity was evaluated according to the recommended procedure and was found to pass the required spillway design flood of full PMF without overflowing the embankment; therefore, the spillway capacity is classified to be adequate.

#### b. Adequacy of Information

Available information, in conjunction with visual observations, is considered to be sufficient to make a Phase I evaluation.

#### c. Need for Additional Investigations

No additional investigation is considered to be required at this time.

#### d. Urgency

It is recommended that the emergency action plan should be implemented within three months from the final issuance of this report and other recommendations should be implemented as soon as possible.

### 7.2 RECOMMENDATIONS

1. The need for replacing the corroded downstream segment of the primary spillway outlet pipe and relocating the barbed wire fence across the discharge channel of the emergency spillway should be evaluated.
2. An emergency action plan should be developed including a formal warning system to alert the downstream residents in the event of an emergency.

APPENDIX A  
PHOTOGRAPHS




PHOTOGRAPH NO. 1  
Upstream Slope (looking Northwest)



PHOTOGRAPH NO. 2  
Dam Crest (looking Northwest)



PHOTOGRAPH NO. 3  
Emergency Spillway Approach Channel (looking downstream)



PHOTOGRAPH NO. 4  
Primary Spillway Inlet Structure



PHOTOGRAPH NO. 5  
Downstream End of Primary Spillway Discharge Pipe



PHOTOGRAPH NO. 6  
A House Immediately Downstream From Dam



PHOTOGRAPH NO. 7  
A Farm 0.6 Mile Downstream From Dam

**APPENDIX B**  
**VISUAL INSPECTION CHECKLIST**

APPENDIX B  
VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Ed Pylkas Dam  
Fed. I.D. # N.Y. 355 DEC Dam No. 67-2067  
River Basin Susquehanna River Basin  
Location: Town Spencer County Tioga  
Stream Name Dean Creek  
Tributary of Catatonk Creek  
Latitude (N) 42° 10.0' Longitude (W) 76° 31.6'  
Type of Dam Earth  
Hazard Category High  
Date(s) of Inspection March 25 and April 30, 1981  
Weather Conditions Partly Cloudy, Temp 40's  
Reservoir Level at Time of Inspection Normal Pool El. 1265.0<sup>(1)</sup>  
(USGS Datum)

b. Inspection Personnel Lawrence Andersen, P.E.; James Poellot,  
P.E.; Bilgin Erel, P.E.; Wah-Tak Chan, P.E.; and Arthur Smith

c. Persons Contacted (Including Address & Phone No.) \_\_\_\_\_

(1) Mr. Sidney Lincoln, R.D. #1, Box 42, Lockwood, N.Y. 14859

(607) 589-6817

(2) Mr. Gary Page, SCS, Broome County, N.Y.

(1) All elevations interpolated from USGS 7.5-minute Van Etten, New York quadrangle dated 1969.

d. History:

Date Constructed 1955 Date(s) Reconstructed \_\_\_\_\_

Designer U.S. Department of Agriculture, Soil Conservation Service

Constructed by Unknown

Owner Mr. Sidney Lincoln

2) Embankment

a. Characteristics

(1) Embankment Material Earth

(2) Cutoff Type None

(3) Impervious Core None

(4) Internal Drainage System None

(5) Miscellaneous ---

b. Crest

(1) Vertical Alignment Good. A portion of the embankment about 0.4 foot below design Elevation 1284.8.

(2) Horizontal Alignment Good

(3) Surface Cracks None

(4) Miscellaneous ---

c. Upstream Slope

(1) Slope (Estimate) 3H:1V (as designed)  
2.9H:1V (as measured)

(2) Undesirable Growth or Debris, Animal Burrows None

(3) Sloughing, Subsidence or Depressions None

(4) Slope Protection Vegetated Slope

(5) Surface Cracks or Movement at Toe None

d. Downstream Slope

(1) Slope (Estimate) 2H:1V (as designed)

1.8H:1V (as measured)

(2) Undesirable Growth or Debris, Animal Burrows None

(3) Sloughing, Subsidence or Depressions None

(4) Surface Cracks or Movement at Toe None

(5) Seepage None

(6) External Drainage System (Ditches, Trenches, Blanket)  
None

(7) Condition Around Outlet Structure Good

(8) Seepage Beyond Toe None

e. Abutments - Embankment Contact

No problems observed.

(1) Erosion at Contact None

(2) Seepage Along Contact None

3) Drainage System

a. Description of System The dam has no internal drainage system.

b. Condition of System N/A

c. Discharge from Drainage System N/A

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.)

None

5) Reservoir

- a. Slopes Moderate to steep, no problems observed.  
\_\_\_\_\_
- b. Sedimentation Unknown, no noticeable problems.  
\_\_\_\_\_
- c. Unusual Conditions Which Affect Dam None  
\_\_\_\_\_

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) Four  
homes in first mile downstream.  
\_\_\_\_\_
- b. Seepage, Unusual Growth None  
\_\_\_\_\_
- c. Evidence of Movement Beyond Toe of Dam None  
\_\_\_\_\_
- d. Condition of Downstream Channel Good  
\_\_\_\_\_

7) Spillway(s) (Including Discharge Conveyance Channel)

- In good condition.  
\_\_\_\_\_  
\_\_\_\_\_
- a. General Service Spillway: 3-foot-square concrete riser  
discharging into a 24-inch outlet pipe.  
Auxiliary Spillway: Vegetated earth channel  
on left abutment.  
\_\_\_\_\_
- b. Condition of Service Spillway Good  
\_\_\_\_\_

c. Condition of Auxiliary Spillway Good

d. Condition of Discharge Conveyance Channel Good

8) Reservoir Drain

Type: Pipe X Conduit - Other -

Material: Concrete \_\_\_ Metal \_\_\_ Other Corrugated Metal Pipe

Size: 6 inches Length Approx. 20 ft. (upstream toe to inlet)

Invert Elevations: Entrance Unknown Exit Unknown

Physical Condition (Describe): Unobservable X

Material: \_\_\_\_\_

Joints: \_\_\_\_\_ Alignment \_\_\_\_\_

Structural Integrity: \_\_\_\_\_

Hydraulic Capability: Upstream end plugged with concrete  
as required by design.

Means of Control: Gate \_\_\_ Valve \_\_\_ Uncontrolled \_\_\_

Operation: Operable \_\_\_ Inoperable X Other \_\_\_

Present Condition (Describe): See note above.

9) Structural

a. Concrete Surfaces The only concrete structure is the  
principal spillway drop inlet structure. Concrete is in  
good condition.

b. Structural Cracking None

c. Movement - Horizontal & Vertical Alignment (Settlement)  
N/A

d. Junctions with Abutments or Embankments   
N/A

e. Drains - Foundation, Joint, Face   
N/A

f. Water Passages, Conduits, Sluices   
N/A

g. Seepage or Leakage   
N/A

h. Joints - Construction, etc. N/A

i. Foundation N/A

j. Abutments N/A

k. Control Gates N/A

l. Approach & Outlet Channels N/A

m. Energy Dissipators (Plunge Pool, etc.) Good condition.

n. Intake Structures Good

o. Stability N/A

p. Miscellaneous ---



APPENDIX C  
ENGINEERING DATA CHECKLIST

APPENDIX C  
ENGINEERING DATA CHECKLIST  
NAME OF DAM: ED PYLKAS

AREA-CAPACITY DATA:

|   | <u>Elevation</u><br>(feet)  | <u>Surface Area</u><br>(acres) | <u>Storage Capacity</u><br>(acre-feet) |
|---|-----------------------------|--------------------------------|--|
| 1) Top of Dam   | <u>1284.4<sup>(1)</sup></u> | <u>24.2</u>                    | <u>206.0</u>                           |
| 2) Design High Water <sup>(2)</sup><br>(Max. Design Pool) | <u>1284.2</u>               | <u>23.6</u>                    | <u>194.0</u>                           |
| 3) Auxiliary Spillway<br>Crest                            | <u>1279.9</u>               | <u>14.7</u>                    | <u>125.0</u>                           |
| 4) Pool Level with<br>Flashboards                         | <u>          </u>           | <u>          </u>              | <u>          </u>                      |
| 5) Service Spillway<br>Crest                              | <u>1265.0</u>               | <u>2.3</u>                     | <u>12.0</u>                            |

(1) Measured low spot.

(2) PMF.

DISCHARGES

|  | <u>Discharge</u><br>(cfs) |
|--|---------------------------|
| 1) Average Daily   | <u>1 ±</u>                |
| 2) Auxiliary Spillway at Maximum High Water<br>(Top of Dam)    | <u>2060</u>               |
| 3) Auxiliary Spillway at Design High Water (Full PMF)          | <u>1870</u>               |
| 4) Principal Spillway at Auxiliary Spillway Crest<br>Elevation | <u>65</u>                 |
| 5) Low Level Outlet  | <u>          </u>         |
| 6) Total of all facilities at Maximum High Water               | <u>2125</u>               |
| 7) Maximum Known Flood   | <u>Unknown</u>            |
| 8) At Time of Inspection                                       | <u>Approx. 1 ±</u>        |

DAM: Ed Pylkas Dam

CREST ELEVATION: 1284.4 (measured low spot)

Type: Earth

Width: 12 feet Length: 420 feet

Spillover Concrete drop inlet and vegetated earth channel

Location Drop inlet: Center of dam; Earth channel: Left abutment

SPILLWAY:

| SERVICE                    |   | AUXILIARY                      |
|----------------------------|---|--------------------------------|
| <u>1265.0</u>              | Elevation   | <u>1279.9</u>                  |
| <u>Concrete Drop Inlet</u> | Type  | <u>Vegetated Earth Channel</u> |
| <u>3 feet</u>              | Width   | <u>54 feet</u>                 |
|                            | <u>Type of Control</u>  |                                |
| <u>Uncontrolled</u>        | Uncontrolled  | <u>Uncontrolled</u>            |
|                            | Controlled:   |                                |
| <u>NA</u>                  | Type<br>(Flashboards; gate)   | <u>NA</u>                      |
| <u>NA</u>                  | Number  | <u>NA</u>                      |
| <u>NA</u>                  | Size/Length   | <u>54 feet long</u>            |
|                            | Invert Material   | <u>Vegetated Earth</u>         |
|                            | Anticipated Length<br>of operating service                                  | <u>Unknown</u>                 |
| <u>160 feet</u>            | Chute Length  | <u>NA</u>                      |
| <u>1 ± foot</u>            | Height Between Spillway Crest<br>and Approach Channel Invert<br>(Weir Flow) | <u>8 ± feet</u>                |

Hydrometeorological Gages:

Type: None

Location: N/A

Records:

Date - N/A

Max. Reading - N/A

FLOODWATER CONTROL SYSTEM:

Warning System: None

Method of Controlled Releases (mechanisms):

None

\_\_\_\_\_

DRAINAGE AREA: 0.7 square mile

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: Wooded/frameland

Terrain - Relief: Moderate

Surface - Soil: Low permeability soil

Runoff Potential (existing or planned extensive alterations to existing surface or subsurface conditions)

High runoff potential due to moderate slope and low infiltration rate.

Potential Sedimentation problem areas (natural or man-made; present or future)

None observed.

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

None observed.

Dikes - Floodwalls (overflow and nonoverflow) - Low reaches along the reservoir perimeter:

Location: None

Elevation: \_\_\_\_\_

Reservoir:

Length at Maximum Pool 800 ± feet

Length of Shoreline at Spillway Crest 1,000 ± feet

APPENDIX D  
HYDROLOGY AND HYDRAULIC ANALYSES

HYDROLOGY AND HYDRAULIC ANALYSIS  
DATA BASE

NAME OF DAM: Ed Pylkas Dam (N.Y. DEC 67-2067)

PROBABLE MAXIMUM PRECIPITATION (PMP) = 22.2 INCHES/24 HOURS<sup>(1)</sup>

| STATION                                   | 1                 | 2   | 3 | 4 | 5 |
|---|-------------------|---|---|---|---|
| Station Description                       | Ed Pylkas Lake    | Ed Pylkas Dam                             |   |   |   |
| Drainage Area (square miles)              | 0.69              | -   |   |   |   |
| Cumulative Drainage Area (square miles)   | 0.69              | 0.69                                      |   |   |   |
| Adjustment of PMP for Drainage Area (%)   | 95 <sup>(2)</sup> |   |   |   |   |
| 6 Hours                                   | 117               | -   |   |   |   |
| 12 Hours                                  | 127               | -   |   |   |   |
| 24 Hours                                  | 136               | -   |   |   |   |
| 48 Hours                                  | 142               | -   |   |   |   |
| 72 Hours                                  | 145               | -   |   |   |   |
| Snyder Hydrograph Parameters              |                   |   |   |   |   |
| $C_p/C_t$ (3)                             | 0.62/1.5          | -   |   |   |   |
| L (miles) <sup>(4)</sup>                  | 1.08              | -   |   |   |   |
| $L_{ca}$ (miles) <sup>(4)</sup>           | 0.42              | -   |   |   |   |
| $t_p = C_t(L \cdot L_{ca})^{0.3}$ (hours) | 1.18              | -   |   |   |   |
| Spillway Data                             |                   |   |   |   |   |
| Crest Length (ft)                         | -                 | See spillway capacity rating calculations |   |   |   |
| Freeboard (ft)                            | -                 |   |   |   |   |
| Discharge Coefficient                     | -                 |   |   |   |   |
| Exponent                                  | -                 |   |   |   |   |

(1) Hydrometeorological Report 33 (Figure 1), U.S. Army, Corps of Engineers, 1956.

(2) Hydrometeorological Report 40, U. S. Weather Bureau, 1965.

(3) Snyder's Coefficients ( $C_p$  and  $C_t$ ) as recommended by Corps of Engineers, Baltimore District, for Susquehanna River Basin.

(4) L = Length of longest water course from outlet to basin divide.

$L_{ca}$  = Length of water course from outlet to point opposite the centroid of drainage area.

STORAGE VS. ELEVATION

| ELEVATION | $\Delta H$ , FEET | AREA (acres) <sup>(1)</sup> | $\Delta VOLUME$ (acre-feet) <sup>(2)</sup> | STORAGE (acre-feet) |
|-----------|-------------------|-----------------------------|--|---------------------|
| 1248.9    |                   | 0                           |  | 0                   |
| 1265.0    | 16.1              | 2.3                         | 12.3                                       | 12.3                |
| 1280.0    | 15.0              | 14.7                        | 114.1                                      | 126.4               |
| 1300.0    | 20.0              | 57.9                        | 678.5                                      | 804.9               |

(1) Planimetered from USGS maps.

(2)  $\Delta Volume = \Delta H/3 (A_1 + A_2 + \sqrt{A_1 A_2})$ .



PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

| OPERATION     | STATION | AREA           | PLAN | RATIOS APPLIED TO FLOWS |                  |                  |                   |                   |                   |                   |                   |                   |
|---------------|---------|----------------|------|-------------------------|------------------|------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|
|               |         |                |      | RATIO 1                 | RATIO 2          | RATIO 3          | RATIO 4           | RATIO 5           | RATIO 6           | RATIO 7           | RATIO 8           | RATIO 9           |
|               |         |                |      | .20                     | .30              | .40              | .50               | .60               | .70               | .80               | .90               | 1.00              |
| HYDROGRAPH AT | 1       | .69<br>( 1.79) | 1    | 449.<br>( 12.72)        | 674.<br>( 19.09) | 859.<br>( 25.45) | 1123.<br>( 31.81) | 1348.<br>( 38.77) | 1573.<br>( 46.53) | 1797.<br>( 50.90) | 2021.<br>( 57.26) | 2247.<br>( 63.62) |
| ROUTED TO     | 2       | .69<br>( 1.79) | 1    | 65.<br>( 1.83)          | 362.<br>( 10.26) | 639.<br>( 18.11) | 917.<br>( 25.97)  | 1179.<br>( 33.37) | 1425.<br>( 40.36) | 1656.<br>( 46.88) | 1876.<br>( 53.12) | 2191.<br>( 59.22) |



# D'APPOLONIA

CONSULTING ENGINEERS, INC.

By DMB Date 5/2/81 Subject EO PYLKAS DAM Sheet No. 1 of 1  
 Chkd. By WJC Date 5/7/81 NY 67-2067 Proj. No. 80-778-01

## SPILLWAY CAPACITY

REF. 1: "DESIGN OF SMALL DAMS", 2<sup>ND</sup> ED., PG. 553

$$V_c = \sqrt{\left(\frac{b+z d_c}{b+2z d_c}\right) d_c g} \quad (\text{Eq. 1})$$

$$H_E = d_c + \frac{V_c^2}{2g} = d_c + \left(\frac{b+z d_c}{b+2z d_c}\right) (d_c g) \left(\frac{1}{2g}\right)$$



$$= \left(\frac{3b+5z d_c}{2b+4z d_c}\right) d_c$$

$$d_c = \frac{-(3b+4H_E z) + \sqrt{(3b+4H_E z)^2 + (4H_E)(10b)}}{10z} \quad (\text{Eq. 2})$$

$$A_c = (z d_c + b) d_c \quad (\text{Eq. 3})$$

$$Q_c = A_c V_c \quad (\text{Eq. 4})$$

REF. 2: LOW LEVEL OUTLET: EL. 1265.0,  $Q_L = 0.0$  CFS; EL. 1266.4,  $Q_L = 50.0$  CFS;  
 EL. 1771.0,  $Q_L = 55.0$  CFS; EL. 1775.0,  $Q_L = 60.0$  CFS.




| LAKE ELEVATION (ft) | $H_E$ (ft) | Eq. 2      | Eq. 3                    | Eq. 1       | Eq. 4                           | Ref. 2      | $Q_c + Q_L$ |
|---------------------|------------|------------|--------------------------|-------------|---------------------------------|-------------|-------------|
|                     |            | $d_c$ (ft) | $A_c$ (ft <sup>2</sup> ) | $V_c$ (fps) | $Q_c$ , SPILLWAY CAPACITY (CFS) | $Q_L$ (CFS) | $Q_T$ (CFS) |
| 1279.9              | 0.0        | 0          | 0                        | 0           | 0                               | 65.0        | 65.0        |
| 1280.5              | 0.6        | 0.4        | 22.9                     | 3.6         | 81.3                            | 65.0        | 146.3       |
| 1281.0              | 1.1        | 0.7        | 43.2                     | 4.8         | 206.5                           | 65.0        | 271.5       |
| 1281.5              | 1.6        | 1.1        | 64.8                     | 5.7         | 370.8                           | 65.0        | 435.8       |
| 1282.0              | 2.1        | 1.4        | 87.6                     | 6.5         | 570.4                           | 65.0        | 635.4       |
| 1282.5              | 2.6        | 1.8        | 111.6                    | 7.2         | 803.6                           | 65.0        | 868.6       |
| 1283.0              | 3.1        | 2.2        | 136.9                    | 7.8         | 1069.6                          | 65.0        | 1134.6      |
| 1283.5              | 3.6        | 2.5        | 163.4                    | 8.4         | 1367.8                          | 65.0        | 1432.8      |
| 1284.0              | 4.1        | 2.9        | 191.2                    | 8.9         | 1698.1                          | 65.0        | 1763.1      |
| 1284.5              | 4.6        | 3.2        | 220.2                    | 9.4         | 2060.7                          | 65.0        | 2125.7      |
| 1285.0              | 5.1        | 3.6        | 250.4                    | 9.8         | 2455.6                          | 65.0        | 2520.6      |
| 1286.0              | 6.1        | 4.3        | 319.7                    | 10.6        | 3343.4                          | 65.0        | 3408.4      |
| 1287.0              | 7.1        | 5.1        | 384.0                    | 11.4        | 4364.2                          | 65.0        | 4429.2      |
| 1288.0              | 8.1        | 5.8        | 458.4                    | 12.0        | 5520.9                          | 65.0        | 5585.9      |
| 1289.0              | 9.1        | 6.6        | 537.9                    | 12.7        | 6816.8                          | 65.0        | 6881.8      |
| 1290.0              | 10.1       | 7.4        | 622.5                    | 13.3        | 8255.5                          | 65.0        | 8320.5      |

TOP OF DAM  
 EL. 1289.4


(2) SCS DRAWING, "DEAN CREEK, PYLKAS DAM, FLOOD ROUTING - MAX. FLOOD", 4/29/55 (PLATE PAGE D5 OF 5)

APPENDIX E  
PLATES

DRAWN BY ACS CHECKED BY STJ/AL DRAWING NUMBER 80-778-B1  
 BY S-6-81 APPROVED BY JHP S-7-81



KEY PLAN



REFERENCE

7.5 MIN. U.S.G.S. VAN ETTEN, N.Y. QUADRANGLE  
 DATED: 1969, SCALE: 1:24000







PLATE I  
 ED PYLKAS DAM  
 VICINITY FLOOD PLAIN & WATERSHED MAP

**D'APOLONIA**

DRAWN BY ACS  
 CHECKED BY JAC  
 APPROVED BY JHP  
 5/7/81  
 DRAWING NUMBER 80-778-B2





DEAN CREEK  
 PULRAS DAM  
 PROFILES  
 TIOGA CO, NEW YORK



U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE  
 ASSISTING

|                            |                             |
|----------------------------|-----------------------------|
| DESIGNED BY<br>R. R. HUBER | FIELD NO. BY<br>W. NIKOLICH |
| DRAWN BY<br>J. BORNSTEIN   | DATE<br>1-10-44             |

PLATE 2

D'APPOLONIA

DRAWN BY AGS 5-6-81 CHECKED BY JF 5/7/81 APPROVED BY JHP 5-7-81 DRAWING 80-778-B3 NUMBER



VICINITY MAP  
USGS QUAD HALPLY NY


LEGEND

- Proposed Improvements
- Stream
- Contour Line
- X- Fence
- I- New Fence
- ▨ Sodded Butters
- ▬ Rip-Rap

All work is subject to Departmental approval under the Conservation Law. Estimated cost \$100,000.

NOVEMBER 1980  
LAT 42° 15' LONG 76° 31' 20"

DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF WATER  
CANTON, NY  
APPROVED



STATE OF NEW YORK  
 DEPARTMENT OF PUBLIC WORKS  
 DIVISION OF CONSTRUCTION  
 ALBANY, N. Y.

This plan for **DEAN CREEK PYLKAS DAM** No. 61-104  
 was prepared by **JULIUS H. HARTMAN** A. S. C. E. in accordance with the  
 provisions of Section 94B of the  
 Conservation Law.  
 Estimated and recommended by the Chief Engineer for  
 approval.  
**Senior ENGINEER** *[Signature]*

APPROVED  
 CHIEF ENGINEER  
 Department of Public Works  
*[Signature]*

DEAN CREEK  
 PYLKAS DAM  
 DAM & POND  
 TIOGA CO., NEW YORK

ASSISTING  
 Tioga County  
 Soil Conservation District  
 New York

|                      |               |
|----------------------|---------------|
| PREPARED BY APPROVAL | FIELD DATA BY |
| DESIGNED BY          | DATE          |
| CHECKED BY           | DATE          |
| DATE                 | SHEET 1 OF 9  |















PLATE 3 *J*



**D'APPOLONIA**

DRAWN BY ACS S.G.H. CHECKED BY JAE S.J.H. DRAWING 80-778-B4  
 APPROVED BY JMP S.J.H. NUMBER





ANTI-SEEP COLLAR  
SHOWING FIRST POUR - TROWEL FINISH SECTION




|   |                           |
|---|---------------------------|
| DEAN CREEK<br>PYLKAS DAM<br>STEEL DETAILS<br>TIOGA CO, NEW YORK |                           |
| U S DEPARTMENT OF AGRICULTURE<br>SOIL CONSERVATION SERVICE      |                           |
| ASSISTING   |                           |
| DRAWN BY<br>R. R. HYDER   | CHECKED BY<br>G. B. BROWN |
| DATE<br>1-194   | SHEET NO.<br>4            |

PLATE 4

2


**D'APPOLONIA**

DRAWN BY 4/2 S CHECKED BY RE 5/7/8/ DRAWING NUMBER 80-778-B5  
 APPROVED BY JMD 5-7-8/





NOTE:  
 LOCATE PIPE TO GO  
 BETWEEN REINFORCING  
 BARS

U.S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE  
 NORTHWESTERN REGION



REINFORCED CONCRETE ANTI-SEEP COLLARS

NOTE  
SEE SHEET 9 FOR FINISH  
INSTRUCTION AND GRAB




|   |              |
|---|--------------|
| DEAN CREEK<br>PYLKAS DAM<br>STRUCTURE DIMENSIONS<br>TIOGA CO, NEW YORK  |              |
| U S DEPARTMENT OF AGRICULTURE<br>SOIL CONSERVATION SERVICE<br>ASSISTING |              |
| DESIGNED BY   | REVISION BY  |
| D. S. WOOD  | A. S. RABOLD |
| CHECKED BY  | DATE         |
| A. S. RABOLD  | 1-104        |
| BY 4-14-48  |              |

PLATE 5 *2*

**D'APPOLONIA**





DEAN CREEK  
PYLKAS DAM  
FLOOD ROUTING - MAX. STORM  
TIOGA CO. NEW YORK

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE  
ASSISTING

DESIGNED BY  
R. HUBER

CHECKED BY  
S. GERMANA


DATE  
J. BORNSTEIN


NO. 1-104

PLATE 6 *2*

**D'APPOLONIA**

|          |         |             |     |                |           |
|----------|---------|-------------|-----|----------------|-----------|
| DRAWN BY | ACS     | CHECKED BY  | SE  | DRAWING NUMBER | 80-778-B7 |
| BY       | S.C. #1 | APPROVED BY | JMP | NUMBER         | 5-7-81    |





ANCE LINE A

|   |                           |
|---|---------------------------|
| DEAN CREEK<br>PYLKAS DAM<br>PROFILE<br>TIOGA CO. NEW YORK                 |                           |
| U. S. DEPARTMENT OF AGRICULTURE<br>SOIL CONSERVATION SERVICE<br>ASSISTING |                           |
| <small>DESIGNED BY</small>  | <small>CHECKED BY</small> |
| R. R. HUBER   | S. BERMANA                |
| A. BORNSTEIN  | 1-104                     |
| <small>DATE</small>   | <small>SCALE</small>      |
| 1-18-34   | 1" = 10'                  |

PLATE 7 2

**D'APPOLONIA**

APPENDIX F  
GEOLOGY MAP

DRAWING NUMBER 80-778-A3


DATE 5/7/81

CHECKED BY JSC

APPROVED BY JAT

ACS 4-29-81

DRAWN BY



GEOLOGY MAP

REFERENCE:  
 GEOLOGIC MAP OF NEW YORK, FINGER LAKES SHEET  
 DATED: 1970, SCALE 1:250,000

**D'APPOLONIA**

DRAWN BY ACS 4-29-81 CHECKED BY J.E. 5/7/87 DRAWING NUMBER 80-778-A6  
 APPROVED BY J.H.D. 5-7-87

# LEGEND

## CANADAWAY GROUP 800-1200 ft. (240-370 m.)




Dcy Machias Formation—shale, siltstone; Rushford Sandstone; Caneadea, Canisteo, and Hume Shales; Canaseraga Sandstone; South Wales and Dunkirk Shales; In Pennsylvania: Towanda Formation—shale, sandstone.

## JAVA GROUP 300-700 ft. (90-210 m.)



Dj Wiscoy Formation—sandstone, shale; Hanover and Pipe Creek Shales.

## WEST FALLS GROUP 1100-1600 ft. (340-490 m.)



Dwr Nunda Formation—sandstone, shale.  
 Dwg West Hill and Gardeau Formations—shale, siltstone; Roricks Glen Shale; upper Beers Hill Shale; Grimes Siltstone.  
 Dwr lower Beers Hill Shale; Dunn Hill, Millport, and Moreland Shales.  
 Dwc Nunda Formation—sandstone, shale; West Hill Formation—shale, siltstone; Corning Shale.  
 Dwrn "New Milford" Formation—sandstone, shale.  
 Dwrg Gardeau Formation—shale, siltstone; Roricks Glen Shale.  
 Dws Slide Mountain Formation—sandstone, shale, conglomerate.  
 Dwrn Beers Hill Shale; Grimes Siltstone; Dunn Hill, Millport, and Moreland Shales.

## SONYEA GROUP 200-1000 ft. (60-300 m.)



Ds In west: Cashaqua and Middlesex Shales.  
 In east: Rye Point Shale; Rock Stream ("Enfield") Siltstone; Pulteney, Sawmill Creek, Johns Creek, and Montour Shales.

## GENESEE GROUP AND TULLY LIMESTONE 200-1000 ft. (60-300 m.)



Dg West River Shale; Genundewa Limestone; Penn Yan and Genesee Shales; all except Genesee replaced eastwardly by Ithaca Formation—shale, siltstone and Sherburne Siltstone.  
 Dgo Oneonta Formation—shale, sandstone.  
 Dgu Unadilla Formation—shale, siltstone.  
 Dt Tully Limestone.

## GEOLOGY MAP LEGEND

REFERENCE:  
 GEOLOGIC MAP OF NEW YORK, FINGER LAKES SHEET  
 DATED: 1970, SCALE: 1:250,000

# D'APPOLONIA

**DAT  
FILM**