

AD-A142 830


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
SUCCESS LAKE DAM (CT. (U) CORPS OF ENGINEERS WALTHAM MA  
NEW ENGLAND DIV MAY 81


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

1

REPORT DOCUMENTATION PAGE

READ INSTRUCTIONS BEFORE COMPLETING FORM

1. REPORT NUMBER CT 00079		2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Success Lake Dam Conn. Coastal Basin, Bridgeport, Conn. NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT	
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)	
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE May 1981	
		13. NUMBER OF PAGES 50	
		15. SECURITY CLASS. (of this report) UNCLASSIFIED	
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED			
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)			
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY,  Success Lake Dam Conn. Coastal Basin Bridgeport, Conn.			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The Success Lake Dam, constructed in 1875, is a 132 ft. long, 17 ft. high structure composed of two earthfill embankments and a central 33 ft. long broad crested spillway. The original timber spillway decking has since been capped with concrete. There is a small single land bridge, across the overflow spillway section. Flow over the spillway is channeled through five 4 ft. wide, 2 ft. high openings, and one 3.3 ft. wide, 2 ft. high, opening formed by the bridge piers. The upstream concrete face of the spillway has a slope of approx. 2H:1V and the masonry downstream face is vertical.			

DTIC  
SELECTE  
JUL 2 1984  
S  
A  
D

AD-A142 830

DTIC FILE COPY

SUCCESS LAKE DAM

CT 00079

CONNECTICUT COASTAL BASIN

BRIDGEPORT, CONNECTICUT

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

MAY 1981



Requested For	<input checked="" type="checkbox"/>
DTIC	<input type="checkbox"/>
Approved	<input type="checkbox"/>
Classification	<input type="checkbox"/>
Revision/	
Availability Codes	
Avail and/or	
Special	

A1

This document has been approved for public release and sale; its distribution is unlimited.

84 06 23 000

CONSULTING  
ENGINEERS

**INTERNATIONAL ENGINEERING COMPANY, INC.**  
A MORRISON-KNUDSEN COMPANY

EASTERN DISTRICT OFFICE  
777 POST ROAD DAREN, CONNECTICUT 06620  
PHONE (203) 655-3345

11410  
2616-110

May 7, 1981

Mr. E. P. Gould  
Project Management Branch  
Department of the Army  
New England Division  
Corps of Engineers  
424 Trapelo Road  
Waltham, Massachusetts 02154

Reference: Contract No. DACW33-81-C-0015  
Inspection and Evaluation of Non-Federal Dams  
FY-81, Southwestern Connecticut

Dear Mr. Gould:

The inspection of Success Lake Dam and subsequent hydrologic-hydraulic investigation revealed that the dam should be classified as having a low hazard potential. The following is an abbreviated Phase I Inspection report to substantiate this classification.

Sincerely,



Reynold A. Hokenson, P. E.  
Project Manager

RAH:mem

Enclosures

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Table of Contents	
Brief Assessment	1-1
Location Map	1-4
APPENDICES	
APPENDIX A - INSPECTION CHECKLIST	A-1
APPENDIX B - ENGINEERING DATA AND CORRESPONDENCE	B-1
APPENDIX C - PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1

DAM INSPECTION PROGRAM

PHASE I INSPECTION REPORT

Identification No: CT 0079

Name of Dam: Success Lake Dam

Town: Bridgeport

County and State: Fairfield, Connecticut

Stream: Yellow Mill Channel

Dates of Inspection: February 5 and 19, 1981

BRIEF ASSESSMENT

The Success Lake Dam impounds Success Lake on the Yellow Mill Channel tributary in Bridgeport, Fairfield County, Connecticut. The structure is currently owned by Remington Arms Company, Inc., 939 Barnum Avenue, Bridgeport, Connecticut. The operation of the facility is the responsibility of Robert H. Gruss, Plant Engineer, Remington Arms Co., Inc., (203) 333-1112. Currently, the impoundment is maintained for aesthetics and wildlife conservation.



The Success Lake Dam, constructed in 1875, is a 132-foot-long, 17-foot-high structure composed of two earthfill embankments and a central 33-foot-long broad crested spillway. The original timber spillway decking has since been capped with concrete. There is a small single land bridge, across the overflow spillway section (Photo 1). Flow over the spillway is channeled through five 4-foot-wide, 2-foot-high openings, and one 3.3-foot-wide, 2-foot-high, opening formed by the bridge piers. The upstream concrete face of the spillway has a slope of approximately 2H:1V and the masonry downstream face is vertical. The downstream slopes of the two-side embankments are formed by vertical stone retaining walls. The upstream slopes also appeared to be vertical stone retaining walls, however, these areas were, for the most part, concealed beneath the water surface and accumulated sediments (Photos 2 and 3).

Two cast iron conduits pass through the earthfill embankment at the right abutment of the dam and provide additional outlets from the impoundment. A 14 inch diameter conduit exits the dam near its base approximately 12 feet from the right side of the spillway. Discharges from this conduit are regulated by a hand operated valve which is housed in a small masonry structure (Photo 9). The second conduit is 8 inches in diameter and emerges from the right embankment, approximately 5 feet below the top of the dam and about 25 feet from the spillway (Photo 7). This conduit extends 126 feet downstream to a small brick structure where, at one time, it provided water for the generation of steam (Photo 8). The brick structure formerly housed equipment for the generation and distribution of steam to the various industrial processes that were performed by Remington Arms Company, Inc., in the 1940's. This equipment was removed from the site and the building was converted to an employee locker room. The 8-inch conduit leading to this building, though deteriorated, is still intact.

Visual inspection of the site indicated that the dam is in poor condition. The inspection revealed the following: deterioration of the vertical downstream face of the spillway, cracked and missing portions of the concrete spillway crest along the downstream edge (Photo 4), cracks along the upstream and downstream interfaces of the spillway and abutments, exposed aggregate on the concrete spillway cap, seepage along the toe of the left embankment has resulted in a 20-foot by 30-foot marshy area approximately 40 feet from the dam, and a potentially inoperable low-level outlet. The seepage beneath the spillway, described in the inspection report submitted by William P. Sanders of the State of Connecticut Water Resource Commission on July 22, 1964 (see Correspondence), was not confirmed during the inspections conducted by IECO on February 2 and 19, 1981. During these inspections, an accumulation of rocks at the base of the spillway, ice formations on the downstream face of the spillway and particularly water flowing over the spillway made it impossible to examine this portion of the dam closely (Photos 5 and 6). Water was observed draining vertically through cracks in the concrete cap near the left upstream spillway abutment, but no corresponding discharge was noted on the downstream

face of the spillway. In addition, localized outward movement of the stone retaining wall and the concrete spillway cap were also found in the vicinity of the left spillway abutment. The effected area is approximately 7 feet wide, but the movement has been slight and is a local condition not threatening the dam.

The Success Lake Dam has a maximum potential storage capacity of 119 acre-feet (ac-ft) and is approximately 17 feet in height. Since the dam falls within the Corp's criteria for the small size category based on storage (between 50 and 1,000 ac-ft), the dam is considered to be SMALL in size. The dam breach analysis was conducted in accordance with the "Rule of Thumb Guidance for Estimating Downstream Dam Failure Hydrographs", dated April 1978, and the potential impact area was defined. Failure of the dam would cause the water surface within the streambed immediately downstream of the dam to rise from 4.7 feet at a prefailure outflow of 310 cfs to 11.1 feet at an outflow of 2,360 cfs. The first floor of the brick structure located approximately 130 feet downstream from the dam is more than 20 feet above the streambed, and this will not be effected by the flood wave. The only remaining other structures adjacent to the Yellow Mill Channel are located 3,500 feet downstream from the dam. These will sustain little or no damage since the water surface within this reach will rise only 1.8 feet above the streambed. Since failure of the dam will cause little or no property damage and no loss of life, the dam has been classified as having a LOW hazard potential.



LOCATION MAP  
CONNECTICUT  
0 2000 4000  
SCALE IN FEET

USGS QUADRANGLE  
BRIDGEPORT 1970

APPENDIX A

INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST  
PARTY ORGANIZATION

PROJECT Success Lake Dam

DATE 02/5 & 19/81

TIME 10:00 a.m.

WEATHER Sunny, Cold

W.S. ELEV. 47.1

PARTY:

INITIALS:

- |                       |                          |
|-----------------------|--------------------------|
| 1. Jeffrey T. Klaucke | JK                       |
| 2. Myron B. Petrovsky | MP                       |
| 3. Ernst H. Buggisch  | EB                       |
| 4. Paul Archer        | PA                       |
| 5. Harold Farnham     | HF (Matthews Associates) |

PROJECT FEATURE:

INSPECTED BY:

- |                             |                |
|-----------------------------|----------------|
| 1. Dam                      | JK, MP, EB, PA |
| 2. Intake Channel           | JK, MP         |
| 3. Valvehouse               | JK, HF, MP     |
| 4. Powerhouse Conduit       | HF, JK, MP     |
| 5. Low Level Outlet         | HF, JK, MP     |
| 6. Low level Outlet Channel | JK, MP, EB, PA |
| 7. Spillway                 | JK, MP, EB     |
| 8. Bridge                   | JK, PA, EB     |

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Dam

NAME: JK, MP, EB, PA

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	47.0
Current Pool Elevation	47.1
Maximum Impoundment to Date	Approximately 50.0
Surface Cracks	None
Pavement Condition	Good
Movement or Settlement of Crest	None
Lateral Movement	Local movement on upstream face near left spillway abutment.
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Cracks along U/S and D/S interfaces with spillway.
Indications of Movement of Structural Items on Slopes	Minor bulging of U/S and D/S retaining walls.
Trespassing on Slopes	None.
Sloughing or Erosion	None
Rock Slope Protection	The exposed U/S walls were irregular and missing stones.
Unusual Movement or Cracking at or near Toes	None
Unusual Embankment or Downstream Seepage	Wet area at D/S toe on the left bank. Seepage noted through valvehouse.
Piping or Boils	Possible piping along low level outlet conduit.

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam DATE: 02/5 & 19/81

PROJECT FEATURE: Dam (Continued) NAME: JK, MF, EB, PA

AREA EVALUATED	CONDITION
Foundation Drainage Features	Unknown
Toe Drains	Unknown
Instrumentation System	None



PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Valvehouse

NAME: JK, HF, MP

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Fair, wooden roof rotted.
Condition of Joints	Good
Spalling	None
Visible Reinforcing	None
Rusting or Staining of Concrete	Near crack in valvehouse wall
Any Seepage or Efflorescence	Seepage noted through crack in valvehouse wall.
Joint Alignment	Good
Unusual Seepage or Leaks in Gate Chamber	None
Cracks	Right wall of valvehouse
Rusting or Corrosion of Steel	Exposed portion of low level outlet conduit.
b. Mechanical and Electrical	
Air Vents	
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	
Mechanical Valve	Not tested at owner's request
Emergency Gates	
Lightning Protection System	
Emergency Power System	
Wiring and Lighting System	

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam DATE: 02/5 & 19/81

PROJECT FEATURE: Low level Outlet NAME: HF, JK, MP

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Conduit	Fair
Rust or Staining on Conduit	Superficial rust on exposed conduit.
Spalling	N/A
Erosion or Cavitation	None
Cracking	None
Alignment of Monoliths	N/A
Alignment of Joints	N/A
Numbering of Monoliths	N/A
<p><u>Note:</u> Only a small portion of the cast iron conduit (approximately 8 in.) was visible.</p>	

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Low Level Outlet Channel

NAME: JK, MP, EB, PA

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Condition at Joints</p> <p>Drain holes</p> <p>Channel</p> <p>Loose Rock or Trees Overhanging Channel</p> <p>Condition of Discharge Channel</p>	<p>N/A</p> <p>Large rocks and 5 to 20 in. diameter trees were found immediately D/S of the outlet and adjacent to the spillway discharge channel.</p> <p>Large rocks have accumulated on the channel floor.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Spillway

NAME: JK, HF, EB

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p> <p>a. Approach Channel</p> <p>    General Condition</p> <p>    Loose Rock Overhanging Channel</p> <p>    Trees Overhanging Channel</p> <p>    Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p>    General Condition of Masonry</p> <p>    Rust or Staining</p> <p>    Spalling of spillway concrete cap</p> <p>    Any Visible Reinforcing</p> <p>    Any Seepage</p> <p>    Drain Holes</p> <p>c. Discharge Channel</p> <p>    General Condition</p> <p>    Loose Rock Overhanging Channel</p> <p>    Trees Overhanging Channel</p> <p>    Floor of Channel</p> <p>    Other Obstructions</p>	<p>Success Lake</p> <p>Loose stones in retaining walls, some stones missing and wall movements noted near spillway.</p> <p>None</p> <p>Near downstream edge of spillway weir.</p> <p>None</p> <p>Some vertical drainage into dam through cracks in the spillway cap.</p> <p>None</p> <p>Fair</p> <p>Loose rocks from downstream walls of spillway have accumulated in discharge channel.</p> <p>Large tree on right bank between valvehouse and spillway.</p> <p>Strewn with large rocks.</p> <p>None</p>

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Bridge

NAME: JK, PA, EB

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - BRIDGE</u>	
a. Super Structure	N/A
Bearings	N/A
Anchor Bolts	N/A
Bridge Seat	N/A
Longitudinal Members	N/A
Under Side of Deck	Good
Secondary Bracing	None
Deck	Good
Drainage System	All 3 inch diameter drains in curbs were free of obstructions.
Railings	Good
Expansion Joints	None
Paint	N/A
b. Piers	
General Condition of Concrete	Good
Alignment of Abutment	
Approach to Bridge	
Condition of Seat & Backwall	
	<p>Note: The bridge is supported 2 feet above the spillway by 4 concrete piers that are founded on the spillway.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam DATE: 02/5 & 19/81

PROJECT FEATURE: Powerhouse Conduit NAME: JK, HF, MP

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - CONTROL TOWER</u></p> <p>a. Concrete and Structural</p> <p>    General Condition</p> <p>    Condition of Joints</p> <p>    Spalling</p> <p>    Visible Reinforcing</p> <p>    Rusting or Staining of Concrete</p> <p>    Any Seepage or Efflorescence</p> <p>    Joint Alignment</p> <p>    Unusual Seepage or Leaks in Gate Chamber</p> <p>    Cracks</p> <p>    Rusting or Corrosion of Steel</p> <p>b. Mechanical and Electrical</p> <p>    Air Vents</p> <p>    Float Wells</p> <p>    Crane Hoist</p> <p>    Elevator</p> <p>    Hydraulic System</p> <p>    Mechanical Valve</p> <p>    Emergency Gates</p> <p>    Lightning Protection System</p> <p>    Emergency Power System</p> <p>    Wiring and Lighting System</p>	<p>N/A</p> <p>Valve inoperable, conduit has not been used since the 1940's.</p>

APPENDIX B

ENGINEERING DATA

SUMMARY OF DATA AND CORRESPONDENCE

<u>DATE</u>	<u>TO</u>	<u>FROM</u>	<u>SUBJECT</u>	<u>PAGE</u>
6/7/66	Mr. W.H. O'Brien III Water Resources Commission State of Connecticut	Joseph W. Cone Civil Engineer	Water Resources Inventory Data  Inspection	B-2  B-3
10/9/64	State of Connecticut Water Resources Commission	J. P. Barry Works Engineer Remington Arms Company, Inc.	Verification upon completion of suggested repairs	B-6
7/22/64	H.M. Pierce Jr. Plant Manager Remington Arms Company, Inc.	William P. Sander Engineer-Geologist State of Connecticut	Suggested spillway repairs  COE Inventory Data	B-7  B-8

111 7

No. \_\_\_\_\_

WATER RESOURCES UNIT  
SUPERVISION OF DAMS  
INVENTORY DATA

Inventoried  
By \_\_\_\_\_

Lat: 41° 12.3'  
Long: 73° 9.9'

Date \_\_\_\_\_

Name of Dam or Pond SUCCESS LAKE

Code No. \_\_\_\_\_

Nearest Street Location Huntington Turnpike

Town Bridgeport

U.S.G.S. Quad. Bridgeport

Name of Stream Unnamed

Owner Remington Arms Company, Inc.

Address Barnum Avenue

Bridgeport, CT

Pond Used For Fire Protection Drainage Area 2.43 sq. mi.

Dimensions of Pond: Width 700' Length 1100' Area 18.3 ac.

Total Length of Dam 125' Length of Spillway 35'

Location of Spillway Center of dam

Height of Pond Above Stream Bed 15'

Height of Embankment Above Spillway 3'

Type of Spillway Construction Concrete cap

Type of Dike Construction Masonry

Downstream Conditions Bridgeport

Summary of File Data \_\_\_\_\_

Remarks \_\_\_\_\_

Would Failure Cause Damage? \_\_\_\_\_ Class \_\_\_\_\_

JOSEPH W. CONE  
CIVIL ENGINEER  
124 HAVEMEYER PLACE  
GREENWICH, CONNECTICUT  
06830

TELEPHONE  
STATE TOWNSEND 9-2152  
COMMISSION  
RECEIVED  
JUN 10 1966  
ANSWERED.....  
REFERRED.....  
FILED.....

June 7, 1966

Mr. William H. O'Brien III  
Water Resources Commission  
State Office Building  
Hartford 15, Conn.

Re: Dam #46 Stillman Pond-Bdpt.  
*AND SUCCESS LAKE DAM*

Dear Mr. O'Brien:

As requested, I have inspected the Stillman Pond Dam and the tributary watershed. Also permission was obtained from Remington Arms office to inspect Success Lake Dam, being escorted by one of their guards, since the condition of this dam is involved with Stillman.

	Success	Stillman
Watershed	2.28 sq.mi.	3.44 sq. mi.
Peak Q pres 100 yr	1250 cfs	1890 cfs
" " 2000 AD 400 yr	4370 "	5130 "

Both dams are solidly constructed and, in my opinion, will not fail but both will be overtopped in the future. Both have very low headroom, Success 6 openings averaging 4'x2'; openings were not measured at Stillman, it was evident that dam is safe although it will be overtopped.

Tracks serving the G.E. Plant will be flooded in the future during a severe storm due to channel of inadequate capacity.

Copies of work sheets, three photos and map of watersheds are enclosed. See Lake Forest for more applicable data.

My recommendation is that your office suggest to Remington Arms and General Electric that there be a standing order that their maintenance men see to it that openings at dams be kept clear of debris during heavy storms, this to reduce frequency of overtopping.

Very truly yours,

  
J. W. Cone

JWC/dr  
Enc: 6

Forest & Grazing  
Forest & Grazing

FOREST 1725 Ac — 1.45 sq mi 1.2  
 25 yr forest  
 (Chart B)  $Q$  Peak = 850 cfs Wooded 1950 Control  
 Entire area developing rapidly. Rolling terrain. 1.08  
 $Q$  present 25 yr =  $RF \times LF \times FF \times Q$  cfs/Ac  
 =  $1 \times 0.8 \times 1 \times 850 = 680$  0.73  
 $Q$  " 100 yr =  $1 \times 0.8 \times 1.8 \times 850 = 1220$  1.37  
 $Q$  " 400 yr =  $1 \times 0.8 \times 3.8 \times 850 = 2530$  2.8  
 " 2000 AD " =  $1 \times 1.0 \times 3.8 \times 850 = 3240$  3.5  
 Compare 3240 with 1955 Floods. 1.5 sq mi. on  $Q = 5050 \text{ JA} = 4150 \text{ P/A}$   
 = 6000 on 1945

SUCCESS 1460 Ac — 2.28 sq mi  
 Entire area developing rapidly except 132 Ac owned by Recreation  
 Rolling terrain rather flat

Chart B  $Q = 1150$  cfs Control  
 $Q$  present 25 yr =  $RF \times LF \times FF \times Q$  695  
 =  $1 \times 0.6 \times 1 \times 1150 = 690$  cfs 0.97  
 " 100 =  $1 \times 0.6 \times 1.8 \times 1150 = 1250$  1.35  
 " 400 =  $1 \times 0.6 \times 3.8 \times 1150 = 2620$  1.8  
 2000 AD " =  $1 \times 1.0 \times 3.8 \times 1150 = 4370$  3.0

Provided River Basin Controls. 1639c area.

STILL 2200 Ac Chart B  $Q = 1500$  Control  
 3 AA sq mi. 455  
 $Q$  present 25 yr =  $RF \times LF \times FF \times Q$   
 =  $1 \times 0.7 \times 1 \times 1500 = 1050$  0.48 cfs/Ac  
 " 100 =  $1 \times 0.7 \times 1.8 \times 1500 = 1890$  0.86  
 " 400 =  $1 \times 0.7 \times 3.8 \times 1500 = 4000$  1.8  
 2000 AD " =  $1 \times 0.9 \times 3.8 \times 1500 = 5130$  2.3

Provided River Basin & G.E. do not leverage 330 Ac

(A)

J.W. U  
5/13/51

Forest # 25

5/4/66  
5/3/66

Lake Forest #25

580  
21.55  
5735

Water shed  
Catchment area  
1043 sq mi  
925 Ac

Lake Forest  
2.52  
11.42  
105 sq mi  
5-10

Storage Ratio 1:14

Fair

Success  
Water shed  
913  
2115.24  
4 | 9.12  
2.28 sq mi  
1460 Ac

Stillman  
Lake Forest  
018  
310.46  
4 | 153  
.038 sq mi  
24 Ac

Owned by Bear Agency  
trib to Success  
11.82  
20539 mi 132 Ac

Storage Ratio 1:61 Very Poor

Stillman Pond below Success

Water shed  
4.70  
21.55  
1.11 sq mi  
750 Ac

Lake Forest  
0.06  
21.55  
1.11 sq mi  
9 Ac

Owned by Bear Agency  
& G.E. trib to  
Stillman including  
trib to Success  
4 | 2.07  
.515 320 Ac.

Storage Ratio 1:83 Very Bad practically 0

TOTAL Stillman #46 (includes Success)

Water shed  
13.76  
27.55  
4 | 13.77  
3.44 sq mi  
2200 Ac  
1460  
750  
2210 (check)

Lake Forest  
Success 24 Ac  
Stillman 9  
Total 33 Ac

Owned by Bear Agency  
Auchiska " 1.1 ± "

Total Storage Ratio 1:67 Very poor





# REMINGTON ARMS COMPANY, INC.

MANUFACTURERS OF  
SPORTING FIREARMS, AMMUNITION  
TRAPS TARGETS  
POWER TOOLS

ARMS AND CARTRIDGE POWERED TOOLS  
ILLION, N. Y.  
AMMUNITION, BRIDGEPORT, CONN  
POWER TOOLS, PARK FOREST, ILL

PETERS CARTRIDGE DIVISION  
BRIDGEPORT, CONN  
TRAPS AND TARGETS, FINDLAY, OHIO  
CABLE - HARTLEY, BRIDGEPORT  
- ALL CODES -

**BRIDGEPORT 2, CONNECTICUT**

October 9, 1964

*SUCCESS LAKE DAM  
BRIDGEPORT*

State of Connecticut  
Water Resources Commission  
State Office Building  
Hartford 15, Connecticut

Attention Mr. William P. Sander, Engineer-Geologist

Gentlemen:

Reference - Your letter of July 22, 1964

The leakage under the spillway is a condition we are aware of and have been checking periodically. There is no apparent increase in the water flow over the past ten years and we, therefore, feel this is not a condition to cause concern. The massive construction of this dam should be adequate if the leaks do not become larger, or general deterioration set in.

We have a periodic inspection set up whereby the quantity of water leaking is measured and checked against previous findings. Any increase will be readily recognized and prompt remedial action will be taken.

The trees specified in your report have been removed.

Very truly yours,

REMINGTON ARMS COMPANY, INC.  
H.M. PIERCE, JR., WORKS MANAGER

*J. P. Barry*  
J. P. Barry  
Works Engineer

JPB:O'L

STATE WATER RESOURCES COMMISSION RECEIVED
OCT 13 1964
ANSWERED _____
REFERRED _____
FILED _____

B-6

July 22, 1964

Mr. H. M. Pierce, Jr., Plant Manager  
Remington Arms Company, Inc.  
Barnum Avenue  
Bridgeport, Connecticut

Dear Sir:

The Water Resources Commission has recently completed an inventory of all the dams in the Town of Bridgeport.

During the inventory, the dam forming Success Lake was inspected and was found to be in need of repair. At the date of the inspection, all stream flow was through leakage under the spillway. In addition, the trees which are growing on the dam should be removed. These points are not critical at the present time but represent a condition which could lead to failure of the dam.

We would appreciate hearing what plans you have to place this structure in a safe condition.

Very truly yours,

William P. Sander  
Engineer - Geologist

WPS:js



APPENDIX C

PHOTOGRAPHS






Photo 1 Top of dam and single lane road.



Photo 2 Upstream face of dam, spillway crest and right dam embankment.



Photo 3 Upstream face of dam, spillway crest and left dam embankment.



Photo 4 Downstream spillway crest and bridge piers.



Photo 5 Downstream face of dam.



Photo 6 Downstream masonry face of spillway.



Photo 7 Downstream masonry face  
of right dam embankment,  
8 inch diameter conduit  
and control valve.




Photo 8 Brick structure and 8 inch diameter conduit.



Photo 9 Low-level outlet and valvehouse.

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



DRAINAGE AREA  
2.30 SQ. MI.

SUCCESS LAKE DAM

INTERNATIONAL ENGINEERING CO DAREN, CONNECTICUT ENGINEER	US ARMY ENGINEER DIV NEW ENGLAND CORPS OF ENGINEERS WALTHAM MASS
--	--

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS  
**DRAINAGE AREA MAP**  
**SUCCESS LAKE DAM**

YELLOW MILL CHANNEL BRIDGEPORT, CONNECTICUT

OWN BY	CHK BY	APP BY	SCALE 1"=2000'
448	B	AAZ	DATE APRIL 1981
			SHEET D-1

Project  
Feature  
ItemNATIONAL DAM INSPECTION PROGRAM (NDIP)  
SUCCESS LAKE DAM, BRIDGEPORT, CT  
CT00079Contract No. 2616-04  
Designed MP  
Checked JFSheet D-1  
File No.  
Date 3/10/81  
Date

## HYDRAULIC / HYDROLOGIC INSPECTION

SUCCESS LAKE DAM, BRIDGEPORT, CT CT00079

I. PERFORMANCE AT PEAK FLOOD CONDITIONS

## 1. MAXIMUM PROBABLE FLOOD

a. WATERSHED CLASSIFIED AS "ROLLING"

b. WATERSHED AREA (D.A.) = 2.30 SQ. MI. \*

\* FROM IECO MEASUREMENTS ON THE BRIDGEPORT USGS QUADRANGLE MAP, CT. FROM U.S. CORPS OF ENGINEERS (ACE) DATA, D.A. IS 2.13 SQ. MI.

## c. EXTRAPOLATING FROM NED-ACE GUIDE CURVES

$$PMF \approx 2080 \text{ CFS / SQ. MI.}$$

## d. THEREFORE, PEAK INFLOW:

$$PMF = 2080 \times 2.3 \approx 4780 \text{ CFS}$$

$$\frac{1}{2} PMF \approx 2390 \text{ CFS}$$

2. SURCHARGE AT PEAK INFLOWS (PMF AND  $\frac{1}{2}$  PMF).

## a. OUTFLOW RATING CURVE

## i. SPILLWAY

THE MASONRY SPILLWAY IN THE MID-SECTION OF SUCCESS LAKE DAM IS

A BROAD-CRESTED WEIR WITH A VERTICAL DOWNSTREAM FACE

(SEE SKETCHES ON P. D-2).






Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Contract No. 2616-54  
 Designed MP  
 Checked Ry  
 File No. \_\_\_\_\_  
 Date 3/10/55  
 Date \_\_\_\_\_

ii. EXTENSION OF THE RATING CURVE FOR SURCHARGE OVERTOPPING THE DAM AND/OR ADJACENT TERRAIN

THE SUCCESS LAKE DAM IS A MASONRY STRUCTURE WITH A TOP ELEVATION OF 50.4 AND TOTAL LENGTH OF 99 FT. THE TERRAINS ADJACENT TO THE DAM HAVE SLOPES APPROXIMATELY 10:1 (SEE SKETCH BELOW).



DUE TO THE IRREGULARITIES IN THE PROFILE AN EQUIVALENT WEIR LENGTH MUST BE COMPUTED. ASSUMING A DISCHARGE COEFFICIENT  $C=2.3$  AND ADOPTING THE SPILLWAY CREST AS DATUM (EL. 47.0), THE OVERTFLOW CAN BE APPROXIMATED BY THE FOLLOWING EQUATIONS:

(1) TOP OF DAM AT EL. 50.4.

$$Q_D = 2.3 \times 132.3 \times (H_3 - 3.4)^{3/2} = 304.3 (H_3 - 3.4)^{3/2}, \quad (H_3 > 3.4 \text{ FT})$$

(2) SLOPING TERRAIN TO THE LEFT AND RIGHT OF THE DAM:

$$L_S = \left(\frac{2}{5}\right) Z (H_3 - 3.4) = \left(\frac{2}{5}\right) 10 (H_3 - 3.4) = 4 (H_3 - 3.4)$$

∴ DISCHARGE OVER LEFT AND RIGHT TERRAINS

$$Q_S = 2 L_S (H_3 - 3.4)^{5/2} = 2 \times 4 (H_3 - 3.4)^{5/2} = 8 (H_3 - 3.4)^{5/2}$$



Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_


Contract No. 2616-CA File No. \_\_\_\_\_  
 Designed M.P. Date 3/10/81  
 Checked By JF Date \_\_\_\_\_

THEREFORE, THE TOTAL OUTFLOW RATING CURVE IS APPROXIMATED BY:

$$Q = 51.3 H_1^{3/2} + 224.4 \left( H_2 - \frac{3}{2} \right)^{1/2} + 304.3 (H_3 - 3.4)^{3/2} + 8 (H_3 - 3.4)^{5/2} \quad H_3 \geq 3.4$$

WHEN  $H_1 < 2 \text{ FT}$ ,  $H_2 = \frac{3}{2}$ ; WHEN  $H_2 > 2$ ,  $H_1 = 0$

THE RESULTING OUTFLOW RATING CURVE IS AS FOLLOWS:





Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Sheet D-5  
 Contract No. 2616-04 File No. \_\_\_\_\_  
 Designed MP Date 3/10/81  
 Checked RF Date \_\_\_\_\_

b. SURCHARGE HEIGHT TO PASS PEAK INFLOWS ( $Q_p$  AND  $Q_p'$ )

i. @  $Q_p = 4780$  CFS  $H_1 \approx 8.6$  FT

ii @  $Q_p' = 2390$  CFS  $H_1' \approx 6.6$  FT

c. EFFECT OF SURCHARGE STORAGE ON PEAK OUTFLOWS :

i. AVERAGE POND AREA WITHIN EXPECTED SURCHARGE :

(1) POND AREA AT FLOW LINE (EL. 47.0)  $A_{47}^* = 12.85$  AC

(2) POND AREA AT EL. 50.0  $A_{50}^* = 30.3$  AC

(3) AREA AT CONTOUR 60.0  $A_{60}^* = 68.8$  AC

\* FROM IECO MEASUREMENTS ON THE BRIDGEPORT USGS QUADRANGLE MAP, CT

ASSUMING NORMAL POOL AT SPILLWAY CREST EL. 47.0, APPROXIMATING  
 STAGE-STORAGE RATING CURVE WAS CONSTRUCTED (SEE P D-6).

ii. DISCHARGE ( $Q_{pe}$ ) AT VARIOUS HYPOTHETICAL SURCHARGE ELEVATIONS :

$H = 9$  FT,  $V = 362$  AC-FT,  $\therefore S = \frac{362}{2.3 \times 53.3} = 2.95$  IN

$H = 7$  FT;  $V = 262$  AC-FT;  $S = 2.14$  IN

$H = 5$  FT;  $V = 162$  AC-FT;  $S = 1.32$  IN

$H = 3$  FT;  $V = 65$  AC-FT;  $S = 0.53$  IN






Project NDIP  
Feature SUCCESS LAKE DAM  
Item \_\_\_\_\_

Contract No. 2516-02 File No. \_\_\_\_\_  
Designed M.P. Date 3/10/81  
Checked J.F. Date \_\_\_\_\_

STAGE-STORAGE AND STAGE-AREA CURVES





Project

NDIP

Feature

SUCCESS LAKE DAM

Item

Contract No.

22 E-04

Designed

M.P.

Checked

by JF

Sheet

D-7

File No.

Date

Date

FROM APPROXIMATE ROUTING NED-ACE GUIDELINES AND 19 IN. MAXIMUM POSSIBLE  
RUNOFF IN NEW ENGLAND:

$$Q_{P_2} = Q_{P_1} \left(1 - \frac{S}{19}\right) \text{ AND FOR } \frac{1}{2} \text{ PMF } Q_{P_2}' = Q_{P_1}' \left(1 - \frac{S}{9.5}\right)$$

∴ FOR THE PREVIOUS HYPOTHETICAL SURCHARGES:

$$H = 9 \text{ FT}; \quad Q_{P_2} = 4038 \text{ CFS}, \quad Q_{P_2}' = 1648 \text{ CFS}$$

$$H = 7 \text{ FT}, \quad Q_{P_2} = 4242 \text{ CFS}, \quad Q_{P_2}' = 1852 \text{ CFS}$$

$$H = 5 \text{ FT}, \quad Q_{P_2} = 4448 \text{ CFS}; \quad Q_{P_2}' = 2058 \text{ CFS}$$

$$H = 3 \text{ FT}, \quad Q_{P_2} = 4647 \text{ CFS}; \quad Q_{P_2}' = 2257 \text{ CFS}$$

d. PEAK OUTFLOWS ( $Q_{P_3}$  AND  $Q_{P_3}'$ ):

USING NED-ACE GUIDELINES "SURCHARGE STORAGE ROUTING" ALTERNATE

METHOD AND RATING CURVE (SEE P. D-4):

$$Q_{P_3} = 4120 \text{ CFS} \quad H_3 = 8.1 \text{ FT}$$

$$Q_{P_3}' = 1950 \text{ CFS} \quad H_3' = 6.05 \text{ FT}$$

3. SPILLWAY CAPACITY RATIO TO PEAK INFLOW AND OUTFLOW.

SPILLWAY CAPACITY TO TOP OF DAM (EL. 50.4) IS 309 CFS

% CAPACITY OF INFLOW PMF : 6

" OUTFLOW " : 8

" INFLOW 1/2 PMF : 13

" OUTFLOW " : 16



Project  
Feature  
ItemNDIP  
SUCCESS LAKE DAMContract No. 268-04  
Designed MP  
Checked DJ JFSheet 2-5  
File No.  
Date 3/5  
DateII. DOWNSTREAM FAILURE HAZARD

## 1. POTENTIAL IMPACT AREA

THE POTENTIAL IMPACT AREA IS LOCATED 3500 FT DOWNSTREAM FROM THE DAM  
LARGE 5-STORY CONCRETE BUILDING  
NEAR BOND STREET, HAS FIRST FLOOR ELEVATION ABOUT 20 FT ABOVE  
THE STREAMBED. THERE IS ALSO THE STATE ROUTE 1 BRIDGE LOCATED  
ABOUT 1/3 MILES DOWNSTREAM FROM THE DAM.

## 2. FAILURE OF SUCCESS LAKE DAM.

## a. BREACH WIDTH

## i. HEIGHT OF DAM:

TOP OF DAM EL. 50.4 ; DAM DOWNSTREAM TOE 34.9;  $\therefore H = 15.5$  FT

## ii. DAM MID-HEIGHT EL. 42.7

 $(50.4 - 15.5/2 = 42.7)$ iii. APPROXIMATE MID-HEIGHT LENGTH:  $L \approx 50$  FT (SPILLWAY LENGTH IS NOT INCLUDED)

\* FROM IECO DRAWINGS

## iv. BREACH WIDTH (SEE NED-AGE DOWNSTREAM FAILURE GUIDELINES)

$$W_b = 0.4 L = 0.4 \times 50 = 20 \text{ FT}$$

b. PEAK FAILURE OUTFLOW ( $Q_p$ )

ASSUME SURCHARGE AT TOP OF DAM (EL. 50.4)



Project  
Feature  
Item

NDIP

SUCCESS LAKE DAM

Contract No. 2616-04

Designed MIP

Checked BJ JF

Sheet 3-9

File No.

Date 3/11/81

Date

i. HEIGHT AT TIME OF FAILURE :  $Y_0 = 15.5$  FTii. SPILLWAY DISCHARGE AT TIME OF FAILURE :  $Q_s = 309$  CFS

iii. BREACH OUTFLOW :

$$Q_b = 8/27 W_b \sqrt{g} Y_0^{3/2} = 8/27 \times 20 \times \sqrt{32.2} \times 15.5^{3/2} = 2052 \text{ CFS}$$

iv. PEAK FAILURE OUTFLOW TO YELLOW MILL CHANNEL TRIBUTARY

$$Q_p = Q_s + Q_b = 309 + 2052 = 2360 \text{ CFS}$$


c. FLOOD DEPTH IMMEDIATELY DOWNSTREAM FROM DAM:

$$Y = 0.44 Y_0 = 0.44 \times 15.5 = 6.8 \text{ FT}$$

d. ESTIMATE OF DOWNSTREAM FAILURE CONDITIONS AT POTENTIAL IMPACT AREA  
(SEE NED-ACE GUIDELINES FOR ESTIMATING DOWNSTREAM FAILURE HYDROGRAPHS)

i. REACH OF YELLOW MILL CHANNEL TRIBUTARY BETWEEN DAM AND IMPACT AREA.

VARIES SIGNIFICANTLY IN SECTION. THE FIRST 1500-FOOT-LONG REACH IS APPROXIMATELY SHAPED AS SHOWN ON THE SKETCH BELOW:



CROSS SECTION REACH 1  
THE AVERAGE SLOPE OF THE REACH IS 0.002 ( $\pm$ )



Project

NDIP

Contract No. 2616-04

Sheet D-10

Feature

SUCCESS LAKE DAM

Designed

MP

File No.

Item

Checked

B JF

Date 3/11/61

Date

## ii SUCCESS LAKE DAM RESERVOIR STORAGE AT TIME OF FAILURE.

STORAGE VOLUME BELOW SPILLWAY CREST APPROXIMATED BY  $\frac{1}{4} A H$ 

$$= \frac{1}{4} \times 12.85 \times 12.1 = 38.9 \text{ AC-FT. SURCHARGE STORAGE TO THE OF THE DAM}$$

(EL. 50.4) IS 80.3 AC-FT (SEE STAGE-SURCHARGE CURVE ON P. D-6).

$$\therefore \text{MAXIMUM STORAGE VOLUME OF THE RESERVOIR IS } 38.9 + 80.3 = 119.2 \text{ AC-FT}$$

$$\text{ASSUME } S_{\text{MAX}} = 119 \text{ AC-FT}$$


iii. PEAK INFLOW TO REACH:  $Q_p = 2360 \text{ CFS}$ 

## iv. APPROXIMATE STAGE AT POTENTIAL IMPACT AREA FAILURE OF SUCCESS LAKE DAM


REACH  $L = 3500 \text{ FT}$ ;  $n = 0.05$ ;  $S = 0.002$ ; COMPUTED STAGE-DISCHARGE

CURVE AND STAGE-AREA CURVE FOR THE BROOK SECTION AS SHOWN ON P. D-9

ARE PLOTTED ON P. D-11.

STAGE-DISCHARGE FOR CHANNEL - REACH 1

### AREA CAPACITY CURVE FOR FIRST REACH (1500 FEET LONG)



46 0660

KE 10 X 10 TO THE INCH • 7 X 10 INCHES  
KEUFFEL & ESSER CO. MADE IN U.S.A.

153  
37  
11.5

Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Sheet D-12  
 File No. \_\_\_\_\_  
 Contract No. 2616  
 Designed EHB  
 Checked By JF  
 Date 3/23/21

PRE FAILURE STAGE 4.7 FT DISCHARGE 309 CFS

INITIAL VOLUME ABSTRACTED  $\approx$  4 AC-FT


H	V	$Q_{P2} = 2360 \left(1 - \frac{V_{OL} - 4}{119}\right)$
3	1.7	2406
6	6.0	2320
9	12.9	2183
12	18.1	2080

RISE IN STAGE  $11.1 - 4.7 = 6.4'$

$Q_{P2} = 2110$  CFS

REACH 2: L = 1400 FT n = 0.05 S = 0.002

STAGE DISCHARGE CURVE FOR REACH 2.




PRE FAILURE STAGE 1.0 FT DISCHARGE 309 CFS  
 INITIAL VOLUME ABSTRACTED V = 4.4 AC-FT  
 VOLUME ABSTRACTED BY REACH 1  $\Delta V_1 = 11.5$  AC-FT  
 ROTTING POINTS FOR GRAPHICAL ROUTING

H	VOL	$Q_{P2} = 2110 \left(1 - \frac{VOL - 4.4}{119 - 11.5}\right)$
1	4.4	2110
3	16.06	1881
6	41.07	1390
9	75.04	723


$Q_{P2} = 1800$  cfs      H = 3.7 FT       $\Delta H = 2.7$  FT

D-14 1/2 JF

### AREA CAPACITY CURVE FOR SECOND BENCH (1400 FEET LONG)



CHANNEL SECTION  
AREA (1000 FT<sup>2</sup>)



46 0660

K•E 10 X 10 TO THE INCH • 7 X 10 INCHES  
KEUFFEL & ESSER CO. MADE IN U.S.A.


Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Contract No. 2616  
 Designed EAB  
 Checked by SF

Sheet D-15  
 File No. \_\_\_\_\_  
 Date 3/25/91  
 Date \_\_\_\_\_

REACH 3: L = 600 FT A = 0.05 S = 0.002

STAGE DISCHARGE CURVE FOR REACH 3




PREFAILURE STAGE  $\approx$  0.7 FT DISCHARGE 309 CFS

INITIAL VOLUME ABSTRACTED  $\approx$  3 AC-FT


H	VOL	$Q_{p2} = 1800 \left(1 - \frac{VOL-3}{119-17.5}\right)$
0.2	1.2	1836
0.6	3.8	1784
1.0	6.5	1730
1.4	9.4	1672
2.0	14.0	1580
3.0	22.5	1410

# AREA CAPACITY CURVE FOR THIRD REACH (L=600 FT)



CHANNEL SECTION  
THIRD REACH

AREA (1000 FT<sup>2</sup>)



46 0660

K-E 10 X 10 TO THE INCH • 7 X 10 INCHES  
KEUFFEL & ESSER CO. MADE IN U.S.A.



INTERNATIONAL ENGINEERING COMPANY, INC.

Project NDIP  
Feature SUCCESS LAKE DAM  
Item \_\_\_\_\_

Contract No. 2616  
Designed EHR  
Checked AJF  
Sheet D-47  
File No. \_\_\_\_\_  
Date 3/23/81  
Date \_\_\_\_\_

$$Q_{P2} = 1620 \text{ CFS} \quad H = 1.8 \text{ FT}$$

$$\text{RISE IN STAGE } \Delta H = 1.8 - 0.7 = 1.1 \text{ FT}$$


III. THE RISE IN STAGE WITHIN THE FIRST REACH WILL NOT EFFECT THE STRUCTURE IMMEDIATELY U/S FROM THE DAM (1<sup>ST</sup> FLOOR EL  $\approx$  20 FT ABOVE STREAM BED) THE RISE IN STAGE WITHIN THE THIRD REACH WILL HAVE LITTLE OR NO EFFECT ON THE STRUCTURES NEAR THE STREAM.



FILMED

8





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

1

REPORT DOCUMENTATION PAGE

READ INSTRUCTIONS BEFORE COMPLETING FORM

1. REPORT NUMBER CT 00079		2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Success Lake Dam Conn. Coastal Basin, Bridgeport, Conn. NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT	
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)	
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE May 1981	
		13. NUMBER OF PAGES 50	
		15. SECURITY CLASS. (of this report) UNCLASSIFIED	
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED			
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)			
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY,  Success Lake Dam Conn. Coastal Basin Bridgeport, Conn.			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The Success Lake Dam, constructed in 1875, is a 132 ft. long, 17 ft. high structure composed of two earthfill embankments and a central 33 ft. long broad crested spillway. The original timber spillway decking has since been capped with concrete. There is a small single land bridge, across the overflow spillway section. Flow over the spillway is channeled through five 4 ft. wide, 2 ft. high openings, and one 3.3 ft. wide, 2 ft. high, opening formed by the bridge piers. The upstream concrete face of the spillway has a slope of approx. 2H:1V and the masonry downstream face is vertical.			

DTIC SELECTED  
JUL 2 1984  
S A D

AD-A142 830

DTIC FILE COPY

SUCCESS LAKE DAM

CT 00079

CONNECTICUT COASTAL BASIN

BRIDGEPORT, CONNECTICUT

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

MAY 1981



Request For	
DTIC	<input checked="" type="checkbox"/>
Unpublished	<input type="checkbox"/>
Classification	<input type="checkbox"/>
Availability/	
Reliability Codes	
Event and/or	
Special	

A1

This document has been approved for public release and sale; its distribution is unlimited.

84 06 20 000

CONSULTING  
ENGINEERS

**INTERNATIONAL ENGINEERING COMPANY, INC.**  
A MORRISON-KNUDSEN COMPANY

EASTERN DISTRICT OFFICE  
777 POST ROAD DAREN, CONNECTICUT 06620  
PHONE (203) 659-3345

11410  
2616-110

May 7, 1981

Mr. E. P. Gould  
Project Management Branch  
Department of the Army  
New England Division  
Corps of Engineers  
424 Trapelo Road  
Waltham, Massachusetts 02154

Reference: Contract No. DACW33-81-C-0015  
Inspection and Evaluation of Non-Federal Dams  
FY-81, Southwestern Connecticut

Dear Mr. Gould:

The inspection of Success Lake Dam and subsequent hydrologic-hydraulic investigation revealed that the dam should be classified as having a low hazard potential. The following is an abbreviated Phase I Inspection report to substantiate this classification.

Sincerely,

*Reynold A. Hokenson*

Reynold A. Hokenson, P. E.  
Project Manager

RAH:mem

Enclosures

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Table of Contents	
Brief Assessment	1-1
Location Map	1-4
APPENDICES	
APPENDIX A - INSPECTION CHECKLIST	A-1
APPENDIX B - ENGINEERING DATA AND CORRESPONDENCE	B-1
APPENDIX C - PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1

DAM INSPECTION PROGRAM

PHASE I INSPECTION REPORT

Identification No: CT 0079  
Name of Dam: Success Lake Dam  
Town: Bridgeport  
County and State: Fairfield, Connecticut  
Stream: Yellow Mill Channel  
Dates of Inspection: February 5 and 19, 1981

BRIEF ASSESSMENT

The Success Lake Dam impounds Success Lake on the Yellow Mill Channel tributary in Bridgeport, Fairfield County, Connecticut. The structure is currently owned by Remington Arms Company, Inc., 939 Barnum Avenue, Bridgeport, Connecticut. The operation of the facility is the responsibility of Robert H. Gruss, Plant Engineer, Remington Arms Co., Inc., (203) 333-1112. Currently, the impoundment is maintained for aesthetics and wildlife conservation.


The Success Lake Dam, constructed in 1875, is a 132-foot-long, 17-foot-high structure composed of two earthfill embankments and a central 33-foot-long broad crested spillway. The original timber spillway decking has since been capped with concrete. There is a small single land bridge, across the overflow spillway section (Photo 1). Flow over the spillway is channeled through five 4-foot-wide, 2-foot-high openings, and one 3.3-foot-wide, 2-foot-high, opening formed by the bridge piers. The upstream concrete face of the spillway has a slope of approximately 2H:1V and the masonry downstream face is vertical. The downstream slopes of the two-side embankments are formed by vertical stone retaining walls. The upstream slopes also appeared to be vertical stone retaining walls, however, these areas were, for the most part, concealed beneath the water surface and accumulated sediments (Photos 2 and 3).

Two cast iron conduits pass through the earthfill embankment at the right abutment of the dam and provide additional outlets from the impoundment. A 14 inch diameter conduit exits the dam near its base approximately 12 feet from the right side of the spillway. Discharges from this conduit are regulated by a hand operated valve which is housed in a small masonry structure (Photo 9). The second conduit is 8 inches in diameter and emerges from the right embankment, approximately 5 feet below the top of the dam and about 25 feet from the spillway (Photo 7). This conduit extends 126 feet downstream to a small brick structure where, at one time, it provided water for the generation of steam (Photo 8). The brick structure formerly housed equipment for the generation and distribution of steam to the various industrial processes that were performed by Remington Arms Company, Inc., in the 1940's. This equipment was removed from the site and the building was converted to an employee locker room. The 8-inch conduit leading to this building, though deteriorated, is still intact.

Visual inspection of the site indicated that the dam is in poor condition. The inspection revealed the following: deterioration of the vertical downstream face of the spillway, cracked and missing portions of the concrete spillway crest along the downstream edge (Photo 4), cracks along the upstream and downstream interfaces of the spillway and abutments, exposed aggregate on the concrete spillway cap, seepage along the toe of the left embankment has resulted in a 20-foot by 30-foot marshy area approximately 40 feet from the dam, and a potentially inoperable low-level outlet. The seepage beneath the spillway, described in the inspection report submitted by William P. Sanders of the State of Connecticut Water Resource Commission on July 22, 1964 (see Correspondence), was not confirmed during the inspections conducted by IECO on February 2 and 19, 1981. During these inspections, an accumulation of rocks at the base of the spillway, ice formations on the downstream face of the spillway and particularly water flowing over the spillway made it impossible to examine this portion of the dam closely (Photos 5 and 6). Water was observed draining vertically through cracks in the concrete cap near the left upstream spillway abutment, but no corresponding discharge was noted on the downstream

face of the spillway. In addition, localized outward movement of the stone retaining wall and the concrete spillway cap were also found in the vicinity of the left spillway abutment. The effected area is approximately 7 feet wide, but the movement has been slight and is a local condition not threatening the dam.

The Success Lake Dam has a maximum potential storage capacity of 119 acre-feet (ac-ft) and is approximately 17 feet in height. Since the dam falls within the Corp's criteria for the small size category based on storage (between 50 and 1,000 ac-ft), the dam is considered to be SMALL in size. The dam breach analysis was conducted in accordance with the "Rule of Thumb Guidance for Estimating Downstream Dam Failure Hydrographs", dated April 1978, and the potential impact area was defined. Failure of the dam would cause the water surface within the streambed immediately downstream of the dam to rise from 4.7 feet at a prefailure outflow of 310 cfs to 11.1 feet at an outflow of 2,360 cfs. The first floor of the brick structure located approximately 130 feet downstream from the dam is more than 20 feet above the streambed, and this will not be effected by the flood wave. The only remaining other structures adjacent to the Yellow Mill Channel are located 3,500 feet downstream from the dam. These will sustain little or no damage since the water surface within this reach will rise only 1.8 feet above the streambed. Since failure of the dam will cause little or no property damage and no loss of life, the dam has been classified as having a LOW hazard potential.




LOCATION MAP

CONNECTICUT

0 2000' 4000'

SCALE IN FEET

SUCCESS LAKE DAM



CONNECTICUT  
QUADRANGLE LOCATION

USGS QUADRANGLE  
BRIDGEPORT 1970

APPENDIX A

INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST  
PARTY ORGANIZATION

PROJECT Success Lake Dam

DATE 02/5 & 19/81

TIME 10:00 a.m.

WEATHER Sunny, Cold

W.S. ELEV. 47.1

PARTY:

INITIALS:

- |                       |                          |
|-----------------------|--------------------------|
| 1. Jeffrey T. Klaucke | JK                       |
| 2. Myron B. Petrovsky | MP                       |
| 3. Ernst H. Buggisch  | EB                       |
| 4. Paul Archer        | PA                       |
| 5. Harold Farnham     | HF (Matthews Associates) |

PROJECT FEATURE:

INSPECTED BY:

- |                             |                |
|-----------------------------|----------------|
| 1. Dam                      | JK, MP, EB, PA |
| 2. Intake Channel           | JK, MP         |
| 3. Valvehouse               | JK, HF, MP     |
| 4. Powerhouse Conduit       | HF, JK, MP     |
| 5. Low Level Outlet         | HF, JK, MP     |
| 6. Low level Outlet Channel | JK, MP, EB, PA |
| 7. Spillway                 | JK, MP, EB     |
| 8. Bridge                   | JK, PA, EB     |

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Dam

NAME: JK, MP, EB, PA

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	47.0
Current Pool Elevation	47.1
Maximum Impoundment to Date	Approximately 50.0
Surface Cracks	None
Pavement Condition	Good
Movement or Settlement of Crest	None
Lateral Movement	Local movement on upstream face near left spillway abutment.
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Cracks along U/S and D/S interfaces with spillway.
Indications of Movement of Structural Items on Slopes	Minor bulging of U/S and D/S retaining walls.
Trespassing on Slopes	None.
Sloughing or Erosion	None
Rock Slope Protection	The exposed U/S walls were irregular and missing stones.
Unusual Movement or Cracking at or near Toes	None
Unusual Embankment or Downstream Seepage	Wet area at D/S toe on the left bank. Seepage noted through valvehouse.
Piping or Boils	Possible piping along low level outlet conduit.

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/61

PROJECT FEATURE: Dam (Continued)

NAME: JK, MF, EB, PA

AREA EVALUATED	CONDITION
Foundation Drainage Features	Unknown
Toe Drains	Unknown
Instrumentation System	None



PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Valvehouse

NAME: JK, HF, MP

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Fair, wooden roof rotted.
Condition of Joints	Good
Spalling	None
Visible Reinforcing	None
Rusting or Staining of Concrete	Near crack in valvehouse wall
Any Seepage or Efflorescence	Seepage noted through crack in valvehouse wall.
Joint Alignment	Good
Unusual Seepage or Leaks in Gate Chamber	None
Cracks	Right wall of valvehouse
Rusting or Corrosion of Steel	Exposed portion of low level outlet conduit.
b. Mechanical and Electrical	
Air Vents	
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	
Mechanical Valve	Not tested at owner's request
Emergency Gates	
Lightning Protection System	
Emergency Power System	
Wiring and Lighting System	

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam DATE: 02/5 & 19/81

PROJECT FEATURE: Low level Outlet NAME: HF, JK, MP

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Conduit	Fair
Rust or Staining on Conduit	Superficial rust on exposed conduit.
Spalling	N/A
Erosion or Cavitation	None
Cracking	None
Alignment of Monoliths	N/A
Alignment of Joints	N/A
Numbering of Monoliths	N/A
<p><u>Note:</u> Only a small portion of the cast iron conduit (approximately 8 in.) was visible.</p>	

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Low Level Outlet Channel

NAME: JK, MP, EB, PA

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u></p>	
<p>General Condition of Concrete</p>	<p>N/A</p>
<p>Rust or Staining</p>	
<p>Spalling</p>	
<p>Erosion or Cavitation</p>	
<p>Visible Reinforcing</p>	
<p>Any Seepage or Efflorescence</p>	
<p>Condition at Joints</p>	
<p>Drain holes</p>	
<p>Channel</p>	
<p>Loose Rock or Trees Overhanging Channel</p>	<p>Large rocks and 5 to 20 in. diameter trees were found immediately D/S of the outlet and adjacent to the spillway discharge channel.</p>
<p>Condition of Discharge Channel</p>	<p>Large rocks have accumulated on the channel floor.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Spillway

NAME: JK, HF, EB

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
<p>a. Approach Channel</p> <p>    General Condition</p> <p>    Loose Rock Overhanging Channel</p> <p>    Trees Overhanging Channel</p> <p>    Floor of Approach Channel</p>	<p>Success Lake</p>
<p>b. Weir and Training Walls</p> <p>    General Condition of Masonry</p> <p>    Rust or Staining</p> <p>    Spalling of spillway concrete cap</p> <p>    Any Visible Reinforcing</p> <p>    Any Seepage</p> <p>    Drain Holes</p>	<p>Loose stones in retaining walls, some stones missing and wall movements noted near spillway.</p> <p>None</p> <p>Near downstream edge of spillway weir.</p> <p>None</p> <p>Some vertical drainage into dam through cracks in the spillway cap.</p> <p>None</p>
<p>c. Discharge Channel</p> <p>    General Condition</p> <p>    Loose Rock Overhanging Channel</p> <p>    Trees Overhanging Channel</p> <p>    Floor of Channel</p> <p>    Other Obstructions</p>	<p>Fair</p> <p>Loose rocks from downstream walls of spillway have accumulated in discharge channel.</p> <p>Large tree on right bank between valvehouse and spillway.</p> <p>Strewn with large rocks.</p> <p>None</p>

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Bridge

NAME: JK, PA, EB

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - BRIDGE</u>	
a. Super Structure	N/A
Bearings	
Anchor Bolts	N/A
Bridge Seat	N/A
Longitudinal Members	N/A
Under Side of Deck	Good
Secondary Bracing	None
Deck	Good
Drainage System	All 3 inch diameter drains in curbs were free of obstructions.
Railings	Good
Expansion Joints	None
Paint	N/A
b. Piers	
General Condition of Concrete	Good
Alignment of Abutment	
Approach to Bridge	
Condition of Seat & Backwall	
	<p><u>Note:</u> The bridge is supported 2 feet above the spillway by 4 concrete piers that are founded on the spillway.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT: Success Lake Dam

DATE: 02/5 & 19/81

PROJECT FEATURE: Powerhouse Conduit

NAME: JK, HF, MP

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - CONTROL TOWER</u></p> <p>a. Concrete and Structural</p> <p>    General Condition</p> <p>    Condition of Joints</p> <p>    Spalling</p> <p>    Visible Reinforcing</p> <p>    Rusting or Staining of Concrete</p> <p>    Any Seepage or Efflorescence</p> <p>    Joint Alignment</p> <p>    Unusual Seepage or Leaks in Gate Chamber</p> <p>    Cracks</p> <p>    Rusting or Corrosion of Steel</p> <p>b. Mechanical and Electrical</p> <p>    Air Vents</p> <p>    Float Wells</p> <p>    Crane Hoist</p> <p>    Elevator</p> <p>    Hydraulic System</p> <p>    Mechanical Valve</p> <p>    Emergency Gates</p> <p>    Lightning Protection System</p> <p>    Emergency Power System</p> <p>    Wiring and Lighting System</p>	<p>N/A</p> <p>Valve inoperable, conduit has not been used since the 1940's.</p>

APPENDIX B

ENGINEERING DATA

SUMMARY OF DATA AND CORRESPONDENCE

<u>DATE</u>	<u>TO</u>	<u>FROM</u>	<u>SUBJECT</u>	<u>PAGE</u>
6/7/66	Mr. W.H. O'Brien III Water Resources Commission State of Connecticut	Joseph W. Cone Civil Engineer	Water Resources Inventory Data  Inspection	B-2  B-3
10/9/64	State of Connecticut Water Resources Commission	J. P. Barry Works Engineer Remington Arms Company, Inc.	Verification upon completion of suggested repairs	B-6
7/22/64	H.M. Pierce Jr. Plant Manager Remington Arms Company, Inc.	William P. Sander Engineer-Geologist State of Connecticut	Suggested spillway repairs  COE Inventory Data	B-7  B-8

1117

No. \_\_\_\_\_

WATER RESOURCES UNIT  
SUPERVISION OF DAMS  
INVENTORY DATA

Inventoried  
By \_\_\_\_\_

Lat: 41° 12.3'

Date \_\_\_\_\_

Long: 73° 9.9'

Name of Dam or Pond SUCCESS LAKE

Code No. \_\_\_\_\_

Nearest Street Location Huntington Turnpike

Town Bridgeport

U.S.G.S. Quad. Bridgeport

Name of Stream Unnamed

Owner Remington Arms Company, Inc.

Address Barnum Avenue

Bridgeport, CT

Pond Used For Fire Protection Drainage Area 2.43 sq. mi.

Dimensions of Pond: Width 700' Length 1100' Area 18.3 ac.

Total Length of Dam 125' Length of Spillway 35'

Location of Spillway Center of dam

Height of Pond Above Stream Bed 15'

Height of Embankment Above Spillway 3'

Type of Spillway Construction Concrete cap

Type of Dike Construction Masonry

Downstream Conditions Bridgeport

Summary of File Data \_\_\_\_\_

Remarks \_\_\_\_\_

Would Failure Cause Damage? \_\_\_\_\_ Class \_\_\_\_\_

JOSEPH W. CONE  
CIVIL ENGINEER  
124 HAVEMEYER PLACE  
GREENWICH, CONNECTICUT  
06830

STATE TOWNSEND 9-2153000
COMMISSION
RECEIVED
JUN 10 1966
ANSWERED _____
REFERRED _____
FILED _____

June 7, 1966

Mr. William H. O'Brien III  
Water Resources Commission  
State Office Building  
Hartford 15, Conn.

Re: Dam #46 Stillman Pond-Bdpt.  
AND SUCCESS LAKE DAM

Dear Mr. O'Brien:

As requested, I have inspected the Stillman Pond Dam and the tributary watershed. Also permission was obtained from Remington Arms office to inspect Success Lake Dam, being escorted by one of their guards, since the condition of this dam is involved with Stillman.

	Success	Stillman
Watershed	2.28 sq.mi.	3.44 sq. mi.
Peak Q pres 100 yr	1250 cfs	1890 cfs
" " 2000 AD 400 yr	4370 "	5130 "

Both dams are solidly constructed and, in my opinion, will not fail but both will be overtopped in the future. Both have very low headroom, Success 6 openings averaging 4'x2'; openings were not measured at Stillman, it was evident that dam is safe although it will be overtopped.

Tracks serving the G.E. Plant will be flooded in the future during a severe storm due to channel of inadequate capacity.

Copies of work sheets, three photos and map of watersheds are enclosed. See Lake Forest for more applicable data.

My recommendation is that your office suggest to Remington Arms and General Electric that there be a standing order that their maintenance men see to it that openings at dams be kept clear of debris during heavy storms, this to reduce frequency of overtopping.

Very truly yours,

  
J. W. Cone

JWC/dr  
Enc: 6

Forest & Grazing  
Forest & Grazing

FOREST 725 Ac — 1.45 sq mi 1.2  
 (Chart B) Q Peak = 850 cfs Wooded 1950 Constant  
 Entire area developing rapidly. Rolling terrain. 1.02  
 $Q$  present 25yr =  $RF \times LF \times FF \times Q$  cfs/Ac  
 =  $1 \times 0.8 \times 1 \times 850 = 680$  0.73  
 $Q$  " 100yr =  $1 \times 0.8 \times 1.8 \times 850 = 1220$  1.32  
 $Q$  " 400yr =  $1 \times 0.8 \times 3.8 \times 850 = 2580$  2.8  
 " 2000AD " =  $1 \times 1.0 \times 3.8 \times 850 = 3240$  3.5  
 Compare 3240 with 1955 Floods. 1.5 sq mi. on  $Q = 5000 \text{ JA} = 4150 \text{ P/1/2}$   
 = 6000 on 1945

SUCCESS 1460 Ac — 2.28 sq mi  
 Entire area developing rapidly except 132 Ac owned by Revere  
 Rolling terrain rather flat

Chart B Q = 1150 cfs Constant  
695  
 $Q$  pres. 25yr =  $RF \times LF \times FF \times Q$   
 =  $1 \times 0.6 \times 1 \times 1150 = 690$  0.97  
 " 100 =  $1 \times 0.6 \times 1.8 \times 1150 = 1250$  0.85  
 " 400 =  $1 \times 0.6 \times 3.8 \times 1150 = 2620$  1.8  
 2000AD " =  $1 \times 1.0 \times 3.8 \times 1150 = 4370$  3.0

Provided Revere Areas Controls. 1639c area.

JF 11/22/54 2200 Ac Chart B Q = 1500 Constant  
3.44 sq mi. 455  
 $Q$  pres 25yr =  $RF \times LF \times FF \times Q$  cfs/Ac  
 =  $1 \times 0.7 \times 1 \times 1500 = 1050$  0.48  
 " 100 =  $1 \times 0.7 \times 1.8 \times 1500 = 1890$  0.86  
 " 400 =  $1 \times 0.7 \times 3.8 \times 1500 = 4000$  1.8  
 2000AD " =  $1 \times 0.9 \times 3.8 \times 1500 = 5130$  2.3

Provided Revere Areas & G.I.E. do not leverage 330 Ac.

(A)

J.W. U  
5/13/54

Forest # 25

5/4/66  
5:30

Lake Forest #25

580  
2155  
5735

Water shed  
Circ. 578 sq mi  
1.443 sq mi  
925 Ac

Lake Forest  
340  
280  
620  
105 sq mi

Storage Ratio 1:14

Fair

Water Success

ac=12

Stillman

Water shed  
913  
2115.24  
4 | 9.12  
2.28 sq mi  
1460 Ac

Lake Forest  
0.18  
310.46  
4 | 153  
.038 sq mi  
24 Ac

Divided by New Area  
Total for Success  
21.82  
20539 mi 132 Ac

Storage Ratio 1:61 Very Poor

Stillman Pool

below Success

Water shed  
4.70  
21536  
4 | 5.36  
1.34 sq mi  
750 Ac

Lake Forest  
0.06  
215.11  
4 | 53  
.013 sq mi  
9 Ac

Divided by Bear Run  
to G.E. trib to  
Stillman including  
trib to Success  
4 | 2.06  
.515 320 Ac.

Storage Ratio 1:83 Very Bad practically 0

TOTAL Stillman #46 (includes Success)

Water shed

Lake Forest

Len. shed 3.15 mi  
Auchilla " 1.1 ± "

13.76  
27.55  
4 | 13.77  
3.44 sq mi  
2200 Ac  
1460  
750  
2210 chie

Success 24 Ac  
Stillman 9  
Total 33 Ac

Total Storage Ratio 1:67 Very poor





# REMINGTON ARMS COMPANY, INC.

MANUFACTURERS OF  
SPORTING FIREARMS, AMMUNITION

TRAPS TARGETS

POWER TOOLS

ARMS AND CARTRIDGE POWERED TOOLS  
MILTON, N. Y.  
AMMUNITION, BRIDGEPORT, CONN.  
POWER TOOLS, PARK FOREST, ILL.

PETERS CARTRIDGE DIVISION  
BRIDGEPORT, CONN.  
TRAPS AND TARGETS, FINDLAY, OHIO  
CABLE - HARTLEY, BRIDGEPORT  
- ALL CODES -

**BRIDGEPORT 2, CONNECTICUT**

October 9, 1964

*SUCCESS LAKE DAM  
BRIDGEPORT*

State of Connecticut  
Water Resources Commission  
State Office Building  
Hartford 15, Connecticut

Attention Mr. William P. Sander, Engineer-Geologist

Gentlemen:

Reference - Your letter of July 22, 1964

The leakage under the spillway is a condition we are aware of and have been checking periodically. There is no apparent increase in the water flow over the past ten years and we, therefore, feel this is not a condition to cause concern. The massive construction of this dam should be adequate if the leaks do not become larger, or general deterioration set in.

We have a periodic inspection set up whereby the quantity of water leaking is measured and checked against previous findings. Any increase will be readily recognized and prompt remedial action will be taken.

The trees specified in your report have been removed.

Very truly yours,

REMINGTON ARMS COMPANY, INC.  
H.M. PIERCE, JR., WORKS MANAGER

*J. P. Barry*  
J. P. Barry  
Works Engineer

JPB:O'L

STATE WATER RESOURCES COMMISSION RECEIVED
OCT 13 1964
ANSWERED _____
REFERRED _____
FILED _____

B-6

July 22, 1964

Mr. H. M. Pierce, Jr., Plant Manager  
Remington Arms Company, Inc.  
Barnum Avenue  
Bridgeport, Connecticut

Dear Sir:

The Water Resources Commission has recently completed an inventory of all the dams in the Town of Bridgeport.

During the inventory, the dam forming Success Lake was inspected and was found to be in need of repair. At the date of the inspection, all stream flow was through leakage under the spillway. In addition, the trees which are growing on the dam should be removed. These points are not critical at the present time but represent a condition which could lead to failure of the dam.

We would appreciate hearing what plans you have to place this structure in a safe condition.

Very truly yours,

William P. Sander  
Engineer - Geologist

WPS:js

STATE DIVISION OF WATER RESOURCES

STATE	DIVISION	DATE	COUNTY	CONC.	NAME	LATITUDE	LONGITUDE	REPORT DATE
CT	79	NEU	001	04	SUCCESS LAKE DAM	4112.3	7309.9	10DEC73

POPULAR NAME	NAME OF IMPONUMENT	
SUCCESS LAKE	SUCCESS LAKE	
REGION	RIVER OR STREAM	
U1 07	TR-YELLOW MILL CHANNEL	
	MILL HULL	
NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
		250000

TYPE OF DAM	YEAR COMPLETED	PURPOSES	IMPONUMENT CAPACITIES		DIST UMN FED R PHV/FED	VEN/DATE
			MAXIMUM STORAGE (ACR-FEET)	REGULATED STORAGE (ACR-FEET)		
C1	1975	0	18	17	124	109
						NEU

REMARKS

20-ESTIMATE 22-ESTIMATE

D/S HAS	SPILLWAY LENGTH (FT)	TYPE	YEAR	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CV)	POWER CAPACITY (KW)	INSTALLED PROPOSED	NO. NAVIGATION LOCKS
125	55							

OWNER	ENGINEERING BY	CONSTRUCTION BY
HEMINGTON ARMS		

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
	03NOV72	PA 571 8ECT 25-11 ST OF CT

REMARKS

Call to reserve clearance. on days notice.  
 Bob Gross Fx 1316.

letter approx. time 1 day  
 2 weeks

APPENDIX C

PHOTOGRAPHS




PHOTO LOCATION PLAN  
SUCCESS LAKE DAM

— SUCCESS LAKE —

57'-0"

33'-0"

42'-0"

BRIDGE PIERS

ROAD

VERTICAL STONE  
RETAINING WALLS

MARSHY AREA

SPILLWAY

VALVEHOUSE

OLD POWERHOUSE

14"  $\phi$  LOW LEVEL  
OUTLET

8"  $\phi$  CONDUIT

8

9

6

7

8

9

6

4

2

3

5





Photo 1 Top of dam and single lane road.



Photo 2 Upstream face of dam, spillway crest and right dam embankment.



Photo 3 Upstream face of dam, spillway crest and left dam embankment.



Photo 4 Downstream spillway crest and bridge piers.



Photo 5 Downstream face of dam.



Photo 6 Downstream masonry face of spillway.



Photo 7 Downstream masonry face  
of right dam embankment,  
8 inch diameter conduit  
and control valve.




Photo 8 Brick structure and 8 inch diameter conduit.



Photo 9 Low-level outlet and valvehouse.

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



DRAINAGE AREA  
2.30 SQ. MI.

SUCCESS LAKE DAM

INTERNATIONAL ENGINEERING CO. US ARMY ENGINEER DIV NEW ENGLAND  
DAREN, CONNECTICUT CORPS OF ENGINEERS  
ENGINEER WALTHAM MASS

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS  
DRAINAGE AREA MAP  
SUCCESS LAKE DAM

YELLOW MILL CHANNEL BRIDGEPORT, CONNECTICUT

OWN BY	CKE BY	APP BY	SCALE 1"=2000'
246	B	MAN	DATE APRIL 1981 SHEET D-1



Project

NATIONAL DAM INSPECTION PROGRAM (NDIP)

Contract No.

2E16-04

Sheet

D-1

Feature

SUCCESS LAKE DAM, BRIDGEPORT, CT

Designed

M.P.

File No.

Date

3/10/81

Item

CT00079

Checked

Ry JF

Date

## HYDRAULIC / HYDROLOGIC INSPECTION

SUCCESS LAKE DAM, BRIDGEPORT, CT CT00079

I. PERFORMANCE AT PEAK FLOOD CONDITIONS

## 1. MAXIMUM PROBABLE FLOOD

a. WATERSHED CLASSIFIED AS "ROLLING"

b. WATERSHED AREA (D.A.) = 2.30 SQ. MI. \*

\* FROM IECO MEASUREMENTS ON THE BRIDGEPORT USGS QUADRANGLE MAP, CT. FROM U.S. CORPS OF ENGINEERS (ACE) DATA, D.A IS 2.43 SQ. MI.

## c. EXTRAPOLATING FROM NED-ACE GUIDE CURVES

$$PMF \approx 2080 \text{ CFS / SQ. MI.}$$

d. THEREFORE, PEAK INFLOW:

$$PMF = 2080 \times 2.3 \approx 4780 \text{ CFS}$$

$$\frac{1}{2} PMF \approx 2390 \text{ CFS}$$

2. SURCHARGE AT PEAK INFLOWS (PMF AND  $\frac{1}{2}$  PMF).

## a. OUTFLOW RATING CURVE

## i. SPILLWAY

THE MASONRY SPILLWAY IN THE MID-SECTION OF SUCCESS LAKE DAM IS



A BROAD-CRESTED WEIR WITH A VERTICAL DOWNSTREAM FACE

(SEE SKETCHES ON P. D-2).



Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Contract No. 266-C File No. \_\_\_\_\_  
 Designed TRP Date 3-5-51  
 Checked LF Date \_\_\_\_\_



THE 33.3-FT-WIDE AND 27.1-FT-LONG SPILLWAY HAS A CONCRETE ROAD BRIDGE WITH 6 OPENINGS THE FIVE OF WHICH HAVE A WIDTH OF 4 FT AND THE ONE OPENING ON THE RIGHT SIDE IS A 3.3-FT WIDE. THE HEIGHT OF THE OPENINGS IS 2 FT ON THE UPSTREAM BRIDGE EDGE AND 2.5 FT ON THE DOWNSTREAM EDGE.

THE TOTAL LENGTH OF THE OPENINGS IS 23.3 FT ( $L_o$ ) AND THE TOTAL AREA OF THE OPENINGS ON THE UPSTREAM SIDE IS 46.6 SQ. FT ( $A_o$ ).

ASSUMING  $C_1 = 2.2$  ( $H < 2$  FT) AND  $C_2 = 0.6$  ( $H > 2$  FT) AND ADOPTING THE SPILLWAY CREST ELEV. 47.0 AS DATUM, THE SPILLWAY DISCHARGE IS

APPROXIMATING BY :

$$Q_s = C_1 L_o H_1^{3/2} + C_2 A_o \sqrt{2g} (H_2 - \frac{3}{2})^{3/2} = 2.2 \times 23.3 \times H_1^{3/2} + 0.6 \times 46.6 \times \sqrt{64.4} (H_2 - \frac{3}{2})^{3/2}$$


$$Q_s = 51.3 H_1^{3/2} + 224.4 (H_2 - \frac{3}{2})^{3/2} \quad (\text{WHEN } H_1 < 2 \text{ FT, } H_2 = \frac{3}{2}; \text{ WHEN } H_2 > 2, H_1 = 0)$$

Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Contract No. 2616-5+ File No. \_\_\_\_\_  
 Designed MP Date 3/10/5  
 Checked RF Date \_\_\_\_\_

ii. EXTENSION OF THE RATING CURVE FOR SURCHARGE OVERTOPPING THE DAM AND/OR ADJACENT TERRAIN

THE SUCCESS LAKE DAM IS A MASONRY STRUCTURE WITH A TOP ELEVATION OF 50.4 AND TOTAL LENGTH OF 99 FT. THE TERRAINS ADJACENT TO THE DAM HAVE SLOPES APPROXIMATELY 10:1 (SEE SKETCH BELOW).



DUE TO THE IRREGULARITIES IN THE PROFILE AN EQUIVALENT WEIR LENGTH MUST BE COMPUTED. ASSUMING A DISCHARGE COEFFICIENT  $C=2.3$  AND ADOPTING THE SPILLWAY CREST AS DATUM (EL. 47.0), THE OVERFLOW CAN BE APPROXIMATED BY THE FOLLOWING EQUATIONS:

- (1) TOP OF DAM AT EL. 50.4.

$$Q_D = 2.3 \times \frac{132.3}{125.3} \times (H_3 - 3.4)^{3/2} = 304.3 (H_3 - 3.4)^{3/2}, \quad (H_3 > 3.4 \text{ FT})$$

- (2) SLOPING TERRAIN TO THE LEFT AND RIGHT OF THE DAM:

$$L_S = \left(\frac{2}{5}\right) H (H_3 - 3.4) = \left(\frac{2}{5}\right) 10 (H_3 - 3.4) = 4 (H_3 - 3.4)$$

∴ DISCHARGE OVER LEFT AND RIGHT TERRAINS

$$Q_S = 2 L_S (H_3 - 3.4)^{5/2} = 2 \times 4 (H_3 - 3.4)^{5/2} = 8 (H_3 - 3.4)^{5/2}$$



Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_


Contract No. 2616-CA File No. \_\_\_\_\_  
 Designed M.P. Date 3/10/81  
 Checked H. JF Date \_\_\_\_\_

THEREFORE, THE TOTAL OUTFLOW RATING CURVE IS APPROXIMATED BY:

$$Q = 51.3 H_1^{3/2} + 224.4 \left( H_2 - \frac{3}{2} \right)^{1/2} + 304.3 (H_3 - 3.4)^{3/2} + 8 (H_3 - 3.4)^{5/2} \quad H_3 \geq 3.4$$

WHEN  $H_1 < 2 \text{ FT}$ ,  $H_2 = \frac{3}{2}$ ; WHEN  $H_2 > 2$ ,  $H_1 = 0$

THE RESULTING OUTFLOW RATING CURVE IS AS FOLLOWS:





Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Contract No. 2616-04 File No. \_\_\_\_\_  
 Designed MP Date 3/10/81  
 Checked JS Date \_\_\_\_\_

Sheet D-5

b. SURCHARGE HEIGHT TO PASS PEAK INFLOWS ( $Q_p$  AND  $Q_p'$ )

i. @  $Q_p = 4780$  CFS  $H_1 \approx 8.6$  FT

ii @  $Q_p' = 2390$  CFS  $H_1' \approx 6.6$  FT

c. EFFECT OF SURCHARGE STORAGE ON PEAK OUTFLOWS :

i. AVERAGE POND AREA WITHIN EXPECTED SURCHARGE :

(1) POND AREA AT FLOW LINE (EL. 47.0)  $A_{47}^* = 12.85$  AC

(2) POND AREA AT EL. 50.0  $A_{50}^* = 30.3$  AC

(3) AREA AT CONTOUR 60.0  $A_{60}^* = 68.8$  AC

\* FROM IECO MEASUREMENTS ON THE BRIDGEPORT USGS QUADRANGLE MAP, CT

ASSUMING NORMAL POOL AT SPILLWAY CREST EL. 47.0, APPROXIMATING  
 STAGE - STORAGE RATING CURVE WAS CONSTRUCTED (SEE P. D-6).

ii. DISCHARGE ( $Q_{p2}$ ) AT VARIOUS HYPOTHETICAL SURCHARGE ELEVATIONS :

$H = 9$  FT,  $V = 362$  AC-FT,  $\therefore S = \frac{362}{2.3 \times 53.3} = 2.95$  IN

$H = 7$  FT;  $V = 262$  AC-FT;  $S = 2.14$  IN

$H = 5$  FT;  $V = 162$  AC-FT;  $S = 1.32$  IN

$H = 3$  FT;  $V = 65$  AC-FT;  $S = 0.53$  IN






Project NDIP  
Feature SUCCESS LAKE DAM  
Item \_\_\_\_\_

Contract No. 26.6-04 File No. \_\_\_\_\_  
Designed T.P. Date 3/10/51  
Checked J.F. Date \_\_\_\_\_

STAGE-STORAGE AND STAGE-AREA CURVES



Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Sheet 3-7  
 Contract No. 26 E-02 File No. \_\_\_\_\_  
 Designed MP Date 3 '58'  
 Checked by JF Date \_\_\_\_\_

FROM APPROXIMATE ROUTING NED-ACE GUIDELINES AND 19 IN MAXIMUM POSSIBLE  
 RUNOFF IN NEW ENGLAND:

$$Q_{P2} = Q_{P1} \left(1 - \frac{S}{19}\right) \text{ AND FOR } \frac{1}{2} \text{ PMF } Q_{P2}' = Q_{P1}' \left(1 - \frac{S}{9.5}\right)$$

∴ FOR THE PREVIOUS HYPOTHETICAL SURCHARGES:

H = 9 FT;	$Q_{P2} = 4038 \text{ CFS};$	$Q_{P2}' = 1648 \text{ CFS}$
H = 7 FT;	$Q_{P2} = 4242 \text{ CFS};$	$Q_{P2}' = 1852 \text{ CFS}$
H = 5 FT;	$Q_{P2} = 4418 \text{ CFS};$	$Q_{P2}' = 2058 \text{ CFS}$
H = 3 FT;	$Q_{P2} = 4647 \text{ CFS};$	$Q_{P2}' = 2257 \text{ CFS}$

d. PEAK OUTFLOWS ( $Q_{P3}$  AND  $Q_{P3}'$ ):

USING NED-ACE GUIDELINES "SURCHARGE STORAGE ROUTING" ALTERNATE  
 METHOD AND RATING CURVE (SEE P. D-4):

$Q_{P3} = 4120 \text{ CFS}$	$H_3 = 8.1 \text{ FT}$
$Q_{P3}' = 1950 \text{ CFS}$	$H_3' = 6.05 \text{ FT}$

3. SPILLWAY CAPACITY RATIO TO PEAK INFLOW AND OUTFLOW.

SPILLWAY CAPACITY TO TOP OF DAM (EL. 50.4) IS 309 CFS

% CAPACITY OF INFLOW PMF :	6
" OUTFLOW " :	8
" INFLOW 1/2 PMF :	13
" OUTFLOW " :	16



Project

NDIP

Feature

SUCCESS LAKE DAM

Item

Contract No.

266-04

Designed

MP

Checked

D

JF

Sheet

D-5

File No.

Date

3/5

Date

## II. DOWNSTREAM FAILURE HAZARD

### 1. POTENTIAL IMPACT AREA

THE POTENTIAL IMPACT AREA IS LOCATED 3500 FT DOWNSTREAM FROM THE DAM  
 LARGE 5-STORY CONCRETE BUILDING  
 NEAR BOND STREET, HAS FIRST FLOOR ELEVATION ABOUT 20 FT ABOVE  
 THE STREAMBED. THERE IS ALSO THE STATE ROUTE 1 BRIDGE LOCATED  
 ABOUT 1/3 MILES DOWNSTREAM FROM THE DAM.

### 2. FAILURE OF SUCCESS LAKE DAM.

#### a. BREACH WIDTH

##### i. HEIGHT OF DAM:

TOP OF DAM EL. 50.4 ; DAM DOWNSTREAM TOE 34.9;  $\therefore H = 15.5$  FT

##### ii. DAM MID-HEIGHT EL. 42.7

( $50.4 - 15.5/2 = 42.7$ )

##### iii. APPROXIMATE MID-HEIGHT LENGTH: $l \approx 50$ FT (SPILLWAY LENGTH IS NOT INCLUDED)

\* FROM IECO DRAWINGS

##### iv. BREACH WIDTH (SEE NED-AGE DOWNSTREAM FAILURE GUIDELINES)

$$W_b = 0.4 l = 0.4 \times 50 = 20 \text{ FT}$$

##### b. PEAK FAILURE OUTFLOW ( $Q_p$ )

ASSUME SURCHARGE AT TOP OF DAM (EL. 50.4)



Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Contract No. 2616-04  
 Designed MP  
 Checked Bj JF  
 Sheet 3-9  
 File No. \_\_\_\_\_  
 Date 3/1/51  
 Date \_\_\_\_\_

i. HEIGHT AT TIME OF FAILURE :  $Y_0 = 15.5$  FT

ii. SPILLWAY DISCHARGE AT TIME OF FAILURE :  $Q_s = 309$  CFS

iii. BREACH OUTFLOW :

$$Q_b = 8/27 W_b \sqrt{g} Y_0^{3/2} = 8/27 \times 20 \times \sqrt{32.2} \times 15.5^{3/2} = 2052 \text{ CFS}$$

iv. PEAK FAILURE OUTFLOW TO YELLOW MILL CHANNEL TRIBUTARY

$$Q_p = Q_s + Q_b = 309 + 2052 = 2360 \text{ CFS}$$


c. FLOOD DEPTH IMMEDIATELY DOWNSTREAM FROM DAM :

$$Y = 0.44 Y_0 = 0.44 \times 15.5 = 6.8 \text{ FT}$$

d. ESTIMATE OF DOWNSTREAM FAILURE CONDITIONS AT POTENTIAL IMPACT AREA  
 (SEE NED-AGE GUIDELINES FOR ESTIMATING DOWNSTREAM FAILURE HYDROGRAPHS)

i. REACH OF YELLOW MILL CHANNEL TRIBUTARY BETWEEN DAM AND IMPACT AREA.

VARIES SIGNIFICANTLY IN SECTION. THE FIRST 1500-FOOT-LONG REACH IS APPROXIMATELY SHAPED AS SHOWN ON THE SKETCH BELOW:



CROSS SECTION REACH 1  
 THE AVERAGE SLOPE OF THE REACH IS  $0.002 (\pm)$



Project

NDIP

Contract No. 2616-04

Sheet D-10

Feature

SUCCESS LAKE DAM

Designed

MP

File No.

Item

Checked

B JF

Date

3/11/81

## ii SUCCESS LAKE DAM RESERVOIR STORAGE AT TIME OF FAILURE.

STORAGE VOLUME BELOW SPILLWAY CREST APPROXIMATED BY  $\frac{1}{4} AH$ 

$$= \frac{1}{4} \times 12.85 \times 12.1 = 38.9 \text{ AC-FT. SURCHARGE STORAGE TO THE OF THE DAM}$$

(EL. 50.4) IS 80.3 AC-FT (SEE STAGE-SURCHARGE CURVE ON P. D-6).

$$\therefore \text{MAXIMUM STORAGE VOLUME OF THE RESERVOIR IS } 38.9 + 80.3 = 119.2 \text{ AC-FT.}$$

$$\text{ASSUME } S_{\text{MAX}} = 119 \text{ AC-FT}$$


iii PEAK INFLOW TO REACH:  $Q_p = 2360 \text{ CFS}$ 

## iv. APPROXIMATE STAGE AT POTENTIAL IMPACT AREA FAILURE OF SUCCESS LAKE DAM


REACH  $L = 3500 \text{ FT}$ ;  $n = 0.05$ ;  $S = 0.002$ ; COMPUTED STAGE-DISCHARGE

CURVE AND STAGE-AREA CURVE FOR THE BROOK SECTION AS SHOWN ON P. D-9

ARE PLOTTED ON P. D-11.

STAGE-DISCHARGE FOR CHANNEL - REACH 1

### AREA CAPACITY CURVE FOR FIRST REACH (1500 FEET LONG)



A (in 1000 #FT)

21.3

21

18

15

12

9

6

3

STAGE (FT)

VOLUME (AC-FT)

30

60

90

120

150

180

46 0660

K·E 10 X 10 TO THE INCH • 7 X 10 INCHES  
KEUFFEL & ESSER CO MADE IN U.S.A.

152  
37  
11.5



Project  
Feature  
Item

NDIP  
SUCCESS LAKE DAM

Contract No. 2616  
Designed EHB  
Checked M JF

Sheet 2-12  
File No.  
Date 3/23/21

PRE FAILURE STAGE 4.7 FT DISCHARGE 309 CFS

INITIAL VOLUME ABSTRACTED 4 AC-FT

H	V	$Q_{P2} = 2360 \left(1 - \frac{10L - 4}{119}\right)$
3	1.7	2406
6	6.0	2320
9	12.9	2183
12	18.1	2080

RISE IN STAGE 11.1 - 4.7 = 6.4'

$Q_{P2} = 2110$  CFS





Project

NDIP

Contract No. 2616

Sheet D-13

Feature SUCCESS LAKE DAM

Designed E.H.B.

File No.

Item


Checked J. JF

Date 3/23/81

Date

REACH 2: L = 1400 FT  $n = 0.05$   $S = 0.002$ 

## STAGE DISCHARGE CURVE FOR REACH 2.



PRE FAILURE STAGE 1.0 FT DISCHARGE 309 CFS  
 INITIAL VOLUME ABSTRACTED  $V = 4.4$  CC-FT  
 VOLUME ABSTRACTED BY REACH 1  $\Delta V_1 = 11.5$  AC-FT  
 ROTTING POINTS FOR GRAPHICAL ROUTING


H	VOL	$Q_{P2} = 2110 \left(1 - \frac{VOL - 4.4}{119 - 11.5}\right)$
1	4.4	2110
3	16.06	1881
6	41.07	1390
9	75.04	723

$Q_{P2} = 1800$  cfs  $H = 3.7$  FT  $\Delta H = 2.7$  FT




D-14 35F

### AREA CAPACITY CURVE FOR SECOND BEACH (1400 FEET LONG)



CHANNEL SECTION  
AREA (1000 FT<sup>2</sup>)



46 0660


K-E 10 X 10 TO THE INCH • 7 X 10 INCHES  
KEUFFEL & ESSER CO. MADE IN U.S.A.

Project NDIP  
 Feature SUCCESS LAKE DAM  
 Item \_\_\_\_\_

Contract No. 2616 Sheet D-15  
 Designed EHB File No. \_\_\_\_\_  
 Checked by SF Date 3/25/91

REACH 3: L = 600 FT A = 0.05 S = 0.002

STAGE DISCHARGE CURVE FOR REACH 3




PREFAILURE STAGE ≈ 0.7 FT DISCHARGE 309 CFS

INITIAL VOLUME ABSTRACTED ≈ 3 AC-FT


H	VOL	$Q_{p2} = 1800 \left(1 - \frac{VOL-3}{119-17.5}\right)$
0.2	1.2	1836
0.6	3.8	1784
1.0	6.5	1730
1.4	9.4	1672
2.0	14.0	1580
3.0	22.5	1410

# AREA CAPACITY CURVE FOR THIRD REACH (L=600 FT.)



CHANNEL SECTION  
THIRD REACH

AREA (1000 FT<sup>2</sup>)



46 0660



INTERNATIONAL ENGINEERING COMPANY, INC.

Project NDIP  
Feature SUCCESS LAKE DAM  
Item \_\_\_\_\_

Contract No. 2016  
Designed EHB  
Checked RJF  
Sheet D-47  
File No. \_\_\_\_\_  
Date 3/23/81  
Date \_\_\_\_\_

$$QP_2 = 1620 \text{ CFS} \quad H = 1.8 \text{ FT}$$

$$\text{RISE IN STAGE } \Delta H = 1.8 - 0.7 = 1.1 \text{ FT}$$

III. THE RISE IN STAGE WITHIN THE FIRST REACH WILL NOT EFFECT THE STRUCTURE IMMEDIATELY D/S FROM THE DAM (1<sup>ST</sup> FLOOR EL  $\approx$  20 FT ABOVE STREAM BED) THE RISE IN STAGE WITHIN THE THIRD REACH WILL HAVE LITTLE OR NO EFFECT ON THE STRUCTURES NEAR THE STREAM.



REPRODUCED

FILMED

8