



MICROCOPY RESOLUTION TEST CHART
NBS 1963-A

CONNECTICUT RIVER BASIN
HAVERHILL, NEW HAMPSHIRE

AD-A156 427

LOWER MOUNTAIN LAKE
N.H. 00195

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



G

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS 01554

ATC FILE COPY

MARCH 1985

85 06 14 025

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1 REPORT NUMBER NH 00195	2 GOVT ACCESSION NO NO 1156127	3 RECIPIENT'S CATALOG NUMBER
4 TITLE (and Subtitle) Lower Mountain Lake NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5 TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7 AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6 PERFORMING ORG. REPORT NUMBER
9 PERFORMING ORGANIZATION NAME AND ADDRESS		8 CONTRACT OR GRANT NUMBER(s)
11 CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
		12 REPORT DATE March 1979
		13 NUMBER OF PAGES 53
14 MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16 DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17 DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18 SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19 KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Riversville, New Hampshire Waterman Brook		
20 ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is an earth embankment structure with a concrete impervious core wall and outer trench. It is 600 ft. long with a maximum height of 15 ft. The spillway is a low head overflow type. The dam is on the Connecticut River and was observed during a recent location along the lower reach of the river.		

DEPARTMENT OF THE ARMY

Corps of Engineers

214 TRAFLET ROAD

CONCORD, MASSACHUSETTS

Dear Governor Callen:

Inclosed is a copy of the Lower Mountain Lake Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, Town & Country Homes, Inc., Haverhill, New Hampshire.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely,



MAX B. SCHEIDER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

LOWER MOUNTAIN LAKE

NH00195

HAVERHILL, NEW HAMPSHIRE

Accession For		
NIH CRA&I	<input checked="" type="checkbox"/>	
NIH TAB	<input type="checkbox"/>	
Unannounced	<input type="checkbox"/>	
Justification		
By		
Distribution/		
Availability Codes		
	Avail	and/or
Dist	Special	

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No: NH00195
Name of Dam: Lower Mountain Lake
Town: Haverhill
County and State: Grafton County, New Hampshire
Stream: Waterman Brook
Date of Inspection: November 20, 1978

BRIEF ASSESSMENT

The Lower Mountain Lake Dam is an earth embankment structure with a continuous impervious earth core and cutoff trench. The dam is 960 feet long with a maximum height of 32.5 feet. Each face of the core wall is sloped at 1H:1V while the pervious upstream shell slopes at 3H:1V. The crest is 13 feet wide and the downstream face slopes at 2H:1V. There are three outlets including an 84-inch overflow pipe spillway, a 24-inch diameter low-level outlet conduit and an emergency spillway.



The dam was designed by the former engineering firm of Rollins, King and McKone Inc., of Manchester, New Hampshire; constructed in 1967 by Moulton Construction of Lebanon, New Hampshire.

Based on the small size and low hazard classification and in accordance with Corps guidelines, the test flood is the 100-year flood. The test flood inflow of 1,580 CFS (420 CSM) produces a routed test flood outflow of 1,242 CFS which overtops the emergency spillway by 2.2 feet. With water level at the top of the dam, the spillways will pass 1,765 CFS (469 CSM) which is 142 percent of the test flood.

The dam is in fair condition. Seepage was observed in five specific locations along the downstream toe of the dam. The following items require attention:

1. Riprap should be replaced where previously removed from the left side of the emergency spillway.
2. The in-place soil characteristics of the emergency spillway should be evaluated by a qualified engineer in order that erosion protection measures can be recommended if necessary.
3. The method of operating the low-level discharge conduit is dangerous and undependable. A service pier should be constructed and the chain operated shear gate should be replaced by a stem operated gate valve.

4. The existing service bridge to the outlet spillway needs painting and the grating on the outlet riser pipe needs replacing.
5. A program of annual inspection should be implemented.
6. Flow characteristics and quantity should be measured and recorded in the area of the downstream low-level outlet conduit.



Walter A. Henry

This Phase I Inspection Report on Lower Mountain Lake Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Richard J. DiBuono

RICHARD DIBUONO, MEMBER
Water Control Branch
Engineering Division

Aramast Mahtesian

ARAMAST MAHTESIAN, MEMBER
Geotechnical Engineering Branch
Engineering Division

Carney M. Terzian

CARNEY M. TERZIAN, CHAIRMAN
Design Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

REPORT

1. PROJECT INFORMATION

1.1 General	1-1
a. Authority	1-1
b. Purpose	1-1
1-2 Description of Project	1-1
a. Location	1-1
b. Description of Dam & Appurtenances	1-1
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-2
g. Purpose	1-3
h. Design & Construction History	1-3
i. Normal Operating Procedures	1-3
1-3 Pertinent Data	1-3
a. Drainage Area	1-3
b. Discharge at Dam Site	1-3
c. Elevations	1-4
d. Reservoir	1-5
e. Storage	1-5
f. Reservoir Surface	1-6
g. Dam	1-6
h. Diversion and Regulating Tunnel	1-7
i. Spillway	1-7
j. Regulating Outlets	1-8

<u>Section</u>	<u>Page</u>
2. ENGINEERING DATA	
2.1 Design	2-1
2.2 Construction	2-2
2.3 Operation	2-2
2.4 Evaluation	2-3
a. Availability	2-3
b. Adequacy	2-3
c. Validity	2-3
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-2
d. Reservoir Area	3-3
e. Downstream Channel	3-3
3.2 Evaluation	3-3
4. OPERATIONAL PROCEDURES	
4.1 Procedures	4-1
4.2 Maintenance of Dam	4-1
4.3 Maintenance of Operating Facilities	4-1
4.4 Description of Warning System in Effect	4-1
4.5 Evaluation	4-1
5. HYDRAULIC AND HYDROLOGIC EVALUATION	
5.1 Evaluation of Features	5-1
a. General	5-1
b. Design Data	5-1
c. Experience Data	5-1
d. Visual Observations	5-1
e. Test Flood Analysis	5-1
f. Dam Failure Analysis	5-2


<u>Section</u>	<u>Page</u>
6. STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	6-1
a. Visual Observation	6-1
b. Design and Construction Data	6-1
c. Operating Records	6-1
d. Post-Construction Changes	6-1
e. Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
d. Need for Additional Investigation	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
a. Operation and Maintenance Procedures	7-2
7.4 Alternatives	7-2

APPENDICES

APPENDIX A - VISUAL INSPECTION CHECK LIST	A-1
APPENDIX B - PROJECT RECORDS AND PLANS	B-1
APPENDIX C - PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC & HYDRAULIC COMPUTATIONS	D-1
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1



OVERVIEW OF
MOUNTAIN LAKE DAM
HAVERHILL, NEW HAMPSHIRE



SOURCE:
 USGS QUADRANGLES
 LISBON, N H 1967
 EAST HAVERHILL, N H 1967
 1:24,000

DUFRESNE-HENRY ENGINEERING CORP 40 WHITE ST. ENCLAND, VT		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORP. OF EN. NEWS 48, TRAV. VE.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS			
LOCATION MAP LOWER MOUNTAIN LAKE DAM			
EAST MONTPELIER		VERMONT	
CLIENT NO.	04-0080	SCALE	1"=2000'
ENR.	200	DATE	1970

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
NAME OF DAM: LOWER MOUNTAIN LAKE

SECTION 1 - PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Dufresne-Henry Engineering Corporation has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to Dufresne-Henry Engineering Corporation under a letter of November 20, 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0010 has been assigned by the Corps of Engineers for this work.

b. Purpose

- (1) Perform technical inspection and evaluation of nonfederal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by nonfederal interests.
- (2) Encourage and prepare the states to initiate quickly effective dam safety programs for nonfederal dams.
- (3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location

Lower Mountain Lake Dam is located in the Town of Haverhill, Grafton County, New Hampshire at 44° 07.1' north latitude and 71° 57.4' west longitude. The site is located on the Waterman Brook, a tributary of the Wild Ammonoosuc River, which drains into the Connecticut River. The dam is located approximately 3,600 feet upstream from the confluence of Waterman Brook and the Wild Ammonoosuc River.

b. Description of Dam and Appurtenances

The Lower Mountain Lake Dam is an earth embankment structure which, according to available drawings, has an impervious core and a cutoff trench (see Figure 1, Appendix B). The overall length of the dam is 960 feet with a maximum height of 32.5 feet.

The emergency spillway (elevation 775.0) is 100 feet wide and is constructed on existing soil. The water surface was lowered during 1978 by constructing a trench in the emergency spillway for the purpose of bypassing the existing streambed so an infiltration gallery could be constructed.

There are two outlet conduits at Lower Mountain Lake. The normal outlet pipe is a 60-inch diameter corrugated metal pipe (invert elevation 755.7 MSL). This outlet is controlled by an 84-inch diameter riser at an overflow elevation of 774.0 feet MSL. The other outlet is a low-level outlet conduit at invert elevation 745.5 feet MSL. This conduit is controlled by a chain operated shear gate as shown in Figure 2, Appendix B.

The outlet channel is 35 feet wide with riprap protection. The surface level of the tailwater is held at a minimum elevation of 757 feet MSL by a gravel cofferdam. A system of infiltration galleries draws water from under the discharge channel as a public source of potable water.

Immediately upstream of this dam is the Upper Mountain Lake. The dam for this lake forms the upstream limits of the Lower Mountain Lake as shown in the Overview Photo.

c. Size Classification

The Lower Mountain Lake Dam has a size classification of small. The dam impounds about 44,000,000 cubic feet (1000 acre-feet) with a water surface at the dam crest elevation of 778.0. A dam with a maximum storage volume of 1000 acre-feet or less, or a height greater than 25 feet but less than 40 feet is classified as small. In this case, both criteria apply.

d. Hazard Classification

The potential for hazard in the event of failure of this dam is low. There are no homes in the areas affected by the flood wave.

e. Ownership

The dam is owned by the Town and Country Homes, Inc., a private entity. This dam is an integral part of a housing development in Haverhill, New Hampshire (see Photo 1, Appendix C).

f. Operator

Lower Mountain Lake Dam has no one individual responsible for the day-to-day operation of the dam. Mr. Robert Messini of Haverhill, New Hampshire (telephone 603-747-2606) handles the annual cleaning procedure and maintains impoundment levels.

g. Purpose of the Dam

The dam serves to impound water for recreation purposes such as fishing, boating and swimming. Also the impoundment provides stored water to increase yield for the public water supply immediately downstream of the dam.

h. Design and Construction History

The dam was designed by D. G. Blanchard, P.E. of the former Rollins, King & McKone, Inc., Manchester, New Hampshire. This design was reviewed and approved by the New Hampshire Water Resources Board. The two design drawings are contained in Appendix B, Figures 1 and 2. This information is in general agreement with observations made during the visual inspection.

The dam was constructed in 1967 by Moulton Construction of Lebanon, New Hampshire. Records of soils information taken during construction are included in Appendix B. As-built drawings are not available; however, based on visual inspection the dam doesn't seem to differ from the design drawings in Appendix B, Figures 1 and 2.

i. Normal Operational Procedures

Debris is annually removed from the pipe spillway and dam crest. The 6-inch diameter cold water outlet valve is operated during the summer months. Otherwise the dam, for all intents and purposes, is not operated.

1.3 Pertinent Data

a. Drainage Area

There is 3.76 square miles of drainage area at the Lower Mountain Lake Dam. The flow at this site is regulated by the Upper Mountain Lake Dam located immediately upstream of the dam. The drainage area is "long and narrow" (see Page vi) with moderate slopes of Class C forested soils. The Waterman Brook is the primary stream above the dam.

b. Discharge at Dam Site

(1) Outlet Works

The pipe spillway is designed for continuous overtopping and thus provides the major outlet at Lower Mountain Lake

Dam. The top of the controlling riser (84-inch diameter) is at elevation 774 feet MSL. The actual outlet is a 60-inch corrugated pipe at an invert elevation of 755.7.

The low-level outlet conduit is a 24-inch corrugated pipe at an invert elevation of 745.5 feet MSL.

The emergency spillway is 100 feet wide located in existing soil near the right side of the dam at elevation 775.0 feet MSL. The slope of the spillway is 0.5 percent in the flow direction.

(2) Maximum Known Flood at Dam Site

There are no records available regarding major flooding at the dam site. Mr. Messini, Operator, informed us that neither the emergency spillway nor the low-level outlet conduit have ever been utilized (except when the trench was cut into the emergency spillway).

(3) Ungated Spillway Capacity at Top of Dam

1325 CFS at 778.0 elevation.

(4) Ungated Spillway Capacity at Test Flood Elevation

835 CFS at 777.2 elevation.

(5) Gated Spillway Capacity at Normal Pool Elevation

Not applicable.

(6) Gated Spillway Capacity at Test Flood Elevation

Not applicable.

(7) Total Spillway Capacity at Test Flood Elevation

835 CFS at 777.2 elevation.

(8) Total Project Discharge at Test Flood Elevation

1242 CFS at 777.2 elevation.

c. Elevation Data

(1) Streambed at Centerline of Dam

744.0 feet above MSL.

(2) Maximum Tailwater

Not applicable.

(3) Upstream Portal Invert Diversion Tunnel

Not applicable.

(4) Recreation Pool (Normal)

774.0 feet above MSL.

(5) Full Flood Control Pool

Not applicable.

(6) Spillway Crest

775.0 feet above MSL.

(7) Design Surcharge (Original Design)

Unknown.

(8) Top Dam

778.0 feet above MSL.

(9) Test Flood Design Surcharge

777.2 feet above MSL.

d. Reservoir

(1) Length of Maximum Pool

5000 feet.

(2) Length of Recreation Pool

5000 feet.

(3) Length of Flood Control Pool

Not applicable.

e. Storage

(1) Recreation Pool (Normal Pool)

760 acre-feet.

(2) Flood Control Pool

Not applicable.

(3) Spillway Crest Pool

820 acre-feet.

(4) Top of Dam
1000 acre-feet.

(5) Test Flood Pool
952 acre-feet.

f. Reservoir Surface (Including Upper Mountain Lake)

(1) Recreation Pool (Normal Pool)
60 acres.

(2) Flood Control Pool
Not applicable.

(3) Spillway Crest
120 acres.

(4) Test Flood Pool
252 acres.

(5) Top Dam
300 acres.

g. Dam

(1) Type
Earth embankment.

(2) Length
960 feet.

(3) Height
Maximum height is 32.5 feet.

(4) Top Width
The top width is 12 feet.

(5) Side Slopes
Upstream - 3H:1V.
Downstream - 2H:1V.

(6) Zoning

Central core of "impervious fill," upstream and downstream shells.

(7) Impervious Core

Impervious earth core (Figure 2, Appendix B).

(8) Cutoff

Impervious earth trench (Figure 2, Appendix B).

(9) Grout Curtain

Not applicable.

(10) Other

Not applicable.

h. Diversion and Regulating Tunnel

Not applicable.

i. Spillway

Service Spillway

Emergency Spillway

(1) Type

84-inch overflow pipe riser.

(1) Type

Trapezoidal open channel.

(2) Length of Weir

22 feet.

(2) Length of Weir

100 feet.

(3) Crest Elevation

774.0 feet above MSL.

(3) Crest Elevation

775.0 feet above MSL.

(4) Gates

None

(5) Upstream Channel

Not applicable.

(6) Downstream Channel

Not applicable.

(7) General

Visual inspection indicates the spillway is functioning as designed.

j. Regulating Outlets

There are two regulating outlets at Lower Mountain Lake Dam. One outlet is a 6-inch diameter cast-iron gate valve at invert elevation 766. This outlet discharges into the 84-inch riser pipe spillway.

The other regulating outlet is a 24-inch diameter low-level discharge conduit at invert elevation 745.5. This conduit is a bituminous coated corrugated galvanized metal pipe controlled by a shear gate as shown in Figure 2, Appendix B.

SECTION 2 - ENGINEERING DATA

2.1 Design Data

The lower Mountain Lake Dam was designed in 1967 by Rollins, King and McKone, Inc., a former engineering firm of Manchester, New Hampshire. The design engineer for the dam, Donald G. Blanchard, P.E., can be contacted at New England College in Henniker, New Hampshire.

Copies of design drawings, approved by the New Hampshire Water Resources Board are contained in Appendix B, Figures 1 and 2.

The design drawings indicate the dam is an earth fill dam with an impervious earthen core and cutoff trench. The cutoff trench was designed to extend five feet into the natural impervious material underneath the entire dam. Downstream embankment slopes were designed at slope of 2H:1V and upstream slopes designed at 3H:1V.

The downstream porous shell was designed to be from 10 feet wide at the top to 40 feet wide at the base. In addition a 3-foot rock coarse gravel blanket was designed under the downstream shell along the entire dam. The core extends to elevation 776 or two feet above the natural pond level of 774. The core is 4 feet wide at the top and slopes down on both sides at 1H:1V.

The dam crest was designed to be 12 feet wide and to pitch down at a slope of 0.003 feet/foot toward both faces.

The emergency spillway was designed to be 100 feet long at the right abutment. The top of the spillway, at elevation 775.0 feet MSL, is designed into the natural soil, cut to an elevation of 774.5 feet MSL. Six inches of loam, seeded and mulched over the entire spillway, was placed on top of the natural ground. Riprap protection was designed along the downstream toe of the dam to limit erosion in the event of use of the emergency spillway.

There were two outlet conduits designed into the dam. An 84-inch diameter bituminous coated corrugated metal culvert (BCCMP) set 18 inches into a concrete pad forms a riser serving as outlet protection. The actual outlet conduit is a 60-inch BCCMP passing through the dam from the riser to a concrete headwall at the downstream toe of the dam. Also built into the riser is a cold water outlet conduit. The conduit is a 6-inch cast-iron pipe controlled by a gate valve set inside the riser. This outlet was required by the New Hampshire Fish and Game Department to supply a flow of cold water for the fish in the downstream channel.

The other outlet conduit was designed in the pre-dam stream channel (invert elevation 745.5 feet MSL). This low-level outlet pipe is a 24-inch diameter BCCMP passing through the dam. The downstream end of the culvert has some riprap protection.

Design calculations regarding the spillway and drainage basin hydraulics are available in Appendix B.

2.2 Construction Data

The dam was constructed between the months of May and July during 1968 by Moulton Construction of Lebanon, New Hampshire. The completed dam was inspected by the New Hampshire Water Resources Board in December 1968. The following items were noted as construction discrepancies from the design drawings and are repeated verbatim below:

1. Channel from principal spillway is 32 feet wide and not 40 feet wide as shown on the plan. However, as it carries only discharge from 60-inch culvert, it probably will cause no trouble.
2. Emergency spillway is 100 feet wide but the hillside edge of spillway is not on 100-foot radius but runs straight from pond. This may be a slight improvement.
3. Principal spillway discharge pipe is laid substantially to straight alignment.
4. There are many stumps in the pool area located several feet below normal full pond. These will undoubtedly cause problems around the principal spillway. However, they have an outer baffle two feet away from the principal spillway (ARMCO corrugated steel pipe - 7 feet in diameter). This baffle is 40 inches wide and extends about 12 inches below top of principal spillway and is ARMCO corrugated steel 11 feet in diameter. There are two 8-inch by 9-inch openings near the top of the baffle in one quadrant. From the top of the spillway to the top of baffle, there is quarter inch hardware cloth screening. No such screening covers the top of the spillway. At present there are about three 4-foot x 6-foot concrete form panels on top of the principal spillway.

Otherwise the dam appears to be constructed as designed.

Other construction information includes soils information tested during construction by Albert Goldberg and Associates, Inc. of Manchester, New Hampshire. This information is included in Appendix B.

2.3 Operation Data

The dam is basically not operated. The only operation which takes place is opening of the 6-inch cold water conduit valve. This valve allows continuous feed water to the infiltration galleries located in the downstream discharge channel. Other operational procedures are annual debris removal from the crest.

2.4 Evaluation of Data

a. Availability

The original design drawings and calculations are available for review from the New Hampshire Water Resources Board in Concord, New Hampshire.

b. Adequacy

The available engineering data are sufficient for the Phase I inspection.

c. Validity

The available engineering data are considered valid on the basis of the visual inspection with exceptions noted in 2.2.

SECTION 3 - VISUAL INSPECTION

3.1 Findings

a. General

Lower Mountain Lake Dam is in fair condition. Constructed in 1968, the dam has weathered eleven years with little evidence of deterioration.

b. Dam

The dam is an earth embankment dam with an earthen impervious core and cutoff trench. There is a pervious shell on the upstream (sloped at 3H:1V) and downstream (sloped at 2H:1V) sides.

The crest, shown in Photo 3, is about 12 feet wide and serves as an unrestricted travel way for vehicles. Generally the crest is in good condition, although there is some minor erosion in the vehicle tracks. The upstream face, shown in Photo 2, of the dam has riprap protection with 100-500 pound stones. The riprap on the upper 2 feet of the slope is partially covered with soil which appears to have been pushed down from the crest (see Photos 2 and 4).

The downstream slope, shown in Photo 9, has no visible discontinuities. There are some small pine trees 2 to 3 feet tall which are beginning to grow on the downstream face. Minor erosion has occurred in some areas and there are some vehicle tracks and footpaths across the slope.

Riprap protection with 500-100 pound stone is provided on the right side of the dam toe in order to prevent erosion from use of the low-level outlet conduit.

Some wet and seepage areas were observed in the vicinity of the downstream toe at the following locations beginning at the left abutment:

1. Fifteen feet to the left of the left end of the outlet structure wall. Some erosion was observed, but no water flow was apparent (see Photo 12).
2. At the right end of the outlet wall, water was observed dripping into the discharge channel (Photo 13).
3. Five feet to the right and 14 feet downstream of the right end of the outlet wall there was a minor seep.

4. A seepage area exists 150 feet to the right of the right end of the outlet structure wall and 30 feet downstream of the toe of the slope. The seepage zone begins at the location of the person shown in Photo 14 and extends downstream to the downstream channel. Iron staining and an oil-like water surface were evident.
5. Seepage was observed at the exit point of a 24-inch diameter pipe, approximately 210 feet right of the outlet-structure (Photos 15 and 16). Large stones up to 4 feet diameter existed around the pipe. As shown in Photo 17, some erosion was evident around the stones. Water was pooled around and downstream of the pipe and some flow was evident. Water has iron staining and oil-like surface appearance. The sound of dripping water was heard coming from inside the pipe.

At the downstream left side of the dam, there is an extensive wet area below the gravel road to the pump station (area is shown in Figure 1, Appendix C). This area appears saturated and cattails and dead hemlocks were noted. This inspection was not sufficient to determine whether the water originated in the reservoir or from the hillside directly above the area.

c. Appurtenant Structures

The outlet structure consists of an 84-inch diameter BCCMP embedded 18 inches into a 10-foot square concrete pad 36 inches deep. This vertical conduit forms a riser which protects the actual outlet pipe from debris. A steel screen fabricated over the top of the riser seems to be structurally unsafe due to corrosion. A 6-inch diameter cast-iron pipe passes through the vertical riser and functions as a cold water outlet pipe controlled by a gate valve. The actual outlet pipe consists of a 5-foot diameter BCCMP laid at a downstream slope of 1 percent. Two 10-foot by 10-foot steel diaphragms are imbedded into the impervious core to prevent flow outside the conduit. A concrete headwall is on the downstream end of the pipe.

Another outlet, the low-level outlet conduit, has been constructed in the predam stream channel. This pipe is a 24-inch BCCMP controlled by a shear gate at the upstream end of the conduit. The downstream end of the 24-inch pipe has been protected from wash with 500-1000 pound riprap. On the day of inspection the outlet conduit was discharging 5-7 GPM of rusty colored water which may be leaking past the shear gate.

The service bridge is embedded directly into the dam crest and extends to the top of the 84-inch riser as shown in Figures 4 and 5. Two 6-inch steel I-beams form the longitudinal

members and the decking is constructed with steel grating. Steel angles (2-inch by 2-inch) form railings. The entire structure is in need of painting.

The emergency spillway at Lower Mountain Lake has been constructed into natural material on the right end of the dam. The spillway appeared to have passed some flow prior to our inspection as shown in Photo 8. However, after discussions with Robert Messini, dam operator, it appears that the dam was lowered by constructing a trench in the spillway channel. The channel was then reworked to the condition shown in the photo. Also, as part of this work the riprap lining the left side of the spillway channel was removed. This riprap should be replaced.

d. Reservoir Area

The reservoir area of Lower Mountain Lake consists of 30 acres with the water level at elevation 774.0 feet MSL (top of riser). The combined reservoir area of Upper and Lower Mountain Lake is 60 acres at normal pool elevation.

e. Downstream Channel

The downstream channel consists of a natural streambed and is in good condition. There is no debris or overhanging vegetation in or near the channel. Directly below the dam, located in the discharge channel, is a system of infiltration galleries. This system withdraws water from under the discharge channel. A pump station to the right of the channel, directly below the dam, is used to transfer the water into a public water system. An adequate water level is maintained in the channel using a cofferdam as shown in Photo 7.

Further downstream the stream passes under the Lane Road and State Route 112 prior to joining the Wild Ammonoosuc River. There are no structures near the discharge channel prior to the confluence with the Wild Ammonoosuc.

3.2 Evaluation

Based on visual inspection, the dam appears to be in fair condition. Significant findings are as follows:

1. The small trees on the downstream slope could create a future seepage problem if they are allowed to grow without limit.
2. Trespassing on the slopes and the crest of the dam has produced minor local erosion.

3. Minor seepage was observed exiting downstream of the dam at several points. No evidence of soil transport was observed. The largest seep was next to a 24-inch pipe referred to in the drawings as "drain pipe" and which is a low-level outlet. This outlet is at the lowest point of the valley and thus the observed flow probably is due to the fact that this area corresponds also to the natural outlet for the blanket drain shown in the drawings.
4. The outlet structure appears to be functioning as designed. There was no debris near the outlet on the day of inspection.
5. Serious operating difficulties could be encountered in attempting to use the shear gate on the 24-inch drain pipe. The operator in attendance was not aware of the valve's existence or its operation. In addition to being easily forgotten should the dam change ownership, the valve could probably be closed only after the impoundment had been completely dewatered should this valve ever have to be opened.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures

The dam is not operated on a regular basis. No operational records exist.

4.2 Maintenance of the Dam

Little or no maintenance has been done on the dam or the appurtenant structures since construction. The grates over the 84-inch diameter riser should be replaced. The service bridge needs painting. Small trees growing on the slope should be cut.

4.3 Maintenance of the Operating Facilities

There is no maintenance provided.

4.4 Description of Any Warning System in Effect

There is no warning system in effect.

4.5 Evaluation

Semiannual cleaning of floatable debris in the impoundment should continue. The wet area below the 24-inch diameter low-level conduit should be checked periodically and flows recorded.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. General

The Lower Mountain Lake Dam is an earth embankment structure with a continuous impervious core wall and cutoff trench. The normal outlet structure is an 84-inch diameter pipe spillway; however, a 6-inch gate valve and/or a 24-inch low-level discharge conduit may be used to carry discharge as well as the emergency spillway.

b. Design Data

The spillway design flows were computed by the State of New Hampshire using the Kinnison-Colby formula. Their design computations for a 100-year flood had 222 CFS flowing through the riser and 678 CFS flowing over the emergency spillway for a total flood outflow of 900 CFS. Their computations are included in Appendix B.

c. Experience Data

There is no written record of overtopping at Lower Mountain Lake Dam. Mr. Robert Messini indicated the pipe spillway had handled all high flows since construction in 1968 without activating the emergency spillway. This indicates the Lake level has not risen above elevation 775.0.

d. Visual Observations

There was no evidence of overtopping at the Lower Mountain Lake Dam. The eroded area in the emergency spillway was described by Mr. Messini to have been disturbed by construction and not by high water levels.

e. Test Flood Analysis

Based on the U. S. Army Corps of Engineers criteria for a small, low-hazard dam, the 100-year frequency flood was selected as the test flood. Using the Soil Conservation Service engineering field manuals, the 100-year flood inflow is 1580 CFS (420 CSM). When routed through the Lower Mountain Lake Dam this results in a routed test flood outflow of 1242 CFS. At this flow the emergency spillway would be overtopped by 2.2 feet of water, but the water level would still be approximately .8 feet lower than the top of the dam.

f. Dam Failure Analysis

Upon dam failure under normal conditions with the water at elevation 774.0, a flow of approximately 13,000 CFS would result. However, under maximum water conditions with the level of water at elevation 778.0 a discharge of approximately 16,000 CFS would be released.

Either of these discharges pose no threat to human life as there are no homes near the channel downstream of the dam. Approximately .6 mile downstream the channel joins the Wild Ammonoosuc River, which would minimize the effects of a dam failure. The Wild Ammonoosuc River near Swiftwater, New Hampshire has a drainage of 57 square miles. The 100-year flood on this river would be approximately 20,000 CFS; hence the dam failure at Lower Mountain Lake would effectively create an event slightly less than a 100-year flood. There is little risk of damaging homes along the Wild Ammonoosuc as there is only one before this river reaches the Ammonoosuc. This home is judged to be about 30 feet above the river and is consequently safe from damage.

The only damage which may occur would be some erosion to New Hampshire State Route 112 as the flood wave could be two to three feet over the road in some low-lying locations.

SECTION 6 - STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

The visual inspection did not disclose any findings which would indicate instability of the foundation of the dam.

b. Design and Construction Data

Design Drawings Nos. 1 and 2 by Rollins, King and McKone, Inc., dated July 10, 1967, and revised May 5, 1968, (see Appendix B, Figures 1 and 2) were reviewed. The plans indicate that the dam was designed to have an impervious core, a cutoff trench extending down to impervious foundation material, and a horizontal coarse gravel drain blanket under the downstream shell of the dam. According to the plans, there is no exit pipe from the coarse gravel drain. Visual verification of these design features was not possible.

The left dike wall of the emergency spillway was constructed extending downstream perpendicular to the axis of the dam rather than curved, as shown on the design drawings. The left wall is also longer than as shown in the plans. Thus the emergency spillway discharge occurs farther downstream of the dam and consequently the riprap along the downstream toe of the dam was not placed.

c. Operating Records

There are no operating records.

d. Post-Construction Changes

There have been some past alterations performed at the emergency spillway which may warrant some additional study. A trench was dug into the emergency spillway in order to lower the dam below the outlet conduit. In addition, the riprap was removed from the left side of the spillway channel at the dam crest interface. If sufficient flows necessitated use of the spillway, these disturbed areas may erode.

e. Seismic Stability

The dam is in Seismic Zone 2 and in accordance with recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS/
REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition

Lower Mountain Lake Dam is considered to be in fair condition. Visual inspection indicates the dam appears to be basically constructed as shown in the design drawings (Appendix B, Figures 1 and 2).

There were several seepage areas located on the downstream face of the dam. The upstream face appears adequately protected with riprap. The normal outlet structure appears to be in acceptable condition with minor repairs as described in Section 7.2.

b. Adequacy of Information

The data available were sufficient to adequately assess the dam and appurtenant structures for a Phase I Investigation. Visual inspection substantiates that the available information is indicative of actual conditions.

c. Urgency

The recommendations given in Section 7.2 should be carried out within one year after receipt of this report.

d. Need for Additional Investigation

As this dam is a small low-hazard dam in fair condition, additional investigations would not be recommended.

7.2 Recommendations

A professional engineer qualified in the design of dams should be engaged to assess the following items:

1. The method of operation of the low-level outlet conduit is not suitable. If the shear gate were ever activated, it may not reseal until the water level dropped the entire 29 feet to allow a manual reseating of the gate. With a public water source immediately downstream, it becomes particularly important to provide a better means of level control.

- a. The shear gate should be replaced with 24-inch cast-iron gate valves.

- b. A service bridge or pier should be constructed to provide safe access to the gate valve.
2. The soils on the emergency spillway should be evaluated with respect to susceptibility to erode. This area has been disturbed by construction as described in Section 5.1.d. Based on this evaluation, specific protection recommendations could be formulated, if necessary.

7.3 Remedial Measures

a. Operation and Maintenance Procedures

The following items are recommended:

1. The small trees growing on the downstream face of the dam should be cut. This area as well as the dam crest should be kept free of such growth in the future.
2. The riprap which was removed from the left side of the emergency spillway should be replaced.
3. The flow exiting next to the 24-inch diameter low-level outlet conduit should be monitored and recorded on a bi-monthly basis.
4. A good grass cover should be maintained on the surface of the emergency spillway.
5. The dam and appurtenances should be inspected on an annual basis.
6. The existing service bridge to the outlet spillway needs painting and the grating on the outlet riser pipe needs replacing.

7.4 Alternatives

Not applicable.

APPENDIX A

VISUAL INSPECTION CHECK LIST

VISUAL INSPECTION CHECK LIST
PARTY ORGANIZATION

PROJECT LOWER MOUNTAIN LAKE DAM

DATE November 22, 1978

TIME 10:00 AM

WEATHER Cold, clear

W.S. ELEV. _____ U.S. _____ DN.S. _____

PARTY:

- | | | | |
|------------------------------------|------------------------|---------------------------|------------|
| 1. <u>Robert E. Dufresne</u> | <u>D-H</u> | 6. <u>Steve Whitehead</u> | <u>GFI</u> |
| 2. <u>James H. Maynes</u> | <u>D-H</u> | 7. <u>Gonzalo Castro</u> | <u>GFI</u> |
| 3. <u>Morris J. Root</u> | <u>D-H</u> | 8. _____ | _____ |
| 4. <u>Ken Stern, New Hampshire</u> | _____ | 9. _____ | _____ |
| | <u>Water Resources</u> | 10. _____ | _____ |
| 5. _____ | _____ | | |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

PERIODIC INSPECTION CHECK LIST

PROJECT LOWER MOUNTAIN LAKE DAM DATE November 20, 1975
 PROJECT FEATURE _____ NAME _____
 DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	
Current Pool Elevation	
Maximum Impoundment to Date	Approximately one foot below level of emergency overflow elevation.
Surface Cracks	Not observed.
Pavement Condition	Not applicable.
Movement or Settlement of Crest	Not observed.
Lateral Movement	Not observed.
Vertical Alignment	Apparently some low spots along crest (<.5').
Horizontal Alignment	Too irregular to judge
Condition at Abutment and at Concrete Structures	Erosion of soil at headwall on culvert downstream.
Indications of Movement of Structural Items on Slopes	Not applicable.
Trespassing on Slopes	Equipment tracks, bike paths observed.
Sloughing or Erosion of Slopes or Abutments	<u>Minor</u> downstream slope.
Rock Slope Protection - Riprap Failures	Riprap in good condition.
Unusual Movement or Cracking at or Near Toes	None observed.
Embankment or Downstream Seepage	Several locations described in text and located on plan (see Figure 1).
Piping or Boils	None observed.
Foundation Drainage Features	None known.
Toe drains	Operating - apparently.
Instrumentation System	None.
Vegetation	Young pine trees growing.

PERIODIC INSPECTION CHECK LIST

PROJECT LOWER MONTICELLI LAKE DAM

DATE November 2, 1978

PROJECT FEATURE _____

NAME _____

DISCIPLINE _____

NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Structural	
General Condition	Good - CMP riser.
Condition of Joints	Not applicable.
Spalling	Not applicable.
Visible Reinforcing	Not applicable.
Rusting or Staining of Concrete	Not applicable.
Any Seepage or Efflorescence	Not applicable.
Joint Alignment	Not applicable.
Seepage or Leaks in Gate Chamber	Gate valve port open - not seated.
Cracks	Not applicable.
Rusting or Corrosion of Steel	Not applicable.
b. Mechanical and Electrical	
Air Vents	None.
Float Wells	None.
Crane Hoist	None.
Elevator	None.
Hydraulic System	None.
Service Gates	6" Gate valve - handle removed.
Emergency Gates	None.
Lightning Protection System	None.
Emergency Power System	None.
Wiring and Lighting System in Gate Chamber	None.

PERIODIC INSPECTION CHECK LIST

PROJECT LOWER MOUNTAIN LAKE DAM

DATE November 20, 1979

PROJECT FEATURE _____

NAME _____

DISCIPLINE _____

NAME _____

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - TRANSITION AND CONCRETE</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining on Concrete</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Cracking</p> <p>Alignment of Monoliths</p> <p>Alignment of Joints</p> <p>Numbering of Monoliths</p>	<p>Headwall good.</p> <p>None.</p> <p>None.</p> <p>None.</p> <p>None.</p> <p>Not applicable.</p> <p>Not applicable.</p> <p>Not applicable.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT LOWER MOUNTAIN LAKE DAM

DATE November 20, 1978

PROJECT FEATURE _____

NAME _____

DISCIPLINE _____

NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	Very good.
Rust or Staining	None.
Spalling	None.
Erosion or Cavitation	None.
Visible Reinforcing	None - tie rods forming.
Any Seepage or Efflorescence	Not applicable.
Condition at Joints	Not applicable.
Drain Holes	None.
Chanel	
Loose Rock or Trees Overhanging Channel	Some trees overhang channel.
Condition of Discharge Channel	Small gravel dam downstream with approximately 2 feet of water standing in impoundment which forms infiltration gallery to a municipal water supply.

PERIODIC INSPECTION CHECK LIST

PROJECT UPPER MOUNTAIN LAKE DAM DATE November 20, 1978
 PROJECT FEATURE _____ NAME _____
 DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<p><u>EMERGENCY SPILLWAY - SPILLWAY WEIR</u> <u>APPROACH AND DISCHARGE CHANNELS</u></p>	
<p>a. Approach Channel General Condition Loose Rock Overhanging Channel Trees Overhanging Channel Floor of Approach Channel</p>	<p>Pond/lake (Upper Mountain Lake).</p>
<p>b. Weir and Training Walls General Condition of Concrete Rust or Staining Spalling Any Visible Reinforcing Any Seepage or Efflorescence Drain Holes</p>	<p>None. None. None. None. None. None. None.</p>
<p>c. Discharge Channel General Condition Loose Rock Overhanging Channel Trees Overhanging Channel Floor of Channel Other Obstructions</p>	<p>Apparent regrading on left side, removal of wall (riprap) to permit traffic on emergency spillway. None. None. Natural ground - disturbed by construction. Relatively free of brush.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT LOCH MOUNTAIN LANE DAM

DATE November 21, 1977

PROJECT FEATURE _____

NAME _____

DISCIPLINE _____

NAME _____

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p>	
<p>a. Approach Channel</p> <p style="padding-left: 20px;">Slope Conditions</p> <p style="padding-left: 20px;">Bottom Conditions</p> <p style="padding-left: 20px;">Rock Slides or Falls</p> <p style="padding-left: 20px;">Log Boom</p> <p style="padding-left: 20px;">Debris</p> <p style="padding-left: 20px;">Condition of Concrete Lining</p> <p style="padding-left: 20px;">Drains or Weep Holes</p>	<p>None</p>
<p>b. Intake Structure</p> <p style="padding-left: 20px;">Condition of Concrete</p> <p style="padding-left: 20px;">Stop Logs and Slots</p>	<p>5.0-foot diameter corrugated galvanized plate culvert set vertically, centered over outlet pipe.</p> <p>Top of culvert is fitted with steel grating. Entire structure was free of debris and in good condition</p>

PERIODIC INSPECTION CHECK LIST

PROJECT LOWEY MOUNTAIN LAKE DAM

DATE November 20, 1979

PROJECT FEATURE _____

NAME _____

DISCIPLINE _____

NAME _____

AREA EVALUATED	CONDITION
----------------	-----------

OUTLET WORKS - SERVICE BRIDGE

a. Super Structure

Bearings	Not applicable.
Anchor Bolts	Not applicable.
Bridge Seat	Resting on corrugated culvert.
Longitudinal Members	6" I-beam paint is chipped.
Under Side of Deck	Steel grate.
Secondary Bracing	Not applicable.
Deck	Steel grate (18-inch catwalk) is serviceable.
Drainage System	Not applicable.
Railings	Angles 1-1/2" x 1-1/2" bolted into longitudinal members.
Expansion Joints	Not applicable.
Paint	Should be painted.

b. Abutments and Piers

General Condition of Concrete	Anchored into soil in dam crest.
Alignment of Abutment	Not applicable.
Approach to Bridge	Not applicable.
Condition of Seat and Backwall	Dam crest.
	Not applicable.

PERIODIC INSPECTION CHECK LIST


PROJECT LOWER MOUNTAIN LAKE DAM DATE November 20, 1979

PROJECT FEATURE _____ NAME _____

DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
RESERVOIR	
Stability of Shoreline	Good. Riprap protection is adequate.
Sedimentation	Not apparent.
Changes in Watershed Runoff Potential	Minor development potential.
Upstream Hazards	1 House on upstream side of dam.
Downstream Hazards	Local road and state highway.
Alert Facilities	None.
Hydrometeorological Gages	None.
Operational and Maintenance Regulations	No written policy.
	a. Open valve when need water to maintain downstream flow for riparian owners.

APPENDIX F
PROJECT RECORDS AND PLANS







ELEVATION
 SECTION
 DETAIL





DETAIL
 CORNER FRAMING



SECTION
 DETAIL



SECTION
 DETAIL



SECTION
 DETAIL

ALL MATERIALS TO BE
 USED AS SHOWN ON DRAWING
 UNLESS OTHERWISE SPECIFIED

SECTION 1
SECTION 2
SECTION 3



SECTION 4
SECTION 5
SECTION 6



... ..
... ..
... ..

... ..
... ..
... ..
... ..
... ..

... ..
... ..
... ..

... ..

... ..
... ..
... ..
... ..


... ..

... ..


... ..
... ..
... ..

... ..
... ..
... ..
... ..

... ..



PLAN
SCALE 1/4" = 10'




CROSS SECTION
SCALE 1/4" = 10'

SECTION THROUGH DAM

SECTION

SECTION THROUGH DAM
SECTION

SECTION
SCALE 1/4" = 10'




CROSS SECTION
SCALE 1/4" = 10'

SECTION THROUGH DAM
SECTION

SECTION THROUGH DAM
SECTION

SECTION THROUGH DAM
SECTION

SECTION THROUGH DAM
SECTION




VERTICAL SCALE 1/4" = 10'


SECTION

SECTION THROUGH DAM
SECTION

SECTION THROUGH DAM
SECTION



SECTION A-A
SECTION B-B
SECTION C-C



SECTION A-A
SECTION B-B
SECTION C-C

SECTION A-A
SECTION B-B
SECTION C-C

SECTION A-A
SECTION B-B
SECTION C-C

March 8, 1967

Mr. Donald Blanchard
Foster Hill Road
Henniker, New Hampshire

Dear Don:

In reference to our conversation on March 6, 1967, I am enclosing the following data you requested on your Mountain Lake project:

- | | |
|-----------------------------|--------------|
| 1. Pond area (Proposed) | 30 Acres |
| 2. Drainage Area | 3.74 sq. mi. |
| 3. 15-year Frequency Storm | 310 cfs. |
| 4. 100-year Frequency Storm | 900 cfs. |

Due to the shape of this drainage area; long and narrow, the 15-year storm is not as large as I anticipated, usually 50% of the 100-year storm.

If you have any other questions regarding these flows, please let me know.

Very truly yours,

Vernon A. Knowlton
Civil Engineer

vak:c

3/7

Domine Area 3.74 Sq Miles = 11
 100' Area 80 Acres = 3.3333333333333333
 Average Area (S) 420' = 3
 Average Area

$$M^{.95} = \frac{0.57287}{.85} = \frac{2867.33}{5155.93} = 0.5563$$

1.50	x	4.5	4.50
1.50	x	3.5	3.50
.87	x	2.25	1.96
.87	x	.75	.65
3.74			10.61

$\frac{10.61}{3.74} = 2.84 \text{ miles} = L$

$$M^{.85} = \frac{0.57287}{.85} = \frac{2867.33}{4582.96} = 0.6256$$

$L^{0.7} = 0.45332 \times 17 = 0.31732 = 2.84$
 $L^{0.5} = 1.5 \times 2.2666 = 3.4$
 $S^{1.5} = 2.62325 = 3.93 + 3.3 = 7.23$
 $S^{2.4} = 2.11 = 6.29585 = 1.776$

$15\% = (0.000036 \times 2.84 + 12.4) \frac{M^{.95}}{C^{.7} L^{0.7}}$

$(36116^2 \times 1.976 \times 5^{16} + 12.4) \frac{3501}{1.067 \times 2.076} = 308 \text{ CFS}$
 $\frac{12.4}{71} = 0.1746$
 $195 \times 2.2501 = 568.77 + 2.215 = 308 \text{ CFS}$

$100\% = (0.394 \times 5^{15} + 20) \frac{M^{.85}}{L^{.5}}$

$(3.44 \times 10^6 \times 5667 \times 10^6 + 200) \frac{3.069}{1.065} = 1.321$

$\frac{296}{2.2} = 134.5$
 $99.6 \times 1.321 = 904 \text{ CFS}$

WAYNE

904 CFS

$\frac{S}{L} < \frac{1100}{\sqrt{1.1}}$
 $\frac{325}{2.34} < \frac{1100}{1.0488}$

FRANCO 102

0/1

Principal Spillway - No screens

$$3(2053 - 279 - 33) \sqrt{3} = Q = 222 \text{ cfs.}$$

$$9(1415) \sqrt{3}$$

$$\frac{222}{12 \sqrt{11}} = \frac{222}{39.3} = 5.6 \sqrt{11} \text{ on vertical skew}$$

"Vertical horiz. pipe

$$\frac{222}{6 \sqrt{11}} = \frac{222}{19.65} = 11.3 \text{ /sec av.}$$

Using $N = 0.021$, w/ 18.8' head on 6" pipe - flow = 255 cfs

Emergency Spillway Need 678 cfs flow

- width = 100'
- bed length = 75'
- bed slope = 0.80
- bed material $n = 0.055$
- head = 2'

678 cfs / 100' = 6.78 cfs/ft

$R_p = 1.48 \sqrt[1.49]{\frac{6.78}{0.055}} = 5.12$

$R_p = 1.815 \sqrt[1.49]{0.300} = 2.12$

Av. Velocity = $\frac{678}{2.12} = 3.2 \text{ /sec}$

If the 1"x2" mesh is used at principal spillway, the width of emergency spillway must be increased from 100' to 140'. However, it will mean this spillway may be needed nearly annually for considerable periods instead of for short times once in about 10 years.

At 1' head in princ. spillway, no flow in emergency spillway. The flow would be 50 cfs. or $1/2 \text{ cfs/ft}$.

$3 \times 16.55 =$

State of New Hampshire

WATER RESOURCES BOARD

37 Pleasant St.
CONCORD 03301

December 19, 1975

Town & Country Homes, Inc.
Mountain Lake
Haverhill, N. H.

Gentlemen:


Under the provisions of RSA-Chapter 482, Sections 8 through 15, the New Hampshire Water Resources Board is authorized to inspect all dams in the state which by reason of their physical condition, height, and location may be a menace to the public safety.

The dam structure (Dam # 112.12) located on your property in
Haverhill, N.H. was inspected on 7-25-74

and as a result of this inspection no discrepancies were found at the time of the inspection which would require any corrective measures.

This letter is provided for your information only. If you have any questions, please feel free to call or write.

Sincerely,



George H. McGee, Sr.
Chairman

GMM/SCB:L

cc: Board of Selectmen
Haverhill, N.H.

N. H. WATER RESOURCES BOARD
Concord, N. H. 03301

DAM SAFETY INSPECTION REPORT FORM

Name: Haverhill Dam Number: 11012

Inspected by: SCB Date: 25 July 1974

Local name of dam or water body: _____

Owner: Town & County Inc Address: _____

Owner was/was not interviewed during inspection.

Drainage Area: _____ sq. mi. Stream: _____

Flood Area: 501 Acre, Storage _____ Ac-Ft. Max. Head _____ Ft.

Foundation: Type Earth, Seepage present at toe - Yes/No, No

Spillway: Type Pipe & Flume, Freeboard over perm. crest: _____

Width 10' 100', Flashboard height _____

Max. Capacity _____ c.f.s.

Embankment: Type Earth, Cover Good Width 20

Upstream slope 3 to 1; Downstream slope 2 to 1

Abutments: Type _____, Condition: Good, Fair, Poor

Spillway or Road Drain: Size 2' x 23' Capacity _____ Type Pipe

Lifting apparatus _____ Operational condition Yes

Changes since construction or last inspection: _____

Downstream development: Homes Down stream

Is this dam/would/would not be a menace if it failed.

Scheduled reinspection date: _____

Remarks: Good Slope

DATE: July 25, 1969
FROM: Robert W. Livingston
Water Resources Engineer
SUBJECT: Mountain Lake Dam #112.12 - Haverhill
TO: Vernon A. Knowlton
Chief Water Resources Engineer

Received a call from Charlie Barry, Fish and Game Conservation Officer of N. Haverhill (787-6212) that persons downstream of said dam were complaining that only a trickle of water was flowing.

Contacted Mr. MacDonald who operates dam for Town and Country. He said he would be in contact with Barry.

RWL/jb

Phone complaint 7/30/69 Walter Moran

REAL ESTATE RESEARCH CORPORATION

4/12.09

July '66

Residential - Recreation Facility Complexes

1. Name of Development Mountain Lake
2. Location (community or nearest one and state) Bath, N. H.
3. Nearest Major Roadways (intersection) U.S. Rt. #302 at N.H. Rt. # 112
4 miles
4. Name, Address and Telephone Number of Developer Town & Country Homes,
Inc., N. H. Highway Hotel, Concord, N. H. 224-7757
5. Size of Development 300 acres: 300 lots
6. Size of Lake: 35 acres
7. Other facilities (golf course, marina, shops, etc.)
Community Center and Bath House
8. Year of Initial Sales 1966
9. Number of Lots and Homes Sold:
0 lots: 0 HOMES
10. Are lots still being sold in the developments? yes, no X

Source:

Name Town & Country Homes, Inc. office

Address _____

*Please use a separate sheet for each project

DATE December 19, 1968

FROM Francis C. Moore *FCM*

SUBJECT Inspection of Mountain Pond, Haverhill (#112.12)

TO Vernon A. Knowlton

On December 17, 1968, I inspected the completed Mountain Pond Dam, Constructed by Moulton Construction Co. of Lebanon for Town and Country Homes, Inc. The following report is made based upon observations with 18" snow on the ground:

- (1) Channel from principal spillway is 32' wide and not 40' wide as shown on the plan. However, as it carries only discharge from 60" culvert, it probably will cause no trouble.
- (2) Emergency spillway is 100' wide but the hillside edge of spillway is not on 100' radius but runs straight from pond. This may be a slight improvement.
- (3) Principal spillway discharge pipe is laid substantially to straight alignment.
- (4) There are many stumps in the pool area located several feet below normal full pond. These will undoubtedly cause problems around the principal spillway. However, they have an outer baffle two feet away from the principal spillway (ARMCO corrugated steel pipe - 7' in diameter): This baffle is 40" wide and extends about 12" below top of principal spillway and is ARMCO corrugated steel 11' in diameter. There are two 8" X 8" openings near the top of baffle in one quadrant. From the top of spillway to top of baffle, there is quarter inch hard ware cloth screening. No such screening covers the top of spillway. At present there are about three 4' X 6' concrete form panels on top of principal spillway.

Based upon ground conditions, it appears that this dam has been constructed essentially according to submitted specifications and with proper operation will create no menace.

FCM/jb

December 20, 1967

Town and Country Homes, Inc.
Highway Hotel
Concord, New Hampshire

Dear Sir:

We are in recent receipt of soil analysis information on your proposed dam across Waterman Brook in Haverhill, New Hampshire.

Examination of the information submitted leads us to conclude that if this material is properly placed it should produce satisfactory results.

The conditions referred to in our August 18, 1967 letter of approval having now been met, you may commence construction on this structure at your convenience.

Very truly yours,

George M. McGee, Sr.
Chairman

G:McG/WK:pm

NAME: Rollins, King & McKona

Sheet Number 1 of 1

TEST NO: 26712 JOB NAME: Mountain Lake Dam

DATE: Sept. 2


LIQUID AND PLASTIC LIMIT DETERMINATIONS DATA AND COMPUTATION SHEET

LL = LIQUID LIMIT TEST - %
 PL = PLASTIC LIMIT TEST - %
 PI = PLASTICITY INDEX - %
 FI = FLOW INDEX - %
 TI = TOUGHNESS INDEX - %

LIQUID LIMIT TEST	1	2	3	4	5	6
Spring Number						
Sample Number	#7	#7	#7			
Container Number	K-14	K-6	S-4			
Number of Blows	8	12	15			
wt. Sample + Tare Wet	55.57	55.49	45.13			
wt. Sample + Tare Dry	50.71	50.61	45.13			
wt. of Water	4.86	4.87	3.00			
Wet	30.87	30.77	30.81			
wt. of Dry Soil	19.84	20.04	14.32			
Water Content	24.5%	22.9%	20.9%			
Liquid Limit						

PLASTIC LIMIT TEST	1	2	3
Spring Number			
Sample Number			
Container Number	NOT OBTAINABLE		
wt. Sample + Tare Wet			
wt. Sample + Tare Dry			
wt. of Water			
Wet			
wt. of Dry Soil			
Water Content			
Plastic Limit			

FLOW CURVE



RESULTS


	1	2	3
LL	21.8%		
PL	-----		
PI	-----		
FI			
TI			
Remarks			

GRAIN SIZE DISTRIBUTION GRAPH - AGGREGATE GRADING CHART

Sample No. 7

Mountain Lake Dam

WET MECHANICAL ANALYSIS



TEST NUMBER	SAMPLE NUMBER	NATURAL & MOISTURE	WL	WP	LP	CLASSIFICATION	REMARKS
PLOTTED BY (Signature)							
CHECKED BY (Signature)							

GRAVE ANALYSIS
 DATA AND COMPUTATION SHEET
 NO. OF SAMPLE & TARE 1074.3 gm.

BOWLING NO. _____

SAMPLE NO. 47

WT. OF TARE 271.5 gm. (TARE NO. 2.12)

DEPTH _____

WT. OF SAMPLE 1074.3 gm.

LOCATION _____

U. S. BUREAU OF STANDARDS SIEVE OPENINGS			WEIGHT RETAINED IN GRAMS	PERCENT RETAINED	CUMULATIVE PERCENT FINER	REMARKS
INCHES	MILLI- METERS	SIEVE MESH				
1.0000	25.400					
0.7500	19.100					
0.5000	12.700					
0.3750	9.520		126.7	12.5%	87.5%	
0.2500	6.350	3				
0.1875	4.750	4	50.7	5.0%	92.5%	
0.1500	3.810	6				
0.1250	3.180	8				
0.0937	2.380	10	62.0	6.3%	98.8%	
0.0750	1.900	12				
0.0625	1.580	15				
0.0500	1.270	20				
0.0375	0.950	30	100.1	9.8%	99.0%	100%
0.0312	0.790	40				
0.0250	0.630	50	100.1	10.2%	100.0%	100%
0.0200	0.500	60				
0.0150	0.380	70				
0.0118	0.300	80				
0.0094	0.240	100	72.5	7.2%	100.0%	100%
0.0075	0.190	150	10.2	1.0%	100.0%	100%
0.0060	0.150	200	60.2	6.0%	100.0%	
0.0048	0.120	270				
		300	250.0	25.0%	100.0%	
TOTAL			1074.3	100.0%		

SOIL COMPACTED IN MOLD @ 100% STANDARD PROCTER

DRY DENSITY = 1206 lb/ft^3
WATER CONTENT = 8.25%

MOLD

DIAM = 10.16 cm HEAD LOSS = 76.2 cm
AREA = 81.1 cm²
HEIGHT = 11.63 cm

PERMEABILITY

TEST	TIME	QUANTITY	k
1	70 MIN.	30.4 cc.	1.06×10^{-5}
2	75 MIN.	27.8 cc.	1.11×10^{-5}
3	150 MIN.	52.0 cc.	1.09×10^{-5}

Name: Quincy - Ind. 200Sample Identification: Quincy No. 3Date: Aug 10, 1947Sheet Number: 22-1

STANDARD COMPACTION

25 blows on each of 3 layers with 5.0 -lb hammer, 12 -in drop.

Cylinder diameter (in.)		Initial wt. of soil, W_0 (lbs.)	
" height (in.)		" water content, w_0	
" volume, V (in. ³)		" wt. of solids, W_{so} (lbs.)	
" constant, $C = \frac{1}{V}$	1/30	" " " water, W_{wo} (lbs.)	
Specific gravity of solids, S			

DATA FOR CURVES

Sample No.	1	2	3	4	5	6
Desired water content (%)						
Desired wt. of water (lbs.)						
Vol. of water added (c.c.)						
Wt. of cyl. - soil, W_c (lbs.)	10.12	10.50	10.70	10.44	10.37	10.27
" " " , W_c (lbs.)	6.17	6.15	6.15	6.15	6.15	6.15
" " soil, W_s (lbs.)	3.95	4.35	4.55	4.29	4.22	4.12
Average water content, w (%)	2.37	3.61	6.24	9.74	12.90	16.20
Point Density, ρ_p (lbs./ft. ³)	119.1	122.5	127.5	131.7	132.6	134.1
Dry density, ρ_d (dry) (lbs./ft. ³)	116.7	117.8	119.8	120.1	117.6	115.9
Void ratio, e						
Degree of saturation, G (%)						
Sat. density, ρ_{sat} (sat.) (lbs./ft. ³)						
" water content, w (sat.) (%)						

WATER CONTENTS

Sample No.	1	2	3	4	5	6
Container No.	C-13	X-24	K-13	R-4	P-16	G-10
Tare + wet soil (grams)	57.43	73.33	76.04	91.40	68.62	91.7
" + dry " (grams)	55.13	71.90	73.99	87.90	62.47	83.0
Vt. of water (grams)	2.30	1.43	2.05	3.50	6.15	7.7
Tare (grams)	30.53	30.61	30.17	30.31	30.91	30.9
Vt. of dry soil (grams)	55.65	41.03	43.32	57.70	51.55	52.0
Water content, w (%)	2.34	3.50	6.23	10.00	11.90	14.8
Container No.	H-16	Q-20	T-10	S-4	U-5	V-7
Tare + wet soil (grams)	77.27	63.12	73.69	73.17	69.3	107.0
" + dry " (grams)	74.73	61.90	71.90	71.20	64.20	97.0
Vt. of water (grams)	2.54	2.22	2.79	2.07	5.07	10.0
Tare (grams)	30.23	31.00	31.11	30.71	30.20	30.0
Vt. of dry soil (grams)	44.50	30.90	40.79	40.49	34.00	67.0

Name: William G. Nelson, Jr.

Sheet Number: 1

JOB NO.: S6712 JOB NAME: Mountain Lake Dam

DATE: Sept 67


LIQUID AND PLASTIC LIMIT DETERMINATIONS
DATA AND COMPUTATION SHEET

LL = LIQUID LIMIT TEST
PL = PLASTIC LIMIT TEST
PI = PLASTICITY INDEX
FI = FLOW INDEX - 5
TI = TOUGHNESS INDEX

LIQUID LIMIT TEST	1	2	3	4	5	6
Boring Number						
Sample Number	#3	#3	#3			
Container Number	K-20	S-12	D-13			
Number of Blows	9	32	13			
Wt. Sample + Tare Wet	53.93	51.82	51.12			
Wt. Sample + Tare Dry	49.51	47.51	47.53			
Wt. of Water	4.42	4.31	3.59			
Tare	31.08	30.69	31.00			
Wt. of Dry Soil	18.43	16.82	16.53			
Water Content	21.9%	19.9%	20.3%			
Liquid Limit						

PLASTIC LIMIT TEST	1	2	3
Boring Number			
Sample Number			
Container Number	NOT OBTAINABLE		
Wt. Sample + Tare Wet			
Wt. Sample + Tare Dry			
Wt. of Water			
Tare			
Wt. of Dry Soil			
Water Content			
Plastic Limit			

FLOW CURVE



RESULTS


	1	2	3
LL	20.1%		
PL	---		
PI	---		
FI			
TI			

DRY DENSITY IN 100/111

115 117 118 119 120 121 122

MAX DRY DENSITY = 120.6 lb/ft³

OPTIMUM WATER CONTENT = 8.25%



NAME _____

DATE Sept. 29, 1957 JOB NO _____

85712

SIEVE ANALYSIS
DATA AND COMPUTATION SHEET

BORING NO _____

WT OF SAMPLE + TARE 1319.0 GM.

SAMPLE NO #3

WT OF TARE 371.5 GM. (TARE NO D-13)

DEPTH _____

WT OF SAMPLE 947.5 GM.

LOCATION _____

U. S. BUREAU OF STANDARDS			WEIGHT RETAINED IN GRAMS	PERCENT RETAINED	CUMULATIVE PERCENT FINER	REMARKS
SIEVE OPENINGS		SIEVE MESH				
INCHES	MILLI- METERS					
1.0000	25.400					
0.7500	19.100					
0.5000	12.700					
0.3750	9.520		207.5	21.9%	73.1%	
0.2500	6.350	3				
0.1875	4.760	4	53.0	5.6%	72.5%	
0.1500	3.810	6				
0.1250	3.175	8				
0.1000	2.540	10	62.0	6.5%	66.0%	
0.0750	1.905	12				
0.0625	1.588	16				
0.0500	1.270	20				
0.0375	0.953	30	112.0	11.8%	51.2%	
0.0300	0.762	40				
0.0250	0.635	50	85.0	9.0%	45.2%	
0.0200	0.508	60				
0.0150	0.381	70				
0.0125	0.318	100	61.0	6.4%	33.8%	
0.0100	0.254	120	49.5	5.2%	33.6%	
0.0075	0.190	180	53.5	5.6%	27.7%	
0.0060	0.152	270				
		PAI	262.0	27.7%		
PASSED						
MESH SIEVE						
			61.0			


GRAIN SIZE DISTRIBUTION GRAPH - AGGREGATE GRADING CHART

DATE Sept. 20, 1957


MAXIMUM SIZE (mm) 20

CONCRETE NO. 3

TEST METHOD



PET MECHANICAL ANALYSIS



GRAIN SIZE IN MILLIMETERS

EVOLUTION NUMBER	SAMPLE NUMBER	NATURAL MOISTURE	WL	Wp	Ip	CLASSIFICATION	REMARKS

TEST METHOD (If different)

DATE TESTED


SUMMARY OF TEST RESULTS

Test	Sample Number 3	Sample Number 7
Sieve	Passing 200 27.7%	Passing 200 42.0%
Liquid Limit	20.1%	21.8%
Plastic limit	NONE	NONE
Maximum Dry Density at	120.6 #/ft ³	Not obtained
Optimum Water Content	3.25%	
Permeability	Average of three tests - 1.09×10^{-5}	

APPENDIX C

PHOTOGRAPHS

1. Identification Sign at Lake Site.
2. Dam Crest. Note Upstream Riprap and Right Dam Abutment.
3. Dam Crest. Note Access Road and Left Abutment.
4. Outlet Structure, Trash Guard and Service Bridge.
5. Service Bridge and Trash Guard.
6. Outlet Conduit Headwall.
7. Dam Outlet and Impoundment Over Infiltration Lines.
8. Emergency Spillway Area. Note Washed Area.
9. View of Downstream Slope of Dam. Note Initial Stages of Forestation.
10. Seep Noted on Downstream Toe Location Described in Figure 1.
11. Pump Station Located Downstream of the Dam.
12. Seepage Zone 15 Feet Left of Left Outlet Structure Wall.
13. Seepage Zone at End of Right Outlet Structure Wall.
14. High Natural Ground and Seepage Zone 30 Feet Downstream of Downstream Toe (Seepage Area is Near Person.)
15. Seepage Around and From 24-Inch Low-Level Outlet. Note Iron Staining and Oil-Like Surface.
16. Seepage Around and From 24-Inch Diameter Pipe.
17. Close-up of Erosion Around Large Stones Placed Around Exit Pipe.






100
100
100




100
100
100



43. View of road leading to
the site.




44. Large barrel at site.



View of the bridge from the north



View of the forest from the north













11. A view of the rock formation at the base of the cliff.

DUPRESNE-HENRY ENGINEERING CORPORATION

BY *[Signature]*
DATE *[Date]*

SUBJECT *[Subject]*
[Additional subject notes]

SHEET NO. *[Number]* OF *[Total]*
JOB NO. *[Job Number]*

[Faint handwritten notes]

DUFRESNE-HENRY ENGINEERING CORPORATION

BY W.A. LEONARD
DATE 3-13-79


SUBJECT MOUNTAIN LAKE (HAVERHILL)
STAGE-D SCHMIDT GAGE

SHEET NO. 3 OF 6
JOB NO. 89-0030

TOP OF DAM 778.0
SPILLWAY ELEV. 777.0
TOP OF RISER 774.0


84" DIAMETER PIPE


Q = 0.0177 h^{3/2}
Q = 0.0177 (778.0 - 777.0)^{3/2} = 0.0177
Q = 0.0177 (777.0 - 777.0)^{3/2} = 0.0000
Q = 0.0177 (776.0 - 777.0)^{3/2} = 0.0000
Q = 0.0177 (775.0 - 777.0)^{3/2} = 0.0000



NOTE: FLOW INTO 84" PIPE (WEIR FLOW)
CONTROLS UP TO ELEV. 777.1

EL.	h (777')	Q INTO 84"	h (ARISE 755.7)		Q INTO 60"	Q OVER SPILLWAY		Q TOT
			ft	ft				
774	0	0			0			0
776	1	73.3	19.3	3.86	390			73.3
776	2	207	20.3	4.06	410	1	1007	459
777	3	381	21.3	4.26	430	2	2027	1098
778	4	586	22.3	4.46	440	3	306	1765





DUPRESNE-HENRY ENGINEERING CORPORATION


BY W. H. ...
 DATE ...

SUBJECT ...

SHEET NO. ... OF ...
 JOB NO. ...

TOP OF DAM 1118.0
 CENTERLINE ELEV. 777.0
 TOP OF CURB 1114.0


90" DIAMETER PIPE



NOTE: FLOW INTO 90" PIPE (WEIR FLOW)
 CONTROLS UP TO ELEV. 777.1

STATION	ELEVATION	Q		...
		
1	1
2	2
3	3
4





DUFRESNE-HENRY ENGINEERING CORPORATION

BY W. H. ...
DATE ...

SUBJECT ...

SHEET NO. ... OF ...
JOB NO. ...

1.15. DATA: ...

$$Q = \dots$$

$$Q = \dots = \underline{\underline{12,500 \text{ cfs}}}$$

1.2. DATA: ...

$$Q = \dots$$

$$Q = \dots = \underline{\underline{12,959 \text{ cfs}}}$$

Assume ...

... by ...

$$\text{critical depth } V = \sqrt{g d_m^3}$$

$$\text{Assume } d_m = 10'$$

$$V = 13.4 \text{ fps}$$

$$Q = AV = (30 \times 75) \times 13.4 = 30,150 \text{ cfs}$$

... 16 feet

... 10 feet

...

DURELL-HILBY ENGINEERING CORPORATION

BY
DATE


SUBJECT

SHEET NO. OF
JOB NO.


ANALYSIS OF

ITEM	DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				
37				
38				
39				
40				
41				
42				
43				
44				
45				
46				
47				
48				
49				
50				
51				
52				
53				
54				
55				
56				
57				
58				
59				
60				
61				
62				
63				
64				
65				
66				
67				
68				
69				
70				
71				
72				
73				
74				
75				
76				
77				
78				
79				
80				
81				
82				
83				
84				
85				
86				
87				
88				
89				
90				
91				
92				
93				
94				
95				
96				
97				
98				
99				
100				

STAGE CHANGE SCHEMATIC AND DETAILED



STAGE CHANGE
400



 15 JUL 1968 10:00 AM
 10-1000-10
 10-1000-10

MOUNTAIN LAKE
 HAZENHILL NEW HAMPSHIRE
 10-1000-10 TEST REPORT RESULTS

JOB SPECIFICATION
 NO. NAME GAIN UNIT TIME TIME RETIME INCT INPT NSTAT
 144 0 10 1 0 0 0 2 0 0
 JOPER NAT
 3 0

SUMMARY JOB SPECIFICATION

APPROXIMATE VALUES OF SIGNAL DATA
 TOTAL SIGNAL LOSS TIME JPK1 JPK2 INAME
 1 0 0 0 0 1

METEOROGRAPH DATA
 TIME 1110 1115 1120 1125 1130 1135 1140 1145 1150 1155 1200
 1 1 3.78 0.0 0.0 1.00 0.140 0 0 LOCAL 0

PRECIP DATA
 WIND FM RAIN WIND WIND WIND WIND WIND WIND WIND WIND WIND
 0.0 17.00 111.00 173.00 133.00 0.0 0.0 0.0

LOSS DATA
 SIGNAL LOSS TIME
 0.0 0.0 1.00 0.0 0.0 1.00 0.00 0.12 0.0 0.0


UNIT TIME GRAPH DATA
 TRF 1.50 1000.75 NAT 0

RECESS DATA

SIGNAL 7.50 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
 APPROXIMATE LOSS VALUES FROM UNIT SYSTEM OF ANY IN THE PERIODS AND SP 0.05 INTERVALS

UNIT	TIME	LOSS								
1	0.00	0.00	1.00	0.00	2.00	0.00	3.00	0.00	4.00	0.00
1	0.05	0.05	1.05	0.05	2.05	0.05	3.05	0.05	4.05	0.05
1	0.10	0.10	1.10	0.10	2.10	0.10	3.10	0.10	4.10	0.10
1	0.15	0.15	1.15	0.15	2.15	0.15	3.15	0.15	4.15	0.15
1	0.20	0.20	1.20	0.20	2.20	0.20	3.20	0.20	4.20	0.20
1	0.25	0.25	1.25	0.25	2.25	0.25	3.25	0.25	4.25	0.25
1	0.30	0.30	1.30	0.30	2.30	0.30	3.30	0.30	4.30	0.30
1	0.35	0.35	1.35	0.35	2.35	0.35	3.35	0.35	4.35	0.35
1	0.40	0.40	1.40	0.40	2.40	0.40	3.40	0.40	4.40	0.40
1	0.45	0.45	1.45	0.45	2.45	0.45	3.45	0.45	4.45	0.45
1	0.50	0.50	1.50	0.50	2.50	0.50	3.50	0.50	4.50	0.50
1	0.55	0.55	1.55	0.55	2.55	0.55	3.55	0.55	4.55	0.55
1	0.60	0.60	1.60	0.60	2.60	0.60	3.60	0.60	4.60	0.60
1	0.65	0.65	1.65	0.65	2.65	0.65	3.65	0.65	4.65	0.65
1	0.70	0.70	1.70	0.70	2.70	0.70	3.70	0.70	4.70	0.70
1	0.75	0.75	1.75	0.75	2.75	0.75	3.75	0.75	4.75	0.75
1	0.80	0.80	1.80	0.80	2.80	0.80	3.80	0.80	4.80	0.80
1	0.85	0.85	1.85	0.85	2.85	0.85	3.85	0.85	4.85	0.85
1	0.90	0.90	1.90	0.90	2.90	0.90	3.90	0.90	4.90	0.90
1	0.95	0.95	1.95	0.95	2.95	0.95	3.95	0.95	4.95	0.95
1	1.00	1.00	2.00	1.00	3.00	1.00	4.00	1.00	5.00	1.00
1	1.05	1.05	2.05	1.05	3.05	1.05	4.05	1.05	5.05	1.05
1	1.10	1.10	2.10	1.10	3.10	1.10	4.10	1.10	5.10	1.10
1	1.15	1.15	2.15	1.15	3.15	1.15	4.15	1.15	5.15	1.15
1	1.20	1.20	2.20	1.20	3.20	1.20	4.20	1.20	5.20	1.20
1	1.25	1.25	2.25	1.25	3.25	1.25	4.25	1.25	5.25	1.25
1	1.30	1.30	2.30	1.30	3.30	1.30	4.30	1.30	5.30	1.30
1	1.35	1.35	2.35	1.35	3.35	1.35	4.35	1.35	5.35	1.35
1	1.40	1.40	2.40	1.40	3.40	1.40	4.40	1.40	5.40	1.40
1	1.45	1.45	2.45	1.45	3.45	1.45	4.45	1.45	5.45	1.45
1	1.50	1.50	2.50	1.50	3.50	1.50	4.50	1.50	5.50	1.50
1	1.55	1.55	2.55	1.55	3.55	1.55	4.55	1.55	5.55	1.55
1	1.60	1.60	2.60	1.60	3.60	1.60	4.60	1.60	5.60	1.60
1	1.65	1.65	2.65	1.65	3.65	1.65	4.65	1.65	5.65	1.65
1	1.70	1.70	2.70	1.70	3.70	1.70	4.70	1.70	5.70	1.70
1	1.75	1.75	2.75	1.75	3.75	1.75	4.75	1.75	5.75	1.75
1	1.80	1.80	2.80	1.80	3.80	1.80	4.80	1.80	5.80	1.80
1	1.85	1.85	2.85	1.85	3.85	1.85	4.85	1.85	5.85	1.85
1	1.90	1.90	2.90	1.90	3.90	1.90	4.90	1.90	5.90	1.90
1	1.95	1.95	2.95	1.95	3.95	1.95	4.95	1.95	5.95	1.95
1	2.00	2.00	3.00	2.00	4.00	2.00	5.00	2.00	6.00	2.00
1	2.05	2.05	3.05	2.05	4.05	2.05	5.05	2.05	6.05	2.05
1	2.10	2.10	3.10	2.10	4.10	2.10	5.10	2.10	6.10	2.10
1	2.15	2.15	3.15	2.15	4.15	2.15	5.15	2.15	6.15	2.15
1	2.20	2.20	3.20	2.20	4.20	2.20	5.20	2.20	6.20	2.20
1	2.25	2.25	3.25	2.25	4.25	2.25	5.25	2.25	6.25	2.25
1	2.30	2.30	3.30	2.30	4.30	2.30	5.30	2.30	6.30	2.30
1	2.35	2.35	3.35	2.35	4.35	2.35	5.35	2.35	6.35	2.35
1	2.40	2.40	3.40	2.40	4.40	2.40	5.40	2.40	6.40	2.40
1	2.45	2.45	3.45	2.45	4.45	2.45	5.45	2.45	6.45	2.45
1	2.50	2.50	3.50	2.50	4.50	2.50	5.50	2.50	6.50	2.50
1	2.55	2.55	3.55	2.55	4.55	2.55	5.55	2.55	6.55	2.55
1	2.60	2.60	3.60	2.60	4.60	2.60	5.60	2.60	6.60	2.60
1	2.65	2.65	3.65	2.65	4.65	2.65	5.65	2.65	6.65	2.65
1	2.70	2.70	3.70	2.70	4.70	2.70	5.70	2.70	6.70	2.70
1	2.75	2.75	3.75	2.75	4.75	2.75	5.75	2.75	6.75	2.75
1	2.80	2.80	3.80	2.80	4.80	2.80	5.80	2.80	6.80	2.80
1	2.85	2.85	3.85	2.85	4.85	2.85	5.85	2.85	6.85	2.85
1	2.90	2.90	3.90	2.90	4.90	2.90	5.90	2.90	6.90	2.90
1	2.95	2.95	3.95	2.95	4.95	2.95	5.95	2.95	6.95	2.95
1	3.00	3.00	4.00	3.00	5.00	3.00	6.00	3.00	7.00	3.00
1	3.05	3.05	4.05	3.05	5.05	3.05	6.05	3.05	7.05	3.05
1	3.10	3.10	4.10	3.10	5.10	3.10	6.10	3.10	7.10	3.10
1	3.15	3.15	4.15	3.15	5.15	3.15	6.15	3.15	7.15	3.15
1	3.20	3.20	4.20	3.20	5.20	3.20	6.20	3.20	7.20	3.20
1	3.25	3.25	4.25	3.25	5.25	3.25	6.25	3.25	7.25	3.25
1	3.30	3.30	4.30	3.30	5.30	3.30	6.30	3.30	7.30	3.30
1	3.35	3.35	4.35	3.35	5.35	3.35	6.35	3.35	7.35	3.35
1	3.40	3.40	4.40	3.40	5.40	3.40	6.40	3.40	7.40	3.40
1	3.45	3.45	4.45	3.45	5.45	3.45	6.45	3.45	7.45	3.45
1	3.50	3.50	4.50	3.50	5.50	3.50	6.50	3.50	7.50	3.50
1	3.55	3.55	4.55	3.55	5.55	3.55	6.55	3.55	7.55	3.55
1	3.60	3.60	4.60	3.60	5.60	3.60	6.60	3.60	7.60	3.60
1	3.65	3.65	4.65	3.65	5.65	3.65	6.65	3.65	7.65	3.65
1	3.70	3.70	4.70	3.70	5.70	3.70	6.70	3.70	7.70	3.70
1	3.75	3.75	4.75	3.75	5.75	3.75	6.75	3.75	7.75	3.75
1	3.80	3.80	4.80	3.80	5.80	3.80	6.80	3.80	7.80	3.80
1	3.85	3.85	4.85	3.85	5.85	3.85	6.85	3.85	7.85	3.85
1	3.90	3.90	4.90	3.90	5.90	3.90	6.90	3.90	7.90	3.90
1	3.95	3.95	4.95	3.95	5.95	3.95	6.95	3.95	7.95	3.95
1	4.00	4.00	5.00	4.00	6.00	4.00	7.00	4.00	8.00	4.00
1	4.05	4.05	5.05	4.05	6.05	4.05	7.05	4.05	8.05	4.05
1	4.10	4.10	5.10	4.10	6.10	4.10	7.10	4.10	8.10	4.10
1	4.15	4.15	5.15	4.15	6.15	4.15	7.15	4.15	8.15	4.15
1	4.20	4.20	5.20	4.20	6.20	4.20	7.20	4.20	8.20	4.20
1	4.25	4.25	5.25	4.25	6.25	4.25	7.25	4.25	8.25	4.25
1	4.30	4.30	5.30	4.30	6.30	4.30	7.30	4.30	8.30	4.30
1	4.35	4.35	5.35	4.35	6.35	4.35	7.35	4.35	8.35	4.35
1	4.40	4.40	5.40	4.40	6.40	4.40	7.40	4.40	8.40	4.40
1	4.45	4.45	5.45	4.45	6.45	4.45	7.45	4.45	8.45	4.45
1	4.50	4.50	5.50	4.50	6.50	4.50	7.50	4.50	8.50	4.50
1	4.55	4.55	5.55	4.55	6.55	4.55	7.55	4.55	8.55	4.55
1	4.60	4.60	5.60	4.60	6.60	4.60	7.60	4.60	8.60	4.60
1	4.65	4.65	5.65	4.65	6.65	4.65	7.65	4.65	8.65	4.65
1	4.70	4.70	5.70	4.70	6.70	4.70	7.70	4.70	8.70	4.70
1	4.75	4.75	5.75	4.75	6.75	4.75	7.75	4.75	8.75	4.75
1	4.80	4.80	5.80	4.80	6.80	4.80	7.80	4.80	8.80	4.80
1	4.85	4.85	5.85	4.85	6.85	4.85	7.85	4.85	8.85	4.85
1	4.90	4.90	5.90	4.90	6.90	4.90	7.90	4.90	8.90	4.90

1 7 15	0.05	0.05	183.
1 7 20	0.05	0.05	187.
1 7 25	0.05	0.05	191.
1 7 30	0.05	0.05	195.
1 7 35	0.05	0.05	199.
1 7 40	0.05	0.05	203.
1 7 45	0.05	0.05	207.
1 7 50	0.05	0.05	211.
1 7 55	0.05	0.05	215.
1 8 00	0.05	0.05	219.
1 8 05	0.05	0.05	223.
1 8 10	0.05	0.05	227.
1 8 15	0.05	0.05	231.
1 8 20	0.05	0.05	235.
1 8 25	0.05	0.05	239.
1 8 30	0.05	0.05	243.
1 8 35	0.05	0.05	247.
1 8 40	0.05	0.05	251.
1 8 45	0.05	0.05	255.
1 8 50	0.05	0.05	259.
1 8 55	0.05	0.05	263.
1 9 00	0.05	0.05	267.
1 9 05	0.05	0.05	271.
1 9 10	0.05	0.05	275.
1 9 15	0.05	0.05	279.
1 9 20	0.05	0.05	283.
1 9 25	0.05	0.05	287.
1 9 30	0.05	0.05	291.
1 9 35	0.05	0.05	295.
1 9 40	0.05	0.05	299.
1 9 45	0.05	0.05	303.
1 9 50	0.05	0.05	307.
1 9 55	0.05	0.05	311.
1 10 00	0.05	0.05	315.
1 10 05	0.05	0.05	319.
1 10 10	0.05	0.05	323.
1 10 15	0.05	0.05	327.
1 10 20	0.05	0.05	331.
1 10 25	0.05	0.05	335.
1 10 30	0.05	0.05	339.
1 10 35	0.05	0.05	343.
1 10 40	0.05	0.05	347.
1 10 45	0.05	0.05	351.
1 10 50	0.05	0.05	355.
1 10 55	0.05	0.05	359.
1 11 00	0.05	0.05	363.
1 11 05	0.05	0.05	367.
1 11 10	0.05	0.05	371.
1 11 15	0.05	0.05	375.
1 11 20	0.05	0.05	379.
1 11 25	0.05	0.05	383.
1 11 30	0.05	0.05	387.
1 11 35	0.05	0.05	391.
1 11 40	0.05	0.05	395.
1 11 45	0.05	0.05	399.
1 11 50	0.05	0.05	403.
1 11 55	0.05	0.05	407.
1 12 00	0.05	0.05	411.
1 12 05	0.05	0.05	415.
1 12 10	0.05	0.05	419.
1 12 15	0.05	0.05	423.
1 12 20	0.05	0.05	427.
1 12 25	0.05	0.05	431.
1 12 30	0.05	0.05	435.
1 12 35	0.05	0.05	439.
1 12 40	0.05	0.05	443.
1 12 45	0.05	0.05	447.
1 12 50	0.05	0.05	451.
1 12 55	0.05	0.05	455.
1 13 00	0.05	0.05	459.
1 13 05	0.05	0.05	463.
1 13 10	0.05	0.05	467.
1 13 15	0.05	0.05	471.
1 13 20	0.05	0.05	475.
1 13 25	0.05	0.05	479.
1 13 30	0.05	0.05	483.
1 13 35	0.05	0.05	487.
1 13 40	0.05	0.05	491.
1 13 45	0.05	0.05	495.
1 13 50	0.05	0.05	499.
1 13 55	0.05	0.05	503.
1 14 00	0.05	0.05	507.
1 14 05	0.05	0.05	511.
1 14 10	0.05	0.05	515.
1 14 15	0.05	0.05	519.
1 14 20	0.05	0.05	523.
1 14 25	0.05	0.05	527.
1 14 30	0.05	0.05	531.
1 14 35	0.05	0.05	535.
1 14 40	0.05	0.05	539.
1 14 45	0.05	0.05	543.
1 14 50	0.05	0.05	547.
1 14 55	0.05	0.05	551.
1 15 00	0.05	0.05	555.
1 15 05	0.05	0.05	559.
1 15 10	0.05	0.05	563.
1 15 15	0.05	0.05	567.
1 15 20	0.05	0.05	571.
1 15 25	0.05	0.05	575.
1 15 30	0.05	0.05	579.
1 15 35	0.05	0.05	583.
1 15 40	0.05	0.05	587.
1 15 45	0.05	0.05	591.
1 15 50	0.05	0.05	595.
1 15 55	0.05	0.05	599.
1 16 00	0.05	0.05	603.
1 16 05	0.05	0.05	607.
1 16 10	0.05	0.05	611.
1 16 15	0.05	0.05	615.
1 16 20	0.05	0.05	619.
1 16 25	0.05	0.05	623.
1 16 30	0.05	0.05	627.
1 16 35	0.05	0.05	631.
1 16 40	0.05	0.05	635.
1 16 45	0.05	0.05	639.
1 16 50	0.05	0.05	643.
1 16 55	0.05	0.05	647.
1 17 00	0.05	0.05	651.
1 17 05	0.05	0.05	655.
1 17 10	0.05	0.05	659.
1 17 15	0.05	0.05	663.
1 17 20	0.05	0.05	667.
1 17 25	0.05	0.05	671.
1 17 30	0.05	0.05	675.
1 17 35	0.05	0.05	679.
1 17 40	0.05	0.05	683.
1 17 45	0.05	0.05	687.
1 17 50	0.05	0.05	691.
1 17 55	0.05	0.05	695.
1 18 00	0.05	0.05	699.
1 18 05	0.05	0.05	703.
1 18 10	0.05	0.05	707.
1 18 15	0.05	0.05	711.
1 18 20	0.05	0.05	715.
1 18 25	0.05	0.05	719.
1 18 30	0.05	0.05	723.
1 18 35	0.05	0.05	727.
1 18 40	0.05	0.05	731.
1 18 45	0.05	0.05	735.
1 18 50	0.05	0.05	739.
1 18 55	0.05	0.05	743.
1 19 00	0.05	0.05	747.
1 19 05	0.05	0.05	751.
1 19 10	0.05	0.05	755.
1 19 15	0.05	0.05	759.
1 19 20	0.05	0.05	763.
1 19 25	0.05	0.05	767.
1 19 30	0.05	0.05	771.
1 19 35	0.05	0.05	775.
1 19 40	0.05	0.05	779.
1 19 45	0.05	0.05	783.
1 19 50	0.05	0.05	787.
1 19 55	0.05	0.05	791.
1 20 00	0.05	0.05	795.
1 20 05	0.05	0.05	799.
1 20 10	0.05	0.05	803.
1 20 15	0.05	0.05	807.
1 20 20	0.05	0.05	811.
1 20 25	0.05	0.05	815.
1 20 30	0.05	0.05	819.
1 20 35	0.05	0.05	823.
1 20 40	0.05	0.05	827.
1 20 45	0.05	0.05	831.
1 20 50	0.05	0.05	835.
1 20 55	0.05	0.05	839.



AD-A156 427

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
LOWER MOUNTAIN LAKE (.. (U) CORPS OF ENGINEERS WALTHAM
RA NEW ENGLAND DIV MAR 79


2/2

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NBS 1963-A

HYDROGRAPH ROUTING

RESERVOIR ROUTING FOR MOUNTAIN LAKE
 ISTAT 1 ICOMP 1 IECOR 0 IITAPC 0 IJPLT 0 INAME 1
 ROUTING DATA
 CLOSS 0.0 CLOSS 0.0 AVG 0.0 IKLS 1 ISAME 0
 NSTPS 1 NSTPL 0 LAG 0 AMSAK 0.0 X ISK 0.0 STORA -1.

ASER 700. 320. 850. 940. 1000. 0. 0. 0. 0. 0.
 LUMS 0. 11. 474. 1125. 1705. 0. 0. 0. 0. 0.


TIME	EOP	SECS	AVG IN	EOP OUT
1 0 10	761.		1.	1.
1 0 20	761.		1.	1.
1 0 30	761.		1.	1.
1 0 40	761.		1.	1.
1 0 50	761.		1.	1.
1 0 60	761.		1.	1.
1 1 10	761.		1.	1.
1 1 20	761.		1.	1.
1 1 30	761.		1.	1.
1 1 40	761.		1.	1.
1 1 50	761.		1.	1.
1 1 60	761.		1.	1.
1 2 10	761.		1.	1.
1 2 20	761.		1.	1.
1 2 30	761.		1.	1.
1 2 40	761.		1.	1.
1 2 50	761.		1.	1.
1 2 60	761.		1.	1.
1 3 10	761.		0.	1.
1 3 20	761.		0.	1.
1 3 30	761.		0.	1.
1 3 40	761.		0.	1.
1 3 50	761.		0.	1.
1 3 60	761.		0.	1.
1 4 10	761.		0.	1.
1 4 20	761.		0.	1.
1 4 30	761.		0.	1.
1 4 40	761.		0.	1.
1 4 50	761.		0.	1.
1 4 60	761.		0.	1.
1 5 10	761.		0.	1.
1 5 20	761.		0.	1.
1 5 30	761.		0.	1.
1 5 40	761.		0.	1.
1 5 50	761.		0.	1.
1 5 60	761.		0.	1.
1 6 10	761.		0.	1.
1 6 20	761.		1.	1.
1 6 30	761.		2.	1.
1 6 40	761.		5.	1.
1 6 50	761.		8.	1.
1 6 60	761.		12.	1.
1 7 10	761.		17.	1.
1 7 20	761.		23.	2.
1 7 30	762.		29.	2.
1 7 40	762.		36.	3.
1 7 50	763.		42.	4.
1 7 60	763.		47.	4.
1 8 10	764.		52.	5.
1 8 20	765.		57.	6.
1 8 30	765.		59.	7.
1 8 40	766.		61.	8.
1 8 50	767.		63.	9.
1 8 60	768.		65.	10.
1 9 10	769.		67.	11.
1 9 20	769.		68.	12.
1 9 30	770.		69.	13.
1 9 40	771.		70.	14.
1 9 50	772.		71.	15.
1 9 60	772.		72.	16.
1 10 10	773.		72.	17.
1 10 20	774.		73.	18.
1 10 30	775.		73.	19.
1 10 40	775.		73.	20.
1 10 50	775.		73.	21.
1 10 60	777.		74.	22.
1 11 10	777.		74.	23.
1 11 20	777.		74.	24.
1 11 30	779.		74.	25.
1 11 40	780.		74.	26.
1 11 50	780.		74.	27.
1 12 00	780.		74.	28.

1 12 20	702.	79.	29.
1 12 30	755.	81.	30.
1 12 40	754.	100.	31.
1 12 50	755.	127.	33.
1 12 60	787.	153.	35.
1 13 10	754.	195.	38.
1 13 20	772.	237.	42.
1 13 30	795.	253.	46.
1 13 40	794.	331.	51.
1 13 50	804.	377.	57.
1 13 60	809.	424.	64.
1 14 10	814.	455.	71.
1 14 20	820.	504.	79.
1 14 30	825.	540.	119.
1 14 40	832.	576.	156.
1 14 50	838.	610.	196.
1 14 60	844.	644.	236.
1 15 10	850.	678.	275.
1 15 20	856.	720.	313.
1 15 30	862.	776.	354.
1 15 40	868.	848.	397.
1 15 50	875.	938.	444.
1 15 60	883.	1044.	505.
1 16 10	892.	1162.	600.
1 16 20	900.	1280.	694.
1 16 30	907.	1366.	791.
1 16 40	915.	1476.	886.
1 16 50	925.	1555.	976.
1 16 60	934.	1581.	1058.
1 17 10	940.	1551.	1126.
1 17 20	945.	1509.	1179.
1 17 30	947.	1446.	1215.
1 17 40	953.	1367.	1236.
1 17 50	951.	1282.	1242.
1 17 60	950.	1199.	1256.
1 18 10	949.	1123.	1221.
1 18 20	947.	1051.	1196.
1 18 30	944.	981.	1166.
1 18 40	941.	909.	1132.
1 18 50	937.	834.	1091.
1 18 60	933.	758.	1045.
1 19 10	928.	680.	994.
1 19 20	923.	602.	940.
1 19 30	916.	525.	882.
1 19 40	912.	452.	822.
1 19 50	905.	384.	761.
1 19 60	901.	323.	700.
1 20 10	893.	272.	641.
1 20 20	890.	230.	584.
1 20 30	885.	194.	529.
1 20 40	880.	167.	479.
1 20 50	876.	152.	444.
1 20 60	872.	146.	422.
1 21 10	868.	140.	396.
1 21 20	865.	135.	375.
1 21 30	862.	129.	354.
1 21 40	857.	124.	334.
1 21 50	856.	119.	315.
1 21 60	853.	114.	298.
1 22 10	851.	110.	281.
1 22 20	848.	106.	266.
1 22 30	846.	101.	252.
1 22 40	844.	97.	238.
1 22 50	842.	93.	226.
1 22 60	841.	90.	214.
1 23 10	837.	86.	203.
1 23 20	837.	83.	192.
1 23 30	836.	79.	185.
1 23 40	834.	76.	173.
1 23 50	833.	73.	165.
1 23 60	832.	70.	157.

SUM


36007.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CF5	1242.	627.	250.	250.	36007.
INCRES		205.	247.	247.	
AG-FI		410.	410.	410.	496.




RUNOFF SUMMARY, AVERAGE FECS

	PLAN	6-HOUR	24-HOUR	72-HOUR	AREA
HYDROGRAPH AT	1	1504.	540.	250.	3.76
RIVER, ET	1	1424.	827.	250.	3.76



APPENDIX E

Information as Contained in the National Inventory of Dams



INVENTORY OF DAMS IN THE UNITED STATES

NAME	LATITUDE (DEC)	LONGITUDE (WEST)	REQUIR DATE (DAY, MO, YR)
NAVIGATION	44° 07.1'	121° 57.4'	2/20/67

NAME OF REFOURMENT

NEAREST TOWN/VILLAGE	POPULATION
NAVIGATION	0

REMARKS: DIST CAN BE D M PRV/FED SCS A NEW/DATE


REMARKS

CONSTRUCTION BY	OPERATION	MAINTENANCE
NAVIGATION	NAVIGATION	NAVIGATION

CONSTRUCTION BY	OPERATION	MAINTENANCE
NAVIGATION	NAVIGATION	NAVIGATION

REQUIR DATE (DAY, MO, YR)	AUTHORITY FOR INSPECTION
2/20/67	NAVIGATION

REMARKS



END

FILMED

8-85

DTIC

