

UNCLASSIFIED

AD 406 245

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION, ALEXANDRIA, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

406 245

63-3-6

ASD-TDR-63-360

406245

INVESTIGATION OF THE RELATIONSHIP OF  
TWINNING TO BRITTLE FRACTURE  
OF REFRACTORY METALS

TECHNICAL DOCUMENTARY REPORT NO. ASD-TDR-63-360  
April 1963

Directorate of Materials and Processes  
Aeronautical Systems Division  
Air Force Systems Command  
Wright-Patterson Air Force Base, Ohio

Project No. 7351, Task No. 735101

(Prepared under Contract No. AF 33(657)-7376  
by the Battelle Memorial Institute, Columbus, Ohio;  
C. N. Reid, A. Gilbert, and G. T. Hahn, authors.)

## NOTICES

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

Qualified requesters may obtain copies of this report from the Armed Services Technical Information Agency, (ASTIA), Arlington Hall Station, Arlington 12, Virginia.

This report has been released to the Office of Technical Services, U.S. Department of Commerce, Washington 25, D.C., for sale to the general public.

Copies of this report should not be returned to the Aeronautical Systems Division unless return is required by security considerations, contractual obligations, or notice on a specific document.

FOREWORD

This report was prepared by the Battelle Memorial Institute, Columbus, Ohio under USAF Contract No. AF 33(657)-7376. This contract was initiated under Project No. 7351, "Metallic Materials", Task No. 735101, "Refractory Metals". The work was administered under the direction of the Directorate of Materials and Processes, Deputy for Technology, Aeronautical Systems Division. Mr. C. S. Hartley was the project engineer.

This report covers work from November 1, 1961, to December 31, 1962.

ABSTRACT

The first year's work on this program is reported. It is concluded that there is good evidence for brittle fracture induced by mechanical twinning in single crystals and polycrystalline Mo-C with grain sizes larger than 0.40 mm. However there is no evidence for such failures in Mo-C of grain size smaller than 0.25 mm, or in high-purity Cb. The effect of recrystallization texture on twinning is demonstrated, and the orientation dependence of twinning in Cb crystals is reported; a most unusual plastic instability is described in crystals of one orientation. It is shown that twinning in Mo-35Re occurs in bursts, which form in less than 2  $\mu$ sec; nucleation of twins occurs only at small strains but lateral growth takes place up to at least 12 per cent strain.

This technical documentary report has been reviewed and is approved.



I. PERLMUTTER  
Chief, Physical Metallurgy Branch  
Metals and Ceramics Laboratory  
Directorate of Materials and Processes

## TABLE OF CONTENTS

	<u>Page</u>
INTRODUCTION . . . . .	1
REVIEW OF THE LITERATURE . . . . .	1
Twinning Crystallography . . . . .	1
The Strain Contribution of Twinning . . . . .	4
The Morphology of Twins . . . . .	4
The Shear Stress for Twinning . . . . .	4
The Kinetics of Twin Growth . . . . .	5
Proposed Mechanisms of Twin Formation . . . . .	7
The Relationship Between Twinning and Fracture . . . . .	8
Cracking at Twin Intersections . . . . .	8
Grain-Boundary Cracking . . . . .	9
Microcracks at Single Twins . . . . .	9
OBJECTIVES . . . . .	10
EXPERIMENTAL PROGRAM . . . . .	10
Mechanical Tests . . . . .	10
Results for Molybdenum . . . . .	12
Tests on Molybdenum of Mean Grain Diameter $d = 0.037$ Mm . . . . .	12
Tests on Molybdenum of Mean Grain Diameter $d = 0.25$ Mm . . . . .	14
Tests on Molybdenum of Mean Grain Diameter $d = 0.40$ Mm . . . . .	14
Tests on Single Crystals of Molybdenum . . . . .	19
Results for Columbium . . . . .	20
Tests in Tension . . . . .	23
Tests in Compression . . . . .	23
Tests of Columbium Single Crystals . . . . .	25
Experiments on the Formation and Growth of Twins . . . . .	32
Study of Initial Growth . . . . .	32
Study of Subsequent Growth . . . . .	34
DISCUSSION . . . . .	39
Twin-Induced Fracture of Molybdenum . . . . .	39
Twin-Induced Fracture of Columbium . . . . .	41
The Effect of Recrystallization Texture on Twinning . . . . .	41
The Mechanical Behavior of Columbium Crystals . . . . .	42
The Kinetics of Twin Growth . . . . .	44
CONCLUSIONS . . . . .	45
LIST OF REFERENCES . . . . .	46

LIST OF TABLES

<u>Table</u>		<u>Page</u>
1	Heat Treatment of Experimental Materials . . . . .	12
2	Predicted Tensile Twinning Stresses Compared With the Observed Flow Stresses . . . . .	43

LIST OF FIGURES

<u>Figure</u>		<u>Page</u>
1	Twinning Systems in Bcc Crystals Numbered According to the Convention of Schmid and Boas . . . . .	2
2	The Operative Twinning Systems as a Function of Crystal Orientation .	3
3	A Comparison of the Grain-Size Dependence of Twinning and Lower Yield Stresses for Iron, According to Hahn et al. , and the Intergranular Fracture Stress, According to Low . . . . .	6
4	The Types of Test Specimen Used in This Investigation . . . . .	11
5	The Temperature Dependence of the Tensile Fracture Stress and the Compressive Yield Stress for Molybdenum of Mean Grain Diameter 0.037 Mm . . . . .	13
6	The Temperature Dependence of the Tensile Fracture Stress and the Compressive Flow Stress for Molybdenum of Mean Grain Diameter 0.25 Mm . . . . .	15
7	Transmission Electron Micrograph Showing Dislocations Generated at a Precipitate Particle in Molybdenum . . . . .	16
8	Examples of Cracks Associated With Twinning in Molybdenum of Mean Grain Diameter $D = 0.40$ Mm After Compression at 78 K . . . . .	17
9	The Grain-Size Dependence of the Brittle Fracture Stress of Molybdenum at 78 K . . . . .	18
10	The Axial Orientations of the Single-Crystal Specimens Used in This Investigation . . . . .	19
11	Examples of Cracks Located at the Intersection of Twins on Systems 3 and 4 in Molybdenum Single Crystal A Compressed at 78 K . . . . .	21
12	Twinning in Single Crystals of Molybdenum . . . . .	22
13	The Temperature Dependence of the Flow Stress at 0.2 Per Cent Plastic Strain for Columbium Tested in Tension and Compression . .	24

LIST OF FIGURES  
(Continued)

<u>Figure</u>		<u>Page</u>
14	Stress-Strain Curves of the Columbium Crystals . . . . .	26
15	Single Crystals of Columbium . . . . .	31
16	Formation of Twins in Mo-35Re . . . . .	33
17	Schematic Diagram of the Circuit Using Budd Strain Gages, S, Type Cb-111, to Study Twin Formation . . . . .	34
18	The Lineal Density of Twins, $N_L$ , in Mo-35Re as a Function of Strain at Room Temperature . . . . .	35
19	The Widths of Four Typical Twin Traces in Mo-35Re as a Function of Strain at Room Temperature . . . . .	37
20	A Comparison of the Extent of Twinning in Specimens of Various Configurations . . . . .	38
21	Transmission Electron Micrograph Illustrating the Dislocation Arrangements Developed in Electron Transparent Foils of Mo-35Re Deformed at Room Temperature . . . . .	40

# INVESTIGATION OF THE RELATIONSHIP OF TWINNING TO BRITTLE FRACTURE OF REFRACTORY METALS

by

C. N. Reid, A. Gilbert, and G. T. Hahn

## INTRODUCTION

There is great contemporary interest in the refractory metals and alloys as advanced structural materials. Good evidence exists that mechanical twinning is capable of creating inter- and transcrystalline cracks in bcc metals, and this must be considered as a possible cause of brittleness in the refractory metals. This research program is intended to produce an appraisal of the evidence for twin-induced fracture among refractory metals, and an understanding of the factors which control its occurrence.

## REVIEW OF THE LITERATURE

Since twinning provides the means for this type of failure, it is desirable first to review current knowledge of the twinning phenomenon itself.

Mechanical twins are produced in body-centered cubic metals by deformation at low temperatures, or at high loading rates. Twins have been observed in iron<sup>(1)</sup> and its binary alloys with silicon<sup>(2)</sup>, phosphorus<sup>(3)</sup>, molybdenum<sup>(3)</sup>, and aluminum<sup>(4)</sup>; in the Group V-A metals vanadium<sup>(5)</sup>, columbium<sup>(6)</sup>, and tantalum<sup>(7)</sup>, and in the Group VI-A elements chromium<sup>(8)</sup>, molybdenum<sup>(9)</sup>, and tungsten<sup>(10)</sup>, and their binary alloys with rhenium<sup>(11,12)</sup>.

### Twinning Crystallography

The twins consist of regions of crystal in which a particular set of  $\{112\}$  planes is homogeneously sheared by 0.707 in a  $\langle 111 \rangle$  direction. The same atomic arrangement may be visualized by a shear of 1.414 in the reverse  $\langle 111 \rangle$  direction, but this larger shear has never been observed. As a consequence of this, twinning systems, as specified by a plane and a direction, are "polarized", the material shears only in one sense of this direction. There are twelve different twinning systems, and these are labeled and illustrated in Figure 1 according to the convention of Schmid and Boas<sup>(13)</sup>. Their "polarization" implies that for a given orientation of the crystal relative to a uniaxial stress only  $x$  systems may operate under tensile loading, and only the remaining  $(12-x)$  systems under compression. Figure 2 taken from Allen et al<sup>(14)</sup> illustrates the twinning systems that are operative in a crystal under tension or compression as a function of the direction of the applied uniaxial stress.





FIGURE 1. TWINNING SYSTEMS IN BCC CRYSTALS NUMBERED ACCORDING TO THE CONVENTION OF SCHMID AND BOAS



A-44184

Stressed in tension systems	$\left\{ \begin{array}{l} 2, 7, 8 \\ 6, 9 \\ 1 \\ 10 \\ 12 \\ 11 \end{array} \right\}$	operate when the orientation is within	$\left\{ \begin{array}{l} ABC \\ BCF \\ ACF \\ BCD \\ BDEC \\ BEC \end{array} \right\}$
Stressed in compression systems	$\left\{ \begin{array}{l} 3, 4, 5 \\ 1 \\ 11 \\ 6, 9 \\ 10 \\ 12 \end{array} \right\}$	operate when the orientation is within	$\left\{ \begin{array}{l} ABC \\ BCF \\ BEA \\ ACF \\ ADC \\ ADE \end{array} \right\}$

FIGURE 2. THE OPERATIVE TWINNING SYSTEMS AS A FUNCTION OF CRYSTAL ORIENTATION<sup>(14)</sup>

### The Strain Contribution of Twinning

The ultimate extent to which twinning may contribute to the strain of a specimen occurs in the case where a crystal of optimum orientation is totally transformed into a twin. According to Schmid and Boas<sup>(13)</sup> the maximum longitudinal strain  $\epsilon_{\max}$  and the optimum orientation are given by maximizing the equation:

$$\epsilon_{\max} = \sqrt{1 + 2s \sin \chi \cos \lambda + s^2 \sin^2 \chi} \quad , \quad (1)$$

where  $s$  is the shear involved in twinning, and  $\chi$  and  $\lambda$  are the angles between the longitudinal specimen axis and the twinning plane and direction, respectively.  $\epsilon_{\max}$  has the value of 41.4 per cent, when  $\chi = \lambda = 54.7$  degrees. In general, however, only a fraction of the matrix transforms into a twin. Geil and Carwile<sup>(15)</sup> made some qualitative observations of twinning in polycrystalline  $\alpha$ -Fe; they reported that twins were initiated only in the early stages of deformation, and that their thickness subsequently increased with further tensile strain until fracture of the specimen occurred.

### The Morphology of Twins

The shapes of twins may be revealed in two dimensions by etching. Both the coherent and noncoherent segments of a mechanical twin boundary etch as readily as grain boundaries, and it is concluded that the twin-boundary energy is high. This has been confirmed by transmission electron microscopy which has revealed a high concentration of dislocations at boundaries<sup>(16)</sup>. Usually a twinned region is extensive in the twinning plane, being limited by the dimensions of the crystal and obstacles such as other twins, but perpendicular to this plane the region is narrow. The twin-matrix interface may have various shapes; it may be smooth with a gradual taper towards the edges of the twinned layer, having the shape of a bi-convex or plane-convex lens. Alternatively the interface may have a complicated fine structure of serrations, undulations, or flamelike features. For example, the sectioning of tungsten<sup>(17)</sup>, molybdenum<sup>(18)</sup>, and columbium<sup>(6)</sup> parallel and perpendicular to the twinning direction has revealed that the twins present consist of sets of parallel prisms whose long dimension is parallel to the twinning direction.

Apart from this variety of boundaries observed in the interiors of bcc metals, Hull<sup>(2)</sup> and Sleswyk<sup>(19)</sup> have reported observations of eruptions on free surfaces of iron-silicon and iron after impingement by growing twins. They observed that in iron and iron-silicon the twin boundary making an acute angle with the surface gave rise to zig-zag indentations of the surface, and they offered explanations in terms of accommodation slip. However it is emphasized that these serrations are not twin-matrix interfaces but a pattern of slip lines.

### The Shear Stress for Twinning

For a long time it has been anticipated that there is a critical shear stress responsible for twinning. This is predicted by both the dislocation theory, and the theory of homogeneous twin formation. However experimental studies of the critical stress for twinning in macroscopic crystals of iron<sup>(14)</sup> and zinc<sup>(20)</sup> contradict this; the critical stress varies with crystal orientation<sup>(14)</sup> and with specimen size<sup>(20)</sup>. Similarly, a

variable twinning stress has been observed in zinc whiskers<sup>(21)</sup>, but the average stress level was about ten times higher than that in bulk material. It is generally argued that there is a critical shear stress but that it never coincides with the nominal stress due to the presence of uncontrolled local stress concentrations within the crystals. These are believed to be more severe in bulk material than in whiskers. The work of Bell and Cahn<sup>(20)</sup> and Siems and Haasen<sup>(22)</sup> on zinc and that of Marcinkowski and Lipsitt<sup>(8)</sup> on chromium indicate that deformation by slip may be a necessary precedent of twinning. This suggests that the local stress concentrations are derived from slip dislocations.

The dislocation pile-up or queue has frequently been visualized as the source of the stress concentration. This conclusion is supported by the observation that transmission electron micrographs taken under conditions where twinning occurs show the dislocations present to be unusually straight and parallel, with a reduced number of jogs, cusps, and trails. This is the case in impacted iron<sup>(23)</sup>, iron deformed slowly at 78 K<sup>(23)</sup>, and Mo-35Re deformed slowly at 300 K<sup>(24)</sup>. The appearance suggests that cross slip is inhibited under these conditions; this is expected to be conducive to pile-up formation, because cross slip provides a means of escape of dislocations from developing queues.

While the validity of a critical shear stress remains to be demonstrated it is known that for a given polycrystalline material there exists a critical nominal stress for twinning. For example, it has been found that in carbon steel the stress for initial twinning is almost independent of temperature and strain rate<sup>(25)</sup>. Studies of iron-silicon<sup>(26)</sup> and mild steel<sup>(27,28)</sup> indicate that this stress depends sharply on grain size in the manner of Figure 3, but in columbium there was found to be no grain-size dependence<sup>(29)</sup> at 20 K.

The effect of interstitial impurities on the occurrence of twinning in bcc metals is disputed. The larger school<sup>(5,30-32)</sup> of thought maintains that increased purity favors deformation by twinning under given testing conditions, whereas the opposite effect has also been reported<sup>(33)</sup>. It is important to establish whether the effect of interstitials is the same when in or out of solution. The work of Edmondson<sup>(34)</sup> suggests it is not; iron crystals quenched to retain nitrogen in solution deformed by slip at 78 K but when quenched and aged causing precipitation, they deformed by twinning. Hence, it appears that interstitials in solution may inhibit twinning. While evidence is contradictory on the role of interstitial impurity, it is clear that the presence of certain substitutional elements can promote twinning most strikingly. For example, phosphorus or molybdenum in iron<sup>(3)</sup> and rhenium in chromium, molybdenum or tungsten<sup>(12)</sup> make twinning the preferred deformation mode under conditions where it did not occur before alloying.

#### The Kinetics of Twin Growth

From the existence of "twinning cry" it has long been believed that twins form very rapidly in bulk material. This has been confirmed in zinc by Jillson<sup>(35)</sup> and Siems and Haasen<sup>(22)</sup> using high-speed cinematography. This method primarily follows the growth in width of existing twin nuclei.

Faster techniques indicate that these nuclei form in times of the order of microseconds. For example, Förster and Scheil<sup>(26)</sup> recorded the changes in electrical




FIGURE 3. A COMPARISON OF THE GRAIN-SIZE DEPENDENCE OF TWINNING AND LOWER YIELD STRESSES FOR IRON, ACCORDING TO HAHN ET AL.,<sup>(27)</sup> AND THE INTERGRANULAR FRACTURE STRESS, ACCORDING TO LOW<sup>(28)</sup>

resistance which accompany twin formation in bismuth, and later Bunshah and Mehl<sup>(37)</sup> performed a similar study on bismuth, zinc, and iron. These workers identified the duration of the resistance transient with the time of formation of a twin. The transient consisted of a simple rounded step; the former authors measured durations between  $5 \times 10^{-6}$  and  $350 \times 10^{-6}$  seconds in bismuth, whereas Bunshah and Mehl measured times between  $0.2 \times 10^{-6}$  and  $1 \times 10^{-6}$  seconds in bismuth, zinc, and iron. There is a lack of agreement here in the values for bismuth.


Mason, McSkimin, and Shockley<sup>(38)</sup> followed twinning in tin by detecting changes in dimensions with a piezoelectric crystal, and Thompson and Millard<sup>(39)</sup> studied cadmium in the same way. The voltage signals from the crystals were more complicated than those from the resistance method, and therefore harder to interpret. However, the wave trains from cadmium were on the average about 100X longer than those from tin.

Recently, there have been observations by transmission electron microscopy of the formation of mechanical twins in ultrathin specimens of tin and zinc. The work of Price<sup>(21)</sup> on zinc whiskers demonstrates that twins nucleate in the absence of dislocations at sites of stress concentration at applied stresses close to the estimated theoretical twinning stress. The twins propagated at lower stresses by the nucleation and movement of twinning dislocations at slow and uniform speeds - quite unlike the cataclysm in bulk material. Fourie, et al.,<sup>(40)</sup> observed the same phenomena in thin foils of tin. However, at present it is not clear that these phenomena are also operative in bulk material.

#### Proposed Mechanisms of Twin Formation

There have been two fundamentally different approaches to twin nucleation. The first envisages the homogeneous formation of a thin lamellar twin of minimum stable size, in a region of locally high stress. The problem has been treated by Orowan<sup>(41)</sup> who derived an activation energy for nucleus formation which is proportional to: (shear stress)<sup>-2</sup>. The theoretical twinning stress may be estimated as the stress which corresponds to an activation energy in the region of 1 ev. The value appropriate to zinc agrees well with that measured experimentally<sup>(21)</sup>, and this may be regarded as support for the mechanism and its treatment by Orowan. The maximum conceivable rate of growth by this mechanism would be realized if the expanding loops of partial dislocation moved out across the radius of the twin lamella in quick succession at sonic velocity. For example, the time taken by a twin lamella of diameter 0.2 mm and thickness  $3 \times 10^{-4}$  mm in Mo-35Re is calculated to be  $> 30$  m $\mu$ sec. Thus the mechanism is consistent with very rapid twin formation.

The second approach visualizes twin formation by a heterogeneity such as a particular dislocation arrangement. Cottrell and Bilby<sup>(42)</sup> have proposed a mechanism for the bcc lattice in which a dislocation dissociates under stress to produce a mobile twinning dislocation and a sessile pole dislocation, according to the equation:



The former moves under stress about the pole along a spiral path, leaving behind a region of twinned crystal. The maximum conceivable rate of growth by this mechanism will be achieved when the fastest segments of the spiralling partial dislocation are

moving with the speed of sound.<sup>(42)</sup> If this is so, then the time taken for a twin lamella of 0.2-mm diameter and  $3 \times 10^{-4}$  mm thick to form in Mo-35Re would be  $>25 \text{ m}\mu\text{sec}$ ; the minimum formation time is about the same for both models. This model is able to account for the crystallography of twins observed in bcc metals, and it correctly predicts that twin growth is very rapid, once the initial dissociation is accomplished. Also, the observed slip preceding twinning may be interpreted as the generation of suitable source dislocations. However, it does not account for the other properties of twinning that have been summarized above, and there has been no direct observation of this dislocation arrangement. No clear choice between these twinning mechanisms can be made at this time.

Sleeswyk<sup>(43)</sup> has proposed a mechanism for the growth of twins along the composition plane. From energy considerations he postulates that a twin is preceded by "emissary" slip dislocations on one in every three  $\{112\}$  planes, and that the remaining noncoherent twin boundary has a low energy due to the absence of a long-range stress field. The emissary dislocations and the low-energy boundary are a consequence of the dissociation of a partial dislocation:

$$-\frac{1}{6} \langle 111 \rangle \rightarrow \frac{1}{3} \langle 111 \rangle - \frac{1}{2} \langle 111 \rangle \quad , \quad (3)$$

on one in every three planes parallel to the composition plane. The theory is very successful at accounting for the uniform shear that extends far beyond the twin-matrix interface, creating surface eruptions and kinks in markers such as subboundaries. Alternatively, however, it seems possible that the same effects might arise when slip dislocations in the surrounding matrix are moved by the long-range stress field of a twin.

#### The Relationship Between Twinning and Fracture

While there are good examples that brittle fracture of bcc metals may occur in the complete absence of twinning<sup>(44)</sup>, and that twinning may occur without brittle failure<sup>(12)</sup>, there have also been demonstrations that twins can produce cracks. Clearly, all three phenomena are well documented, and differences in behavior arise from variations in the material and in the experimental conditions.

#### Cracking at Twin Intersections

The investigations of iron-silicon by Hull<sup>(2)</sup> and Honda<sup>(45)</sup> have demonstrated that cracks are frequently created at the line of intersection of two twin lamellae in single crystals stressed in tension along a  $\langle 100 \rangle$  direction. Edmondson<sup>(34)</sup> has observed similar behavior in iron crystals. Apparently, in order to nucleate cracks, it is necessary that the line of intersection lies in the  $\{100\}$  plane situated approximately perpendicular to the applied stress. Similarly, Cahn<sup>(9)</sup> observed cracks at the intersection of twins in crystals of molybdenum deformed in compression. Sleeswyk<sup>(46)</sup> has published a model for crack formation at twin intersections which depends on an interaction of the emissary dislocations from the two twins, producing crack dislocations according to the equation:

$$\frac{1}{2}[111] + \frac{1}{2}[\bar{1}\bar{1}\bar{1}] \rightarrow [100] \quad (4)$$

However, as Hull<sup>(47)</sup> has pointed out, the intersection of two simultaneously advancing twins would appear to be much less likely than the intersection of an existing twin by a growing one. Hornbogen<sup>(3)</sup> had advanced another hypothesis. He argues that since twins form very rapidly they emit stress waves which may produce cleavage cracks when reflected by an obstacle such as an intersected twin. Hornbogen has observed cracking at a twin intersection, the geometry of which is consistent with this idea.

#### Grain-Boundary Cracking

Studies of polycrystalline bcc metals have demonstrated that a grain boundary may part when a twin impinges upon it. In particular, Parker and Mueller<sup>(18)</sup> have published examples of this in molybdenum, and Marcinkowski and Lipsitt<sup>(8)</sup> have observed similar cases in chromium. Indirect evidence for this appears in Figure 3 which illustrates the close similarity between the twinning stress of iron and the intergranular fracture stress for mild steel. Materials containing appreciable grain-boundary segregation are perhaps the most likely candidates for this type of failure.

#### Microcracks at Single Twins

Small cracks have frequently been observed within twin lamellae<sup>(8)</sup> and at non-coherent irregularities on the twin-matrix interface<sup>(48)</sup>. By providing crack nuclei under conditions where propagation is favorable, these may sometimes lead to total failure, as suggested by Low<sup>(48)</sup>. Furthermore, there have been indications that a twin boundary is a preferred region for crack propagation. (10, 49)

It appears that all these cases of crack nucleation occur at sites of local stress concentration, and it is plausible to conclude that the cracks are a consequence of this magnified stress.

There have been many observations near cleavage fractures of twins whose relationship to the crack was not in any of the above categories.<sup>(33)</sup> It is strongly suspected that these twins were generated by the stress field of the propagating crack, and Bilby and Bullough<sup>(50)</sup> have justified this by calculation. In this case the crack generates the twins, the reverse of the situation that was considered above. As a rule, twins generated by the fracture are narrow, are situated in the immediate vicinity of the fracture, and are not continuous across the failure.<sup>(51)</sup> It is important in fractography to identify whether a twin is related to the fracture, and if so, whether it is a cause or an effect.

In summary, it may be said that current knowledge of mechanical twinning is very incomplete. No mechanism for nucleation and growth of twins has been fully verified, and it is not clear why the growth kinetics should differ so widely between the bulk material and electron-transparent foil. The observed relationship between the nominal twinning stress, temperature, strain rate, and grain size is not adequately understood. Furthermore the effect on twinning in bcc metals of dissolved and undissolved interstitial elements has been incompletely investigated or rationalized. Finally the concentrations of stress that are associated with twins and their intersections have been only qualitatively revealed. Clarification of any of these questions should contribute to the understanding of twin-induced fracture.

## OBJECTIVES

Molybdenum and columbium are the subjects of this investigation; they represent the extremes of ductility exhibited by the refractory metals. The primary objective is to discover the conditions under which these materials undergo twin-induced cracking. Those under study are, first, the testing conditions such as temperature and loading rate and, second, the conditions of the material such as its grain size and interstitial content. This involves a program of mechanical testing followed by metallographic examination.

Stress concentrations are associated with twin lamellae and they may be relaxed by the processes of slip, further twinning, or the generation of cracks. In bulk material, the initial growth of a twin is very rapid and the surrounding material is subjected to a high loading rate. Under these conditions, slip is limited by the mobility of the dislocations and hence twinning or cracking is favored. One of the most dangerous aspects of twinning then appears to be its kinetics of growth, and a further objective of this program has been to observe quantitatively the formation and growth of twins in a bcc material. The questions to which answers are sought include:


- (1) Do twins form singly or in bursts?
- (2) What is the growth rate of a twin or burst of twins?
- (3) How does the contribution of twinning vary with the extent of deformation?

It was decided that this phase of the program would be conducted with the alloy Mo-35Re, enabling difficult experiments to be carried out at room temperature, and eliminating the inconvenience of a cold chamber.


## EXPERIMENTAL PROGRAM

### Mechanical Tests


Compression- and tension-test specimens, illustrated in Figure 4, were prepared by grinding and electropolishing from material in each condition under study. These were tested in an Instron machine, Model TT-C-L, at a given strain rate and at temperatures between 78 K and 298 K. These temperatures were attained by means of a liquid-nitrogen evaporator of modified Wessel design<sup>(52)</sup>. In addition, some tensile tests were made at 20 K in a hydraulic machine, but facilities for compression at this temperature were not available. Since there is greater ductility in compression, it was argued that comparison of behavior in tension and compression should establish whether the brittle-fracture stress can be identified with the stress for yielding or twinning. Furthermore, it was considered that compression loading would be favorable for studying crack nucleation in the absence of propagation.



a. Round Tensile Specimen



b. Sheet Tensile Specimen



c. Compression bar

Scale - Twice actual

FIGURE 4. THE TYPES OF TEST SPECIMENS USED IN THIS INVESTIGATION

## Results for Molybdenum

Commercial arc-cast molybdenum has been investigated over a wide range of recrystallized grain sizes. The purity level and conditions of heat treatment are summarized in Table 1. It has been estimated<sup>(53)</sup> that the dissolved interstitial content remaining in molybdenum after moderate cooling rates is as follows:

<u>Hydrogen</u>	<u>Carbon</u>	<u>Nitrogen</u>	<u>Oxygen</u>
0.1 ppm	0.1-1 ppm	1 ppm	1 ppm

It is concluded that this material was saturated with nitrogen and oxygen, and highly saturated with carbon. The grain-boundary phase that was present was therefore probably a carbide.

TABLE 1. HEAT TREATMENT OF EXPERIMENTAL MATERIALS

Material	Supplier	Supplier's Analysis, ppm	Time at Temperature, hours	Temperature, C	Cooling Rate	Atmosphere	Mean Grain Diameter, mm
Molybdenum	Universal Cyclops Steel Corporation	C: 330	1/2	1330	Cool to ambient temperature in approximately 1 hour	Hydrogen	0.037
		N: 30	1/2	1910		Hydrogen	0.25
		O: 15	1	2000		Vacuum,	0.40
		H: 10				4 x 10 <sup>-5</sup> mm	
Columbium	Wah Chang Corporation	C: 30 N: 56 O: 60 H: 3	1	1500	Ditto	Vacuum, 1 x 10 <sup>-5</sup> mm	0.38
Mo-35 at. % Re (first order)	Chase Brass and Copper Company		1	1800	"	Vacuum, <5 x 10 <sup>-5</sup> mm	0.20
Mo-35 at. % Re (later order)	Chase Brass and Copper Company		1	1800	"	Vacuum, <5 x 10 <sup>-5</sup> mm	0.11

Mechanical tests on molybdenum were conducted at a strain rate of  $2.7 \times 10^{-2}$  per min. All specimens tested in tension at 173 K and below underwent a preyield brittle fracture.

Tests on Molybdenum of Mean Grain Diameter  $d = 0.037$  Mm. Grain sizes were measured by lineal counting of grain boundary intercepts on polished and etched sections of the specimens. The stress parameters measured when molybdenum with the smallest grain size was tested are given in Figure 5. Similar stress temperature relations were observed by Alers et al.<sup>(54)</sup> for molybdenum of comparable grain size. Since no twins were revealed by a metallographic examination of these specimens, it is impossible to correlate the fracture of this material with twinning, despite the fact that the fracture stresses lie approximately on a temperature plateau, which is commonly considered to be a property of twinning. At 78 K, the yield stress in compression is about 30 per cent higher than the tensile fracture stress, and a few isolated inter- and transcrystalline cracks were observed in the compression bars.




FIGURE 5. THE TEMPERATURE DEPENDENCE OF THE TENSILE FRACTURE STRESS AND THE COMPRESSIVE YIELD STRESS FOR MOLYBDENUM OF MEAN GRAIN DIAMETER 0.037 MM

Tests on Molybdenum of Mean Grain Diameter  $d = 0.25$  Mm. The behavior of molybdenum of an intermediate grain size is illustrated in Figure 6. Again, no twins were observed in any of these specimens. There is a close similarity between the fracture stress and the compressive yield stress, and this, together with the absence of twins, implies that the failures were slip induced. Examination of the fracture surface of a specimen tested at 78 K revealed both cleavage and grain-boundary facets; the failure appeared to originate at a facet of the latter kind. Specimens that were compressed below 130 K exhibited serrated stress-strain curves, and subsequently were seen to contain both inter- and transcrystalline cracks.

Since no twins were observed in the above specimens by optical microscopy, an examination was made in the electron microscope to determine if small twins were present beyond optical resolution; such twins have been cited by Sleeswyk<sup>(46)</sup> to be responsible for brittle fracture. Compression and tension specimens of the above two grain sizes were prepared for transmission electron microscopy, after deformation at 78 K. In the preparation, disks 0.03 inch thick were sliced from the specimen by grinding; these were then indented by an electrolytic jet, and subsequently thinned to the point of perforation by electrolysis. The electrolyte used was 75 per cent by volume ethyl alcohol and 25 per cent by volume sulfuric acid. In these foils, dislocations and precipitates were visible, and Figure 7 is an example of a dislocation array generated at a precipitate in a tensile specimen of intermediate grain size. However, no cases of microtwinning were ever observed.

Tests on Molybdenum of Mean Grain Diameter  $d = 0.40$  Mm. In tests of the material with a large grain size, the tensile fracture stresses at 20 K and 78 K coincide with the compressive yield stress at 78 K to within 1 per cent. When a compression specimen was metallographically sectioned after undergoing 3 per cent strain at 78 K, it was seen to contain numerous inter- and transcrystalline cracks; a minority of these were associated with twins as illustrated in Figure 8. It is felt that the cracks have relieved stresses around the twins rather than vice versa. For example, microcracks were observed at both ends of a twin; it seems to be too fortuitous that a pair of cracks were nucleated by some other mechanism, in positions such that they were exactly bridged by a twin, and therefore it is considered that the twin nucleated one or both cracks.

A fractographic examination was made of tensile bars tested at 20 K and 78 K. The failures were composed largely of cleavage facets, with some grain-boundary facets visible. The fracture origins appeared to be intercrystalline surfaces, identified by their aplanar shape and the presence there of a second phase. When the original fracture surface of the 20 K test bar was barely removed by polishing, two types of thin markings were seen; one type was visible before etching and the other only after etching. It was concluded from this and from their appearance that both cracks and twins were located near to the main fracture. They were distributed randomly on the cross section of the specimen and were not especially associated with the region where the failure started. No twins or cracks were observed in sections of the specimen away from the fracture.

In Figure 9 the tensile fracture stress pertaining to 78 K is plotted against the inverse square root of the average grain diameter for the above three grain sizes. There is no grain-size dependence, whereas the twinning stress usually depends strongly on grain size; it is concluded that brittle fracture does not occur at the onset of twinning.




FIGURE 6. THE TEMPERATURE DEPENDENCE OF THE TENSILE FRACTURE STRESS AND THE COMPRESSIVE FLOW STRESS FOR MOLYBDENUM OF MEAN GRAIN DIAMETER 0.25 MM



14,000X

FIGURE 7. TRANSMISSION ELECTRON MICROGRAPH SHOWING DISLOCATIONS GENERATED AT A PRECIPITATE PARTICLE IN MOLYBDENUM






FIGURE 9. THE GRAIN-SIZE DEPENDENCE OF THE BRITTLE FRACTURE STRESS OF MOLYBDENUM AT 78 K

Tests on Single Crystals of Molybdenum. A length of single crystal was grown from a rod of arc-cast molybdenum by the method of electron-bombardment floating-zone melting.<sup>(55)</sup> This treatment reduced the concentration of carbon from 330 ppm to 270 ppm, while oxygen and nitrogen remained at less than 10 ppm. Since little purification occurred, the molybdenum was still highly saturated with a random distribution of carbides; the principal result of this treatment was a removal of all grain boundaries and their attendant segregation.

Two compression cylinders were prepared from the crystal by a process of grinding and electropolishing. Their axial orientations are indicated in Figure 10 to be within 6 degrees of  $[011]$ .




FIGURE 10. THE AXIAL ORIENTATIONS OF THE SINGLE-CRYSTAL SPECIMENS USED IN THIS INVESTIGATION

The first, Crystal A, was compressed at 78 K with a strain rate of  $4 \times 10^{-2}$  / min to a strain of 1.9 per cent. Deformation proceeded entirely by slip and the stress-strain relation was smooth and monotonic with a flow stress of 108,500 psi at 0.08 per cent strain.

After being aged for 30 min at 500 C, this crystal was retested under the same conditions, whereupon profuse twinning occurred at a stress of 116,200 psi. This corresponds to a shear stress of 55,700 psi acting on the observed twinning systems. After 0.2 per cent strain, the specimen was unloaded and examined. Many cracks had developed and these were all either parallel to the specimen axis or following twin-matrix interfaces. Several interesting features were observed:

- (1) Fourteen cracks were observed on a longitudinal section of this crystal and of these, as many as 11 had formed at the intersections of two twins; examples of these appear in Figure 11. The intersecting twins belong to the Schmid-Boas Twinning Systems 3 and 4. Both longitudinal and interface cracks were observed at the points of intersection.
- (2) Frequently the wider twin traces contained small transverse cracks like those in Figure 11d.
- (3) The center of one large longitudinal crack coincided with a subboundary for some distance; it may be seen in Figure 12a that the boundary contained some exceptionally large precipitates which may have initiated the crack.
- (4) An example of the shear strain ahead of a twin lamella is seen in Figure 12b which shows the shear produced in a region of a subboundary directly ahead of a terminated twin. Sleswyk<sup>(43)</sup> has previously observed this in iron and attributed it to emissary dislocations.
- (5) Figure 12c illustrates a twin that was interrupted by a colony of precipitate particles. In three dimensions, the twin probably formed around this colony.

The second "as-grown" molybdenum crystal, Crystal B, was compressed about 2 per cent at 78 K under a strain rate of 4/min. A small number of twins formed on Systems 3 and 4, but the twinning was much less profuse than in the aged crystal. It is thought likely that the formation of these twins caused the drop in load that was observed at a tensile stress of 117,000 psi. Resolved onto Systems 3 and 4, this corresponds to a shear stress of 56,200 psi, which is in good agreement with the value for Crystal A. Intersection of twins was rare, but at one intersection of Systems 3 and 4, the small crack in Figure 12d was observed on a longitudinal section of the crystal. No other cracks were observed, either on this section or on the circumference of the specimen. It is probably significant that in these crystals the propensity of cracks is proportional to the propensity of twinning.

The difference in behavior between the two crystals is striking. It may be argued that the prestrain-age treatment received by Crystal A handicapped slip vis-a-vis twinning by first relaxing any grown-in stresses and then immobilizing all the dislocations.

In summary, the experience with the single crystals has been that 3-4 twin intersections are the major source of crack nucleation under these deformation conditions.

#### Results for Columbium

The mechanical properties of commercial columbium prepared by electron-beam melting have been evaluated. The material was received from the manufacturer as swaged rods with the low interstitial content specified in Table 1. Trouble was encountered inducing uniform recrystallization and eventually only one uniform grain size was produced, with a mean grain diameter of 0.38 mm. The heat treatment involved is summarized in Table 1. It has been estimated that the interstitial content that would be in solid solution after such a treatment is:<sup>(53)</sup>

- (1) Fourteen cracks were observed on a longitudinal section of this crystal and of these, as many as 11 had formed at the intersections of two twins; examples of these appear in Figure 11. The intersecting twins belong to the Schmid-Boas Twinning Systems 3 and 4. Both longitudinal and interface cracks were observed at the points of intersection.
- (2) Frequently the wider twin traces contained small transverse cracks like those in Figure 11d.
- (3) The center of one large longitudinal crack coincided with a subboundary for some distance; it may be seen in Figure 12a that the boundary contained some exceptionally large precipitates which may have initiated the crack.
- (4) An example of the shear strain ahead of a twin lamella is seen in Figure 12b which shows the shear produced in a region of a subboundary directly ahead of a terminated twin. Sleeswyk<sup>(43)</sup> has previously observed this in iron and attributed it to emissary dislocations.
- (5) Figure 12c illustrates a twin that was interrupted by a colony of precipitate particles. In three dimensions, the twin probably formed around this colony.

The second "as-grown" molybdenum crystal, Crystal B, was compressed about 2 per cent at 78 K under a strain rate of 4/min. A small number of twins formed on Systems 3 and 4, but the twinning was much less profuse than in the aged crystal. It is thought likely that the formation of these twins caused the drop in load that was observed at a tensile stress of 117,000 psi. Resolved onto Systems 3 and 4, this corresponds to a shear stress of 56,200 psi, which is in good agreement with the value for Crystal A. Intersection of twins was rare, but at one intersection of Systems 3 and 4, the small crack in Figure 12d was observed on a longitudinal section of the crystal. No other cracks were observed, either on this section or on the circumference of the specimen. It is probably significant that in these crystals the propensity of cracks is proportional to the propensity of twinning.

The difference in behavior between the two crystals is striking. It may be argued that the prestrain-age treatment received by Crystal A handicapped slip vis-a-vis twinning by first relaxing any grown-in stresses and then immobilizing all the dislocations.

In summary, the experience with the single crystals has been that 3-4 twin intersections are the major source of crack nucleation under these deformation conditions.

#### Results for Columbium

The mechanical properties of commercial columbium prepared by electron-beam melting have been evaluated. The material was received from the manufacturer as swaged rods with the low interstitial content specified in Table 1. Trouble was encountered inducing uniform recrystallization and eventually only one uniform grain size was produced, with a mean grain diameter of 0.38 mm. The heat treatment involved is summarized in Table 1. It has been estimated that the interstitial content that would be in solid solution after such a treatment is:<sup>(53)</sup>




FIGURE 11. EXAMPLES OF CRACKS LOCATED AT THE INTERSECTION OF TWINS ON SYSTEMS 3 AND 4 IN MOLYBDENUM SINGLE CRYSTAL A COMPRESSED AT 18 K




100X

a. Large Crack Located at a Low - Angle Boundary in Molybdenum Crystal A




500X

b. Shear of a Low-Angle Boundary by a Nearby Terminated Twin in Molybdenum Crystal A



750X

c. The Interruption of a Twin by a Cluster of Precipitates in Molybdenum Single Crystal A



750X

d. Small Crack Situated at the Intersection of Twins on Systems 3 and 4 in Molybdenum Crystal B

FIGURE 12. TWINNING IN SINGLE CRYSTALS OF MOLYBDENUM

<u>Hydrogen</u>	<u>Carbon</u>	<u>Nitrogen</u>	<u>Oxygen</u>
9000	100	300	1000

It is concluded that all the interstitials present were in solid solution; consistent with this, no second phase was ever observed by metallographic examination.

Tests in Tension. Strained in tension at  $4 \times 10^{-2}$ /min, the commercial columbium was ductile at 77 K and above, deforming entirely by slip, and failing by shear with a high reduction in area (82 per cent). The stress-strain curve shows a small yield point and slow strain hardening, both of which diminish with temperature. No metallographic evidence of twinning was ever found in these tests even when the specimen was aged in situ before the test and the imposed strain rate was raised to as high as 4/min. At 20 K, however, profuse twinning occurred by deforming at a rate of  $4 \times 10^{-2}$ /min. After only 0.3 per cent strain, the lineal twin density ( $N_L$ ) was 6.0/mm, every grain containing twins. After 7.0 per cent strain, the value of  $N_L$  was unchanged, but the average width of the traces had increased by about a factor of 1.6, implying that twin nucleation had ceased at small strains. The twins were distributed uniformly across the diameter and length of the specimens and no cracks were observed. Other investigators have observed twinning in columbium under tension only at 20 K and below.<sup>(29)</sup> After 7.0 per cent uniform deformation, a neck formed in the specimen where, at 31 per cent reduction in area, the specimen failed by cleavage. The precise point of the failure's origin could not be located by a fractographic examination, although the approximate position was determined. Within the necked region the number of twin traces was not significantly higher than in the rest of the specimen but their width was about 60 per cent greater, so it is concluded that, at the point of fracture, twin nucleation had ceased and deformation was taking place entirely by slip and growth of existing twins.

Tests in Compression. Identical material was deformed in compression at a rate of  $3 \times 10^{-2}$ /min. At temperatures above 120 K deformation proceeded by slip, and Figure 13 shows the excellent agreement between the upper-yield-stress (or flow stress) values obtained in tension and compression. Below 120 K, however, behavior was strikingly dissimilar; in tension, deformation occurred by slip, whereas compression caused prolific twinning throughout the entire specimen and the yield stress lay well below the value for tension. There appears to be a fundamental difference between compression and tension in promoting twinning in this polycrystalline columbium. McHargue<sup>(6)</sup> observed a similar ease of twinning in columbium under compression at 78 K, but sought to explain this solely on the basis of purity. In these experiments, however, the material is not a variable; the phenomenon occurs when two identical tension specimens are strained, one in tension, the other in compression. This negates a basic tenet of this study, viz., that it is valid and useful to correlate the behavior of polycrystalline material in tension with that in compression, and so there is a strong incentive to rationalize the phenomenon.

Slip on a given system can proceed in either sense of the slip direction, so the identical slip behavior in tension and compression is predictable. However, twinning systems are polarized, as was discussed earlier, and different systems must operate in tension and compression. In a randomly oriented polycrystalline aggregate the resolved shear stresses would favor twinning by compression in grains oriented near




FIGURE 13. THE TEMPERATURE DEPENDENCE OF THE FLOW STRESS AT 0.2 PER CENT PLASTIC FOR COLUMBIUM TESTED IN TENSION AND COMPRESSION

(110) and by tension in grains oriented near (100). It would be expected, therefore, that such an aggregate would show twinning in both tension and compression. That this is not observed implies that the aggregate is not randomly oriented, but has a [110] preferred orientation. This was confirmed experimentally by an X-ray method that has been described by Barrett<sup>(56)</sup>. A forward-reflection flat-plate photograph was taken of the gage of a polycrystalline tension specimen; the latter was rotated at 1 revolution/sec in order that a maximum number of grains were examined, and copper radiation was used. The measurements indicated that the specimen possessed a [110] fiber texture, combined with some cylindrical texture.<sup>(57)</sup> This texture tends to occur in a bcc metal that has undergone cold wire-drawing without intermediate heat treatment.<sup>(58)</sup> The manufacturer's report states that this material underwent the following operations:

- (1) The ingot was forged at 650 C from 8- to 4-inch diameter.
- (2) This bar was then rod rolled at 430 C to 1.25-inch diameter.
- (3) This operation was followed by swaging at 430 C to 0.325-inch diameter.
- (4) Finally, the rod was cold swaged to 0.270-inch diameter, and centerless ground to 0.250-inch diameter.

A recrystallization texture is anticipated after such intensive fabrication.

The following experiment confirmed that the texture was responsible for the observed readiness to form twins under compression. A compression cylinder was prepared with its axis transverse to the swaged rod, and its behavior was compared to that of an identical specimen machined parallel to the rod. After 6 per cent strain at 78 K the value of  $N_L$  was 16/mm in the latter sample. However, in the specimen with transverse texture a large volume of some 500 grains contained no twins whatever after this deformation. The remainder of the specimen was composed of anomalously large grains that did contain twins, but since the tendency to form twins generally increases with grain size, this can be rationalized. The important conclusion is considered to be that twinning in compression can be significantly reduced by changing the preferred orientation.

Tests of Columbium Single Crystals. The mechanical properties of columbium single crystals were studied over a wide range of orientation at 78 K. This was intended to check the above argument concerning texture that crystals with a (110) orientation tend to deform in compression by twinning and in tension by slip. Furthermore, it was desired to know the orientation dependence of twinning and of cleavage.

Tension and compression specimens were prepared by grinding and electropolishing from seeded crystals that were grown by electron-bombardment floating-zone melting. Their longitudinal axes are indicated in Figure 10. A high zoning speed of 9.7 in./hr was used in order to achieve a minimum of purification, and thereby keep the composition of the single crystals similar to that of the polycrystalline material.

Tension and compression tests were made at a rate of  $4 \times 10^{-2}$ /min and the stress-strain relations that were measured are reproduced in Figure 14. Crystal 1,




FIGURE 14. STRESS-STRAIN CURVES OF THE COLUMBIUM CRYSTALS




FIGURE 14. (Continued)




FIGURE 14. (Continued)




FIGURE 14. (Continued)


whose axis was close to  $[110]$ , deformed in compression by prolific twinning on Systems 4, 3, and 6 (in order of diminishing prevalence), at a resolved shear stress of 33,800 psi. Figure 15a illustrates the extent of twinning after 6.5 per cent strain. The stress-strain curve consisted of large serrations that diminished as the strain increased. Crystal 2 of similar orientation deformed in tension entirely by slip; it displayed a yield point at a tensile stress of 113,800 psi, followed immediately by necking to a chisel edge failure. The behavior of these crystals confirms the hypothesis that a  $[110]$  texture would lead to deformation by different modes in compression and tension.

Crystals 3 and 4, oriented near  $[111]$ , deformed under tension entirely by slip; no twins were observed in a metallographic examination. The slip behavior was most unusual. Crystal 3 followed the stress-strain curve illustrated in Figure 14; after a slight upper yield point, the load fell gently until at 1.5 per cent plastic strain, the load fell catastrophically by some 80 per cent. This relaxation of the specimen took place very rapidly, generating a loud noise. Following this phenomenon, the specimen behaved elastically until the test was stopped for inspection. Apparently the plastic flow had occurred predominantly in very thin layers as indicated by Figure 15b. The plane of the massive shear (although somewhat distorted) is between the plane of maximum shear stress and the nearest  $(110)$  plane, at about 12 degrees from the latter. The direction of the shear is, surprisingly, only 8 degrees from the  $[001]$  direction. It is not possible to say from this evidence whether this anomalous shear direction is due simply to slip on one unusual system, or is the vector sum of approximately equal slip in the  $[\bar{1}11]$  and  $[1\bar{1}1]$  directions. This phenomenon has the appearance of being an adiabatic plastic instability<sup>(59)</sup>, except that the temperature at which it was observed is unusually high.

Crystal 4 exhibited similar behavior, as may be seen in Figure 14. The test was carried to failure, which occurred by a cleavage, associated with the massive shear step; the fracture appears in Figure 15d. The origin of the failure was traced to the central marking that is horizontal in the illustration. This marking appeared to be the line of intersection between the plane of massive shear and another slip plane whose slip lines were on the surface. Certainly it was not related to twinning, since none was observed by sectioning and etching. This unexpected case of cleavage must have been slip induced.

Upon compressing Crystal 5 of similar orientation, the flow stress was considerably smaller than the values in tension. No dynamic instabilities occurred, but the crystal showed the same preference for concentrated slip in thin lamellae, as demonstrated in Figure 15c. When slip is heterogeneous, the local strain rate, and hence the flow stress, will depend on the number of regions that are deforming. The wide range in flow stress observed between Crystals 3, 4, and 5 may be qualitatively explained in terms of observed differences in the number of regions of local slip; Crystal 5 contained the most regions, followed in descending order by Crystals 3 and 4. Consequently, the corresponding flow stresses are expected to ascent in this order; in practice the values were in the order of 127,000, 151,400, and 158,700 psi.

Crystals 6 and 7, oriented near  $(\bar{1}12)$ , deformed entirely by slip. The flow stresses in tension and compression coincided to within 3 per cent, as expected of slip behavior. The observed rate of strain hardening was essentially zero, even under compression; this led to necking and a chisel edge failure in tension.



50X

a. Profuse Twinning on Systems 3, 4, and 6 in Columbium Crystal 1 After Compression at 78 K



15X

c. Appearance of Columbium Crystal 5 After Compression at 78 K



15X

b. Shear Step in Columbium Crystal 3 After Tensile Deformation at 78 K



15X

d. Fracture Surface of Columbium Crystal 4

FIGURE 15. SINGLE CRYSTALS OF COLUMBIUM

Similarly, Crystals 8, 9, and 10, oriented near (001), deformed entirely by slip; again, the flow stresses coincided to within 7 per cent. In the crystals tested in tension there was a tendency towards the plastic instability of Crystals 3 and 4, and several small drops in load were observed; it was established by metallographic sectioning that no twins were present. Failure in tension occurred by shear.


#### Experiments on the Formation and Growth of Twins

The formation of twins in specimens of Mo-35Re under stress was recorded by movie photography at speeds up to 16,000 frames/sec. Specimens of polycrystalline material, having undergone the heat treatment described in Table 1, were mounted in the grips of a small hydraulic straining device which was fitted to the stage of a metalurgical bench microscope. A carbon-arc lamp, operating from dc, illuminated the specimen, and a Fastax movie camera Model WF-1 was used to photograph the specimen surface through the microscope. Rolls of high-speed film of about 1-second duration were exposed at 6,000 and 16,000 ft/sec, during which time the specimen was strained by actuating a manual hydraulic pump. Successful records of the formation of twins were subsequently magnified further by projection. The following observations were made from these films:


- (1) The first twins to form belonged to bursts; later twins sometimes formed singly. A typical burst had a value of  $N_L = 5/\text{mm}$ .
- (2) Bursts of twins, covering many contiguous grains, became visible in the time interval of 60  $\mu\text{sec}$  between adjacent frames. When first visible, the width of a twin trace was of the order of  $3 \times 10^{-4}$  mm, and its length generally extended across a grain, as in Figure 16a.
- (3) The only growth observed was a slow increase in width of the twin traces throughout the duration of the film.

Apparently, there were two distinct phases of growth: initial and subsequent. Initial growth was too rapid to record at any intermediate stage, and therefore its mode and kinetics are unknown, except that it occurred within 60  $\mu\text{sec}$ . During subsequent growth, the dimensions of the twins increased much less rapidly; meanwhile the specimen was being strained continuously, but it was not possible to correlate subsequent growth with the plastic strain, since there was no provision for measuring the latter. Other experiments were conducted in order to make this correlation.

Study of Initial Growth. Since initial growth occurs in less than 60  $\mu\text{sec}$ , the phenomenon is beyond the time resolution of Battelle's movie cameras, and it was necessary to devise a faster technique. It was decided to measure the strain-time relation that accompanies twinning in a tension test, arguing that during twin growth a simultaneous increase in strain occurs, having the same kinetics. Strain was measured by an arrangement of electrical resistance gages, and their output was displayed against time on an oscilloscope; the trace was recorded by Polaroid photography. The arrangement of gages is represented in Figure 17; by using two gages bonded onto the specimen in this way, the only strains recorded were those affecting either gage alone, such as those due to localized bursts of twinning; elastic or plastic strains under both gages were ignored. The amplifier and oscilloscope were chosen as having the highest frequency response for





90X



90X

a. Adjacent Frames of the Movie Film Illustrating the Formation of a Twin Burst in Less Than 150  $\mu\text{sec}$



b. Two Signals From the Strain Gages Recorded on the C. R. O.

The units of the vertical scale represent about 300  $\mu\text{in.}/\text{in.}$ ,  
and those of the horizontal scale 1  $\mu\text{sec}$ .

FIGURE 16. FORMATION OF TWINS IN Mo-35Re

a given gain, of all the apparatus available. The oscilloscope was internally triggered to display only a single sweep of the beam, so that subsequent repetitive sweeps would not fog the film.




FIGURE 17. SCHEMATIC DIAGRAM OF THE CIRCUIT USING BUDD STRAIN GAGES, S, TYPE Cb-111, TO STUDY TWIN FORMATION

The C. R. O. was a Tektronix oscilloscope, Type 585, with a Type d plug-in unit; the d. c. was supplied by a Dumont strain gage controller, Type 335.

Tensile tests were made on specimens of Mo-35Re of the configuration described above. They carried two gages connected according to Figure 17, and the signals recorded are reproduced in Figure 16b. The strain-time relations consist of a step in strain, about  $200 \mu\text{in.}/\text{in.}$  high, the transient of which lasts about  $2 \mu\text{sec.}$  The size of this signal is consistent with that expected from a burst of twins lying partly under one gage. When step signals of known rise time were fed into the amplifier and oscilloscope it was found that the apparatus had limited frequency response; a  $3 \mu\text{sec.}$  rise time was distorted to one of  $1.5 \mu\text{sec.}$  Therefore, the  $2 \mu\text{sec.}$  rise time of the twinning signal must be regarded as a maximum figure only. It is concluded that bursts of twins form in Mo-35Re under stress in less than  $2 \mu\text{sec.}$

#### Study of Subsequent Growth

A study was made of the contribution of twinning to deformation as a function of the degree of strain and the strain rate used.

Tensile tests were performed at room temperature on specimens of Mo-35Re of the configuration and heat treatment summarized in Figure 4 and Table 1. Electro-polished specimens were strained to about 7 per cent at a rate of  $4 \times 10^{-3}/\text{min.}$  At intervals of plastic strain, measured by fiducial marks on the specimen, the tests were interrupted and the specimens unloaded. Their surfaces were replicated by the cellulose acetate method.<sup>(60)</sup> The shadowed replicas provide a two-dimensional record of the occurrence of twinning from which the lineal density of twins,  $N_L$ , has been measured. This is presented as a function of plastic strain in Figure 18. To determine the effect of the replicating interruptions, a sample was strained continuously to about 7 per cent. The value of  $N_L$  obtained is significantly higher than that obtained in the interrupted test.




FIGURE 18. THE LINEAL DENSITY OF TWINS,  $N_L$ , IN Mo-35Re AS A FUNCTION OF STRAIN AT ROOM TEMPERATURE

The effect of strain rate was subsequently evaluated. Identical specimens were strained without interruption to about 7 per cent at strain rates of  $4 \times 10^{-3}$  in./in./min and 4 in./in./min. The values of  $N_L$  measured on these samples agree to within the statistical uncertainty ( $\pm 2X$  standard error) and appear in Figure 18. The number of twins generated is insensitive to strain rates in this range.

During straining of these specimens it was observed that existing twins increased in width. The widths of four twin traces are plotted against plastic strain in Figure 19.

From these graphs it is clear that the contribution of twinning to the deformation of Mo-35Re is almost complete at 2 per cent plastic strain, whereas twinning is theoretically able to contribute up to about 40 per cent strain. The widening of twins provides a small contribution up to at least 12 per cent strain. These results agree with the qualitative observations of Geil and Carwile<sup>(15)</sup> on twins in  $\alpha$ -Fe.

It may be remarked that at small strains ( $>1/2$  per cent), the rate of formation and widening of the twins accounts for most of the strain of the specimen, as computed by: (the volume fraction of twinned material)  $\times$  40 per cent.

One of the above specimens was successively sectioned to determine whether the twins seen on the surface as steps were representative of those below the surface, revealed by etching. This is a pertinent question regarding the interpretation of the movies of twin formation. In progressively polishing away the surface,  $N_L$  increased by about 30 per cent in the first  $2 \times 10^{-3}$ -inch depth, and thereafter stayed constant. On the other hand the average random width of the twin traces at both surface and center of the specimen was the same:

At the surface,  $7.8 \times 10^{-5}$  inch (81 observations)

At the center,  $7.9 \times 10^{-5}$  inch (50 observations).

The trace shapes visible on the surface were qualitatively the same below. For instance, in some cases serrated twin interfaces were visible on the surface, and the same serrations were also visible when the surface was polished away. It appears then that the surface tilts are reasonably representative of the interior. The slightly low value of  $N_L$  at the surface may mean that twins whose shear lies in the surface are not visible as steps, and etching is necessary to reveal them.

As a more abundant supply of Mo-35Re became available, it was decided to compare the twinning propensity of these thin sheet specimens, only 4 grains in thickness, with that of truly bulk material. Accordingly, tension and compression test bars of the type in Figure 4 were prepared by grinding. These were heat treated in the same manner as the earlier material, according to Table 1; however, the resulting grain size was only about one-half the magnitude of the earlier supply of alloy. With this variable involuntarily present, it was necessary to repeat some tests on the sheet samples for comparison with the bulk material. Sheet samples were strained in tension without interruption at a rate of  $4 \times 10^{-3}$ /min, each to a different value of strain between 0.5 and 6.5 per cent. The values of the lineal density of twins,  $N_L$ , are plotted against strain in Figure 20: the general relationship is the same as was found earlier, but the values of  $N_L$  are higher, and reach saturation at smaller strains. The bulk tension specimen containing about 25 grains across a diameter and the compression specimen containing about 50 grains were strained at a rate of  $4 \times 10^{-3}$ /min to 6.5 per cent. Their values




FIGURE 19. THE WIDTHS OF FOUR TYPICAL TWIN TRACES IN Mo-35Re AS A FUNCTION OF STRAIN AT ROOM TEMPERATURE




FIGURE 20. A COMPARISON OF THE EXTENT OF TWINNING IN SPECIMENS OF VARIOUS CONFIGURATIONS

of  $N_L$  are superimposed on Figure 20. There is similar twinning propensity between the thin and bulk specimens deformed in tension; bulk samples show somewhat more twinning when compressed. This may suggest the presence of some fiber texture similar to that in the polycrystalline columbium. Apparently, then, the data gained from sheet specimens is applicable also to truly three-dimensional material.

Attempts were made to observe twin nucleation by transmission electron microscopy, with a view to deciding whether it occurs homogeneously or at the sites of heterogeneities such as dislocations. Electron transparent foils of Mo-35Re were strained in tension within an RCA Model EMU 3E microscope while under observation at room temperature. Foil tensile specimens were prepared from annealed, rolled sheet of 0.010-in. thickness by erosion with an electrolytic jet to an "I"-shaped plan. The center of these foils was then thinned by electrolysis until perforation started. The electrolyte used was 75 per cent by volume ethyl alcohol and 2.5 per cent by volume sulfuric acid. Before straining, the electron transparent regions of the foils were viewed and a photographic map made. The foils were strained then manually while under observation and maps of the transparent regions were made at small increments of strain. Although twins did form in the foil they were not abundant at the magnifications used, and no case of twin formation occurred within the field of view. The dislocations observed in this alloy were unusually straight, containing few jogs or trails; frequently arrays of dislocations were generated by straining, similar to that illustrated in Figure 21.

## DISCUSSION

### Twin-Induced Fracture of Molybdenum

It has been clearly demonstrated above that if twins are formed in this material they are invariably coexistent with inter- or transgranular cracks. There is little doubt that the twin intersections of Figure 11 have generated the attendant cleavages, and that the impingement of twins on grain boundaries in Figure 8 has generated intergranular cracking. On this evidence, twins and their intersections are very efficient crack generators; rarely were twin intersections or twin-grain boundary junctions observed without associated cracks. This implies that the occurrence of twin-induced fracture under tension depends solely on whether the specimen in question deforms initially by twinning; it is expected that if it does, fracture will inevitably follow.

In molybdenum with a mean grain size of 0.25 mm and smaller, no twinning was observed under any conditions by optical and electron microscopy. This and the grain size-fracture stress relation of Figure 9 infer that fracture did not occur at the onset of twinning. The fracture origins identified were segments of grain boundary at which impurity segregates were visible. Apparently these sites are very effective crack nuclei, so that the material is brittle at or even below the compressive yield stress. Therefore, the mechanism seems to be that slip-induced grain-boundary rupture initiates a cleavage failure.

In the molybdenum of mean grain size 0.40 mm, twinning was observed after compression at 78 K, generating the cracks of Figure 8. However the majority of cracks observed were not associated with visible twins, and it appears that the above mechanism of crack initiation was still operative. Under tension at 20 K and 78 K this material



60,000X

FIGURE 21. TRANSMISSION ELECTRON MICROGRAPH ILLUSTRATING THE DISLOCATION ARRANGEMENTS DEVELOPED IN ELECTRON TRANSPARENT FOILS OF Mo-35Re BY DEFORMATION AT ROOM TEMPERATURE

failed in a brittle manner. Again, the fracture origins were grain-boundary facets on which segregates were visible; no twinlike traces were visible on these facets, such as the conspicuous markings on the fracture surfaces of vanadium<sup>(61)</sup>. However narrow twin traces of less than  $1\text{-}\mu$  width were observed across a section in the immediate vicinity of the failures. It is very difficult to decide whether these were formed prior to crack initiation or after it. It is known that twins form in very rapid bursts, and these twins may be a typical burst that preceded and perhaps triggered the failure. Alternatively since no twins were visibly associated with the fracture origin, they may merely have been generated by the stress field of the propagating failure. On the basis of available evidence it is not possible to distinguish between these alternatives. Fracture initiation appears here to be a competition between the slip and twinning mechanisms and the latter type of failure must be considered as a distinct possibility in molybdenum of this condition.

In single crystals, grain-boundary initiation of cleavage is eliminated. Thus, it is expected that the twinning mechanism of crack nucleation will be highly effective in single crystals. So far the efficacy of twins has been demonstrated only on [110] crystals under compression. However on the basis of this evidence and that reviewed earlier for iron and iron-silicon, it is expected that molybdenum crystals tested in tension along a [100] direction will also exhibit a twin-induced brittle fracture.

#### Twin-Induced Fracture of Columbium

There is no question of twin-induced brittle fracture of columbium at any temperature above 20 K, because all fractures were preceded by considerable plastic deformation. At temperatures above 78 K, ductile shear fractures were observed in the absence of twinning, whereas at 20 K a cleavage fracture occurred after uniform deformation of 7 per cent and 31 per cent reduction in area. In the latter case twinning contributed to the deformation, by nucleation and growth at small strains and by growth alone at high strains. Since the twins were still growing at the point of fracture, as indicated by their greater average width in the necked region, it is entirely possible that they contributed to the initiation of the cleavage failure. It is proposed to eliminate twinning by prestrain at high temperature, and observe the behavior at 20 K, to see if twins are essential to the initiation of cleavage.

The occurrence of twinning at 20 K had an interesting effect on the strain-hardening behavior. At 78 K flow became unstable as soon as yielding began, and deformation was confined to a neck. This indicates that the magnitude of the initial strain-hardening rate was less than 109,000 psi, the tensile strength. However at 20 K the formation of twins throughout the specimen induced uniform deformation up to 7 per cent strain, and a high initial strain-hardening rate of 885,000 psi was observed. Apparently the twins initiate slip uniformly throughout the specimen and postpone the instability.

The Effect of Recrystallization Texture on Twinning. It is considered that sufficient evidence has been marshalled to account for the different modes of deformation in columbium under tension and compression in terms of a recrystallization texture. First, it was established that a [110] fiber texture was present in the specimens; secondly it was demonstrated that changing the texture direction with respect to the specimen axis changes the propensity for twinning; lastly it was shown that single

crystals with a [110] axis deform by twinning in compression and by slip in tension, which simulates the behavior of the component grains of the aggregate with a [110] texture.

This experience indicates that tension and compression behavior can be correlated only in the absence of texture. It also emphasizes the influence of preferred orientation over twinning in polycrystalline specimens. This implies that, in reporting twinning behavior and twinning stresses of polycrystalline material, it is as important to report the presence or absence of any texture as it is to report, say, the grain size. This is rarely done, complicating the direct comparison of data from different material.

The Mechanical Behavior of Columbium Crystals. From the point of view of twinning, the most significant behavior was that of the [110] crystals which deformed by twinning in compression and by slip in tension. If the columbium specimen, Crystal 1, is compared with molybdenum Crystals A and B, the difference in character between these two metals is illustrated: twinning in all these crystals was predominantly on Systems 3 and 4, but, whereas cracks were usually generated at twin intersections in molybdenum, they were never observed at the same type of intersection in columbium.

At first it appears that the behavior of Crystals 1 and 2 may be rationalized in terms of the resolved shear stress on the slip and twinning planes. In compression, the shear stress factor ( $\cos \phi \cos \lambda$ ) has a value of 0.47 for the available twinning systems, whereas in tension this value falls to 0.33. On the other hand, for slip the factor is 0.46 in both tension and compression, so the shear stress for twinning vis-a-vis that for slip is 50 per cent higher in compression than in tension. The most conspicuous inconsistency with the existence of a critical shear stress is the case of the [100] crystals deformed in tension. The values of the factor ( $\cos \lambda \cos \phi$ ) for twinning and slip systems are almost identical to those of the [110] crystal in compression. However, unlike the latter, no twinning occurred.

If the shear-stress value at which twinning started in Crystal 1 is taken as the critical shear stress, predictions can be made of the tensile stresses at which twinning would be expected to occur in the other crystals. Table 2 compares these predictions with observation. In Crystals 3, 4, and 10, slip occurred at a stress lower than predicted, and thus no check could be made. However, in all the other crystals, the predicted twinning stresses were exceeded by up to 40 per cent without any twin formation, after which deformation proceeded by slip. Clearly, the above value of a macroscopic "critical" shear stress for twinning cannot be taken seriously.

The concept of a critical shear stress for twinning was further confounded by the behavior of the molybdenum single crystals. The first crystal was compressed at 78 K up to a flow stress of 146,000 psi at 1.9 per cent strain without the formation of twins. The crystal was then aged at a temperature considered too low for dislocation rearrangement (500 C) and retested; it deformed by twinning at 117,000 psi. If this twinning stress were really critical, the crystal could not have previously sustained a much higher stress without twinning.

TABLE 2. PREDICTED TENSILE TWINNING STRESSES COMPARED WITH THE OBSERVED FLOW STRESSES

Crystal	Tensile Twinning Stress, psi, Calculated From the Observed Twinning Stress of Crystal 1	Observed Tensile Flow Stress at 0.08% Strain, psi	Observed Deformation Mode	Observed Flow Stress Resolved Onto the Optimum (110) Slip System, psi
1		71,900	Twinning	34,200
2	106,000	113,850	Slip	52,300
3	161,000	151,400	Slip	49,200
4	155,000	158,700	Slip	53,100
5	84,500	124,100	Slip	45,900
6	84,500	108,350	Slip	47,700
7	86,700	120,700	Slip	55,500
8	118,600	94,800	Slip	42,200
9	68,300	88,500	Slip	39,300
10	68,000	90,900	Slip	40,400

However, regardless of the mechanism visualized, the concept of a critical shear stress for twinning that prevails locally at twin nuclei remains a plausible hypothesis. Possibly, it is the internal stress concentrations that vary with orientation rather than the value of the shear stress.

Similarly, Table 2 shows that there is no truly critical macroscopic shear stress for slip; when the flow stresses are resolved onto the optimum (110) planes there is considerable orientation dependence, in common with many foregoing single-crystal studies. For slip, the discovery by Gilman and Johnston<sup>(62)</sup> of a relationship between the mean dislocation velocity  $\bar{v}$  and the applied stress  $\sigma$  has rendered obsolete the former concept. They showed that, in a tensile test, the imposed strain rate  $\dot{\epsilon}$  must be matched by elastic  $\dot{\epsilon}_e$  and plastic  $\dot{\epsilon}_p$  contributions:

$$\dot{\epsilon} = \dot{\epsilon}_e + \dot{\epsilon}_p \quad (5)$$

These may be written:

$$\dot{\epsilon} = \frac{1}{M} \frac{d\sigma}{dt} + 0.5 b \rho \bar{v}(\sigma) \quad (6)$$

where  $M$  is the elastic modulus of specimen and testing machine,  $\rho$  is the density of moving dislocations, and  $b$  is their Burger's vector. In mechanical tests of single crystals there is no control over the number of moving dislocations  $\rho$ . If this were to vary among crystals of different orientations then  $\bar{v}(\sigma)$  would have to vary inversely to maintain the equality of Equation (6); this would lead to a variety of values for  $\sigma$ , the flow stress. For example, the [111] crystals of columbium exhibited a marked tendency towards very localized slip, and it is likely that the number of dislocations participating in flow in this case is different from that of, say, a [011] crystal in which slip was much more uniform. It has been estimated<sup>(63)</sup> that for columbium,  $\bar{v}$  may be expressed:

$$\bar{v} \propto \sigma^{1.5} \quad (7)$$

Since variations of up to 30 per cent are observed in the resolved flow stress from crystal to crystal, this implies that  $\rho$  may vary by up to a factor of 50. With no control over  $\rho$ , it would be old fashioned to expect a critical resolved shear stress for slip.

The catastrophic shearing of thin layers of the [111] crystals at 78 K is a strange phenomenon from two points of view. First, the crystallography of the shear is quite unprecedented in bcc crystals, and secondly, it is unusual to observe this type of instability at such a high temperature. Since the unstable flow did not end in fracture, it was clearly not due to permanently inadequate strain hardening, like the well-known phenomenon of "necking". Also, it was established by metallographic sectioning that the instability was not due to twinning. Since the instability was only temporary, it may have been due to adiabatic heating of the specimen in the following steps. A region of the specimen is deforming normally, but due to small values of the specific heat and thermal conductivity the heat generated during deformation causes a finite rise in temperature. If the flow stress of the material is very temperature dependent, this warming of the specimen may cause an appreciable increase in the rate of deformation. This in turn will generate heat more rapidly and, if the rates of heat dissipation and work hardening do not increase correspondingly, a cyclic chain of events is initiated leading to higher and higher deformation rates. It is stopped in a hard machine when the rapidly deforming specimen relaxes the applied load. Basinski<sup>(59)</sup> has published a quantitative treatment of this type of instability; the factors promoting the instability are as follows:

- (1) A large dependence of flow stress on temperature; columbium, columbium being a bcc metal, fulfills this condition, as shown by Figure 13.
- (2) The concentration of flow into a small volume; the deforming lamella was only about 0.005 inch thick in these crystals.
- (3) A small value of the specific heat per unit volume; if the value for columbium is interpolated at 78 K from Reference (64), it is not particularly small, being comparable with that for iron.
- (4) A small value of the thermal conductivity; the value for columbium is about a quarter the value for iron at 78 K. <sup>(64)</sup>

Although columbium does not fulfill Conditions (3) and (4) especially well, it satisfies Conditions (1) and (2) very well. In fact it is perhaps the unusually localized deformation of this material that is largely responsible for the phenomenon at such an unprecedented temperature.

The highly unusual shear direction situated near [001] is most plausibly rationalized as being the net result of approximately equal slip in the conventional [111] and [1 $\bar{1}$ 1] directions. Alternatively, the effect could be due to slip dislocations of a [001] Burger's vector. However this is considered less likely because the shear direction is actually about 9 degrees away from [001] and such dislocations have never been observed.

#### The Kinetics of Twin Growth

It has been established by this work that a burst of twins forms in Mo-35Re in less than 2  $\mu$ sec. The formation of a twin is expected to generate a shear-stress wave, which, in propagating may initiate further twinning, leading to a burst. If this is so, then the duration of a burst is expected to be similar to the time taken by a sound wave emanating across the area of material covered by the burst. The speed of shear-stress waves,  $c$ ,

was measured in Mo-35Re by measuring the resonant frequency of a cylindrical bar attached to an Elastomat Model 500 dynamic modulus machine. The value obtained for  $c$  was  $3.1 \times 10^5$  cm/sec. The bursts observed by photography covered an area of approximately  $3 \times 3$  mm, and the time taken by a shear-stress wave to cross this area is  $1 \mu\text{sec}$ ; this value is less than  $2 \mu\text{sec}$ , so the above mechanism of burst initiation by stress waves is consistent with the observations.

Figures 18 and 20 illustrate that the nucleation of twins occurs only at small strains; apparently conditions favorable for nucleation exist only at small strains, despite the fact that the nominal stress is continuously rising. Probably, after 3 per cent strain, enough mobile dislocations have been generated to continue deformation largely by slip. However, Figure 19 shows that some thickening of twin lamellae occurs up to 12 per cent strain; this is consistent with the gradual growth observed in electron transparent zinc<sup>(21)</sup> and tin<sup>(40)</sup>. The mechanism observed was the nucleation and movement of twinning partial dislocations, which, because of a small Burger's vector, are expected to occur at modest stresses. This model may well have application to Mo-35Re in bulk.

#### CONCLUSIONS

- (1) Twin-induced cracking is observed in  $[011]$  single crystals of molybdenum-carbon and in polycrystalline molybdenum-carbon with a grain size of 0.40 mm compressed at 78 K.
- (2) Fractures of molybdenum-carbon with grain sizes of 0.25 mm and smaller are by grain-boundary-induced cleavage at temperatures above 77 K.
- (3) Twin-induced fracture is not observed above 20 K in high-purity columbium with a grain size of 0.38 mm, nor it is observed at 78 K in columbium single crystals of widely varied orientation.
- (4) Polycrystalline columbium containing a  $[011]$  fiber texture deforms at 78 K by different modes in tension and compression.
- (5) Unstable shearing of  $[\bar{1}11]$ -oriented columbium crystals in the  $[001]$  direction was observed at 78 K when they were deformed in tension.
- (6) Bursts of twins are formed in Mo-35Re under tension at 298 K in a period of time  $< 2 \mu\text{sec}$ . The contribution of twinning to the deformation of Mo-35Re decreases with increasing strain.

LIST OF REFERENCES

- (1) Paxton, H. W. , Acta Met. , 1, 141 (1953).
- (2) Hull, D. , Acta Met. , 8, 11 (1960).
- (3) Hornbogen, E. , Trans. AIME, 221, 711 (1961).
- (4) Cahn, R. W. , and Coll, J. A. , Acta Met. , 9, 138 (1961).
- (5) McHargue, C. J. , Acta Met. , 8, 900 (1960).
- (6) McHargue, C. J. , Trans. AIME, 224, 334 (1962).
- (7) Barrett, C. S. , and Bakish, R. , Trans. AIME, 212, 122 (1958).
- (8) Marcinkowski, M. J. , and Lipsitt, H. A. , Acta Met. , 10, 95 (1962).
- (9) Cahn, R. W. , Inst. Met. , 83, 493 (1945-55).
- (10) Wolff, U. E. , Trans. AIME, 224, 327 (1962).
- (11) Lawley, A. , and Maddin, R. , Trans. AIME, 224, 573 (1962).
- (12) Jaffee, R. I. , Maykuth, D. J. , and Douglas, R. W. , AIME Symposium on Refractory Metals, Detroit, 1960, Intersciences Publishers, Inc. , New York (1961).
- (13) Schmid, E. , and Boas, I. W. , Plasticity of Crystals, F. A. Hughes & Co. Limited, London (1950), p 72.
- (14) Allen, N. P. , Hopkins, B. E. , and McLennan, J. E. , Proc. Roy. Soc. 234A, 221 (1956).
- (15) Geil, G. W. , and Carwile, N. L. , Trans. AIME, 197, 213 (1953).
- (16) Keh, A. S. , and Weissmann, S. , Conference on The Impact of Electron Microscopy on The Theories of The Strength of Crystals, Berkeley, 1961. To be published by Intersciences Publishers, Inc. , New York.
- (17) Probst, H. B. , Trans. AIME, 221, 741 (1961).
- (18) Mueller, F. O. , and Parker, E. R. , ONR Technical Report 222 (52), June, 1960.
- (19) Sleeswyk, A. W. , DeGeus, A. , and Helle, J. N. , To be published in Acta Met.
- (20) Bell, R. L. , and Cahn, R. W. , Proc. Roy. Soc. , 239A, 494 (1957).
- (21) Price, P. B. , Proc. Roy. Soc. , 260A, 251 (1961).

- (22) Siems, V. R. , and Haasen, P. , Z. Metallkunde, 49, 213 (1958).
- (23) Leslie, W. C. , Hornbogen, E. , and Dieter, G. E. , J. Iron Steel Inst. , 200, 622 (1962).
- (24) Votava, E. , Acta Met. , 10, 744 (1962).
- (25) Maiden, C. J. , Acta Met. , 7, 297 (1959).
- (26) Hull, D. , Acta Met. , 9, 191 (1961).
- (27) Hahn, G. T. , Cohen, M. , and Averbach, B. L. , J. Iron Steel Inst. , 200, 634 (1962).
- (28) Low, J. R. , Relation of Properties To Microstructures, Am. Soc. Metals, Cleveland (1954).
- (29) Adams, M. A. , Roberts, A. C. , and Smallman, R. E. , Acta Met. , 8, 328 (1960).
- (30) Anderson, R. W. , and Bronisz, S. E. , Acta Met. , 7, 645 (1959).
- (31) Simonsen, E. B. , Act Met. , 8, 809 (1960).
- (32) Wellings, J. F. , and Maddin, R. , University of Pennsylvania Report, 1962.
- (33) Low, J. R. , and Feustel, R. G. , Acta Met. , 1, 185 (1953).
- (34) Edmondson, B. , Proc. Roy. Soc. , 264A, 176 (1961).
- (35) Jillson, D. C. , Trans. AIME, 188, 1009 (1950).
- (36) Förster, V. F. , and Scheil, E. , Z. Metallkunde, 32, 165 (1940).
- (37) Bunshah, R. F. , and Mehl, R. F. , WADC Technical Report, 54-332 (September, 1954).
- (38) Mason, W. P. , McSkimin, M. J. , and Shockley, W. , Phys. Rev. , 73, 1213 (1948).
- (39) Thompson, N. , and Millard, D. J. , Phil. Mag. , 43, 422 (1952).
- (40) Fourie, J. T. , Weinberg, F. , and Boswell, W. C. , Acta Met. , 8, 851 (1960).
- (41) Koehler, J. S. , Seitz, F. , Read, W. T. , Shockley, W. , and Orowan, E. , Dislocations in Metals, AIME, New York (1954), p 119.
- (42) Cottrell, A. M. , and Bilby, B. A. , Phil. Mag. , 42, 573 (1951).
- (43) Sleswyk, A. W. , Acta Met. , 10, 705 (1962).
- (44) Hahn, G. T. , Averbach, B. L. , Owen, W. S. , and Cohen, M. , Fractures, John Wiley & Sons, Inc. , New York (1959), p 91.

- (45) Honda, R. , J. Phys. Soc. Japan, 16, 1309 (1961).
- (46) Sleeswyk, A. W. , Acta Met. , 10, 803 (1962).
- (47) Hull, D. , Conference on Fracture, Seattle, 1962.
- (48) Low, J. R. , Fracture, John Wiley & Sons, Inc. , New York (1959), p 114.
- (49) Berry, J. M. , Trans. ASM, 51, 556 (1959).
- (50) Bilby, B. A. , and Bullough, R. , Phil. Mag. , 45, 631 (1954).
- (51) Deruyttere, A. , and Greenough, G. B. , Phil. Mag. , 45, 624 (1954).
- (52) Wessel, E. , Proc. ASTM, 540 (1956).
- (53) Hahn, G. T. , Gilbert, A. , and Jaffee, R. I. , Conference on Refractory Metals, Chicago, 1962.
- (54) Alers, G. A. , Armstrong, R. W. , and Bechtold, J. H. , Trans. AIME, 212, 523 (1958).
- (55) Calverley, A. , Davis, M. , and Lever, R. , J. Sci. Inst. , 34, 142 (1957).
- (56) Barrett, C. S. , Structure of Metals, McGraw-Hill Inc. , New York (1952), p 170.
- (57) Leber, S. , Trans. ASM, 53, 697 (1960).
- (58) Barrett, G. S. , Structure of Metals, McGraw-Hill Inc. , New York (1952), p 444.
- (59) Basinski, Z. S. , Proc. Roy. Soc. , 240A, 229 (1957).
- (60) Young, A. P. , and Marsh, L. L. , Trans. AIME, 212, 247 (1958).
- (61) Clough, W. R. , and Pavlovic, A. S. , Trans. ASM, 52, 948 (1960).
- (62) Johnston, W. G. , and Gilman, J. J. , J. Appl. Phys. , 30, 129 (1959).
- (63) Hahn, G. T. , Acta Met. , 10, 727 (1962).
- (64) Goldsmith, A. , Waterman, T. E. , and Hirschhorn, H. J. , Handbook of Thermo-physical Properties of Solid Materials, MacMillan, New York (1961), p 464.

DISTRIBUTION LIST

ASD (ASAPRL, Library)  
Wright-Patterson AFB, Ohio

ASD (ASAPT) (3)  
Wright-Patterson AFB, Ohio

ASD (ASAPR, Mr. Daniels)  
Wright-Patterson AFB, Ohio

ASD (ASNRFM, Mr. Middendorp)  
Wright-Patterson AFB, Ohio

ASD (ASRCN) (6)  
Wright-Patterson AFB, Ohio

ASD (ASRCM)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-32) (50)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-31)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-33)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-34)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-3)  
Wright-Patterson AFB, Ohio

ASD (ASRC)  
Wright-Patterson AFB, Ohio

ASD (ASRCE, Library) (2)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-2)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-1)  
Wright-Patterson AFB, Ohio

ASD (BWFRR) (4)  
Wright-Patterson AFB, Ohio

ASD (ASOPR, Mr. Michael)  
Wright-Patterson AFB, Ohio

ASD (ASNVSS, Mr. B. Cohen)  
Wright-Patterson AFB, Ohio

ASD (ASNSFS, Mr. Rosenkranz)  
Wright-Patterson AFB, Ohio

ASD (ASRM)  
Wright-Patterson AFB, Ohio

ASD (ASRCE-21, Mr. Hjelm)  
Wright-Patterson AFB, Ohio

ASD (ASRCT-4, L/Col. Morse)  
Wright-Patterson AFB, Ohio

ASD (ASRCT, L/Col. Hughes) (3)  
Wright-Patterson AFB, Ohio

ASD (ASRCT-1, Mr. Albrecht)  
Wright-Patterson AFB, Ohio

ASD (ASRCE) (2)  
Wright-Patterson AFB, Ohio

ASD (ASNE)  
Wright-Patterson AFB, Ohio

ASD (ASNLA)  
Wright-Patterson AFB, Ohio

ASD (ASNNI)  
Wright-Patterson AFB, Ohio

ASD (ASNPO)  
Wright-Patterson AFB, Ohio

ASD (ASNC)  
Wright-Patterson AFB, Ohio

ASD (ASNDA)  
Wright-Patterson AFB, Ohio

ASD (ASRSS)  
Wright-Patterson AFB, Ohio

DISTRIBUTION LIST

(Continued)

ASD (ASRE)  
Wright-Patterson AFB, Ohio

ASD (ASYIM, Capt. Bubba)  
Wright-Patterson AFB, Ohio

ASD (ASEP)  
Wright-Patterson AFB, Ohio

ASD (ASRMDS-21)  
Wright-Patterson AFB, Ohio

ASD (ASRCM-4)  
Wright-Patterson AFB, Ohio

ASD (ASRCP)  
Wright-Patterson AFB, Ohio

ASD (ASTIA, TISIA) (30)  
Arlington Hall Station  
Arlington 12, Virginia

ASD (OTS Stock)  
1200 South Eads Street  
Arlington, Virginia

AFSC ST Liaison Office  
Ames Research Center  
Moffett Field, California

AFSC Liaison Office  
Langley Research Center (NASA)  
Langley Air Force Base, Virginia

AFSC Scientific & Technical Liaison  
Office  
NASA Lewis Research Center  
Attn: G. M. Ault  
21000 Brookpark Road  
Cleveland 35, Ohio

AFSC Scientific & Technical Liaison  
Office  
NASA Lewis Research Center  
Attn: Lt. Col. D. J. Iddins  
21000 Brookpark Road  
Cleveland 35, Ohio

AFSC Scientific & Technical Liaison  
Office  
NASA Lewis Research Center  
Attn: J. W. Weeton  
21000 Brookpark Road  
Cleveland 35, Ohio

U. S. Atomic Energy Commission  
Division of Technical Information  
Extension  
Attn: Document Management Branch  
P. O. Box 62  
Oak Ridge, Tennessee

AFSC (RTK, Lt. Col. H. C. Hamlin)  
R&T Division  
Bolling AFB  
Washington 25, D. C.

United States Atomic Energy Commission  
Attn: W. F. Sheely  
Washington 25, D. C.

U. S. Atomic Energy Commission  
New York Operations Office  
Attn: Library  
376 Hudson Street  
New York 14, New York

U. S. Atomic Energy Commission  
Attn: M. J. Whitman  
Division of Reactor Development  
Washington 25, D. C.

U. S. Atomic Energy Commission  
Attn: Mr. S. S. Christopher  
Division of Reactor Development  
Washington 25, D. C.

Advanced Metals Research Corporation  
Attn: Dr. Sheldon Moll  
625 McGrath Highway  
Somerville 45, Massachusetts

Advanced Technology Laboratories  
Attn: Dr. Dennis D. Foley  
369 Whisman Road  
Mountain View, California

DISTRIBUTION LIST

(Continued)

Aerojet-General Corporation  
Attn: J. W. Campbell  
B/159, D/326  
Azusa, California

Aerojet-General Corporation  
Liquid Rocket Plant Department 9636  
Attn: G. R. Jansen  
P. O. Box 1947  
Sacramento, California

Aerojet-General Corporation  
Attn: P. L. Jordan  
Department 326  
Structural Materials Division  
Azusa, California

Aerojet-General Corporation  
Solid Rocket Plant  
Attn: R. J. Kotfila Dept. 4610  
Box 1947  
Sacramento, California

Aerojet General Corporation  
Attn: A. V. Levy  
Solid Rocket Plant Dept. 4610  
Sacramento, California

Aerojet-General Corporation  
Technical Library  
Bldg. 2015 Dept. 2410  
P. O. Box 1947  
Sacramento 9, California

Aerojet-General Corporation  
Solid Rocket Plant  
Attn: R. E. Matt Dept. 4610  
Materials Research and Development  
P. O. Box 1947  
Sacramento, California

Aerojet-General Corporation  
Attn: S. E. Slosarik, Head Non-  
Metallics Section  
Department 4610  
Solid Rocket Plant  
Box 1947  
Sacramento, California

Aerojet-General Corporation  
Solid Rocket Plant  
Attn: Dr. Arthur J. Stosick  
P. O. Box 1947  
Sacramento, California

Aerojet-General Corporation  
Solid Rocket Plant  
Attn: Mr. J. J. Warga Dept. 4610  
Box 1947  
Sacramento, California

Aeronutronic  
Attn: Dr. E. Harmon  
Box 697  
Newport Beach, California

Aerospace Corporation  
Attn: S. L. Channon, Metallic Materials  
Section  
San Bernardino, California

Aerospace Corporation  
Attn: Aerospace Library  
Technical Reports Group  
(W. J. Bennison)  
P. O. Box 95085  
Los Angeles 45, California

Aerospace Corporation  
Attn: H. Conrad  
P. O. Box 95085  
Los Angeles 45, California

AiResearch Manufacturing Company  
of Arizona  
Attn: Librarian  
P. O. Box 5217  
Phoenix 34, Arizona

AiResearch Manufacturing Company  
of Arizona  
The Garrett Corporation  
Attn: E. A. Kovacevich  
402 South 35th Street  
Phoenix, Arizona

DISTRIBUTION LIST

(Continued)

AiResearch Manufacturing Company  
Attn: Virgil K. Crawford  
Supervisor, Materials & Processes  
Engineering  
9851 Sepulveda Blvd.  
Los Angeles 45, California

Ajax Steel and Forge Company  
Attn: Mr. A. Lumsden  
205 Adair Street  
Detroit 7, Michigan

Allegheny Ludlum Steel Corporation  
Attn: W. W. Dyrkacz  
Division Manager of Quality  
Control  
Watervliet, New York

Allegheny Ludlum Steel Corporation  
Attn: P. A. Santoli  
Research Center  
Brackenridge, Pennsylvania

Allis-Chalmers Mfg. Company  
Attn: William D. Stimmel  
Research Laboratories Library  
P. O. Box 512  
Milwaukee 1, Wisconsin

Alloyd Electronics Corporation  
Attn: N. W. Kirshenbaum  
35 Cambridge Parkway  
Cambridge 42, Massachusetts

American Bosch Arma Corporation  
Arma Division  
Attn: F. Stirbl  
Garden City, New York

Argonne National Laboratory  
9700 S. Cass Avenue  
Argonne, Illinois

Armetco, Incorporated  
Attn: Robert Knight  
776 Kemrow Avenue  
Wooster, Ohio

Armour Research Foundation  
Illinois Institute of Technology  
Attn: Dr. W. Rostoker  
Chicago 16, Illinois

Astropower, Inc.  
Attn: Dr. N. A. Tiner  
Research Scientist  
2968 Randolph Avenue  
Costa Mesa, California

Atlantic Research Corporation  
Attn: Mr. E. L. Olcott  
Shirley Highway at Edsall Road  
Alexandria, Virginia

Atomics International Division  
North American Aviation  
Attn: Mr. John P. Page  
Engineering Materials Group  
Fuel & Materials Department  
8900 DeSoto Street  
Canoga Park, California

Avco Research and Advanced Development  
Attn: J. M. Williams  
Acting Manager  
Materials Department  
Wilmington, Massachusetts

BSD  
Attn: BSRPS-2 (Maj. I. K. Holdener)  
AF Unit Post Office  
Los Angeles 45, California

Battelle Memorial Institute  
Attn: Dr. R. I. Jaffee  
Technical Manager  
Department of Metallurgy  
505 King Avenue  
Columbus 1, Ohio

Battelle Memorial Institute  
Defense Metals Information Center  
505 King Avenue  
Columbus 1, Ohio

DISTRIBUTION LIST

(Continued)

Battelle Memorial Institute  
Attn: H. R. Ogden  
505 King Avenue  
Columbus 1, Ohio

Bell Aerosystems Company  
Attn: G. F. Kappelt  
Director, Engr. Lab.  
P. O. Box 1  
Buffalo 5, New York

Bendix Products Aerospace Division  
The Bendix Corporation  
Attn: Ceramic Engineering Department  
701 Bendix Drive  
South Bend, Indiana

Bethlehem Steel Company, Inc.  
Attn: J. S. Marsh  
Bethlehem, Pennsylvania

The Boeing Company  
Aerospace Division  
Attn: E. E. Bauer 2-5545 28-81  
(Interplant)  
P. O. Box 3707  
Seattle 24, Washington

The Boeing Company  
Aerospace Division  
Attn: E. G. Czarnecki  
Department Manager Structures  
Technology Department  
P. O. 3707  
Seattle, Washington

The Boeing Company  
Attn: Librarian  
Box 3707 Org 23930  
Seattle, Washington

The Boeing Company  
Aerospace Division  
Attn: Mr. J. T. Stacy  
P. O. Box 3707  
Seattle 24, Washington

The Boeing Company  
Aero-Space Division  
Attn: Mr. J. W. Sweet  
Chief Metallurgist  
P. O. Box 3707  
Seattle 24, Washington

Bridgeport Brass Company  
Attn: H. G. Carmichael  
P. O. Box 344  
Ashtabula, Ohio

Bridgeport Brass Company  
Reactive Metals, Inc.  
Attn: L. G. McCoy  
Niles, Ohio

Brooks and Perkins, Inc.  
Attn: Dr. Ross, Vice-President  
Research and Engineering  
1950 West Fort Street  
Detroit 16, Michigan

Brookhaven National Laboratory  
Information and Publication Division  
Attn: Classified Document Groups  
Upton, New York

William L. Bruckart  
Metallurgical and Marketing Consultant  
85 Inglewood Drive  
Pittsburgh 28, Pennsylvania

California Institute of Technology  
Attn: Dr. Pol Duwez  
Professor of Mechanical Engineering  
Pasadena, California

University of California  
Material Science Department  
Attn: Prof. Garreth Thomas  
Berkeley, California

University of California  
Lawrence Radiation Laboratory  
Technical Information Division  
Attn: Dr. R. K. Wakerling  
Berkeley 4, California

DISTRIBUTION LIST

(Continued)

University of California  
Radiation Laboratory  
P. O. Box 808  
Livermore, California

University of California  
Lawrence Radiation Laboratory  
Attn: R. F. Bunshah  
P. O. Box 808  
Livermore, California

University of California  
Metallurgy Department  
Attn: Dr. John Dorn  
Berkeley, California

Case Institute of Technology  
Metals Research Laboratory  
Attn: Professor W. M. Baldwin, Jr.  
Cleveland, Ohio

Carnegie Institute of Technology  
Metals Research Laboratory  
Pittsburgh 13, Pennsylvania

Carnegie Institute of Technology  
Metals Research Laboratory  
Attn: Dr. C. L. McCabe  
Schenley Park  
Pittsburgh 13, Pennsylvania

Chance Vought Corporation  
Materials Development  
Aeronautics Division  
Attn: Robert A. Hart  
P. O. Box 6267  
Dallas 22, Texas

Chrysler Corporation Missile Division  
Materials Laboratory  
Attn: R. E. Mahr, Manager  
P. O. Box 2628  
Detroit 31, Michigan

University of Cincinnati  
Research Foundation  
Attn: Dr. M. Hoch  
Cincinnati 21, Ohio

Cleveland Tungsten, Inc.  
Attn: Mr. T. A. Havens  
10200 Meech Avenue  
Cleveland 5, Ohio

Cleveland Twist Drill Company  
Attn: R. D. Leshar  
Manufacturing Research  
Box 6656  
Cleveland 14, Ohio

Clevite Corporation  
Research Center  
Attn: Library  
540 East 105th Street  
Cleveland 8, Ohio

Climax Molybdenum Company, Inc.  
Attn: Norman L. Deuble  
1270 Avenue of Americas  
New York 20, New York

Climax Molybdenum Company  
Attn: Mr. M. Semchyshen  
14410 Woodrow Wilson Avenue  
Detroit 38, Michigan

Climax Molybdenum Company of Michigan  
Attn: Mr. G. A. Timmons  
14410 Woodrow Wilson  
Detroit 38, Michigan

U. S. Department of Commerce  
Patent Office  
Attn: Scientific Library  
Washington 25, D. C.

Consolidated Vacuum Corporation  
Attn: Mr. G. J. Ramsay  
1775 Mt. Read Boulevard  
Rochester 3, New York

Continental Aviation & Engineering  
Corporation  
Attn: Mr. F. E. Olmstead  
Chief Metallurgist  
12700 Kercheval Avenue  
Detroit 15, Michigan

DISTRIBUTION LIST

(Continued)

Convair  
Division of General Dynamics  
Attn: W. H. Steurer Materials  
San Diego 12, California

Cornell Aeronautical Laboratory, Inc.  
Attn: Dr. John Beal  
4455 Genesee Street  
Buffalo 21, New York

Cornell University  
School of Chemical and Metallurgical  
Engineering  
Olin Hall  
Attn: G. V. Smith  
Ithaca, New York

Crucible Steel Company of America  
Central Research Laboratory  
Attn: Mr. E. J. Dulis  
234 Atwood Street  
Pittsburgh 13, Pennsylvania

Crucible Steel Company of America  
Central Research Laboratory  
Attn: Research Librarian  
234 Atwood Street  
Pittsburgh 13, Pennsylvania

Curtiss-Wright Corporation  
Curtiss Division  
Attn: Mr. W. C. Schulte,  
Chief Engineer  
Materials  
U. S. Route 46  
Caldwell, New Jersey

Curtiss-Wright Corporation  
Wright Aeronautical Division  
Attn: Mr. Jesse Sohn, Manager Metallurgy  
Wood-Ridge, New Jersey

Curtiss-Wright Corporation  
Metals Processing Division  
Attn: Mr. C. F. Wagner  
Manager of Research  
760 Northland Avenue  
P. O. Box 13  
Buffalo 15, New York

Office of Assistant Secretary of Defense  
Research and Engineering  
The Pentagon  
Attn: Mr. John Barrett  
Washington, D. C.

Douglas Aircraft Company, Inc.  
Missile & Space Systems Division  
Attn: J. L. Waisman, Chief  
Materials Research &  
Production Methods  
Department A-260  
3000 Ocean Park Boulevard  
Santa Monica, California

Douglas Aircraft Company, Inc.  
Missiles and Space Division  
Attn: Mr. H. Leggett  
3000 Ocean Park Boulevard  
Santa Monica, California

The Dow Chemical Company  
Attn: Dr. J. W. Fredrickson  
Metallurgical Laboratory  
Midland, Michigan

Dynatech Corporation  
Attn: James Turner  
17 Tudor Street  
Cambridge, Massachusetts

Eastern Stainless Steel Corporation  
Attn: C. W. Koontz  
Baltimore 3, Maryland

E. I. dePont deNemours & Company  
Experimental Stations  
Attn: F. J. Anders, Jr.  
Pigment Department  
Wilmington 98, Delaware

E. I. duPont deNemours and Company,  
Inc.  
Engineering Research Laboratory  
Attn: Mr. R. W. Heckel  
Wilmington 98, Delaware

DISTRIBUTION LIST  
(Continued)

E. I. duPont deNemours & Company,  
Inc.  
Pigments Department  
Attn: H. B. Hix  
Supervisor - Columbian Sales  
Metal Products  
Wilmington 98, Delaware

E. I. duPont deNemours & Company,  
Inc.  
Pigments Department  
Attn: E. M. Mahla  
Technical Assistant Director  
Metal Products  
Wilmington 98, Delaware

Elliott Company  
Attn: Mr. J. A. Cameron  
Chief Metallurgist  
Jeanette, Pennsylvania

EOAR (ERTM, Capt. E. J. Myers)  
Brussels  
Belgium

Fairchild Stratos Corporation  
Aircraft-Missiles Division  
Attn: Engineering Library  
Hagerstown, Maryland

Fansteel Metallurgical Company  
Attn: Chief Metallurgist  
North Chicago, Illinois

Federal Aviation Agency  
Airframe Branch, FS-120  
Washington 25, D. C.

Federal Aviation Agency  
Aviation Research and Development  
Service  
Attn: RD-554  
Washington 25, D. C.

Firth Sterling, Inc.  
Attn: Mr. R. C. Painter  
3113 Forbes Avenue  
Pittsburgh 30, Pennsylvania

Firth Sterling, Inc.  
Attn: Dr. C. H. Toensing  
Director, Powder Metals Research  
P. O. Box 71  
Pittsburgh 30, Pennsylvania

University of Florida  
Metallurgy Research Laboratory  
College of Engineering  
Attn: Dr. F. N. Rhines  
Gainesville, Florida

Ford Motor Company  
Scientific Laboratory  
Technical Information Section  
Attn: Mrs. L. B. Phillips  
P. O. Box 2053  
Dearborn, Michigan

General Atomic  
Division of General Dynamics Corporation  
Attn: Library  
P. O. Box 608  
San Diego 12, California

General Dynamics/Astronautics  
Attn: Mr. H. Micken  
Mail Zone 290-30  
P. O. Box 1128  
San Diego 12, California

General Dynamics/Pomona  
A Division of General Dynamics  
Corporation  
Attn: Mr. R. J. Sneed  
Physics and Infrared Section  
Mail Zone 6-91  
Pomona, California

General Electric Company  
Thomson Engineering Laboratory (SAED)  
Attn: R. D. Halverstadt  
1000 Western Avenue  
W. Lynn 3, Massachusetts

DISTRIBUTION LIST

(Continued)

General Electric Company  
Nuclear Materials and Propulsion  
Operations  
Attn: V. P. Calkins  
P. O. Box 132  
Cincinnati 15, Ohio

General Electric Company  
Lamp Metals and Components  
Department  
Attn: Stephen Foldes  
Engineering 731  
21800 Tungsten Road  
Cleveland 17, Ohio

General Electric Company  
General Engineering Laboratory  
Attn: Mr. R. W. Hardt 37-2053  
Schenectady, New York

General Electric Company  
FPD Flight Propulsion Laboratory  
Department  
Attn: L. P. Jahnke  
Cincinnati 15, Ohio

General Electric Corporation  
Lamp Metals and Components Parts  
Department  
Attn: Sam Leber Eng. Nr. 731  
21800 Tungsten Road  
Cleveland 17, Ohio

General Electric Company  
Nuclear Materials and Propulsion  
Operations  
Attn: J. McGurty  
P. O. Box 132  
Cincinnati 15, Ohio

General Electric Company  
The Whitney Library  
P. O. Box 1088  
Schenectady, New York

General Electric Company  
Lamp Metals & Components Department  
Attn: J. W. Pugh  
Manager Metallurgical Studies &  
Alloys Division  
21800 Tungsten Road  
Cleveland 17, Ohio

General Electric Company  
Refractory Metals Project  
Attn: L. G. Rattray  
Cleveland 17, Ohio

General Electric Company  
Attn: Dr. J. W. Semmel, Jr.  
Building 100 F104  
Evendale, Ohio

General Electric Company  
Large Steam Turbine-Generator  
Department  
Attn: B. M. Wundt, Structural Engineer  
Schenectady, New York

General Motors Corporation  
Allison Division  
Attn: D. K. Hanink, Manager Materials  
Laboratories Activity  
P. O. Box 894  
Indianapolis 6, Indiana

General Motors Corporation  
Research Laboratories  
Attn: Dr. Robert F. Thomson  
Head Metallurgical  
Engineering Department  
12 Mile and Mound Roads  
Warren, Michigan

General Telephone and Electronics  
Laboratories  
Attn: Leslie L. Seigle  
Scientist in Charge of Metallurgy  
Bayside 60, New York

DISTRIBUTION LIST

(Continued)

Grumman Aircraft Engineering  
Corporation  
Attn: Engineering Library, Plant 5  
Bethpage, Long Island, New York

Hamilton Standard Division  
Division of United Aircraft Corporation  
Attn: H. P. Langston  
Windsor Locks, Connecticut

Harvey Aluminum, Inc.  
Attn: Mr. G. A. Moudry  
19200 South Western Avenue  
Torrance, California

Haynes Stellite Company  
Attn: B. R. Barrett  
Kokomo, Indiana

Haynes Stellite Company  
Divisions of Union Carbide  
Corporation  
Attn: G. A. Fritzlen  
1020 West Park Avenue  
Kokomo, Indiana

Horizons, Inc.  
Attn: Library  
2905 East 79th Street  
Cleveland 4, Ohio

Hughes Aircraft Company  
Attn: Technical Document Center  
Florence and Teals  
Culver City, California

U. S. Department of Interior  
Bureau of Mines, Region I  
Attn: Mr. Haruo Kato  
P. O. Box 492  
Albany, Oregon

U. S. Department of Interior  
Bureau of Mines  
Attn: Dr. Edward A. Rowe  
1605 Evans Avenue  
Reno, Nevada

U. S. Department of the Interior  
Bureau of Mines, Region IV  
Attn: Mr. James Rowland  
Rolla, Missouri

U. S. Department of the Interior  
Bureau of Mines  
Attn: Chief Metallurgist  
R. 4624, Interior Building  
Washington 25, D. C.

U. S. Department of the Interior (2 cys)  
Bureau of Mines  
Attn: Librarian, Region I  
Albany, Oregon

The International Nickel Company, Inc.  
Huntington Alloy Products Division  
Attn: M. P. Buck  
Technical Advisor  
67 Wall Street  
New York 5, New York

Ipsen Industries, Inc.  
P. O. Box 500  
Rockford, Illinois

Mr. J. E. Joers, Production Division  
Director of Procurement and Production  
Office DCS/Materiel, The Pentagon  
Washington, D. C.

John Hopkins University  
Applied Physics Laboratory  
8621 Georgia Avenue  
Silver Spring, Maryland

Jet Propulsion Laboratory  
California Institute of Technology  
Attn: Materials Section  
4800 Oak Grove Drive  
Pasadena 3, California

Kawecki Chemical Company  
Attn: H. T. Sharpe  
220 East 42nd Street  
New York 17, New York

DISTRIBUTION LIST  
(Continued)

Kennecott Copper Corporation  
Attn: H. Lanier  
161 East 42nd Street  
New York 17, New York

Koppers Company, Inc.  
Metal Products Division  
Attn: G. F. Hyde, Manager  
Metallurgical and Chemical  
Laboratory  
Baltimore 3, Maryland

Ladish Company  
Attn: C. A. Furgason  
Vice President Research &  
Metallurgy  
Cudahy, Wisconsin

Lehigh University  
Department of Metallurgical  
Engineering  
Attn: Dr. J. F. Libsch  
Bethlehem, Pennsylvania

Linde Company Speedway Laboratories  
Attn: Dr. Milton Stern  
1500 Polco Street  
Indianapolis 24, Indiana

Lockheed Missiles & Space (2 cys)  
Company  
Technical Information Center (50-14)  
Attn: Dr. W. A. Kozumplik, Manager  
3251 Hanover Street  
Palo Alto, California

Lockheed Missiles and Space Company  
Attn: T. E. Tietz  
3251 Hanover Street  
Palo Alto, California

Lockheed California Company  
Materials and Processes  
Attn: Mr. George G. Wald  
Burbank, California

Lockheed Missiles and Space Company  
Attn: Roger A. Perkins  
Department 52-30  
3251 Hanover Street  
Palo Alto, California

Los Alamos Scientific Laboratory  
Attn: Document Custodian  
P. O. Box 1663  
Los Alamos, New Mexico

Lycoming Division  
AVCO Corporation  
Attn: Dr. H. K. Adenstedt  
550 South Main Street  
Stratford, Connecticut

ManLabs, Inc.  
21 Erie Street  
Cambridge 39, Massachusetts

Martin-Marietta Corporation  
Attn: K. R. Agricola  
P. O. Box 179, Mail No. L-8  
Denver 1, Colorado

Martin-Marietta Corporation  
Attn: Materials Engineering Section  
Mail No. J366  
Baltimore 3, Maryland

Martin-Marietta Corporation  
Attn: Mr. Rudolf H. Thielemann  
Director  
Metals Technology Laboratory  
9340 S. W. Barnes Road  
Portland, Oregon

Marquardt Aircraft Corporation  
Attn: Albert Bennett  
16555 Saticoy Street  
Van Nuys, California

The Marquardt Corporation  
Attn: S. Sklarew, Supervisor  
Non-Metallic Materials Unit  
Materials & Process Laboratory  
16555 Saticoy Street  
Van Nuys, California

DISTRIBUTION LIST  
(Continued)

The Marquardt Corporation  
Materials and Processing  
Attn: M. J. Albom  
16555 Saticoy Street  
Van Nuys, California

Marquardt Aircraft Company  
Attn: J. W. Chambers  
16555 Saticoy Street  
Van Nuys, California

Massachusetts Institute of  
Technology  
Attn: Dr. M. C. Flemings  
Room 35-316  
Cambridge 39, Massachusetts

Massachusetts Institute of  
Technology  
Attn: Dr. John Wulff  
Room 35-318  
Cambridge 39, Massachusetts

Materials Advisory Board  
National Academy of Sciences  
Attn: Dr. J. R. Lane  
Washington 25, D. C.

Materials Research Corporation  
Attn: S. Weinig  
Orangeburg, New York

Mellon Institute of Industrial  
Research  
440 Fifth Avenue  
Pittsburgh 13, Pennsylvania

Metcut Research Associates, Inc.  
Attn: Dr. J. F. Kahles  
Vice President  
3980 Rosslyn Drive  
Cincinnati 9, Ohio

Michigan College of Mining and  
Technology  
Department of Metallurgical Engineering  
Attn: Dr. R. L. Smith  
Houghton, Michigan

Minnesota Mining and Manufacturing  
Company  
Attn: T. R. Bergstrom  
2301 Hudson Road  
St. Paul 19, Minnesota

McDonnell Aircraft Corporation  
Attn: H. J. Siegel, Department 272  
P. O. Box 516  
St. Louis 66, Missouri

McDonnell Aircraft Corporation  
Attn: R. D. Detrich  
Assistant Supervisor  
Engineering Library  
P. O. Box 516  
St. Louis 66, Missouri

National Aeronautics and Space  
Administration  
Lewis Research Center  
Attn: Mr. R. W. Hall  
21000 Brookpark Road  
Cleveland 11, Ohio

National Aeronautics and Space  
Administration  
Plumbrook Reactor  
Attn: C. B. Hartley  
Sandusky, Ohio

National Aeronautics and Space  
Administration  
Lewis Research Center  
Attn: R. A. Lad  
21000 Brookpark Road  
Cleveland 35, Ohio

NASA - Lewis Research Center  
Space Electric Power Office  
Attn: Tom Moss  
21000 Brookpark Road  
Cleveland 35, Ohio

National Research Corporation  
Attn: Mr. John Ham  
Research Associates  
70 Memorial Drive  
Cambridge 42, Massachusetts

DISTRIBUTION LIST

(Continued)

National Research Corporation  
Metals Division  
Attn: Dr. M. L. Torti  
Director Metallurgical Research  
70 Memorial Drive  
Cambridge 42, Massachusetts

U. S. Naval Ordnance Test Station  
Attn: Materials Research Branch  
Code 4526  
China Lake, California

Chief  
Office of Naval Research  
Attn: Dr. Salkowitz  
Metallurgy Branch  
Washington, D. C.

New England Materials Laboratory,  
Inc.  
Attn: Robert Widmer  
35 Commercial Street  
Medford 55, Massachusetts

New York Naval Shipyard  
Material Laboratory Library  
Building 291, Code 911B  
Brooklyn 1, New York

Chief  
Bureau of Naval Weapons  
Department of the Navy  
Attn: Materials Branch, RRMA  
Washington 25, D. C.

North American Aviation, Inc.  
Attn: G. A. Fairbairn  
Engineering Metallic Materials  
Laboratory  
Los Angeles 45, California

North American Aviation, Inc.  
Space & Information Systems Division  
Attn: Technical Information Center  
Department 486-14  
(For J. O. Huffman)  
12214 Lakewood Boulevard  
Downey, California

North American Aviation  
Attn: D. E. Myers  
Department 56  
Group 752  
Columbus, Ohio

United Nuclear Corporation  
Development Division  
Attn: Library  
5 New Street  
White Plains, New York

Nuclear Metals, Inc.  
Attn: Document Library  
P. O. Box 125  
West Concord, Massachusetts

Nuclear Metals, Inc.  
Attn: Dr. E. J. Rapperport  
Concord, Massachusetts

AFOSR (SRPS, Capt. R. A. Schalow)  
Washington 25, D. C.

Oak Ridge National Laboratory  
Attn: Mr. W. C. Thurber  
Metals and Ceramics Division  
P. O. Box X  
Oak Ridge, Tennessee

Ohio State University  
Department of Metallurgy  
Attn: Dr. Rudolph Speiser  
124 West 17th Avenue  
Columbus 10, Ohio

Office of the Chief of Ordnance  
Department of the Army  
Attn: ORDTB Materials  
Washington, D. C.

Oregon Metallurgical Corporation  
Attn: Mr. Russell G. Hardy  
Chief Metallurgist  
P. O. Box 484  
Albany, Oregon

DISTRIBUTION LIST

(Continued)

Oregon Metallurgical Corporation  
Attn: Mr. S. M. Shelton  
P. O. Box 484  
Albany, Oregon

University of Pennsylvania  
Attn: Dr. R. Maddin  
Philadelphia 4, Pennsylvania

Polytechnic Institute of Brooklyn  
Attn: Prof. G. J. Fischer  
333 Jay Street  
Brooklyn 1, New York

Pratt and Whitney Aircraft  
Connecticut Operations - CANEL  
Attn: L. M. Raring  
P. O. Box 611  
Middletown, Connecticut

Rand Corporation  
Attn: Library  
1700 Main Street  
Santa Monica, California

Rensselaer Polytechnic Institute  
Department of Materials Engineering  
Attn: Dr. E. F. Nippes  
Troy, New York

Republic Aviation Corporation  
R. F. Wichser, Adv. Systems &  
Research  
Attn: F. W. Eversley, Jr.  
Applied Research and Development  
Farmingdale, Long Island, New York

Republic Steel Corporation  
Attn: Mr. D. H. Ruhnke  
Massillon, Ohio

Rocketdyne  
A Division of North American  
Aviation, Inc.  
Materials Research  
Attn: Dr. W. T. Chandler  
6633 Canoga Avenue  
Canoga Park, California

Rocketdyne  
A Division of North American  
Aviation, Inc.  
Attn: D. E. Roda  
6633 Canoga Avenue  
Canoga Park, California

Ryan Aeronautical Company  
Attn: Mr. W. G. Hubbell  
Department 310  
Engineering Division  
2701 Harbor Drive  
San Diego 12, California

Sandia Corporation  
Sandia Base  
Attn: Technical Library  
Albuquerque, New Mexico

Sandia Corporation  
Sandia Base  
Attn: J. Read Holland  
Department 5130  
Albuquerque, New Mexico

U. S. Small Business Administration  
Attn: Mr. G. W. Seymour, Chief  
Research & Development Division  
Vermont and H Streets  
Washington 25, D. C.

Sixth Regional Office  
U. S. Small Business Administration  
Attn: Mr. J. E. Shondel  
1370 Ontario Street  
Cleveland 13, Ohio

Solar Aircraft Company  
Research & Development Division  
Attn: Dr. A. Metcalfe  
San Diego, California

Solar  
Attn: Mr. J. Welty  
San Diego, California

DISTRIBUTION LIST  
(Continued)

Southwest Research Institute  
Attn: Mr. Steve Simpson  
8500 Culebra Road  
San Antonio 6, Texas

SSD (SSRTR, Mag. Eiler)  
AF Unit Post Office  
Los Angeles 45, California

Space Technology Laboratories, Inc.  
Attn: Dr. J. M. Denney  
Manager - Materials Department  
1 Space Park  
Redondo Beach, California

Special Metals, Inc.  
Attn: Research Librarian  
Middle Settlement Road  
New Hartford, New York

Stanford Research Institute  
Material Sciences Division  
Attn: Mr. E. P. Farley  
Ceramic Technologist  
Menlo Park, California

Stanford University  
Department of Materials Science  
Attn: B. A. Wilcox  
Stanford, California

Stanford Research Institute  
Material Sciences Division  
Attn: Edward S. Wright  
Menlo Park, California

Stauffer Metals Division  
Attn: Dr. J. Hum  
1201 South 47th Street  
Richmond, California

Steel Improvement and Forge Company  
Attn: Chief Metallurgist  
970 East 64th Street  
Cleveland 3, Ohio

Super Alloy Forge, Incorporated  
Hamburg, Michigan

Sylvania Electric Products, Inc.  
Chemical & Metallurgical Division  
Attn: Mr. P. W. Felten, Chief Engineer  
Towanda, Pennsylvania

Sylvania Corning Nuclear Corporation  
Attn: Mr. L. Sama  
P. O. Box 59  
Bayside 60, New York

Syracuse University  
Metallurgical Research Laboratories  
Attn: Volker Weiss  
Associate Professor of Metallurgy  
Building D-6 Collendale Campus  
Syracuse 10, New York

Temescal Metallurgical Corporation  
Attn: Dr. Charles Hunt  
2850 Seventh Street  
Berkeley 10, California

Texaco Experiment, Incorporated  
Attn: R. C. Scott  
P. O. Box 1-T  
Richmond 2, Virginia

Thiokol Chemical Corporation  
Attn: J. A. Bryson, Head  
Physics Department  
Brigham City, Utah

Thiokol Chemical Corporation  
Reaction Motors Division  
Attn: Raymond C. Kopituk  
Denville, New Jersey

Thompson-Ramo-Wooldridge, Inc.  
Attn: W. A. Johnson  
23555 Euclid Avenue  
Cleveland 17, Ohio

Timken Roller Bearing Company  
Attn: E. S. Rowland  
Canton, Ohio

DISTRIBUTION LIST  
(Continued)

Union Carbide Metals Company  
Attn: Dr. R. W. Fountain  
P. O. Box 580  
Niagara Falls, New York

Union Carbide Nuclear Company  
Attn: Mr. R. G. Jordan  
P. O. Box Y  
Oak Ridge, Tennessee

Headquarters, USAF  
Attn: AFRST-PM  
Washington 25, D. C.

Headquarters, USAF  
Attn: AFRST-PM  
(Maj. H. P. Hawkes, Jr.)  
Washington 25, D. C.

United Technology Corporation  
Attn: Mr. M. A. Schwartz  
Materials Technology Department  
P. O. Box 358  
Sunnyvale, California

Universal Cyclops Steel Corporation  
Attn: Library  
Bridgeville, Pennsylvania

Wah Chang Corporation  
Albany Division  
Attn: Mr. M. D. McNabb  
P. O. Box 366  
Albany, Oregon

Wah Chang Corporation  
Albany Division  
Attn: S. A. Worcester  
P. O. Box 366  
Albany, Oregon

Commanding Officer  
Watertown Arsenal  
Attn: Mr. S. V. Arnold  
Watertown, Massachusetts

Watertown Arsenal  
Ordnance Materials Research Office  
Attn: Mr. Norman L. Reed  
Assistant Director  
Watertown 72, Massachusetts

Department of Weapon Systems Support  
Training  
3345th Technical School, USAF  
Chanute Technical Training Center (ATC)  
UNITED STATES AIR FORCE  
Chanute Air Force Base, Illinois

Westinghouse Electric Corporation  
Lamp Division  
Attn: Dr. R. H. Atkinson  
Bloomfield, New Jersey

Westinghouse Electric Corporation  
Research Laboratories  
Attn: R. T. Begley  
Beulah Road, Churchill Borough  
Pittsburgh 35, Pennsylvania

Westinghouse Electric Corporation  
Attn: D. C. Goldberg  
Director Space Materials  
Department  
Churchill Borough  
R & D Center  
Pittsburgh 35, Pennsylvania

Westinghouse Electric Corporation  
Attn: Librarian  
Box 10864  
Pittsburgh 36, Pennsylvania

Westinghouse Electric Corporation  
Attn: Dr. F. L. Orrell, Manager  
Development Contracts  
P. O. Box 128  
Blairsville, Pennsylvania

Wyandotte Chemicals Corporation  
Research Division  
Attn: Librarian  
Wyandotte, Michigan

DISTRIBUTION LIST

(Continued)

Wyman-Gordon Company  
Attn: Mr. Arnold Rustay  
Worcester Street  
North Grafton, Massachusetts

Dr. Ervin E. Underwood  
Lockheed Missiles & Space Company  
Building 201  
3251 Honover Street  
Palo Alto, California

Aerojet General Corporation  
Attn: C. L. Meyers  
D/4610, 2019  
Solid Rocket Plant  
P. O. Box 1947  
Sacramento, California

Scientific and Technical Information  
Facility  
Attn: NASA Representative (S-AK/DL)  
P. O. Box 5700  
Bethesda, Maryland

Mr. B. E. Hopkins  
Metallurgy Division  
National Physical Laboratory  
Teddington, Middlesex  
England  
[ASD (ASYF, Mr. Troyan)]  
(Wright-Patterson AFB, Ohio)

Mr. R. S. Barnes  
Metallurgy Division  
A. E. R. E. Harwell  
Berkshire  
England  
[ASD (ASYF, Mr. Troyan)]  
(Wright-Patterson AFB, Ohio)

Dr. E. Smith  
Materials Division  
C. E. G. B. Research Laboratory  
Leatherhead, Surrey  
England  
[ASD (ASYF, Mr. Troyan)]  
(Wright-Patterson AFB, Ohio)

Dr. G. A. Geach  
Research Laboratory  
A. E. I. Limited  
Aldermaston, Berkshire  
England  
[ASD (ASYF, Mr. Troyan)]  
(Wright-Patterson AFB, Ohio)

Dr. T. Churchman  
Materials Division  
G. E. G. B. Nuclear Laboratories  
Berkeley, Gloucester  
England  
[ASD (ASYF, Mr. Troyan)]  
(Wright-Patterson AFB, Ohio)

Materials Research Laboratories, Inc.  
Attn: Dr. E. J. Ripling  
22333 Governors Highway  
Richton Park, Illinois

Dr. A. H. Cottrell  
Department of Metallurgy  
University of Cambridge  
Cambridge  
England  
c/o ASD (ASYF, Mr. Troyan)  
Wright-Patterson AFB, Ohio

Dr. P. B. Hirsch  
University of Cambridge  
Cavendish Laboratory  
Cambridge  
England  
c/o ASD (ASYF, Mr. Troyan)  
Wright-Patterson AFB, Ohio

Crucible Steel Company of America  
Central Research Laboratory  
Attn: Mr. R. Westgren  
234 Atwood Street  
Pittsburgh 13, Pennsylvania

General Electric Company  
FPLD  
Attn: Dr. W. Chang  
Cincinnati 15, Ohio

DISTRIBUTION LIST

(Continued)

University of Michigan  
Research Institute  
Attn: Dr. J. W. Freeman  
2211 East Engineering Building  
Ann Arbor, Michigan

Chief, Bureau of Naval Weapons  
Department of the Navy  
Attn: Mr. N. E. Promisel  
Washington 25, D. C.

Oak Ridge National Laboratories  
Metallurgy Laboratory  
Attn: Dr. C. J. McHargue  
P. O. Box 212  
Oak Ridge, Tennessee

Office of Scientific Research  
Attn: Mr. C. Yost  
Washington, D. C.

Aero Corporation  
Materials Research Department  
Attn: Dr. S. R. Maloof  
Wilmington, Massachusetts

Aeronautical Research Laboratory  
Attn: ARZ (Mr. E. J. Hassell)  
Wright-Patterson AFB, Ohio

Armetco Corporation  
Attn: A. E. Franks  
776 Kemrow Avenue  
Wooster, Ohio

Dr. R. W. Cahn  
Department of Materials  
University College of North Wales  
Bangor, North Wales  
United Kingdom  
c/o ASD (ASYF, Mr. Troyan)  
Wright-Patterson AFB, Ohio

General Electric Company  
Research Laboratory  
Attn: Mr. D. Lillie  
P. O. Box 1088  
Schenectady, New York

General Telephone and Electronics  
Laboratories, Inc.  
Bayside Laboratories  
Attn: Dr. C. D. Dickinson  
Bayside 60  
Long Island, New York

Dr. Walter S. Owen  
Department of Metallurgy  
University of Liverpool  
Liverpool 3  
England  
c/o ASD (ASYF, Mr. Troyan)  
Wright-Patterson AFB, Ohio

Massachusetts Institute of Technology  
Department of Metallurgy  
Attn: Dr. Morris Cohen  
Cambridge 39, Massachusetts

Massachusetts Institute of Technology  
Department of Metallurgy  
Attn: Prof. N. J. Grant  
Cambridge, Massachusetts

Massachusetts Institute of Technology  
Department of Metallurgy  
Attn: Dr. David A. Thomas  
Cambridge 39, Massachusetts

The Ohio State University  
Department of Metallurgical Engineering  
Attn: Prof. J. W. Spretnak  
Columbus, Ohio

Pratt and Whitney Aircraft  
Metallurgy Department  
Attn: Mr. G. H. Rowe  
CANEL  
Middletown, Connecticut

Rutgers, The State University  
Bureau of Engineering Research  
Attn: Dr. S. Weissmann  
New Brunswick, New Jersey

DISTRIBUTION LIST  
(Continued)

Prof. A. G. Quarrell  
Department of Metallurgy  
St. George's Square  
Sheffield 1  
England  
c/o ASD (ASYF, Mr. Troyan)  
Wright-Patterson AFB, Ohio

Commanding Officer  
Springfield Armory  
Attn: TIU  
Springfield 1, Massachusetts

Thompson Ramo Wooldridge  
Attn: Dr. A. Nemy  
23555 Euclid Avenue  
Cleveland 17, Ohio

University of Virginia  
Attn: Dr. R. R. Nash  
Thornton Hall  
Charlottesville, Virginia

<p>Aeronautical Systems Division, Dir/Materials and Processes, Metals &amp; Ceramics Lab, Wright-Patterson AFB, Ohio. Rpt No. ASD-TDR-63-360. INVESTIGATIONS OF THE RELATIONSHIP OF TWINNING TO BRITTLE STRUCTURE OF REFRACTORY METALS. Final report, 48 pp. Incl illus., tables, 64 refs.</p> <p>Unclassified Report</p> <p>The first year's work on this program is reported. It is concluded that there is good evidence for brittle fracture induced by mechanical twinning in single crystals and polycrystalline Mo-C with grain sizes larger than 0.40 mm. However there is no evidence for such failures in Mo-C of grain size smaller than 0.25 mm, or in high-purity Cb. The effect of recrystallization texture on twinning is demonstrated, and the</p> <p style="text-align: center;">( over )</p>	<p>1. Refractory metals 2. Crystal structure</p> <p>I. AFSC Project 7351, Task 735101 II. Contract No. III. AF 33(657)-7376 IV. Battelle Memorial Institute, Columbus, Ohio V. C. N. Reid, A. Gilbert, G. T. Hahn VI. Avail from OTS VII. In ASTIA collection</p>	<p>Aeronautical Systems Division, Dir/Materials and Processes, Metals &amp; Ceramics Lab, Wright-Patterson AFB, Ohio. Rpt No. ASD-TDR-63-360. INVESTIGATIONS OF THE RELATIONSHIP OF TWINNING TO BRITTLE STRUCTURE OF REFRACTORY METALS. Final report, 48 pp. Incl illus., tables, 64 refs.</p> <p>Unclassified Report</p> <p>The first year's work on this program is reported. It is concluded that there is good evidence for brittle fracture induced by mechanical twinning in single crystals and polycrystalline Mo-C with grain sizes larger than 0.40 mm. However there is no evidence for such failures in Mo-C of grain size smaller than 0.25 mm, or in high-purity Cb. The effect of recrystallization texture on twinning is demonstrated, and the</p> <p style="text-align: center;">( over )</p>	<p>1. Refractory metals 2. Crystal structure</p> <p>I. AFSC Project 7351, Task 735101 II. Contract No. III. AF 33(657)-7376 IV. Battelle Memorial Institute, Columbus, Ohio V. C. N. Reid, A. Gilbert, G. T. Hahn VI. Avail from OTS VII. In ASTIA collection</p>
<p>orientation dependence of twinning in Cb crystals is reported; a most unusual plastic instability is described in crystals of one orientation. It is shown that twinning in Mo-35Re occurs in bursts, which form in less than 2 <math>\mu</math>sec; nucleation of twins occurs only at small strains but lateral growth takes place up to at least 12 per cent strain.</p> <p style="text-align: center;">( over )</p>	<p>orientation dependence of twinning in Cb crystals is reported; a most unusual plastic instability is described in crystals of one orientation. It is shown that twinning in Mo-35Re occurs in bursts, which form in less than 2 <math>\mu</math>sec; nucleation of twins occurs only at small strains but lateral growth takes place up to at least 12 per cent strain.</p> <p style="text-align: center;">( over )</p>	<p>orientation dependence of twinning in Cb crystals is reported; a most unusual plastic instability is described in crystals of one orientation. It is shown that twinning in Mo-35Re occurs in bursts, which form in less than 2 <math>\mu</math>sec; nucleation of twins occurs only at small strains but lateral growth takes place up to at least 12 per cent strain.</p> <p style="text-align: center;">( over )</p>	<p>orientation dependence of twinning in Cb crystals is reported; a most unusual plastic instability is described in crystals of one orientation. It is shown that twinning in Mo-35Re occurs in bursts, which form in less than 2 <math>\mu</math>sec; nucleation of twins occurs only at small strains but lateral growth takes place up to at least 12 per cent strain.</p> <p style="text-align: center;">( over )</p>